







Assessmen	nt Campus	Linked Bldg	Addition	Room	Assessment		Description	Building System		Building System		Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID		System			Year	Status		L1	L2	L3	L4						
4822	Batavia High School	1899 - Ceilings, Acoustical Suspended Systems - 1995	East 2-Story Classrooms (1995	Science Lab		Sent to Maintenance	ACT in poor condition; rust/corrosion on ACT grid, ceiling panels in poor condition; rust/corrosion on ceiling-mounted mechanical	Interiors	Interior Construction		Acoustical Suspended Ceilings	1-Must Do	Poor	2250	\$8	Square Foot	\$16,875
4827	Batavia High School	1717 - Flooring, Carpet - 1971	LRC, Classrooms (1971)	Learning Center		Sent to Maintenance	Carpet looks original to the space and appears worn throughout. Per Capital Projects Plan, scheduled to be replaced. (B119D) "The Back Room" Lounge.	Interiors	Interior Finishes	Flooring	Carpeting	1-Must Do	Poor	12570	\$7	Square Foot	\$81,705
4837	Batavia High School	2010 - Plumbing, Plumbing Fixtures - 1995		Science Lab	2020	Sent to Maintenance	Library Work Room Sinks: leaking faucets C202, C204,	Services	Plumbing	Domestic Water Distribution	Plumbing Fixtures	1-Must Do	Poor	16	\$2,500	Each	\$40,000
4854	Batavia High School	2011 - Plumbing,	North Classrooms, SW Mechanical (2009)	Science Lab		Sent to Maintenance	Sink: Sinks aren't connected. Lights didn't come on at same time D205. Sink: Sinks aren't connected to water	Services	Plumbing	Domestic Water Distribution	Plumbing Fixtures	1-Must Do	Poor	0	\$2,500	Each	\$0
4990	Batavia High School	1951 - Interior Wall Finish, Paint Original	-	Toilet		Sent to Maintenance	Wall paint in poor condition. Quantity reflects total SF of all lister spaces. Toilets in A110 - Mens' Team Locker Room		Interior Finishes		Wall Painting and Coating	1-Must Do	Poor	185	\$2	Square Foot	\$416
4991	Batavia High School	1728 - Plumbing, Plumbing Fixtures - Original		Toilet		Sent to Maintenance	Fixtures in poor condition boys by B124 Girls by B124	Services	Plumbing	Domestic Water Distribution	Plumbing Fixtures	1-Must Do	Poor	0	\$2,000	Each	\$0
5007	Batavia High School	2019 - Interior Wall Finish, Tile - 1971	LRC, Classrooms (1971)	Abandoned Toilet		Sent to Maintenance	Poor condition; Room still contains mosaic ceramic floor tile and ceramic wall tile; no fixtures; used as storage.	Interiors	Interior Finishes	Wall Finishes	Tile Wall Finish	1-Must Do	Poor	926	\$30	Square Foot	\$27,780
5017	Batavia High School	1804 - Ceilings, Acoustical Suspended Systems - 1995 Entry	Central Area, South Entrance (1995)	Toilet	2020	Sent to Maintenance	damaged tile and rusted ceiling grid (add photo). Boys by Café	Interiors	Interior Construction		Acoustical Suspended Ceilings	1-Must Do	Poor	601	\$8	Square Foot	\$4,508
5023	Batavia High School	1821 - Flooring,	Central Area, South Entrance (1995)	Toilet	2020	Sent to Maintenance	flooring ceramic tile grout is very dirty throughout (attach photo). Cost to replace. boys by cafe. girls by cafe.	Interiors	Interior Finishes	Flooring	Tile Flooring	1-Must Do	Poor	550	\$30	Square Foot	\$16,500
5029	Batavia High School	1975 - Interior Wall Finishes, Wall Base - 1995	Central Area, South Entrance (1995)	Toilet	2020	Sent to Maintenance	Wall base SGFT base; grout very dirty (attch photo). Cost to clean. Boys by cafe Girls by cafe	Interiors	Interior Finishes	Wall Finishes		1-Must Do	Poor	130	\$2	Linear Foot	\$260
5036	Batavia High School	1991 - Interior Wall Finish, Paint 1995	Central Area, South Entrance (1995)	Toilet		Sent to Maintenance	Wall paint is in fair condition - stained/scuffed throughout. Quantity reflects total SF of all listed spaces. Boys in c wing 1. Boys by c119. Boys by Café.		Interior Finishes		Wall Painting and Coating	1-Must Do	Poor	1100	\$2	Square Foot	\$2,475












Accommont	Commune	Linkod Bldg	Addition Boo	m Assa	amont Assessmen	t Description	Duilding Custom	Duilding Custom	Duilding Custom	Duilding Custom	Deionity	Facility Candition	Quantity	Linit Cost	Unit Of Magazina	Estimated Cost
Assessment	t Campus	Linked Bldg	Addition Roo		sment Assessmer	t Description			Building System		Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID 5120	Datavia High	System 1695 - Interior	Office / Po		Sent to	HM door frame in poor condition.	L1	L2	L3 Interior Doors	L4 Interior Swinging	1 Must Do	Poor	1	\$2,400	Each	\$2,400
5128	Batavia High School	Doors, Swinging-	Office / Pi	iii-Out 2020		-	Interiors	Interior Construction	Interior Doors	Doors	1-Must Do	Poor	1	\$2,400	Each	\$2,400
	SCHOOL	Wood - Original			Maintenance	, , ,	,	Construction		Doors						
		wood - Original				frame. B114A (Pull-Out) - Bottom of frame										
5164	Datavia High	1704 - Flooring,	Classraan	s 2020	Sent to	is in very bad condition VCT in poor condition. Portions of	Interiors	Interior Finishes	Flooring	Resilient Flooring	1 Must Do	Poor	1723	\$12	Square Foot	\$20,676
5104	Batavia High School	VCT - Original	Classroon	2020		•	interiors	interior rinishes	FIOOTING	Resilient Flooring	1-iviust Do	P001	1/23	\$12	Square Foot	\$20,070
	SCHOOL	VCI - Original			Maintenance	floor are cracking and bubbling. Damaged and discolored tiles near										
						casework. Cost to replace VCT with										
						rubber flooring.										
						rubber noornig.										
						B112.										
						B113										
5178	Batavia High	1732 - Fixed	Classroon	s 2020	Sent to	Casework in poor condition. Cost to	Fauinment and	Furnishings	Fixed Furnishings	Casework	1-Must Do	Poor	140	\$800	Linear Foot	\$112,000
3176	School	Equipment,	Classicon	2020	Maintenance		Furnishings	i urinsinings	Tixed Fulfillstilligs	Casework	1-Wast Do	1 001	140	7800	Linear 100t	7112,000
	3011001	Casework -			Wallicellance	replace entirely.	i urilisilligs									
		Original				B107 - Upper cabinets have										
		Original				delaminated in several locations.										
						Chunks missing out on the corner of	f									
						desk legs.	'									
						B114 - Lower cabinets missing doors	s									
						and others missing pulls.										
5188	Batavia High	1894 - Interior	North Central Classroom	s 2020	Sent to	Wood door in poor condition -	Interiors	Interior	Interior Doors	Interior Swinging	1-Must Do	Poor	1	\$1,950	Square Foot	\$1,950
3233	School	Doors, Swinging-	Classrooms (1969)	2020	Maintenance	·		Construction		Doors	2		-	\$2,555	3444.6.000	4 1/330
		Wood - 1969	(2000,			visible, see photo.										
		11000 1505				visite, see prioto:										
						A126										
5197	Batavia High	1898 - Ceilings,	North Central Classroom	s 2020	Sent to	ACT in poor condition - all tiles are	Interiors	Interior	Suspended Ceiling	Acoustical	1-Must Do	Poor	653	\$8	Square Foot	\$4,898
	School	Acoustical	Classrooms (1969)		Maintenance			Construction	Construction	Suspended				7-		7 1,000
		Suspended	0.000.000 (2000)		- Trained Tariot	201104,04888.		Constituction	0011361 4061011	Ceilings						
		Systems - 1969				A127				85						
5240	Batavia High	1685 - Exterior	LRC, Classrooms Classroom	s 2020	Sent to	Windows are original and not	Shell	Exterior Vertical	Exterior Windows	Exterior	1-Must Do	Poor	50	\$100	Square Foot	\$5,000
	School	Windows,	(1971)		Maintenance			Enclosures		Operating				,		, , , , , ,
		Operating - 1971				temperature change near them.				Windows						
						Pull down shades do not work. Cost										
						to replace windows (\$100) and										
						shades (\$90).										
						,,,,,										
						B103										
5243	Batavia High	1909 - Flooring,	North Central Office / Po	III-Out 2020	Sent to	VCT is in Poor Condition. Cost to	Interiors	Interior Finishes	Flooring	Resilient Flooring	1-Must Do	Poor	80	\$12	Square Foot	\$960
	School	VCT - 1969	Classrooms (1969)		Maintenance	replace VCT with rubber flooring.										
			, ,			A123A (Graphics Office) - yellowed										
						and stained										
5252	Batavia High	1910 - Flooring,	East 2-Story Classroon	s 2020	Sent to	VCT in poor condition - almost 50%	Interiors	Interior Finishes	Flooring	Resilient Flooring	1-Must Do	Poor	5652	\$12	Square Foot	\$67,824
	School	VCT - 1995	Classrooms (1995)		Maintenance	-										
						and stained, different colors of tile										
						throughout room, tiles separating.										
						Cost to replace VCT with rubber										
						flooring.										
						C102.										
						C103.										
1						C104.										
						C105.										
						C107.										
						C113.										
						C119.										
<u> </u>	1					C113.										1









Assessment ID	t Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cos
5258	Batavia High School	1921 - Interior Partitions, Fixed- CMU - 1995	East 2-Story Classrooms (1995	Classrooms (i)	2020	Sent to Maintenance	CMU in poor condition - cracking through blocks at corner, large sealant separations at corners.	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	1-Must Do	Poor	30	\$15	Linear Foot	\$450
						_	C103										
5294	Batavia High School	1984 - Electrical, Lighting Fixtures - 2009	North Classrooms, SW Mechanical (2009)	Classrooms	2020	Sent to Maintenance	Lighting in poor condition. Lights flickered when they came on, didn't all turn on right away. D105 - one fixture out. D108 - a couple lights not fully	Services	Electrical	Lighting	Lighting Fixtures	1-Must Do	Poor (0	\$8	Square Foot	\$0
							illuminated.										
5299	Batavia High School	1698 - Ceilings, Acoustical Suspended Systems - Original		Storage/Mechanic al	2020	Sent to Maintenance	ACT ceiling in poor condition. Maintenance office by b124	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	1-Must Do	Poor	72	\$8	Square Foot	\$540
5326	Batavia High School	1909 - Flooring, VCT - 1969	North Central Classrooms (1969	_	2020	Sent to Maintenance	stained and missing tiles. Cost to replace VCT with rubber flooring. located in A124	Interiors	Interior Finishes	Flooring	Resilient Flooring	1-Must Do	Poor 2	200	\$12	Square Foot	\$2,400
5340	Batavia High School	1896 - Interior Doors, Swinging- Wood - 1995	Central Area, South Entrance (1995)	Storage	2020	Sent to Maintenance	Interior wood door in poor condition. Janitor in mid c wing	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	1-Must Do	Poor :	1	\$1,950	Each	\$1,950
5345	Batavia High School	1850 - Interior Doors, Swinging- Hollow Metal - 1995	Central Area, South Entrance (1995)	Storage	2020	Sent to Maintenance	Interior HM frame in poor condition. Cost to replace. Janitor in mid c wing	. Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	1-Must Do	Poor	1	\$450	Each	\$450
5348	Batavia High School	1804 - Ceilings, Acoustical Suspended Systems - 1995 Entry	Central Area, South Entrance (1995)	Storage	2020	Sent to Maintenance	rusting grid; damaged ceiling tile Storage near Café TR	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	1-Must Do	Poor 8	83	\$8	Square Foot	\$623
5349	Batavia High School	1825 - Flooring, VCT - 1995 Entry	Central Area, South Entrance (1995)	Storage	2020	Sent to Maintenance	stained/damaged throughout (attach photo). Cost to replace VCT with rubber flooring. Storage near Café TR Cafe storage	Interiors	Interior Finishes	Flooring	Resilient Flooring	1-Must Do	Poor :	334	\$12	Square Foot	\$4,008
5352	Batavia High School	1744 - Slab on Grade - 1995	Central Area, South Entrance (1995)	Storage	2020	Sent to Maintenance	Epoxy flooring in poor condition. Janitor/elec by c119	Substructure	Slabs-On-Grade	Standard Slabs-on- Grade		1-Must Do	Poor 8	80	\$20	Square Foot	\$1,600
5358	Batavia High School	1974 - Interior Wall Finishes, Wall Base - 1995	Central Area, South Entrance (1995)	Storage	2020	Sent to Maintenance	Wall base in poor condition or missing. Storage near Café TR	Interiors	Interior Finishes	Wall Finishes		1-Must Do	Poor	37	\$6	Linear Foot	\$222
5360	Batavia High School	1991 - Interior Wall Finish, Paint - 1995	East 2-Story Classrooms (1995	, , , , , , , , , , , , , , , , , , ,	2020	Sent to Maintenance	Wall paint in poor condition. Quantity reflects total SF of all listed spaces. Janitor in mid c wing. Janitor/elec by c119.	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	1-Must Do	Poor :	145	\$2	Square Foot	\$326
5367	Batavia High School	1825 - Flooring, VCT - 1995 Entry	Central Area, South Entrance (1995)	Storage	2020	Sent to Maintenance	VCT tile missing or damaged near entry. Cost to replace VCT with rubber flooring. A146B	Interiors	Interior Finishes	Flooring	Resilient Flooring	1-Must Do	Poor	796	\$12	Square Foot	\$9,552
5414	Batavia High School	1993 - Interior Wall Finish, Paint - 2009	North - Classrooms, SW - Mechanical	Storage	2020	Sent to Maintenance	Wall paint is in poor condition. D113	Interiors	Interior Finishes		Wall Painting and Coating	1-Must Do	Poor 3	385	\$2	Square Foot	\$866









ssessment	Campus	Linked Bldg	Addition	Room	Assessment	Assessment	Description	Building System L1		Building System		Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cos
	Batavia High School	System 1909 - Flooring, VCT - 1969	Classrooms (1969)		Year 2020	Sent to Maintenance	VCT in poor condition. Cost to replace VCT with rubber flooring. Room #: A123	Interiors	L2 Interior Finishes	L3 Flooring	L4 Resilient Flooring	1-Must Do	Poor	1099	\$12	Square Foot	\$13,188
5452	Batavia High School	1909 - Flooring, VCT - 1969	North Central Classrooms (1969)	Art Rooms	2020	Sent to Maintenance	VCT in poor condition. Cost to replace VCT with rubber flooring. Room #: A123	Interiors	Interior Finishes	Flooring	Resilient Flooring	1-Must Do	Poor	1099	\$12	Square Foot	\$13,188
5465	Batavia High School	1753 - Exterior Windows, Operating - 1995	East 2-Story Classrooms (1995)	Classrooms	2020	Sent to Maintenance	Window jammed in open position - district has been notified. C212	Shell	Exterior Vertical Enclosures	Exterior Windows	Exterior Operating Windows	1-Must Do	Immediate Need	24	\$100	Square Foot	\$2,400
5483	Batavia High School	1984 - Electrical, Lighting Fixtures - 2009	North Classrooms, SW Mechanical (2009)	Science Classrooms	2020	Sent to Maintenance	Lighting in poor condition - Lights flickered when they came on, didn't all turn on right away, 1 took about 30 sec to turn on, another out.	Services	Electrical	Lighting	Lighting Fixtures	1-Must Do	Poor	0	\$8	Square Foot	\$0
5501	Batavia High School	2005 - HVAC, Ventilation-Unit Ventilators - 1995	East 2-Story Classrooms (1995)	Classrooms	2020	Sent to Maintenance	Unit vent in poor condition - front grille is on the floor. C118	Services	Heating, Ventilation, and Air Conditioning (HVAC)	Ventilation	Supply Air	1-Must Do	Poor	1	\$4,500	Each	\$4,500
5510	Batavia High School	1929 - Fixed Equipment, Casework - 1969	North Central Classrooms (1969)	Art Rooms	2020	Sent to Maintenance	Room #: A123 Edgebanding is peeling. Plastic Laminate is worn on surface of doors/drawings (attach photo). Cost to replace entirely.	Equipment and Furnishings	Furnishings	Fixed Furnishings	Casework	1-Must Do	Poor	32	\$800	Linear Foot	\$25,600
5582	Batavia High School	1951 - Interior Wall Finish, Paint - Original		Toilet	2020	Sent to Maintenance	Wall paint in poor condition. Quantity reflects total SF of all listed spaces. Mens Faculty Center - paint is cracking on plan north wall and needs to be repainted. Womens Faculty Center	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	1-Must Do	Poor	282	\$2	Square Foot	\$635
5738	Batavia High School	2111 - Fixed Equipment, Window Treatments- Manual - 1995	East 2-Story Classrooms (1995)	Classrooms	2020	Sent to Maintenance	Blinds in poor condition. C105	Equipment and Furnishings	Furnishings	Fixed Furnishings	Window Treatments	1-Must Do	Poor	60	\$90	Square Foot	\$5,400
5740	Batavia High School		North Classrooms, SW Mechanical (2009)	Classrooms	2020	Sent to Maintenance	Wood door in poor condition - edges very chipped, veneer scratched.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	1-Must Do	Poor	1	\$1,950	Each	\$1,950
5853	Batavia High School	1910 - Flooring, VCT - 1995		Stair		Sent to Maintenance	VCT flooring cracked at doorway, broken/missing tiles at exterior doors. Cost to replace VCT with rubber flooring. Stair by C107 level 1.	Interiors	Interior Finishes	Flooring	Resilient Flooring	1-Must Do	Poor	406	\$12	Square Foot	\$4,872
5869	Batavia High School	1910 - Flooring, VCT - 1995	East 2-Story Classrooms (1995)	Elevator	2020	Sent to Maintenance	VCT flooring in poor condition. Cost to replace VCT with rubber flooring. C-Wing Elevator	Interiors	Interior Finishes	Flooring	Resilient Flooring	1-Must Do	Poor	50	\$12	Square Foot	\$600
5877	Batavia High School	1804 - Ceilings, Acoustical Suspended Systems - 1995 Entry	Central Area, South Entrance (1995)	Corridor		Sent to Maintenance	ACT ceiling in poor condition (bowed/damaged tile throughout; stained grid (attach photo). E/W Corridor between café and Gym	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	1-Must Do	Poor	1800	\$8	Square Foot	\$13,500









				_				D 11 11 C 1		D 11 11 0 1	5 11 11 6 1	- · ·					- · · · · · · · · · · · · · · · · · · ·
Assessment	Campus	Linked Bldg	Addition	Room	Assessmen		Description			Building System		Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID 5883	Batavia High	System 1825 - Flooring,	Central Area,	Corridor	Year 2020	Status Sent to	VCT flooring in poor condition	L1 Interiors	L2 Interior Finishes	L3 Flooring	L4 Resilient Flooring	1 Must Do	Poor	1800	\$12	Square Foot	\$21,600
3003	School	<u>.</u>	South Entrance	Corridor	2020	Maintenance	(cracking in tile). Cost to replace VCT		interior rinishes	Flooring	Resilient Flooring	1-Must Do	1001	1800	\$12	Square Foot	\$21,600
	3011001	VCI - 1555 Entry	(1995)			Maintenance	with rubber flooring.										
			(1333)				E/W Corridor between café and										
5887	Batavia High	1974 - Interior	Central Area,	Corridor	2020	Sent to	Wall base in poor condition (SGFT is	Interiors	Interior Finishes	Wall Finishes		1-Must Do	Poor	500	\$2	Linear Foot	\$1,000
	School	Wall Finishes,	South Entrance			Maintenance	dirty, scratched and grout is dirty).								7-		7 - 7 - 7 - 7
		Wall Base - 1995	(1995)				E/W Corridor between café and										
5894	Batavia High	1990 - Interior	Central Area,	Corridor	2020	Sent to	paint is stained/scuffed throughout.	Interiors	Interior Finishes	Wall Finishes	Wall Painting and	1-Must Do	Poor	1800	\$2	Square Foot	\$4,050
	School	Wall Finish, Paint -	South Entrance			Maintenance	Quantity reflects total SF of all listed				Coating						
		1995 Entry	(1995)				spaces.										
							E/W Corridor between café and										
5917	Batavia High		LRC, Classrooms	Corridor	2020	Sent to	Exterior HM door in poor condition;	Shell	Exterior Vertical	Exterior Doors	Exterior Entrance	1-Must Do	Poor	2	\$1,200	Each	\$2,400
	School	Entrance Doors,	(1971)			Maintenance	1 pair with sidelites and transoms.		Enclosures	and Grilles	Doors						
		Hollow Metal -					Cost to replace door and hardware.										
		1971				_	Corridor btwn B115 + B114						_	_	1		
5918	Batavia High	1687 - Exterior		Corridor	2020	Sent to	Exterior HM frame in poor condition	Shell	Exterior Vertical	Exterior Doors	Exterior Entrance	1-Must Do	Poor	1	\$600	Each	\$600
	School		(1971)			Maintenance	(extremely rusted). Cost to replace.		Enclosures	and Grilles	Doors						
		Hollow Metal -					Corridor btwn B115 + B114										
5919	Batavia High	1971 1699 - Ceilings,	LRC, Classrooms	Corridor	2020	Sent to	ACT ceiling in poor condition (frame	Interiors	Interior	Suspended Ceiling	Acquetical	1-Must Do	Poor	940	\$8	Square Foot	\$7,050
3313	School	Acoustical	(1971)	Corridor	2020	Maintenance	rusted near door, soffit and adjacent		Construction	Construction	Suspended	1-Must Do	POOI	940	30	Square Foot	\$7,030
	3011001	Suspended	(1971)			ivialifice	tiles water damaged)	-	Construction	Construction	Ceilings						
		Systems - 1971					Corridor btwn B115 + B114				Cellings						
5921	Batavia High		LRC, Classrooms	Corridor	2020	Sent to	VCT flooring in poor condition. Cost	Interiors	Interior Finishes	Flooring	Resilient Flooring	1-Must Do	Poor	950	\$12	Square Foot	\$11,400
	School	VCT - 1971	(1971)			Maintenance	to replace VCT with rubber flooring.			3.3 0					ľ		, ,
			,				Corridor btwn B115 + B114										
5977	Batavia High	1825 - Flooring,	Central Area,	corridor	2020	Sent to	VCT flooring in fair condition. Cost	Interiors	Interior Finishes	Flooring	Resilient Flooring	1-Must Do	Poor	1800	\$12	Square Foot	\$21,600
	School	VCT - 1995 Entry	South Entrance			Maintenance	to replace VCT with rubber flooring.										
			(1995)				Corridor south of A103										
5978	Batavia High	1990 - Interior	Central Area,	corridor	2020	Sent to	Wall paint in poor condition.	Interiors	Interior Finishes	Wall Finishes	Wall Painting and	1-Must Do	Poor	1800	\$2	Square Foot	\$4,050
	School	Wall Finish, Paint -				Maintenance	Quantity reflects total SF of all listed				Coating						
		1995 Entry	(1995)				spaces.										
							Corridor south of A103.						_		4		4
6023	Batavia High	1709 - Interior		Fitness Center	2020	Sent to	Interior HM door's paint touch-up	Interiors	Interior	Interior Doors	Interior Swinging	1-Must Do	Poor	1	\$1,500	Each	\$1,500
	School	Doors, Swinging-				Maintenance	required and panic hardware is		Construction		Doors						
		Hollow Metal - Original					rusted. Cost to replace door and hardware.										
		Original					A103										
6033	Batavia High	1709 - Interior		Locker Room	2020	Sent to	Interior HM door, paint touch-up	Interiors	Interior	Interior Doors	Interior Swinging	1-Must Do	Poor	3	\$1,500	Each	\$4,500
0000	School	Doors, Swinging-		200110111100111	2020	Maintenance	required and panic hardware is		Construction		Doors	2			\$2,500	200	ψ .,σσσ
		Hollow Metal -					rusted.										
		Original					A104W Locker Room.										
		J					A108Men's Locker Room.										
							A110 Mens' Team Locker Room										
							(Doors are due for replacement,										
							damaged throughout)										
6043	Batavia High	1743 - Interior		Locker Room	2020	Sent to	wall base in poor condition.	Interiors	Interior Finishes	Wall Finishes		1-Must Do	Poor	175	\$6	Linear Foot	\$1,050
	School	Wall Finishes,				Maintenance	A110 Mens' Team Locker Room										
		Wall Base -															
6049	Batavia High	1670 - Slab on		Locker Room	2020	Sent to	, , ,	Substructure	Slabs-On-Grade	Standard Slabs-on	-	1-Must Do	Poor	2908	\$20	Square Foot	\$58,160
	School	Grade - Original				Maintenance	A104W Locker Room1670 SF			Grade							
							A108Men's Locker Room1238 SF			1							










Assessment	Campus	Linked Bldg	Addition	Room	Assessmen	t Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	e Estimated Cost
ID	Campus	System	, tadition	illooiii	Year	Status	Description	L1	L2	L3	L4	·······································	ruemey condition	Quantity	Oint Cost	ome or measure	25timated cost
6059	Batavia High	1974 - Interior	Central Area,	Cafeteria	2020	Sent to	Wall base in poor condition (SGFT	Interiors	Interior Finishes	Wall Finishes		1-Must Do	Poor	450	\$6	Square Foot	\$2,700
	School	Wall Finishes,	South Entrance			Maintenance	base scuffed and dirty grout								·		'
		Wall Base - 1995	(1995)				throughout (attach photo); vinyl										
		Entry					wall base in good condition).										
							A100										
6060	Batavia High	1990 - Interior	Central Area,	Cafeteria	2020	Sent to	Wall paint in poor condition (stained	Interiors	Interior Finishes	Wall Finishes	Wall Painting and	1-Must Do	Poor	9800	\$2	Square Foot	\$22,050
	School	Wall Finish, Paint -	South Entrance			Maintenance	and chipped throughout; peeling at				Coating						
		1995 Entry	(1995)				exterio steel lintels). Quantity										
							reflects total SF of all listed spaces.										
							A100						_		400		4
6085	Batavia High		Central Area,	W locker room	2020	Sent to	Epoxy flooring in poor condition.	Interiors	Interior Finishes	Flooring	Fluid-Applied	1-Must Do	Poor	2715	\$20	Square Foot	\$54,300
	School		South Entrance (1995)			Maintenance	A106				Flooring						
6117	Batavia High	Entry 1853 - Interior	BFAC, Fieldhouse	Storage	2020	Sent to	Interior HM door in poor condition.	Interiors	Interior	Interior Doors	Interior Swinging	1-Must Do	Poor	1	\$1,500	Each	\$1,500
0117	School	Doors, Swinging-	(2011)	Storage	2020	Maintenance	F112JSTORAGE	interiors	Construction	interior Doors	Doors	1-iviust DO	POOI	1	\$1,500	EdCII	\$1,500
	3011001	Hollow Metal -	(2011)			Wantenance	TIZISTORAGE		Construction		20013						
		2011															
6137	Batavia High		East 2-Story	Corridor,	2020	Sent to	C-Wing, 2nd floor corridor near	Interiors	Interior Finishes	Flooring	Resilient Flooring	1-Must Do	Poor	46	\$60	Linear Foot	\$2,760
	School	VCT - 1995	Classrooms (1995			Maintenance	elevator and into classroom -								,		, ,
			,				building expansion joint is failing/in										
							poor condition										
6142	Batavia High	2111 - Fixed	East 2-Story	Classrooms	2020	Sent to	Blinds in poor condition, C-wing,	Equipment and	Furnishings	Fixed Furnishings	Window	1-Must Do	Poor	120	\$90	Square Foot	\$10,800
	School	Equipment,	Classrooms (1995	5)		Maintenance	2nd floor classrooms (except C219)	Furnishings			Treatments						
		Window															
		Treatments-															
		Manual - 1995															
6155	Batavia High	1703 - Flooring,	Central Area,	Toilet	2020	Sent to	flooring ceramic tile grout is very	Interiors	Interior Finishes	Flooring	Tile Flooring	1-Must Do	Poor	400	\$30	Square Foot	\$12,000
	School	Ceramic Tile -	South Entrance			Maintenance	dirty throughout (attach photo).										
		Original	(1995)				Cost to replace tile.										
6150	Potovio High	1021 Interior	Fact 2 Stone	Toilet	2020	Cont to	Toilets in A106	fintariars	Interior	Interior Dartitions	Interior Fixed	1 Must Do	Door	10	\$15	Linear Foot	\$150
6158	Batavia High School	1921 - Interior Partitions, Fixed-	East 2-Story Classrooms (1995		2020	Sent to Maintenance	Crack in CMU at southwest corner or room previously sealed; needs	interiors	Interior Construction	Interior Partitions	Partitions	1-Must Do	Poor	10	\$12	Linear Foot	\$150
	SCHOOL	CMU - 1995	Classioonis (1993	9)		iviaintenance	resealed.		Construction		Partitions						
		CIVIO - 1993					South Girls Toilet, 2nd floor										
6159	Batavia High	1748 - Exterior	Central Area,		2020	Sent to	Weep vents missing at face brick	Shell	Exterior Vertical	Exterior Walls	Exterior Wall	1-Must Do	Poor	18	\$12	Linear Foot	\$216
	School		South Entrance			Maintenance	below windows; currently gaps in		Enclosures		Veneer				*		7
		Entry	(1995)				mortar joints. Cost to tuckpoint.										
		,	,				East portion of entrance addition,										
							near 1971 addition.										
6160	Batavia High	1684 - Exterior	LRC, Classrooms		2020	Sent to	Weep vents missing at face brick	Shell	Exterior Vertical	Exterior Walls	Exterior Wall	1-Must Do	Poor	24	\$12	Linear Foot	\$288
	School	Face Brick - 1971	(1971)			Maintenance	below windows; currently gaps in		Enclosures		Veneer						
							mortar joints. Cost to tuckpoint.										
							South portion of addition, near 1995	5									
							entrance addition.										
6161	Batavia High		Central Area,		2020	Sent to	Expansion joint material missing	Shell	Exterior Vertical	Exterior Walls	Exterior Wall	1-Must Do	Poor	14	\$60	Linear Foot	\$840
	School		South Entrance			Maintenance	where additions join; east portion of	f	Enclosures		Veneer						
		Entry	(1995)				entrance addition, near 1971										
6163	Potovio Liink	1960 5-4	Fact 2 Ctam		2020	Cont to	addition.	Chall	Exterior Vantia - I	Fytorion Walls	Exterior Mail	1 Must De	Door	1.4	¢60	Lincar Fast	¢940
6162	Batavia High		East 2-Story	-1	2020	Sent to	' ' '	Shell	Exterior Vertical	exterior walls	Exterior Wall	1-Must Do	Poor	14	\$60	Linear Foot	\$840
	School	Face Brick - 1995	Ciassi oomis (1995	2)		Maintenance	condition where addition joins with 1971 addition.		Enclosures		Veneer						
6164	Batavia High	3883 - Exterior	East 2-Story		2020	Sent to		Shell	Exterior Vertical	Exterior Walls	Exterior Wall	1-Must Do	Poor	56	\$60	Linear Foot	\$3,360
0104	School		Classrooms (1995	5)	2020	Maintenance		SHEII	Enclosures	LACETION WAIIS	Construction	I WIGST DO	7 001	50	900	Linear 1 00t	73,300
	3011001	i i ccust - 1555	C.0331 OOI113 (133)	"		Maniferiance	east and west (courtyard) sides of		Liciosaies		Construction						
							east and west (courtvaro) sides of										









1.					1.	T -				D 11 11 11 11 11 11 11 11 11 11 11 11 11	B !!!! 6 .		- 11: 0 II:				T 10 .
Assessmen	t Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
6165	Batavia High School		BFAC, Fieldhouse (2011)		2020	Sent to Maintenance	Expansion joint material in poor condition between precast panels at BFAC flyspace (east and west facades).	Shell	Exterior Vertical Enclosures	Exterior Walls	Exterior Wall Construction	1-Must Do	Poor	96	\$60	Linear Foot	\$5,760
6172	Batavia High School	4243 - Exterior Architectural Wall Panels	North Classrooms, SW Mechanical (2009)		2020	Sent to Maintenance	Exterior architectural panels are in poor condition; face finish is delaminating and bubbling across entire facade. May require replacement of window system depending on system construction/installation.	Shell	Exterior Vertical Enclosures	Exterior Walls	Exterior Wall Construction	1-Must Do	Poor	340	\$45	Square Foot	\$37,800
6178	Batavia High School	1736 - Sitework, Parking Lot Pavement			2020	Sent to Maintenance	Per Capital Projects Plan - Wilson St. parking lot scheduled for replacement in 2032, but in poor condition. Cost to replace with heavy duty asphalt.	Sitework	Site Improvements	Parking Lots	Parking Lot Pavement	1-Must Do	Poor :	188000	\$8	Square Foot	\$1,410,000
6184	Batavia High School	4821 - Plumbing, Domestic Water Piping			2020	Sent to Maintenance	Per Capital Project Plan - replace domestic water piping in building areas prior to 1995 additions and renovations. Does not include fixture replacement or removal of chase	Services	Plumbing	Domestic Water Distribution	Domestic Water Piping	1-Must Do	Poor :	1	\$475,000	Lump Sum	\$475,000
6187	Batavia High School	1722 - HVAC, Heating-RTU			2020	Sent to Maintenance	Per Capital Projects Plan - RT-1 and RT-2 in poor condition.	Services	Heating, Ventilation, and Air Conditioning (HVAC)	Heating Systems		1-Must Do	Poor 2	2	\$122,500	Each	\$245,000
6188	Batavia High School	1723 - HVAC, Ventilation-AHU			2020	Sent to Maintenance	Per Capital Projects Plan - AHU S1, 2, 3, 4, 5, 6, 7 in poor condition	Services	Heating, Ventilation, and Air Conditioning (HVAC)	Ventilation	Supply Air	1-Must Do	Poor :	1	\$800,000	Lump Sum	\$800,000
6229	Batavia High School	5292 - Exterior Site Lighting			2013	Sent to Maintenance	Per Capital Projects Plan & 2013 site Master Plan - stadium lighting scheduled for replacement with modification of bleachers.	Sitework	Electrical Site Improvements	Site Lighting	Area Lighting	1-Must Do	Poor :	1	\$450,000	Lump Sum	\$450,000
6230	Batavia High School	5292 - Exterior Site Lighting			2013	Sent to Maintenance	Per Capital Projects Plan and 2013 Site Master Plan - tennis court lighting scheduled for replacement. Cost includes escalation from 2013.	Sitework	Electrical Site Improvements	Site Lighting	Area Lighting	1-Must Do	Poor :	1	\$550,000	Lump Sum	\$550,000
7827	Batavia High School	8419 - Exterior, Guardrails and Handrails	BFAC, Fieldhouse (2011)		2020	Sent to Maintenance	Exterior HM handrails and guardrails are rusted. Cost to remove and replace.	Sitework	Site Improvements	Pedestrian Plazas and Walkways		1-Must Do	Poor 2	26	\$125	Linear Foot	\$3,250
7831	Batavia High School	1674 - Exterior Windows, Fixed - Original			2020	Sent to Maintenance	Original steel windows rusting and infill panel damaged; H/LS report indicates single pane windows should be replaced. Cost to replace.	Shell	Exterior Vertical Enclosures	Exterior Windows	Exterior Fixed Windows	1-Must Do	Poor :	100	\$90	Square Foot	\$9,000
7832	Batavia High School	1738 - Sitework, Pedestrian Pavement			2020	Sent to Maintenance	Concrete sidewalk damaged.	Sitework	Site Improvements	Pedestrian Plazas and Walkways	Pedestrian Pavement	1-Must Do	Poor	70	\$10	Square Foot	\$700
7834	Batavia High School	1672 - Exterior Face Brick - Original			2020	Sent to Maintenance	Control joint in brick is in poor condition.	Shell	Exterior Vertical Enclosures	Exterior Walls	Exterior Wall Veneer	1-Must Do	Poor :	10	\$10	Linear Foot	\$100
7835	Batavia High School	8469 - Exterior, Landscaped Beds			2020	Sent to Maintenance	Exterior raised landscape bed wall flashing/term bar damaged; rigid insulation board showing; retaining wall separating. Remove and	Sitework	Site Improvements	Landscaping		1-Must Do	Poor :	1	\$5,000	Lump Sum	\$0








ssessment	Campus	Linked Bldg	Addition	Room	Assessment	Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cos
ssessment ID	Campus	System	Addition	KOOIII	Year	Status	Description	L1	L2	L3	L4	Filority	racinty Condition	Quantity	Oill Cost	Jiii Oi weasure	Estimated COS
7836	Batavia High School	5129 - Roofing, Steep and Curvilinear Slope - 2011	BFAC, Fieldhouse (2011)		2020	Sent to Maintenance	Downspouts damaged.	Shell	Exterior Horizontal Enclosures	Roofing	Steep Slope Roofing	1-Must Do	Poor	3	\$50	Each	\$150
7837	Batavia High School	5128 - Roofing, Steep and Curvilinear Slope - 2009	North Classrooms, SW Mechanical (2009)		2020	Sent to Maintenance	Downspout at entrance column eroding landscape; connect to storm sewer system or provide splashblock.	Shell	Exterior Horizontal Enclosures	Roofing	Steep Slope Roofing	1-Must Do	Poor	1	\$50	Each	\$50
4814	Batavia High School	1699 - Ceilings, Acoustical Suspended Systems - 1971	LRC, Classrooms (1971)	Learning Center	2020	Sent to Maintenance	Learning Center - Smaller section of ACT that extends down the middle of the space. Several tiles have stains and slight water damage	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	2-Should Do	Fair	2000	\$8	Square Foot	\$15,000
4816	Batavia High School	1716 - Flooring, VCT - 1971	LRC, Classrooms (1971)	Learning Center	2020	Sent to Maintenance	(B119D) "The Back Room" Lounge. Cost to replace VCT with rubber flooring.	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	560	\$12	Square Foot	\$6,720
4821	Batavia High School	1850 - Interior Doors, Swinging- Hollow Metal - 1995	East 2-Story Classrooms (1995)	Science Lab	2020	Sent to Maintenance	Interior HM frames are in fair condition. C202, C204, C209, C211, C215, and C217	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	14	\$60	Each	\$840
4823	Batavia High School	1899 - Ceilings, Acoustical Suspended Systems - 1995	East 2-Story Classrooms (1995)	Science Lab	2020	Sent to Maintenance	ACT in a fair condition. C209, C211, C215, and C217	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	2-Should Do	Fair	4500	\$8	Square Foot	\$33,750
4825	Batavia High School	1910 - Flooring, VCT - 1995	East 2-Story Classrooms (1995)	Science Lab	2020	Sent to Maintenance	VCT in fair condition. Cost to replace VCT with rubber flooring. C202, C204, C209, C211, C215, C217	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	6750	\$12	Square Foot	\$81,000
4826	Batavia High School	1827 - Flooring, VCT - 2009	North Classrooms, SW Mechanical (2009)	Science Lab	2020	Sent to Maintenance	VCT separating throughout room. Cost to replace VCT with rubber flooring. D205	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	1211	\$12	Square Foot	\$14,532
4830	Batavia High School	1758 - Exterior Windows, Fixed	LRC, Classrooms (1971)	Exterior, Learning Center	2020	Sent to Maintenance	Learning Center (east wall, south courtyard) - Interior screens have various rips. Windows appear original to the addition. Horizontal pull down blinds are in above average condition but are aged as well. Cost to replace windows.	Shell	Exterior Vertical Enclosures	Exterior Windows	Exterior Fixed Windows	2-Should Do	Fair	200	\$90	Square Foot	\$18,000
4832	Batavia High School	1975 - Interior Wall Finishes, Wall Base - 1995	East 2-Story Classrooms (1995)	Science Lab	2020	Sent to Maintenance	Wall base in fair condition. C202, C204, C209, C211, C215, and C217	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	832	\$6	Linear Foot	\$4,992
4833	Batavia High School	1991 - Interior Wall Finish, Paint - 1995	East 2-Story Classrooms (1995)	Science Lab	2020	Sent to Maintenance	Paint could use a refresh in entire addition. Quantity reflects total SF of all listed rooms. C202, C204, C209, C211, C215, and C217	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	6750	\$2	Square Foot	\$15,188
4835	Batavia High School	1759 - Exterior Windows, Fixed - 1995	East 2-Story Classrooms (1995)	Science Lab	2020	Sent to Maintenance	Exterior window in fair condition. Verify size in field. Cost to replace. C202, C204, C209, C211, C215, and C217	Shell	Exterior Vertical Enclosures	Exterior Windows	Exterior Fixed Windows	2-Should Do	Fair	336	\$90	Square Foot	\$30,240
4840	Batavia High School	2010 - Plumbing, Plumbing Fixtures - 1995		Science Lab	2020	Sent to Maintenance	Sinks in fair condition C209, C211, C215, and C217	Services	Plumbing	Domestic Water Distribution	Plumbing Fixtures	2-Should Do	Fair	0	\$2,500	Each	\$0
4843	Batavia High School	1951 - Interior Wall Finish, Paint - Original		Learning Center	2020	Sent to Maintenance	Work Room (Teacher's) - Portion of brick wall is not painted most likely due to repair. Quantity reflects total room SF.		Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	710	\$2	Square Foot	\$1,598









Assessment	Campus	Linked Bldg	Addition	Room	Assessment	t Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID		System			Year	Status		L1	L2	L3	L4						
4844	Batavia High	•	North	Science Lab	2020	Sent to	Wall paint in fair condition.	Interiors	Interior Finishes	Wall Finishes	Wall Painting and	2-Should Do	Fair	3256	\$2	Square Foot	\$7,326
	School		Classrooms, SW			Maintenance	Quantity reflects the total SF in all				Coating						
		2009	Mechanical				listed spaces.										
			(2009)				D201, D205, and D209										
4845	Batavia High	1986 - Fixed	East 2-Story	Science Lab	2020	Sent to	Wood Science lab casework in fair	Equipment and	Furnishings	Fixed Furnishings	Casework	2-Should Do	Fair	960	\$800	Linear Foot	\$768,000
	School	Equipment,	Classrooms (1995)			Maintenance	condition. Cost to replace entirely.	Furnishings									
		Casework - 1995					C202, C204, C209, C211, C215, and										
							C217										
4849	Batavia High		North	Science Lab	2020	Sent to	Lighting is in fair condition	Services	Electrical	Lighting	Lighting Fixtures	2-Should Do	Fair	0	\$8	Square Foot	\$0
	School		Classrooms, SW			Maintenance	D201, D205										
		2009	Mechanical														
4853	Batavia High	O,		Science Lab	2020	Sent to	sink is in fair condition	Services	Plumbing	Domestic Water	Plumbing Fixtures	2-Should Do	Fair	0	\$2,500	Each	\$0
	School	Plumbing Fixtures				Maintenance	D201,			Distribution							
		- 2009	Mechanical														
4865	Batavia High	1709 - Interior		Toilet	2020	Sent to	Interior HM frame in fair condition.	Interiors	Interior	Interior Doors	Interior Swinging	2-Should Do	Fair	1	\$60	Each	\$60
	School	Doors, Swinging-				Maintenance	Boys by B124		Construction		Doors						
		Hollow Metal -															
		Original															
4966	Batavia High	1709 - Interior		Toilet	2020	Sent to	Interior HM door in fair condition.	Interiors	Interior	Interior Doors	Interior Swinging	2-Should Do	Fair	4	\$1,500	Each	\$6,000
	School	Doors, Swinging-				Maintenance	Cost to replace door and hardware.		Construction		Doors						
		Hollow Metal -					Girls by B124.										
		Original					Boys by B124.										
							Mens Faculty Center.										
							Womens Faculty Center.										
4969	Batavia High	1700 - Ceilings,		Toilet	2020	Sent to	GWB ceiling in fair condition.	Interiors	Interior	Suspended Ceiling	Suspended	2-Should Do	Fair	500	\$12	Square Foot	\$6,000
	School	Gypsum - Original				Maintenance	Toilets in A110 - Mens' Team Locker		Construction	Construction	Plaster and						
							Room				Gypsum Board						
4970	Batavia High	1698 - Ceilings,		Toilet	2020	Sent to	ACT ceiling in fair condition.	Interiors	Interior	Suspended Ceiling		2-Should Do	Fair	470	\$8	Square Foot	\$3,525
	School	Acoustical				Maintenance	Girls by B124.		Construction	Construction	Suspended						
		Suspended					B-Wing South 1st Floor - Boys Toilet.				Ceilings						
		Systems - Original					B-Wing South 1st Floor - Girls Toilet.										
4980	Batavia High	1703 - Flooring,		Toilet	2020	Sent to	Ceramic tile flooring in fair condition	Interiors	Interior Finishes	Flooring	Tile Flooring	2-Should Do	Fair	478	\$5	Square Foot	\$2,390
	School	Ceramic Tile -				Maintenance	- tile and grout is dirty throughout.										
		Original					Cost to clean grout and tiles.										
							Toilets in A110 - Mens' Team Locker										
							Room (185sf).										
							Mens Faculty Center (115 sf).										
							Womens Faculty Center (178 sf)										
4994	Batavia High	1914 - Interior		Toilet	2020	Sent to	Toilet partition in fair condition.	Interiors	Interior	Interior	Toilet, Bath, and	2-Should Do	Fair	0	\$1,800	Each	\$0
	School	Specialties, Toilet				Maintenance	Confirm quantity. Cost to replace		Construction	Specialties	Laundry						
		Compartments -					with solid phenolic partitions.				Accessories						
		Original					Girls by B124.										
							B-Wing South 1st Floor - Boys Toilet.										
							B-Wing South 1st Floor - Girls Toilet.										
	Batavia High	1729 - Electrical,		Toilet	2020	Sent to	0 0	Services	Electrical	Lighting	Lighting Fixtures	2-Should Do	Fair	0	\$8	Square Foot	\$0
	School	Lighting Fixtures -				Maintenance	Toilets in A110 - Mens' Team Locker										
		Original					Room										
5008	Batavia High		,	Toilet	2020	Sent to	interior wood door in fair condition.	Interiors	Interior	Interior Doors	Interior Swinging	2-Should Do	Fair	3	\$1,950	Each	\$5,850
	School		South Entrance			Maintenance	Cost to replace door and hardware.		Construction		Doors						
		Wood - 1995	(1995)				Girls in C wing1.										
							Boys by c119.										
							door into TR is damaged at bottom.										
		1					A106 - Boys by Café.										










Assessmen	t Campus	Linked Bldg	Addition	Room	Assessment	Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cos
ID		System			Year	Status		L1	L2	L3	L4						
5010	Batavia High School	1850 - Interior Doors, Swinging- Hollow Metal - 1995	East 2-Story Classrooms (1995	Toilet	2020	Sent to Maintenance	interior HM frames are in fair condition. Cost to repaint frame. Girls in C wing1. Boys in c wing 1. Staff in c wing 1. Girls by c119. Boys by c119.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	5	\$60	Each	\$300
5015	Batavia High School	1804 - Ceilings, Acoustical Suspended Systems - 1995 Entry	Central Area, South Entrance (1995)	Toilet	2020	Sent to Maintenance	ACT ceiling is in fair condition. Boys in c wing 1. Boys by c119.	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	2-Should Do	Fair	505	\$8	Square Foot	\$3,788
5020	Batavia High School	1910 - Flooring, VCT - 1995	East 2-Story Classrooms (1995	Toilet	2020	Sent to Maintenance	VCT flooring in fair condition. Cost to replace VCT with rubber flooring. Boys by c119	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	41	\$12	Square Foot	\$492
5024	Batavia High School	1907 - Flooring, Ceramic Tile - 1969	North Central Classrooms (1969	Toilet		Sent to Maintenance	flooring ceramic tile grout needs cleaning. Cost to clean grout. 126D - Student TR	Interiors	Interior Finishes	Flooring	Tile Flooring	2-Should Do	Fair	109	\$5	Square Foot	\$545
5026	Batavia High School	1855 - Interior Partitions, Fixed- CMU - 1995 Entry	Central Area, South Entrance (1995)	Toilet	2020	Sent to Maintenance	CMU wall is in fair condition. Verify scope. Cost to repair cracks. Girls by c119	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair	0	\$15	Linear Foot	\$0
5028	Batavia High School	1975 - Interior Wall Finishes, Wall Base - 1995	Central Area, South Entrance (1995)	Toilet	2020	Sent to Maintenance	Wall Base in fair condition. Boys by c119	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	76	\$6	Linear Foot	\$456
5034	Batavia High School	1991 - Interior Wall Finish, Paint 1995	Central Area, - South Entrance (1995)	Toilet	2020	Sent to Maintenance	Wall paint in fair condition. Quantity reflects total SF of all listed spaces. Girls in C wing 1. Staff in c wing 1. Girls by c119.	/ Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	583	\$2	Square Foot	\$1,312
5039	Batavia High School	2010 - Plumbing, Plumbing Fixtures - 1995	Central Area, South Entrance (1995)	Toilet	2020	Sent to Maintenance	plumbing fixtures in fair condition A106 Boys in c wing 1 Boys by c119 yellowed seats on WC and one WC is out of order Girls by Café	Services	Plumbing	Domestic Water Distribution	Plumbing Fixtures	2-Should Do	Fair	0	\$2,000	Each	\$0
5041	Batavia High School	1841 - Interior Specialties, Toilet Compartments - 1995 Entry		Toilet	2020	Sent to Maintenance	Toilet partition in fair condition. Cost to replace with solid phenolic partition; confirm quantity. A106	Interiors	Interior Construction	Interior Specialties	Toilet, Bath, and Laundry Accessories	2-Should Do	Fair	6	\$1,800	Each	\$10,800
5045	Batavia High School	1695 - Interior Doors, Swinging- Wood - Original		Office / Pull-Out		Sent to Maintenance	B115, B116, B117, B122 - Panels are chipping near hinges, B122E - Panels are chipping near hinges. Cost to replace door and hardware.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	9	\$1,950	Each	\$17,550










Assessmen	t Campus	Linked Bldg	Addition	Room	Assessment		Description	Building System				Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
5046	Batavia High School	System 1896 - Interior Doors, Swinging- Wood - 1995	East 2-Story Classrooms (1995)	Toilet	2020	Sent to Maintenance	Interior HM frames are in fair condition. Cost to repaint frames. C-Wing South, 2nd Floor - Girls Toilet. C-Wing South, 2nd Floor - boys Toilet. C-Wing South, 2nd Floor - staff Toilet. C-Wing North, 2nd Floor - Girls Toilet. C-Wing North, 2nd Floor - boys Toilet.	Interiors	Interior Construction	Interior Doors	L4 Interior Swinging Doors	2-Should Do	Fair	6	\$60	Each	\$360
5047	Batavia High School	1804 - Ceilings, Acoustical Suspended Systems - 1995 Entry	Classrooms (1995)		2020	Sent to Maintenance	ACT ceilings are in fair condition. C-Wing South, 2nd Floor - Girls Toilet. C-Wing South, 2nd Floor - boys Toilet. C-Wing South, 2nd Floor - staff Toilet. C-Wing North, 2nd Floor - Girls Toilet. C-Wing North, 2nd Floor - boys Toilet.	Interiors	Interior Construction	Suspended Ceiling Construction	g Acoustical Suspended Ceilings	2-Should Do	Fair	1033	\$8	Square Foot	\$7,748
5060	Batavia High School	1717 - Flooring, Carpet - 1971	LRC, Classrooms (1971)	Office / Pull-Out	2020	Sent to Maintenance	Career Counselor (In the Library) - Carpet is the same as the original carpet in the adjacent LRC	Interiors	Interior Finishes	Flooring	Carpeting	2-Should Do	Fair	100	\$7	Square Foot	\$650
5061	Batavia High School	1710 - Interior Partitions, Fixed- CMU - Original	LRC, Classrooms (1971)	Office / Pull-Out	2020	Sent to Maintenance	Career Counselor (In the Library) - Vertical cracking in the corners of the room and in the middle of the wall at joints. Confirm quantity.	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair	10	\$15	Linear Foot	\$150
5072	Batavia High School	2017 - Interior Specialties, Toilet Compartments - 1995	East 2-Story Classrooms (1995)	Toilet	2020	Sent to Maintenance	Toilet partitions in fair condition. C-Wing South, 2nd Floor - Girls Toilet. C-Wing South, 2nd Floor - boys Toilet. C-Wing North, 2nd Floor - Girls Toilet. C-Wing North, 2nd Floor - boys Toilet. Uncludes 4 ADA stalls. Cost to replace with solid phenolic stalls.	Interiors	Interior Construction	Interior Specialties	Toilet, Bath, and Laundry Accessories	2-Should Do	Fair	20	\$1,800	Each	\$36,000
5081	Batavia High School	1797 - Interior Doors, Swinging- Wood - 2009	North Classrooms, SW Mechanical	Toilet	2020	Sent to Maintenance	Interior wood door in fair condition Cost to replace door and hardware. Toilet in d102		Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$1,950	Each	\$1,950
5085	Batavia High School	1852 - Interior Doors, Swinging- Hollow Metal - 2009	North Classrooms, SW Mechanical (2009)	Toilet	2020		Interior HM frame in fair condition. Cost to repaint. Toilet in d102		Interior Construction	Interior Doors	Interior Swinging Doors		T dill	1	·	Each	\$60
5092	Batavia High School	1822 - Flooring, Ceramic Tile - 2009 Admin	South Admin Addition (2009)	Toilet	2020	Sent to Maintenance	Ceramic tile flooring's Grout is dirty throughout - tiles are in good shape Cost to clean grout. Mens in Office. Womens in Office		Interior Finishes	Flooring	Tile Flooring	2-Should Do	Fair	133	\$5	Square Foot	\$665










Assessmen	t Campus	Linked Bldg	Addition	Room	Assessment		Description			Building System		Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID	5	System		-	Year	Status		L1	L2	L3	L4	2.61 11.5		20	A.F.		4450
5096	Batavia High School	1977 - Interior Wall Finishes,	North Classrooms, SW	Toilet	2020	Sent to Maintenance	Wall base in fair condition, ceramic		Interior Finishes	Wall Finishes		2-Should Do	Fair	30	\$5	Square Foot	\$150
	SCHOOL	Wall Base - 2009	Mechanical			iviaintenance	tile base, grout needs cleaning. Cost to clean grout.										
		Wall base - 2003	(2009)				TR in Kitchen										
5103	Batavia High	1984 - Electrical,	North	Toilet	2020	Sent to	Lighting fixtures are in fair	Services	Electrical	Lighting	Lighting Fixtures	2-Should Do	Fair	0	\$8	Square Foot	\$0
	School	Lighting Fixtures -	Classrooms, SW			Maintenance	condition.										
		2009	Mechanical				Girls by d100										
			(2009)				Toilet in d102										
							Poor light distribution throughout restroom										
							Mens in Office										
5105	Batavia High	1805 - Ceilings,	North	Toilet	2020	Sent to	ACT ceilings are in fair condition.	Interiors	Interior	Suspended Ceiling	Acoustical	2-Should Do	Fair	469	\$8	Square Foot	\$3,518
	School	Acoustical	Classrooms, SW			Maintenance			Construction		Suspended				·	•	
		Suspended	Mechanical				D-Wing 2nd Floor- Girls Toilet.				Ceilings						
		Systems - 2009	(2009)				D-Wing 2nd Floor- boys Toilet										
5111	Batavia High	1695 - Interior		Office / Pull-Out		Sent to	HM Frames are in Fair condition.	Interiors	Interior	Interior Doors	Interior Swinging	2-Should Do	Fair	18	\$60	Each	\$1,080
	School	Doors, Swinging-				Maintenance	Cost to repaint frames.		Construction		Doors						
		Wood - Original					A106 - paint touch-up required, A108B - paint touch-up required,										
							B108,										
							B114,										
							B115,										
							B116,										
							B117,										
							B118F - HM Base is damaged on										
							both sides of door, B120 - Frame is scratched on the										
							edges throughout,										
							B121 - Frame is scratched on the										
							edges throughout,										
							B122 (Faculty Center South) - Doors										
							throughout are original HM Doors										
							and require some touch up paint,										
							B122 (Faculty Center North) - Doors										
							throughout are original HM Doors and require some touch up paint,										
							B122A										
							B122B										
5126	Batavia High	1853 - Interior	BFAC, Fieldhouse	Toilet	2020	Sent to	Interior HM frame in fair condition.	Interiors	Interior	Interior Doors	Interior Swinging	2-Should Do	Fair	2	\$60	Each	\$120
	School	Doors, Swinging-	(2011)			Maintenance	Cost to repaint.		Construction		Doors						
		Hollow Metal -					FIELDHOUSE GIRLS.										
F400	5	2011		055 / 5 11 0 +	2020		FIELDHOUSE BOYS					2.61 11.5		•	460		4400
5129	Batavia High School		North Central Classrooms (1969	Office / Pull-Out	2020	Sent to Maintenance	HM Frames are in Fair condition. Cost to repaint.	Interiors	Interior Construction	Interior Doors	Interior Swinging	2-Should Do	Fair	3	\$60	Each	\$180
	SCHOOL	Wood - Original	Classioonis (1969	"		iviaintenance	A123A - paint touch-up required,		Construction		Doors						
		Wood Original					A125A - paint touch-up required,										
							A129A - paint touch-up required										
5130	Batavia High		BFAC, Fieldhouse	Toilet	2020	Sent to		Interiors	Interior	Interior Doors	Interior Swinging	2-Should Do	Fair	2	\$75	Each	\$150
	School		(2011)			Maintenance	Cost to repaint.		Construction		Doors						
		Hollow Metal -					FIELDHOUSE GIRLS.										
F122	Patavia III-l	2011	DEAC Fieldham	Toilet	2020	Cont to	FIELDHOUSE BOYS CMU walls are in fair condition. Cost	Intoriora	Interior	Interior Postitions	Interior Fixed	2-Should Do	Fair	0	\$15	Linos: Fost	\$0
5132	Batavia High School		BFAC, Fieldhouse (2011)	rollet	2020	Sent to Maintenance	CMU walls are in fair condition. Cost to repair cracking, confirm quantity.	miteriors	Interior Construction	Interior Partitions	Partitions	2-วิกิบนเนิ D0	rdII	U	\$12	Linear Foot	υ¢
	3611001	CMU - 2011	(2011)			.viamitenante	FIELDHOUSE GIRLS.		Construction		. ar arabits						
		—	i .	i i	i i	Î.	=:::==::	i .	İ	i i	1	i .	i i		1	i i	1










					T				T = 111	5 11 5 .			o				
Assessment ID	Campus	Linked Bldg	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
	Batavia High	System 1994 - Interior	BFAC, Fieldhouse	Toilet	2020	Sent to	Wall paint in fair condition. Quantity		Interior Finishes	Wall Finishes	Wall Painting and	2-Should Do	Fair	111	\$2	Square Foot	\$250
	School	Wall Finish, Paint -		Tonet	2020	Maintenance	reflects total SF of listed spaces.	III.CETIOTS	interior rinishes	vuii i iiiisiies	Coating	2 3110414 20			7-	Square root	7230
		2011	,				FIELDHOUSE GIRLS.										
							FIELDHOUSE BOYS.										
5141	Batavia High	1747 - Slab on	BFAC, Fieldhouse	Toilet	2020	Sent to	Epoxy/SC floorings in fair condition.	Substructure	Slabs-On-Grade	Standard Slabs-on	-	2-Should Do	Fair	472	\$20	Square Foot	\$9,440
	School	Grade - 2011	(2011)			Maintenance	FIELDHOUSE GIRLS.			Grade							
							Fieldhouse Boys										<u> </u>
	Batavia High	1695 - Interior		Classrooms	2020	Sent to	HM door frame in fair condition -	Interiors	Interior	Interior Doors	Interior Swinging	2-Should Do	Fair	2	\$60	Each	\$120
	School	Doors, Swinging- Wood - Original				Maintenance	Interior side of frame is scratched		Construction		Doors						
		wood - Original					on edges throughout. Cost to repaint.										
							repairt.										
							B107.										
5153	Batavia High	1709 - Interior		Classrooms	2020	Sent to	HM door frame in fair condition.	Interiors	Interior	Interior Doors	Interior Swinging	2-Should Do	Fair	2	\$60	Each	\$120
	School	Doors, Swinging-				Maintenance	Cost to repaint.		Construction		Doors						
		Hollow Metal -															
		Original					B112, B114										
	Batavia High	1675 - Exterior		Classrooms	2020	Sent to	HM door in fair condition - Door is	Shell	Exterior Vertical	Exterior Doors	Exterior Entrance	2-Should Do	Fair	2	\$2,000	Each	\$4,000
	School	Entrance Doors,				Maintenance	rusting and slightly damaged at the		Enclosures	and Grilles	Doors						
		Hollow Metal -					jamb condition. Cost to replace HM door and hardware.										
		Original					B112, B125										
5159	Batavia High	1698 - Ceilings,		Classrooms	2020	Sent to	ACT in fair condition - Tiles are	Interiors	Interior	Suspended Ceiling	Acoustical	2-Should Do	Fair	2551	\$8	Square Foot	\$19,133
	School	Acoustical				Maintenance	starting to bow and some have		Construction		Suspended					1	, -,
		Suspended					damage on their edges.				Ceilings						
		Systems - Original															
							B109, B112, B114										
	Batavia High	1704 - Flooring,		Classrooms	2020	Sent to	VCT in fair condition - Sratches and	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	1710	\$12	Square Foot	\$20,520
	School	VCT - Original				Maintenance	dimpling under tiles throughout.										
							Cost to replace VCT with rubber flooring.										
							moornig.										
5162	Batavia High	1797 - Interior	South Admin	Office / Pull-Out	2020	Sent to	Fair Condition Overall.	Interiors	Interior	Interior Doors	Interior Swinging	2-Should Do	Fair	3	\$1,950	Each	\$5,850
	School	Doors, Swinging-	Addition (2009)			Maintenance	B101 - Frames have damage at the		Construction		Doors						
		Wood - 2009					edges and bottom.										
							B101B.										
							D117.										<u> </u>
	Batavia High	1970 - Flooring,		Classrooms	2020	Sent to	Carpet in fair condition.	Interiors	Interior Finishes	Flooring	Carpeting	2-Should Do	Fair	682	\$7	Square Foot	\$4,433
	School	Carpet - Original				Maintenance	B106										
5166	Batavia High	1710 - Interior		Classrooms	2020	Sent to	B106 CMU in fair condition. Quantity	Interiors	Interior	Interior Partitions	Interior Fixed	2-Should Do	Fair	30	\$15	Linear Foot	\$450
	School	Partitions, Fixed-		Classioonis	2020	Maintenance	reflects approximate lengths of	interiors	Construction	interior Fartitions	Partitions	2-3110010 00	i ali	30	713	Lillear 1 00t	3430
	3011001	CMU - Original				- Ivianice	cracks.		Construction		T di titionis						
							B106 - Sealant and vertical cracking										
							at corners.										
							B107 - Corridor wall on interior side										
							has some gouges in the blocks and										
							grout is cracking.										
							B112, B113 - Wall is cracking and spalling near exterior windows.										
5168	Batavia High	1708 - Interior		Classrooms	2020	Sent to	GWB in fair condition - GWB wall is	Interiors	Interior	Interior Partitions	Interior Fixed	2-Should Do	Fair	856	\$15	Square Foot	\$12,840
	School	Partitions, Fixed -		0,033,001113	2020	Maintenance	cracking vertically where the wall		Construction		Partitions	2 Silodia Do	, un		713	Square 100t	712,070
1			1		1			1		1		1			1		
		GWB - Original					meets CMU corridor wall.										
		GWB - Original					meets CMU corridor wall.										










Assessment	Campus	Linked Bldg	Addition	Room	Assessmen	nt Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID	Campus	System	radicion		Year	Status	Description	L1	L2	L3	L4	inonty	racinty condition	Quantity	Oint Cost	ome or measure	Lotimated cost
	Batavia High	1951 - Interior		Classrooms	2020	Sent to	Paint in fair condition - Several walls		Interior Finishes	Wall Finishes	Wall Painting and	2-Should Do	Fair	6150	\$2	Square Foot	\$13,838
	School	Wall Finish, Paint -				Maintenance	could use touch up or re-painting,				Coating				* -		7 = 2,22 2
		Original					scuffed throughout. Quantity				Jan 6						
		3 3					reflects total SF of listed spaces.										
							•										
							B106.										
							B107.										
							B112.										
							B113.										
							B125.										
							B114.										
5175	Batavia High	1732 - Fixed		Classrooms	2020	Sent to	Casework in fair condition - some	Equipment and	Furnishings	Fixed Furnishings	Casework	2-Should Do	Fair	153	\$800	Linear Foot	\$122,400
	School	Equipment,				Maintenance	cabinets/counters delaminating,	Furnishings									
		Casework -					some edges missing p-lam all										
		Original					together. Cost to replace entirely.										
							B106.										
							B109.										
							B112.										
							B113.										
5180	Batavia High			Office / Pull-Out	2020	Sent to	HM Doors are in Fair Condition, Cost	Interiors	Interior	Interior Doors	Interior Swinging	2-Should Do	Fair	1	\$75	Each	\$75
	School		Classrooms (1969)			Maintenance	to repaint.		Construction		Doors						
		Hollow Metal -					A125A - paint touch-up required										
		1969															
5181	Batavia High	1673 - Exterior		Exterior,	2020	Sent to	Exterior windows in fair condition;	Shell	Exterior Vertical	Exterior Windows		2-Should Do	Fair	720	\$100	Square Foot	\$72,000
	School	Windows,		Courtyard		Maintenance	tall strip windows with infill panels.		Enclosures		Operating						
		Operating -		(Original Building))		Approx. 120 SF each.				Windows						
		Original					D442 D442 D444										
							B112, B113, B114										
							H/LS report indicates single pane										
							windows should be replaced. Cost										
							to replace.										
5182	Batavia High	1673 - Exterior		Classrooms	2020	Sent to	Exterior windows in fair condition -	Shall	Exterior Vertical	Exterior Windows	Exterior	2-Should Do	Fair	150	\$100	Square Foot	\$15,000
3102	School	Windows,		Classicoms	2020	Maintenance	appears to be staining at aluminum	Silen	Enclosures	Exterior vviiidows	Operating	2 Should bo	l un	150	7100	Squareroot	\$15,000
	3611001	Operating -				- Iviairice il arice	windows, see photos. Verify size in		Enclosures		Windows						
		Original					field. Cost to replace.										
							Потак обосто портавох										
							B125										
5185	Batavia High	1725 - HVAC,		Classrooms	2020	Sent to	Fair condition - Fin tubes near	Services	Heating,	Facility HVAC	Facility Hydronic	2-Should Do	Fair	2	\$0	Each	\$0
	School	Distribution-				Maintenance	exterior wall is in average shape		Ventilation, and	Distribution	Distribution						
		Hydronic					with some an exterior housing that		Air Conditioning	Systems							
							is hit over time.		(HVAC)								
							B112, B113										
5190	Batavia High			Classrooms	2020	Sent to	HM door frame in fair condition,	Interiors	Interior	Interior Doors	Interior Swinging	2-Should Do	Fair	1	\$60	Square Foot	\$60
	School		Classrooms (1969)			Maintenance	paint touch up required.		Construction		Doors						
		Wood - 1969															
							A126										









Assessment	Campus	Linked Bldg	Addition	Room	Assessmen	Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cos
ID	-	System			Year	Status		L1	L2	L3	L4	•	,	•			
	Batavia High School	1709 - Interior Doors, Swinging- Hollow Metal - Original		Office / Pull-Out		Sent to Maintenance	HM Doors are in Fair Condition. A108B - paint touch-up required, B114 - Appears to be original door, surface damage on interior side near jamb, B122 - Frames throughout are original HM Doors and require some touch up paint, B122A - Door leading to corridor has scratches on both sides, B122C - Door has minor marks on both sides and has a narrow lite in good condition. Door hardware is not accessible, B122E - Doors scratched on both sides leading to Faculty Center.	Interiors	Interior Construction	Interior Doors	Interior Swinging 2-Doors	Should Do	Fair	6	\$1,500	Each	\$9,000
5192	Batavia High	1873 - Interior	North Central	Classrooms	2020	Sent to	Cost to replace HM doors and hardware. HM door frame in fair condition,	Interiors	Interior	Interior Doors	Interior Swinging 2-	Should Do	Fair	3	\$60	Each	\$180
	School	Doors, Swinging- Hollow Metal - 1969	Classrooms (1969)			Maintenance	paint touch up required. A121, A127, A128		Construction		Doors						
	Batavia High School	1873 - Interior Doors, Swinging- Hollow Metal - 1969	North Central Classrooms (1969)	Classrooms	2020	Sent to Maintenance	HM door in fair condition, paint touch up required. A121. A127. A128.	Interiors	Interior Construction	Interior Doors	Interior Swinging 2- Doors	Should Do	Fair	3	\$75	Each	\$225
	Batavia High School	1873 - Interior Doors, Swinging- Hollow Metal - 1969	North Central Classrooms (1969)	Office / Pull-Out	2020	Sent to Maintenance	HM Doors are in Fair Condition. A125A (Pull-Out Space) - paint touch-up required	Interiors	Interior Construction	Interior Doors	Interior Swinging 2- Doors	Should Do	Fair	1	\$75	Each	\$75
5198	Batavia High School	1909 - Flooring, VCT - 1969	North Central Classrooms (1969)	Classrooms	2020	Sent to Maintenance	VCT in fair condition - a few damaged tiles. Cost to replace VCT with rubber flooring. A127	Interiors	Interior Finishes	Flooring	Resilient Flooring 2-	Should Do	Fair	653	\$12	Square Foot	\$7,836
	Batavia High School	1698 - Ceilings, Acoustical Suspended Systems - Original		Office / Pull-Out		Sent to Maintenance	ACT is in Fair Condition. B107A - Minor water damage on some tiles, slightly older tiles, B114 - Ceiling tiles starting to bow, B114A, B115, B116, B117, B118D, B123 (Conference), B123 (Office) - TILES ARE BOWING.	Interiors	Interior Construction		Suspended Ceilings	Should Do	Fair	3249	\$8	Square Foot	\$24,368
5207	Batavia High School		North Central Classrooms (1969)	Classrooms)	2020	Sent to Maintenance	CMU in fair condition - some cracking at joint with columns.	Interiors	Interior Construction	Interior Partitions	Interior Fixed 2- Partitions	Should Do	Fair	20	\$15	Linear Foot	\$300










Assessmer	nt Campus	Linked Bldg	Addition	Room	Assessment		Description Building System		Building System		Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID		System			Year	Status	L1	L2	L3	L4				4		4
5213	Batavia High School	1929 - Fixed Equipment, Casework - 1969	North Central Classrooms (1969	Classrooms 9)	2020	Sent to Maintenance	Casework in fair condition - Equipment and powdercoat finish on metal casework is worn away at bottom of cabinet doors. Cost to replace entirely.	Furnishings	Fixed Furnishings	Casework	2-Should Do	Fair	50	\$800	Linear Foot	\$40,000
5217	Batavia High School	1805 - Ceilings, Acoustical Suspended Systems - 2009	South Admin Addition (2009)	Office / Pull-Out	2020	Sent to Maintenance	ACT is in Fair Condition. B100. D110A. D117 - large water stains.	Interior Construction		Acoustical Suspended Ceilings	2-Should Do	Fair	694	\$8	Square Foot	\$5,205
5219	Batavia High School	1895 - Interior Doors, Swinging- Wood - 1971	LRC, Classrooms (1971)	Classrooms	2020	Sent to Maintenance	Wood doors in fair condition - Scratches and scuffed on the interior face. Door has half lite with wire. Cost to replace door and hardware.	Interior Construction		Interior Swinging Doors	2-Should Do	Fair	5	\$1,950	Each	\$9,750
5221	Batavia High School	1895 - Interior Doors, Swinging- Wood - 1971	LRC, Classrooms (1971)	Classrooms	2020	Sent to Maintenance	HM frames in fair condition. Cost to repaint. B103. B104. B115. B116. B117.	Interior Construction		Interior Swinging Doors	2-Should Do	Fair	5	\$60	Each	\$300
5222	Batavia High School	1849 - Interior Doors, Swinging- Hollow Metal - 1971	LRC, Classrooms (1971)	Classrooms	2020	Sent to Maintenance	HM frames in fair condition. Cost to repaint. B104A	Interior Construction		Interior Swinging Doors	2-Should Do	Fair	1	\$60	Each	\$60
5223	Batavia High School	1849 - Interior Doors, Swinging- Hollow Metal - 1971	LRC, Classrooms (1971)	Classrooms	2020	Sent to Maintenance	HM door in fair condition - Door is much older compared to the renovation of the space. Cost to repaint.	Interior Construction		Interior Swinging Doors	2-Should Do	Fair	1	\$75	Each	\$75
5224	Batavia High School	1699 - Ceilings, Acoustical Suspended Systems - 1971	LRC, Classrooms (1971)	Classrooms	2020	Sent to Maintenance	B104A ACT in fair condition - Slightly bowing throughout and some water spots. B103. B115. B116.	Interior Construction		Acoustical Suspended Ceilings	2-Should Do	Fair	3643	\$8	Square Foot	\$27,323
5228	Batavia High School	1716 - Flooring, VCT - 1971	LRC, Classrooms (1971)	Classrooms	2020	Sent to Maintenance	VCT in fair condition. Cost to replace VCT with rubber flooring. B103. B115. B116. B117.	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	3643	\$12	Square Foot	\$43,716









Assassment	t Commune	Links of Bloks	Addition	Doom.	Assassman	Assessment	Description	Duilding Custom	Building System	Building Custom	Building System	Duiouitu	Facility Condition	Ougatitu	Linit Cost	Linit Of Massura	Estimated Cost
Assessment ID	t Campus	Linked Bldg System	Addition	Room	Assessmer Year	nt Assessment Status	Description	L1	L2	L3	L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
5237	Batavia High	1704 - Flooring,		Office / Pull-Out		Sent to	VCT is in Fair Condition. Cost to	Interiors	Interior Finishes	Flooring	Resilient Flooring	2 Should Do	Fair	4075	\$12	Square Foot	\$48,900
3237	School	VCT - Original		Office / Pull-Out	2020	Maintenance	replace VCT with rubber flooring.	iliteriors	interior rinishes	Flooring	Resilient Flooring	2-3110ulu D0	raii	+075	\$12	Square Foot	340,300
	School	VC1 - Original					B114,										
							B114A,										
							B115,										
							B116,										
							B117,										
							B119A - VCT has larger scratches										
							and is bubbling at door entrance,										
							B119B - VCT has larger scratches										
							and is bubbling at door entrance,										
							B120 - Chairs have scratched the										
							floor near the desk,										
							B122 - VCT flooring in kitchenette										
							area is starting to separate at seams										
							slighty. No cracks are evident										
5241	Batavia High	1996 - HVAC,	LRC, Classrooms	Classrooms	2020	Sent to	Unit vent in fair condition - Housing	Services	Heating,	Ventilation	Supply Air	2-Should Do	Fair	1	\$4,500	Each	\$4,500
	School		(1971)				around wall units are slightly		Ventilation, and		11.7				, ,		
		Ventilators - 1971	,				damaged throughout.		Air Conditioning								
									(HVAC)								
							B103										
5242	Batavia High	1896 - Interior	East 2-Story	Classrooms	2020	Sent to	Wood door in fair condition - veneer	Interiors	Interior	Interior Doors	Interior Swinging	2-Should Do	Fair	19	\$1,950	Each	\$37,050
	School	Doors, Swinging-	Classrooms (1995)			Maintenance	is scratched and chipped, especially		Construction		Doors						
		Wood - 1995					at bottom. Cost to replace door and										
							hardware.										
							C101.										
							C102.										
							C103.										
							C104.										
							C105.										
							C107.										
							C110.										
							C111.										
							C112.										
							C113.										
							C114.										
							C116.										
1							C117.										
							C118.										
							C119.										
							C120.										
							C121.										
							C122.										
							C123.		1		1	İ					1

17 of 96 Print Date: 2/22/2021







			T	I					1		1	1					
Assessment	t Campus	Linked Bldg	Addition	Room		Assessment	Description		Building System			Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID	Data da Ulab	System	F+ 2 Ct	Classes	Year	Status	LINA de su forças do feiro con divisos	L1	L2	L3	L4	2.65 -	Fair (22	¢co.	F	ć4 220
5245	Batavia High School	1896 - Interior Doors, Swinging- Wood - 1995	East 2-Story Classrooms (1995)	Classrooms		Maintenance	HM door frame in fair condition - paint chipped, rusting at base. Cost to repaint.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair 2	22	\$60	Each	\$1,320
							C100. C101. C102.										
							C103. C104.										
							C105. C107. C109.										
							C110. C111. C112.										
							C113. C114.										
							C115. C116. C117.										
							C118. C119.										
							C120. C121. C122.										
5248	Batavia High School	1899 - Ceilings, Acoustical	East 2-Story Classrooms (1995)	Classrooms			C123. ACT in fair condition.	Interiors		Suspended Ceiling	g Acoustical Suspended	2-Should Do	Fair 4	1470	\$8	Square Foot	\$33,525
		Suspended Systems - 1995					C100 - Cracked tile, 5 water damaged ceiling tile. C104 - 50% ceiling tiles are bowing. C106. C115. C110 - 75% ceiling tiles are slightly				Ceilings						
5250	Batavia High School		East 2-Story Classrooms (1995)	Classrooms		Sent to Maintenance	bowing. VCT in fair condition - scuffed throughout, cracked/chipped tiles, wax finish worn off. Cost to replace	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair :	12524	\$12	Square Foot	\$150,288
							VCT with rubber flooring. C100. C101.										
							C106. C109. C110.										
							C111. C112. C114.										
							C114. C115. C116. C117.										
							C120. C121.										
							C122. C123.										










Assessment ID	t Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Co
5256	Batavia High School	1921 - Interior Partitions, Fixed- CMU - 1995	East 2-Story Classrooms (199	Classrooms 5)	2020	Sent to Maintenance	CMU in fair condition - stair step cracks in a couple walls, sealant separation at corners.	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair	100	\$15	Linear Foot	\$1,500
							C101. C105. C107. C109. C120. C121.										
	Batavia High School	1845 - Interior Partitions, Fixed- GWB - 1995	East 2-Story Classrooms (199	Classrooms 5)	2020	Sent to Maintenance	C123. GWB wall in fair condition. C119, C120, C100, C118	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair	0	\$15	Square Foot	\$0
	Batavia High School	1975 - Interior Wall Finishes, Wall Base - 1995	East 2-Story Classrooms (199	Classrooms 5)	2020	Sent to Maintenance	Wall base in fair condition - very scuffed in all classrooms, small portions delaminating from wall.	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	2670	\$6	Linear Foot	\$16,020
							C101. C102. C103. C105.										
							C107. C109. C111. C112.										
							C113. C114. C116. C117.										
							C119. C120. C121. C122.										
							C123. C104. C106.										
							C110. C115. C118.										










Assessmen	t Campus	Linked Bldg	Addition	Room	Assessment		Description				Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID	D	System	5 . 2 6:		Year	Status	5 · · · · · · · · · · · · · · · · · · ·	L1	L2	L3	L4	2.61 11.5		10000	42		442.750
5262	Batavia High School	1991 - Interior Wall Finish, Paint 1995	East 2-Story - Classrooms (1995)	Classrooms		Sent to Maintenance	Paint in fair condition. Quantity reflects total SF of all listed spaces.	Interiors	Interior Finishes		Wall Painting and Coating	2-Should Do	Fair	19000	\$2	Square Foot	\$42,750
		1333					C101.										
							C102.										
							C103.										
							C105. C107.										
							C107.										
							C111.										
							C112.										
							C113.										
							C114. C116.										
							C116. C117.										
							C119.										
							C120.										
							C121.										
							C122.										
							C123. C100.										
							C104.										
							C106.										
							C110.										
							C115.										
							C118 - fair throughout room with 2 larger areas of peeling paint.										
5263	Batavia High	1986 - Fixed	East 2-Story	Classrooms	2020	Sent to	Casework in fair condition - looks	Equipment and	Furnishings	Fixed Furnishings	Casework	2-Should Do	Fair	340	\$800	Linear Foot	\$272,000
	School	Equipment,	Classrooms (1995)			Maintenance	old and worn, some doors crooked										
		Casework - 1995					pulls missing, p-lam chipped. Cost t	0									
							replace entirely.										
							C100.										
							C101.										
							C102.										
							C103.										
							C105. C107.										
							C109.										
							C111.										
							C112.										
							C113. C114.										
							C114. C116.										
							C117.										
							C121.										
							C104.										
							C110. C115.										
5266	Batavia High	1753 - Exterior	East 2-Story	Classrooms	2020	Sent to	Operable window in fair condition.	Shell	Exterior Vertical	Exterior Windows	Exterior	2-Should Do	Fair	100	\$100	Square Foot	\$10,000
	School	Windows, Operating - 1995	Classrooms (1995)				Cost to replace.		Enclosures		Operating Windows						
		. 5					C104 - rips in window screen.										
							C103 - rip in window screen.										
							C107 - paint flaking off interior										
1							lintel.										1










Assessment	t Campus	Linked Bldg	Addition Roo	m Assessme	nt Assessment	Description	Building System	Building System	Building System	Building Syste	m Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID		System		Year	Status		L1	L2	L3	L4		, , , , , , , , , , , , , , , , , , , ,				
5267	Batavia High School	1753 - Exterior	East 2-Story Classroom (1995)		Sent to Maintenance	Operable windows in fair condition, scold air leakage apparent. Cost to replace.	Shell	Exterior Vertical Enclosures	Exterior Windows		2-Should Do	Fair	912	\$100	Square Foot	\$91,200
						C101. C102. C105. C109. C111. C112. C114. C116. C117. C119. C120. C121. C122. C123. C100. C106. C110.										
						C115.										
						C118.										
	Batavia High School		East 2-Story Classroom (1995)	ns 2020	Sent to Maintenance	Unit vent in fair condition - finish is scratched/scuffed in multiple places.		Heating, Ventilation, and Air Conditioning (HVAC)	Ventilation	Supply Air	2-Should Do	Fair	5	\$4,500	Each	\$22,500
						C105. C113. C119. C121.										
	Batavia High School	1797 - Interior Doors, Swinging- Wood - 2009	North Classroom Classrooms, SW Mechanical (2009)	as 2020	Sent to Maintenance	Wood door in fair condition. Cost to I replace door and hardware. D103. D105. D106. D107. D108.		Interior Construction		Interior Swingin Doors	g 2-Should Do	Fair	6	\$1,950	Each	\$11,700
	Batavia High School		North Classroom Classrooms, SW Mechanical (2009)	2020 as	Sent to Maintenance			Interior Construction		Interior Swingin Doors	g 2-Should Do	Fair	9	\$60	Each	\$540










Assessment	Campus	Linked Bldg	Addition	Room	Assessmen	t Assessment	Description	Ruilding System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID	Campus	System	Addition	Koom	Year	Status	Description	L1	L2	L3	L4	Filolity	racinty Condition	Quantity	Onit Cost	Offic Of Measure	Littillated Cost
	Batavia High School	1827 - Flooring, VCT - 2009	North Classrooms, SW Mechanical (2009)	Classrooms	2020	Sent to Maintenance	VCT in fair condition. Cost to replace VCT with rubber flooring. D102. D104. D105. D106. D107. D108. D109.	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	7844	\$12	Square Foot	\$94,128
5277	Batavia High School	1709 - Interior Doors, Swinging- Hollow Metal - Original		Storage/Mechan	nic 2020	Sent to Maintenance	HM door in fair condition. A110C. paint touch-up required. A104D, A105B, A105D, A109B, A109A, B126A, B126D, B110B	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	9	\$75	Each	\$675
5281	Batavia High School	2017 - Interior Specialties, Toilet Compartments - 1995	,	Toilet	2020	Sent to Maintenance	Toilet partition is in fair condition. Cost to replace with solid phenolic partition. Confirm quantity. Girls by c119 Boys by c119	Interiors	Interior Construction	Interior Specialties	Toilet, Bath, and Laundry Accessories	2-Should Do	Fair	0	\$1,800	Each	\$0
5289	Batavia High School	Wall Finish, Paint - 2009	North Classrooms, SW Mechanical (2009)	Classrooms	2020	Sent to Maintenance	Paint is in fair condition. Quantity reflects total SF of all listed spaces. D101. D102. D103. D104. D105. D106. D107. D108. D109.	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	7844	\$2	Square Foot	\$17,649
5293	Batavia High School	Lighting Fixtures - 2009	North Classrooms, SW Mechanical (2009)	Classrooms	2020	Sent to Maintenance	Lighting in fair condition. Lights flickered when they came on, didn't all turn on right away. D101. D102. D103. D104. D106. D107. D109.	Services	Electrical	Lighting	Lighting Fixtures	2-Should Do	Fair	0	\$8	Square Foot	\$0
5298	Batavia High School	1698 - Ceilings, Acoustical Suspended Systems - Original		Storage/Mechan al	nic 2020	Sent to Maintenance	ACT ceiling in fair condition. B126A (307 sf). Holes in ACT throughout for piping (88 SF). B122D	Interiors	Interior Construction	Suspended Ceiling Construction	g Acoustical Suspended Ceilings	2-Should Do	Fair	395	\$8	Square Foot	\$2,963
	Batavia High School	1704 - Flooring, VCT - Original		Storage/Mechan al	nic 2020		VCT flooring is in fair condition, scratches throughout. Cost to replace VCT with rubber flooring. B126A, B111, B122D	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	392	\$12	Square Foot	\$4,704
	Batavia High School	1670 - Slab on Grade - Original		Storage/Mechan	nic 2020		Epoxy flooring in fair condition. Maintenance office by b124. B126D	Substructure	Slabs-On-Grade	Standard Slabs-or Grade	ì-	2-Should Do	Fair :	170	\$20	Square Foot	\$3,400









Assessment	Campus	Linked Bldg	Addition	Room	Assessmen	t Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID		System			Year	Status		L1	L2	L3	L4						
5305	Batavia High	1670 - Slab on		Storage/Mecha	inic 2020	Sent to	Epoxy flooring in fair condition.	Substructure	Slabs-On-Grade	Standard Slabs-on	-	2-Should Do	Fair	93	\$20	Square Foot	\$1,860
5308	School	Grade - Original 1709 - Interior		al	:- 2020	Maintenance	Maintenance office by b124 Interior HM frame in fair condition.	latariana	lataria.	Grade	Interior Swinging	2 Chauld Da	Fair	0	\$60	Fash	\$540
5308	Batavia High School	Doors, Swinging-		Storage/Mecha	inic 2020	Sent to Maintenance	A110C.	Interiors	Interior Construction	Interior Doors	Doors	2-Should Do	Fair	9	\$60	Each	\$540
	3611001	Hollow Metal -		ui		Walltenance	paint touch-up required.		Construction		20013						
		Original					A104D, A105B, A105D, A109B,										
							A109A, B126A, B126D, B111										
5309	Batavia High	1710 - Interior		Storage/Mecha	nic 2020	Sent to	CMU wall in fair condition.	Interiors	Interior	Interior Partitions	Interior Fixed	2-Should Do	Fair	0	\$40	Square Foot	\$0
	School	Partitions, Fixed-		al		Maintenance	Maintenance office by b124		Construction		Partitions						
		CMU - Original					HOLES IN CMU - cost to repair holes Confirm quantity.	•									
							B111										
5313	Batavia High	1951 - Interior		Storage/Mecha	nic 2020	Sent to	Wall paint in fair condition. Quantity	Interiors	Interior Finishes	Wall Finishes	Wall Painting and	2-Should Do	Fair	345	\$2	Square Foot	\$776
	School	Wall Finish, Paint	-	al		Maintenance	reflects total SF of all listed spaces.				Coating						
		Original					Maintenance office by b124.										
		1-00 0 W					B126A.								4.0		4. 0.0
5317	Batavia High School	1700 - Ceilings, Gypsum - Original		Storage/Mecha	inic 2020	Sent to Maintenance	GWb ceiling in fair condition. B126D	Interiors	Interior Construction	Suspended Ceiling Construction	Suspended Plaster and	2-Should Do	Fair	154	\$12	Square Foot	\$1,848
	301001	Gypsuiii - Originai		ai		ivialiteilalice	B120D		Construction	Construction	Gypsum Board						
5321	Batavia High	1873 - Interior	North Central	Storage	2020	Sent to	paint touch-up needed .	Interiors	Interior	Interior Doors	Interior Swinging	2-Should Do	Fair	1	\$75	Each	\$75
	School	Doors, Swinging-	Classrooms (1969	9)		Maintenance	Drying Room - located between		Construction		Doors						
		Hollow Metal -					A123 and A124										
		1969															
5323	Batavia High	1898 - Ceilings,	North Central	Storage	2020	Sent to	paint on grid.	Interiors	Interior	Suspended Ceiling		2-Should Do	Fair	200	\$8	Square Foot	\$1,500
	School	Acoustical Suspended	Classrooms (1969	9)		Maintenance	Storage Room - limited lighting due to activities in room; portion of		Construction	Construction	Suspended Ceilings						
		Systems - 1969					ceiling is painted concrete; located				Cellings						
		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					in A124										
5331	Batavia High	1979 - Electrical,	North Central	Storage	2020	Sent to	one cover is broken	Services	Electrical	Lighting	Lighting Fixtures	2-Should Do	Fair	0	\$8	Square Foot	\$0
	School		Classrooms (1969	9)		Maintenance	Drying Room located between A123										
5242	Data da Hisb	1969	Carabarat Assas	Ct	2020	C 1	and A124	Later de la constitución de la c	Interview.	lata da Da ana	Lataria Carinala	2.65	Fair.	2	675	Fh	6225
5342	Batavia High School	1850 - Interior Doors, Swinging-	Central Area, South Entrance	Storage	2020	Sent to Maintenance	Interior HM door in fair condition. C115B.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	3	\$75	Each	\$225
	3011001	Hollow Metal -	(1995)			Wallitellance	Storage in stair by c122.		Construction		D0013						
		1995	(needs paint touch-up -										
							Cafe storage										
5343	Batavia High	1850 - Interior	Central Area,	Storage	2020	Sent to	Interior HM frame in fair condition	- Interiors	Interior	Interior Doors	Interior Swinging	2-Should Do	Fair	4	\$60	Each	\$240
	School	Doors, Swinging-	South Entrance			Maintenance	C115B.		Construction		Doors						
		Hollow Metal - 1995	(1995)				Electrical in c wing 1. Janitor/elec by c119.										
		1993					Storage in stair by c122										
5350	Batavia High	1825 - Flooring,	Central Area,	Storage	2020	Sent to	VCT flooring in fair condition. Cost	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	141	\$12	Square Foot	\$1,692
	School	VCT - 1995 Entry	South Entrance			Maintenance	to replace VCT with rubber flooring.										
			(1995)				Storage A102T by Dishwashing?										
5351	Batavia High	1744 - Slab on	Central Area,	Storage	2020	Sent to	Epoxy flooring in fair condition.	Substructure	Slabs-On-Grade	Standard Slabs-on	-	2-Should Do	Fair	118	\$20	Square Foot	\$2,360
	School	Grade - 1995	South Entrance (1995)			Maintenance	Janitor in mid c wing . Electrical in c wing 1			Grade							
5353	Batavia High	1855 - Interior	Central Area,	Storage	2020	Sent to	CMU wall in fair condition. Cost to	Interiors	Interior	Interior Partitions	Interior Fixed	2-Should Do	Fair	0	\$15	Linear Foot	\$0
5555	School	Partitions, Fixed-	South Entrance	3.0.00		Maintenance	repair cracking, confirm quantity.		Construction		Partitions	_ = ===================================		-	7-0		7.0
		CMU - 1995 Entry					C115B.										
							Electrical in c wing 1.										
FC=-		1075	0	6.	2000	6	Janitor/elec by c119.			NAC II Et a d		2.61		100	A.C.		4500
5355	Batavia High School	1975 - Interior Wall Finishes,	Central Area, South Entrance	Storage	2020	Sent to Maintenance	Wall base in fair condition.	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	100	\$6	Linear Foot	\$600
	301001	Wall Base - 1995	(1995)			ivialitellance	C115B										
	1	Wan Dase - 1993	(1000)					1	1	1	I		1		I	1	1

23 of 96 Print Date: 2/22/2021










sessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cos
5359	Batavia High School		East 2-Story Classrooms (1995	Storage)	2020	Sent to Maintenance	Wall paint in fair condition. Quantity reflects total SF of all listed spaces. C115B. Electrical in c wing 1.	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	950	\$2	Square Foot	\$2,138
5363	Batavia High School	1850 - Interior Doors, Swinging- Hollow Metal - 1995	Central Area, South Entrance (1995)	Storage	2020	Sent to Maintenance	Interior HM door paint touch-up required. A102C	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$75	Each	\$75
5366	Batavia High School	1850 - Interior Doors, Swinging- Hollow Metal - 1995	Central Area, South Entrance (1995)	Storage	2020	Sent to Maintenance	Interior HM frame in fair condition. A102C	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$60	Each	\$60
5378	Batavia High School		South Admin Addition (2009)	Storage	2020	Sent to Maintenance	Walls were given one coat of paint that doesn't look completely finished. Quantity reflects total SF of all listed spaces. B102B	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	62	\$2	Square Foot	\$140
5384	Batavia High School	1797 - Interior Doors, Swinging- Wood - 2009	North Classrooms, SW Mechanical	Music Rooms	2020	Sent to Maintenance	Cost to replace door and hardware. Room #: E101, E103, E106K, E107, E108, E109, E109A, E109B, E109C	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	9	\$1,950	Each	\$17,550
5386	Batavia High School	1852 - Interior Doors, Swinging- Hollow Metal - 2009	North Central Classrooms (1969)	Arts)	2020	Sent to Maintenance	Interior HM doors in fair condition. Room #: A120, A123, A124, A125	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	4	\$75	Each	\$300
5389	Batavia High School	1760 - Exterior Entrance Doors, Hollow Metal - 2011	BFAC, Fieldhouse (2011)	Set Building	2020	Sent to Maintenance	Exterior HM door in fair condition. Room #: F106	Shell	Exterior Vertical Enclosures	Exterior Doors and Grilles	Exterior Entrance Doors	2-Should Do	Fair	1	\$75	Each	\$75
5391	Batavia High School	1807 - Ceilings,	BFAC, Fieldhouse (2011)	Music Rooms	2020	Sent to Maintenance	ACT in fair condition. Room #: E101, E103, E107, E107A, E108, E109, E109B, E110	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	2-Should Do	Fair	7000	\$8	Square Foot	\$52,500
5398	Batavia High School	, 1810 - Ceilings, Gypsum - 2009	North Classrooms, SW Mechanical	Music Rooms	2020	Sent to Maintenance	Room #: E101, E107, E109, E109B	Interiors	Interior Construction	Suspended Ceiling Construction	Suspended Plaster and Gypsum Board	2-Should Do	Fair	1479	\$12	Square Foot	\$17,748
5401	Batavia High School	1797 - Interior Doors, Swinging- Wood - 2009	North Classrooms, SW Mechanical	Storage	2020	Sent to Maintenance	Interior wood door in fair condition. Cost to replace door and hardware. D112, D116A	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	2	\$1,950	Each	\$3,900
5404	Batavia High School	Doors, Swinging-	North Classrooms, SW Mechanical (2009)	Storage	2020	Sent to Maintenance	Interior HM frame in fair condition. Cost to repaint. D100A, D113, D112	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	3	\$60	Each	\$180
5408	Batavia High School	VCT - 2009	North Classrooms, SW Mechanical	Storage	2020	Sent to Maintenance	VCT flooring in fair condition. Cost to replace VCT with rubber flooring. D113	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	389	\$12	Square Foot	\$4,668
5410	Batavia High School		North Classrooms, SW Mechanical	Storage	2020	Sent to Maintenance	Epoxy flooring in fair condition. E114, E116	Substructure	Slabs-On-Grade	Standard Slabs-on Grade	-	2-Should Do	Fair	94	\$20	Square Foot	\$1,880
5413	Batavia High School	Wall Finishes,	North Classrooms, SW Mechanical	Storage	2020	Sent to Maintenance	Wall base in fair condition. D116A	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	36	\$6	Linear Foot	\$216
5415	Batavia High School	Wall Finish, Paint -	North Classrooms, SW Mechanical	Storage	2020	Sent to Maintenance	Walls were given one coat of paint that doesn't look completely finished.	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	105	\$2	Square Foot	\$236









Assessment	t Campus	Linked Bldg	Addition	Room	Assessment	Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID		System			Year	Status		L1	L2	L3	L4						
5417	Batavia High School		North Classrooms, SW Mechanical	Storage	2020	Sent to Maintenance	lighting is in fair condition D113	Services	Electrical	Lighting	Lighting Fixtures	2-Should Do	Fair	385	\$8	Square Foot	\$3,080
5425	Batavia High		North	Science Prep.	2020	Sent to	ACT ceiling is in a fair condition.	Interiors	Interior	Suspended Ceiling	Acoustical	2-Should Do	Fair	350	\$8	Square Foot	\$2,625
	School	Acoustical Suspended	Classrooms, SW Mechanical			Maintenance	2 water damaged ceiling tile. D207		Construction	Construction	Suspended Ceilings						7-7
		Systems - 2009	(2009)														
5426	Batavia High	1827 - Flooring,	North	Science Prep.	2020	Sent to	VCT flooring is in a fair condition.	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	350	\$12	Square Foot	\$4,200
	School	VCT - 2009	Classrooms, SW Mechanical (2009)			Maintenance	Cost to replace VCT with rubber flooring. D207										
5430	Batavia High	1993 - Interior	North	Science Prep.	2020	Sent to	Wall paint is in a fair condition.	Interiors	Interior Finishes	Wall Einiches	Wall Painting and	2-Should Do	Fair	700	\$2	Square Foot	\$1,575
3430	School		- Classrooms, SW Mechanical	Science Frep.	2020	Maintenance	Quantity reflects total SF of all listed spaces.		interior Finishes	wall Fillisties	Coating	2-3110ulu D0	raii	700	\$2	Square Foot	\$1,373
			(2009)				D203, D207										
5432	Batavia High	1896 - Interior	East 2-Story	Classrooms	2020	Sent to	Wood door in fair condition -	Interiors	Interior	Interior Doors	Interior Swinging	2-Should Do	Fair	1	\$1,950	Each	\$1,950
	School	Doors, Swinging- Wood - 1995	Classrooms (199	5)		Maintenance	interior glass stop on vision lite is damaged, glass rattles. Cost to replace door and hardware.		Construction		Doors						
							C216										
5434	Batavia High	1896 - Interior	East 2-Story	Classrooms	2020	Sent to	HM door frame in fair condition.	Interiors	Interior	Interior Doors	Interior Swinging	2-Should Do	Fair	16	\$60	Each	\$960
3434	School		Classrooms (199			Maintenance	The door frame in rail condition.	III CIIOIS	Construction	interior boors	Doors	2 3110010 00	T un	10	300	Eden	7500
	3611001	Wood - 1995	Clussi 001113 (155)	5/		- Iviamice and	C200.		Construction		20013						
							C201.										
							C203.										
							C205.										
							C206.										
							C207.										
							C208.										
							C210.										
							C212.										
							C213.										
							C214.										
							C216.										
							C218.										
							C219.										
							C220.										
							C221.										
5435	Batavia High	1899 - Ceilings,	East 2-Story	Classrooms	2020	Sent to	ACT in fair condition.	Interiors	Interior	Suspended Ceiling		2-Should Do	Fair	12050	\$8	Square Foot	\$90,375
	School	Acoustical	Classrooms (199	5)		Maintenance			Construction	Construction	Suspended						
		Suspended					C200.				Ceilings						
		Systems - 1995					C201.										
							C203.										
							C205.										
							C206.										
							C207.										
							C208.										
							C210.										
							C212.										
							C213.										
							C214.										
							C216.										
							C218. C220.										
							C220. C221.										
<u> </u>						1	C221.	1		1	1	1					










Assessment	Campus	Linked Bldg	Addition	Room	Assessment		Description		Building System L2	Building System L3		Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID 5438	Batavia High School	System 1910 - Flooring, VCT - 1995	East 2-Story Classrooms (1995	Classrooms 5)	Year 2020	Status Sent to Maintenance	VCT in fair condition. Cost to replace VCT with rubber flooring.	L1 Interiors	Interior Finishes	Flooring	L4 Resilient Flooring	2-Should Do	Fair	12050	\$12	Square Foot	\$144,600
			,				C200.										
							C201.										
							C203.										
							C205. C206.										
							C206.										
							C208.										
							C210.										
							C212.										
							C213.										
							C214. C216.										
							C218.										
							C220.										
							C221.										
5443	Batavia High	1921 - Interior	East 2-Story	Classrooms	2020	Sent to	CMU in fair condition - Most CMU in	Interiors	Interior	Interior Partitions		2-Should Do	Fair	0	\$40	Square Foot	\$0
	School		Classrooms (1995	5)		Maintenance	good condition; south wall has water damage with CMU/paint		Construction		Partitions						
		CMU - 1995					eroding. Confirm quantity, cost to										
							repair CMU.										
							C200										
5444	Batavia High			Storage/Mechani		Sent to	Interior HM frame in fair condition.	Interiors	Interior	Interior Doors	Interior Swinging	2-Should Do	Fair	7	\$60	Each	\$420
	School	Doors, Swinging-	(2011)	al/IT		Maintenance	F106A.		Construction		Doors						
		Hollow Metal - 2011					F112M. F112K.										
		2011					F112L.										
							F114.										
							F114A.										
5440	5	1000 51 :			2020		F115.				D 11:	2.61 11.5		750	440		40.246
5449	Batavia High School	1909 - Flooring, VCT - 1969	North Central Classrooms (1969	Art Rooms	2020	Sent to Maintenance	Cost to replace VCT with rubber flooring.	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	768	\$12	Square Foot	\$9,216
	3011001	VC1 - 1303	Classicomis (1909	7)		iviaiiiteilalice	Room #: A131										
5453	Batavia High	1975 - Interior	East 2-Story	Classrooms	2020	Sent to	Wall base in fair condition.	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	1800	\$6	Linear Foot	\$10,800
	School	Wall Finishes,	Classrooms (1995	5)		Maintenance											
		Wall Base - 1995					C200.										
							C201. C203.										
							C205.										
							C206.										
							C207.										
							C208.										
							C210.										
							C212. C213.										
							C213.										
							C214.										
	1						C218.										
				(1	1	6220					1			1	I	
							C220.										
F454	Data da Unit	2024 Jahanian	DEAC ELLIPS	Characa /A A - ala	- 2020	Contto	C221.	latarians	Interior Finish	Mall Finish -	Tile Mell State	2 Ch - 11 2 2 -	Fair	F227	¢20	Caucara Frank	Ć157.140
5454	Batavia High School	2024 - Interior Wall Finish, Tile -		Storage/Mechani		Sent to Maintenance	C221. STAINED TILE AND MISSING TILE.	Interiors	Interior Finishes	Wall Finishes	Tile Wall Finish	2-Should Do	Fair	5237	\$30	Square Foot	\$157,110










C213. C214. C216. C218. C220. C221.

Building Our Future









Assessmen ID	nt Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cos
5467	Batavia High School	1827 - Flooring, VCT - 2009	North Classrooms, SW Mechanical (2009)	Music Rooms		Sent to Maintenance	Room #: E101, E103, E106A, E107A, E107B, E109B, E109C Chips in VCT, scratches and general wear and tear. Cost to replace VCT with rubber flooring.		Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	4015	\$12	Square Foot	\$48,180
5469	Batavia High School	1753 - Exterior Windows, Operating - 1995	East 2-Story Classrooms (1995	Classrooms	2020	Sent to Maintenance	Exterior windows in fair condition - cold air leakage, screens have holes Verify size in field. Cost to replace. C200. C201. C203. C205. C206. C207. C208. C210. C213. C214. C216. C218. C219. C220. C221.		Exterior Vertical Enclosures	Exterior Windows	Exterior Operating Windows	2-Should Do	Fair	720	\$100	Square Foot	\$72,000
5472	Batavia High School	1985 - Electrical, Lighting Fixtures		Storage/Mechani al/IT		Sent to Maintenance	lighting in fair condition F107A	Services	Electrical	Lighting	Lighting Fixtures	2-Should Do	Fair	0	\$8	Square Foot	\$0
5473	Batavia High School	2005 - HVAC, Ventilation-Unit Ventilators - 1995	East 2-Story Classrooms (1995	Classrooms		Sent to Maintenance	Unit vents in fair condition. C200. C201. C203. C205. C206. C207. C208. C210. C121. C213. C214. C216. C218. C219. C220. C220.		Heating, Ventilation, and Air Conditioning (HVAC)			2-Should Do		16	\$4,500		\$72,000
5475	Batavia High School	1797 - Interior Doors, Swinging- Wood - 2009	North Classrooms, SW Mechanical (2009)	Science Classrooms		Sent to Maintenance	HM door frames in fair condition. D202. D204. D206. D208.	Interiors	Interior Construction		Interior Swinging Doors	2-Should Do	Fair	4	\$60	Each	\$240









Assessment	Campus	Linked Bldg	Addition	Room	Assessmen	Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID	Campus	System	Addition	Koom	Year	Status	Description	L1	L2	L3	L4	riionty	racinty condition	Quantity	Onit Cost	Offic Of Weasure	Estimated Cost
5477	Batavia High School	VCT - 2009	North Classrooms, SW Mechanical (2009)	Science Classrooms	2020	Sent to Maintenance	VCT in fair condition. Cost to replace VCT with rubber flooring. D202. D204. D206.	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	3534	\$12	Square Foot	\$42,408
5480	Batavia High School	- I	North Classrooms, SW Mechanical (2009)	Science Classrooms	2020	Sent to Maintenance	D208. Paint in fair condition. Quantity reflects total SF of all listed spaces. D202. D204. D206. D208.	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	3534	\$2	Square Foot	\$7,952
5482	Batavia High School	Lighting Fixtures - 2009	North Classrooms, SW Mechanical (2009)	Science Classrooms	2020	Sent to Maintenance		Services	Electrical	Lighting	Lighting Fixtures	2-Should Do	Fair	0	\$8	Square Foot	\$0
5487	Batavia High School		East 2-Story Classrooms (1995)	Classrooms	2020	Sent to Maintenance	Wall base in poor condition - Wall base separating from wall, 1 LF, very scuffed throughout.	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	1	\$6	Linear Foot	\$6
5496	Batavia High School		North Classrooms, SW Mechanical	Music Rooms	2020	Sent to Maintenance	Room #: E106A, E106B. Dent in gyp walls. Confirm quantity.	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair	0	\$15	Square Foot	\$0
5502	Batavia High School		South Admin Addition (2009)	Music Rooms	2020	Sent to Maintenance	Room #: E106C, E106D Scuffed up base.	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	86	\$6	Linear Foot	\$516
5506	Batavia High School	1993 - Interior Wall Finish, Paint - 2009	North Classrooms, SW Mechanical (2009)	Exploratories	2020	Sent to Maintenance	Paint in fair condition. Quantity reflects total SF of all listed spaces. D110. D111. D114. D115. D116.	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	6100	\$2	Square Foot	\$13,725
5507	Batavia High School	Wall Finish, Paint - 2009	North Classrooms, SW Mechanical (2009)	Music Rooms	2020	Maintenance	Paint in fair condition. Quantity reflects total SF of all listed spaces. E101. E103. E107. E108. E109. E109B. E1101.	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	7834	\$2	Square Foot	\$17,627










Assessment	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
5514	Batavia High School		South Admin Addition (2009)	Office / Pull-Out		Sent to Maintenance	VCT is in Fair Condition. Cost to replace VCT with rubber flooring. B100L - VCT flooring is scuffed throughout, B101 - VCT surface in good condition, but seams are beginning to separate throughout, B102 - VCT surface in good condition, but seams are beginning to separate throughout	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	1389	\$12	Square Foot	\$16,668
5515	Batavia High School		LRC, Classrooms (1971)	Classrooms	2020	Sent to Maintenance	CMU in fair condition. Cost to repair cracking. B115. B116. B117.	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair	0	\$15	Linear Foot	\$0
5516	Batavia High School	1973 - Interior Wall Finishes, Wall Base - 1971	LRC, Classrooms (1971)	Classrooms	2020	Sent to Maintenance	Wall base in fair condition. B115. B116. B117.	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	350	\$6	Linear Foot	\$2,100
5518	Batavia High School	1989 - Interior Wall Finish, Paint - 1971	LRC, Classrooms (1971)	Classrooms	2020	Sent to Maintenance	Paint in fair condition. Quantity reflects total SF of all listed spaces. B115. B116. B117.	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	2575	\$2	Square Foot	\$5,794
5519	Batavia High School	1988 - Fixed Equipment, Casework - 1971	LRC, Classrooms (1971)	Classrooms	2020	Sent to Maintenance	Casework in fair condition. Cost to replace entirely. B115. B116. B117.	Equipment and Furnishings	Furnishings	Fixed Furnishings	Casework	2-Should Do	Fair	100	\$800	Linear Foot	\$80,000
5521	Batavia High School	1685 - Exterior Windows, Operating - 1971	LRC, Classrooms (1971)	Classrooms	2020	Sent to Maintenance		Shell	Exterior Vertical Enclosures	Exterior Windows	Exterior Operating Windows	2-Should Do	Fair	60	\$100	Square Foot	\$6,000
	Batavia High School	VCT - 2009 Admin	South Admin Addition (2009)	Office / Pull-Out		Sent to Maintenance	VCT is in Fair Condition. Cost to replace VCT with rubber flooring. B100L - VCT flooring is scuffed throughout, B101 - VCT surface in good condition, but seams are beginning to separate throughout, B102 - VCT surface in good condition, but seams are beginning to separate throughout	Interiors	Interior Finishes		Resilient Flooring			1389	\$12	Square Foot	\$16,668
5524	Batavia High School	Equipment,	North Classrooms, SW Mechanical	Exploratories	2020	Sent to Maintenance	Cost to replace entirely. Room #: D115	Equipment and Furnishings	Furnishings	Fixed Furnishings	Casework	2-Should Do	Fair	60	\$800	Linear Foot	\$48,000








Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cos
5525	Batavia High School	1987 - Fixed Equipment, Casework - 2009	North Classrooms, SW Mechanical (2009)	Music Rooms	2020	Sent to Maintenance	Room #: E109B STORAGE SHELVES BENDING UNDER WEIGHT OF INSTRUMENTS. Cost to replace entirely.	Equipment and Furnishings	Furnishings	Fixed Furnishings		2-Should Do	Fair	44	\$800	Linear Foot	\$35,200
5526	Batavia High School	1987 - Fixed Equipment, Casework - 2009	North Classrooms, SW Mechanical (2009)	Music Rooms	2020	Sent to Maintenance	Cost to replace entirely. Room #: E101. E101A. E103. E105. E107. E107A. E107B. E109A.	Equipment and Furnishings	Furnishings	Fixed Furnishings	Casework	2-Should Do	Fair :	100	\$800	Linear Foot	\$80,000
5530	Batavia High School		North Classrooms, SW Mechanical	Exploratories	2020	Sent to Maintenance	Room #: D110 D114	Services	Electrical	Lighting	Lighting Fixtures	2-Should Do	Fair ()	\$8	Square Foot	\$0
5532	Batavia High School	1	North Classrooms, SW Mechanical	Music Rooms	2020	Sent to Maintenance	Room #: E109B	Services	Electrical	Lighting	Lighting Fixtures	2-Should Do	Fair ()	\$8	Square Foot	\$0
5539	Batavia High School	2032 - Flooring, Epoxy - 2011	BFAC, Fieldhouse (2011)	BFAC Spaces	2020	Sent to Maintenance	Room #: F100 BFAC Vestibule. F106. F107. F110. F109 Mens and Womens RR.	Interiors	Interior Finishes	Flooring	Fluid-Applied Flooring	2-Should Do	Fair :	10375	\$20	Square Foot	\$207,500
5540	Batavia High School	2032 - Flooring, Epoxy - 2011	North Classrooms, SW Mechanical	Music Rooms	2020	Sent to Maintenance	Room #: E110	Interiors	Interior Finishes	Flooring	Fluid-Applied Flooring	2-Should Do	Fair :	732	\$20	Square Foot	\$14,640
5550	Batavia High School	1709 - Interior Doors, Swinging- Hollow Metal - Original		FACS	2020	Sent to Maintenance	HM door in fair condition. B110	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair 2	2	\$75	Each	\$150
5553	Batavia High School	1704 - Flooring, VCT - Original		FACS	2020	Sent to Maintenance	VCT in fair condition. Cost to replace VCT with rubber flooring. B110	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair :	1180	\$12	Square Foot	\$14,160
5570	Batavia High School	1853 - Interior Doors, Swinging- Hollow Metal - 2011		Building Trades F111	2020	Sent to Maintenance		Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	4	\$75	Each	\$300
5579	Batavia High School	1710 - Interior Partitions, Fixed- CMU - Original		Toilet	2020	Sent to Maintenance	CMU is cracking and spalling in several locations 5 SF. Mens Faculty Center. Womens Faculty Center.	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair :	10	\$15	Linear Foot	\$150
5580	Batavia High School		BFAC, Fieldhouse (2011)	Building Trades F111	2020	Sent to Maintenance	Concrete flooring in fair condition - needs to be repainted, cracks in concrete at doorway. Confirm cost for refinishing concrete without replacing. Current cost to repair cracking only. F111	Substructure	Slabs-On-Grade	Standard Slabs-on Grade		2-Should Do	Fair	3723	\$10	Square Foot	\$37,230









Assessment	t Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
5592	Batavia High	1852 - Interior	North	Kitchen/Servery	2020	Sent to	HM Door in fair condition: paint	Interiors	Interior	Interior Doors	Interior Swinging	2-Should Do	Fair	2	\$75	Each	\$150
3332	School	Doors, Swinging-	Classrooms, SW	Kitchen, Servery	2020	Maintenance	touch-up required.	IIICIIOI3	Construction	interior boors	Doors	2 Should bo	l un	_	7,3	Lucii	7130
	3011001	Hollow Metal -	Mechanical			Widirectionec	toden ap required.		Construction		20013						
		2009	(2009)				A102A Kitchen										
5596	Batavia High	1970 - Flooring,	(2003)	Office / Pull-Out	2020	Sent to	Carpet is in Fair Condition.	Interiors	Interior Finishes	Flooring	Carpeting	2-Should Do	Fair	642	\$7	Square Foot	\$4,173
3330	School	Carpet - Original		omee, run out	2020	Maintenance	B107A - Carpet is splitting at				ou. potB	2 3.10 4.14 2 5		· · · ·	Ψ,	oqua.c.root	ψ ·/= / ·3
							transition with VCT. Older carpet in										
							general,										
							B118D,										
							B123 -CARPET IS WORN										
5598	Batavia High	1717 - Flooring,	LRC, Classrooms	Office / Pull-Out	2020	Sent to	Carpet is in Fair Condition	Interiors	Interior Finishes	Flooring	Carpeting	2-Should Do	Fair	100	\$7	Square Foot	\$650
	School	Carpet - 1971	(1971)			Maintenance											
5601	Batavia High	2037 - Flooring,	South Admin	Office / Pull-Out	2020	Sent to	Carpet is in Fair Condition.	Interiors	Interior Finishes	Flooring	Carpeting	2-Should Do	Fair	626	\$7	Square Foot	\$4,069
	School	Carpet - 2009	Addition (2009)			Maintenance	B101 (Dean Reception) - Carpet										
							worn down at reception chairs										
5603	Batavia High	1747 - Slab on		Office / Pull-Out	2020	Sent to	Concrete Slab is in Fair Condition.	Substructure	Slabs-On-Grade	Standard Slabs-on	1-	2-Should Do	Fair	300	\$25	Square Foot	\$7,500
	School	Grade - 2011	(2011)			Maintenance	Confirm cost to refinish concrete			Grade							
							flooring without replacing.										
5604	Data da Histo	2020 - 51	DEAC Elabora	Office / Bull Out	2020	Combine	F111 (Building Trades Office)	lata da sa	Interior Finish	Eleccione	Carra atia a	2.65	Fair	300	\$7	C	Ć4 0F0
5604	Batavia High School	2029 - Flooring, Carpet - 2011	(2011)	e Office / Pull-Out	2020	Sent to Maintenance	Carpet is in Fair Condition. F111 (Building Trades Office)	Interiors	Interior Finishes	Flooring	Carpeting	2-Should Do	rair	300	\$7	Square Foot	\$1,950
5607	Batavia High	1710 - Interior	(2011)	Office / Pull-Out	2020	Sent to	CMU Wall is in Fair Condition.	Interiors	Interior	Interior Partitions	Interior Fixed	2-Should Do	Fair	n	\$15	Linear Foot	\$0
3007	School	Partitions, Fixed-		Office / Full-Out	2020	Maintenance	Confirm quantity, cost to repair	interiors	Construction	interior Fartitions	Partitions	2-3110010 00	i ali	J	713	Linear 100t	ÇÜ
	5611001	CMU - Original				Wallitellance	cracking.		Construction		T di titions						
		Civio Original					B115,										
							B116,										
							B117										
5644	Batavia High	1920 - Interior	North Central	Office / Pull-Out	2020	Sent to	CMU Wall is in Fair Condition.	Interiors	Interior	Interior Partitions	Interior Fixed	2-Should Do	Fair	0	\$40	Linear Foot	\$0
	School	Partitions, Fixed-	Classrooms (1969	9)		Maintenance	Confirm quantity, cost to repair		Construction		Partitions						
		CMU - 1969					damaged CMU.										
							A123A (Graphics Office) - several										
							nail holes need to be filled										
5645	Batavia High	1854 - Interior	LRC, Classrooms	Office / Pull-Out	2020	Sent to	CMU Wall is in Fair Condition.	Interiors	Interior	Interior Partitions		2-Should Do	Fair	20	\$15	Linear Foot	\$300
	School	Partitions, Fixed-	(1971)			Maintenance	Career Counselor (In LMC) - Vertical		Construction		Partitions						
		CMU - 1971					cracking in the corners of the room										
							and in the middle of the wall at										
							joints.										
5652	Batavia High	1708 - Interior		Office / Pull-Out	2020	Sent to	Confirm quantity. GWB walls are in Fair condition.	Interiors	Interior	Interior Partitions	Interior Fixed	2-Should Do	Fair	<u> </u>	\$15	Square Foot	\$0
3032	School	Partitions, Fixed -		Office / Pull-Out	2020	Maintenance		interiors	Construction	interior Partitions	Partitions	2-3110010 00	raii	J	\$15	Square Foot	ŞU
	3011001	GWB - Original				ivialifice	B118 - GWB corners need to be		Construction		raititions						
		GWD - Original					patched near reception desk,										
							B122,										
							B123,										
							B124,										
							B124A,										
							B124B,										
							B124C,										
							B124D,										
							B124E										
5653	Batavia High		Central Area,	Office / Pull-Out	2020	Sent to	GWB walls are in Fair condition.	Interiors	Interior	Interior Partitions		2-Should Do	Fair	14	\$6	Linear Foot	\$84
	School		South Entrance			Maintenance	Cost to repair sealant.		Construction		Partitions						
		GWB - 1995	(1995)				B100M (Counselor Reception) -										
							Sealant at door to corridor is										
							cracking verticallly along the HM					1					











Assessment ID	t Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
5654	Batavia High School	1846 - Interior Partitions, Fixed- GWB - 2009 Admin	South Admin Addition (2009)	Office / Pull-Out	2020	Sent to Maintenance	GWB walls are in Fair condition. Confirm quantity/scope. B100B - Scuffs on interior or corridor wall, B100C - Scuffs on interior or corridor wall, B100D - Scuffs on interior or corridor wall		Interior Construction	Interior Partitions		2-Should Do	Fair	0	\$15	Square Foot	\$0
5658	Batavia High School	1743 - Interior Wall Finishes, Wall Base - Original		Office / Pull-Out	2020	Sent to Maintenance	Wall base is in Good condition. B115, B116, B117	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	360	\$6	Linear Foot	\$2,160
5741	Batavia High School	1711 - Interior Doors, Swinging- Wood - 1995 Entry	Central Area, South Entrance (1995)	Kitchen/Servery	2020	Sent to Maintenance	Wood door in fair condition. A102A Kitchen	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$1,950	Each	\$1,950
5742	Batavia High School	1857 - Interior Partitions, Fixed- CMU - 2009	North Classrooms, SW Mechanical	Science Prep.	2020	Sent to Maintenance	CMU walls are in fair condition - ~6lf stair step crack by door. D207	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair	6	\$15	Linear Foot	\$90
5743	Batavia High School	1698 - Ceilings, Acoustical Suspended Systems - Origina		Corridor	2020	Sent to Maintenance	ACT in fair condition. Main corridor by gyms. B-CORRIDOR - MISMATCHED TILES, SOME BOWING, SCRATCHES, MINOR DAMAGE. B-CORRIDOR NORTH OF FAC CENTER (TEAL LOCKERS) - SOME DAMAGED GRIDS OUTSIDE FAC CENTER.		Interior Construction		Acoustical Suspended Ceilings	2-Should Do	Fair	6000	\$8	Square Foot	\$45,000
5748	Batavia High School	1852 - Interior Doors, Swinging- Hollow Metal - 2009	North Classrooms, SW Mechanical (2009)	Corridor	2020	Sent to Maintenance	Interior HM door in fair condition. D-wing corridors level 1. E CORRIDOR - CHORAL	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	2	\$75	Each	\$150
5749	Batavia High School	1852 - Interior Doors, Swinging- Hollow Metal - 2009	North Classrooms, SW Mechanical (2009)	Corridor	2020	Sent to Maintenance	Interior HM frame in fair condition. D-wing corridors level 1. E CORRIDOR - CHORAL	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	2	\$60	Each	\$120
5752	Batavia High School	1805 - Ceilings, Acoustical Suspended Systems - 2009	North Classrooms, SW Mechanical (2009)	Corridor	2020	Sent to Maintenance	ACT ceiling in fair condition. E CORRIDOR. E CORRIDOR - CHORAL	Interiors	Interior Construction		Acoustical Suspended Ceilings	2-Should Do	Fair	2400	\$8	Square Foot	\$18,000
5755	Batavia High School	1827 - Flooring, VCT - 2009	North Classrooms, SW Mechanical (2009)	Corridor	2020	Sent to Maintenance	VCT flooring in fair condition. Cost to replace VCT with rubber flooring. D-wing corridors level 1. E CORRIDOR - CHORAL.	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	6300	\$12	Square Foot	\$75,600
5756	Batavia High School	2037 - Flooring, Carpet - 2009	North Classrooms, SW Mechanical	Corridor	2020	Sent to Maintenance	Carpet flooring in fair condition (STAINING FROM SALT). E CORRIDOR	Interiors	Interior Finishes	Flooring	Carpeting	2-Should Do	Fair	2110	\$7	Square Foot	\$13,715
5758	Batavia High School	1977 - Interior Wall Finishes, Wall Base - 2009	North Classrooms, SW Mechanical	Corridor	2020	Sent to Maintenance	Wall base in fair condition. D-wing corridors level 1. E CORRIDOR - CHORAL	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	1250	\$6	Linear Foot	\$7,500
5761	Batavia High School	1993 - Interior Wall Finish, Paint 2009	North	Corridor	2020	Sent to Maintenance	Paint in fair condition. Quantity reflects total SF of all listed spaces. D-wing corridors level 1. E CORRIDOR. E CORRIDOR - CHORAL.	Interiors	Interior Finishes		Wall Painting and Coating	2-Should Do	Fair	10100	\$2	Square Foot	\$22,725









ssessment	Campus	Linked Bldg	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cos
5767	Batavia High School	System 1765 - Exterior Entrance Doors,	North Classrooms, SW	Corridor	2020	Sent to Maintenance	MINOR RUSTING AT EXTERIOR BASE OF DOOR; SCRATCHED. Cost to		Exterior Vertical Enclosures	Exterior Doors and Grilles	Exterior Entrance Doors	2-Should Do	Fair	1	\$7,500	Each	\$7,500
		Aluminum - 2009	Mechanical (2009)				replace door and hardware. E CORRIDOR - CHORAL										
5772	Batavia High School	1852 - Interior Doors, Swinging- Hollow Metal - 2009	North Classrooms, SW Mechanical (2009)	Stair	2020	Sent to Maintenance	Interior HM frame in fair condition. Stair by d110 level 2	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$60	Each	\$60
5775	Batavia High School	2037 - Flooring, Carpet - 2009	North Classrooms, SW Mechanical	Stair	2020	Sent to Maintenance	Carpet flooring in fair condition. Stair by d110 level 1	Interiors	Interior Finishes	Flooring	Carpeting	2-Should Do	Fair	343	\$7	Square Foot	\$2,230
5779	Batavia High School	1993 - Interior Wall Finish, Paint - 2009	North -Classrooms, SW Mechanical (2009)	Stair	2020	Sent to Maintenance	Paint in fair condition. Quantity reflects total SF of all listed spaces. Stair by d110 level 1. Stair by d110 level 2.	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	500	\$2	Square Foot	\$1,125
5783	Batavia High School	1814 - Interior Railings and Handrails - 2009	North Classrooms, SW Mechanical (2009)	Stair	2020	Sent to Maintenance	stairs pipe and handrails in fair condition. Cost to repaint. Stair by d110 level 1. Stair by d110 level 2.	Interiors	Interior Construction	Interior Specialties	Interior Railings and Handrails	2-Should Do	Fair	52	\$20	Linear Foot	\$1,040
5786	Batavia High School	1852 - Interior Doors, Swinging- Hollow Metal - 2009	North Classrooms, SW Mechanical (2009)	Vestibule	2020	Sent to Maintenance	Interior HM door in fair condition. D-wing middle vestibule	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$75	Each	\$75
5787	Batavia High School	1852 - Interior Doors, Swinging- Hollow Metal - 2009	North Classrooms, SW Mechanical (2009)	Vestibule	2020	Sent to Maintenance	Interior HM frame in fair condition. D-wing middle vestibule	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$60	Each	\$60
5789	Batavia High School	2037 - Flooring, Carpet - 2009	North Classrooms, SW Mechanical	Vestibule	2020	Sent to Maintenance	Carpet flooring in fair condition. D-wing middle vestibule	Interiors	Interior Finishes	Flooring	Carpeting	2-Should Do	Fair	90	\$7	Square Foot	\$585
5802	Batavia High School	1992 - Interior Wall Finish, Paint - 2009 Admin	South Admin Addition (2009)	Corridor	2020	Sent to Maintenance	Wall paint in fair condition. Quantity reflects total SF of all listed spaces. 2009 office corridor	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	650	\$2	Square Foot	\$1,463
5803	Batavia High School	1983 - Electrical, Lighting Fixtures - 2009 Admin	South Admin Addition (2009)	Corridor	2020	Sent to Maintenance	Lighting in fair condition (All lights do not have same color temperature and plastic screens look dirty). 2009 office	Services	Electrical	Lighting	Lighting Fixtures	2-Should Do	Fair	0	\$8	Square Foot	\$0
5804	Batavia High School	1825 - Flooring, VCT - 1995 Entry	Central Area, South Entrance (1995)	Lobby	2020	Sent to Maintenance	VCT flooring in fair condition. Cost to replace VCT with rubber flooring. Main entrance lobby	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	3270	\$12	Square Foot	\$39,240
5805	Batavia High School	1748 - Exterior Face Brick - 1995 Entry	Central Area, South Entrance (1995)	Lobby	2020	Sent to Maintenance	Brick wall in fair condition. Cost to clean brick, confirm quantity. Main entrance lobby	Shell	Exterior Vertical Enclosures	Exterior Walls	Exterior Wall Veneer	2-Should Do	Fair	0	\$5	Square Foot	\$0
5806	Batavia High School	1916 - Interior Partitions, Fixed- GWB - 1995 Entry	Central Area, South Entrance (1995)	Lobby	2020	Sent to Maintenance	GWB wall in fair condition. Main entrance lobby	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair	0	\$15	Square Foot	\$0
5807	Batavia High School	1974 - Interior Wall Finishes, Wall Base - 1995	Central Area, South Entrance (1995)	Lobby	2020	Sent to Maintenance	Wall base in fair condition. Main entrance lobby	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	200	\$6	Linear Foot	\$1,200
5808	Batavia High School	1990 - Interior Wall Finish, Paint - 1995 Entry	Central Area,	Lobby	2020	Sent to Maintenance	Wall paint in fair condition. Quantity reflects total SF of all listed spaces. Main entrance lobby	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	1500	\$2	Square Foot	\$3,375









ssessment	Campus	Linked Bldg System	Addition	Room	Assessment	Assessment Status	Description	Building System	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
5809	Batavia High School	1754 - Exterior Windows, Operating - 1995 Entry	Central Area, South Entrance (1995)	Lobby, Cafeteria	2020	Sent to Maintenance	Smaller exterior windows in fair to good condition. Verify size in field, not shown on plan. Main entrance lobby, atrium area. 25 windows?	Shell	Exterior Vertical Enclosures	Exterior Windows		2-Should Do	Fair	0	\$100	Square Foot	\$0
5810	Batavia High School	2021 - Interior Wall Finish, Tile - 1995 Entry	Central Area, South Entrance (1995)	Lobby	2020	Sent to Maintenance	Ceramic tile flooring in fair condition. Cost to clean grout. Main entrance lobby	Interiors	Interior Finishes	Wall Finishes	Tile Wall Finish	2-Should Do	Fair	499	\$5	Square Foot	\$2,495
5811	Batavia High School	1767 - Exterior Entrance Doors, Aluminum - 1995 Entry	Central Area, South Entrance (1995)	Lobby	2020	Sent to Maintenance	Exterior alum door in fair condition. Cost to replace door and hardware. Main entrance lobby	Shell	Exterior Vertical Enclosures	Exterior Doors and Grilles	Exterior Entrance Doors	2-Should Do	Fair	1	\$7,500	Each	\$7,500
5814	Batavia High School	1821 - Flooring, Ceramic Tile - 1995 - Entry	Central Area, South Entrance (1995)	Lobby	2020	Sent to Maintenance	Ceramic wall tile in fair condition. Cost to clean grout. Main entrance lobby	Interiors	Interior Finishes	Flooring	Tile Flooring	2-Should Do	Fair	1100	\$5	Square Foot	\$5,500
5815	Batavia High School	1896 - Interior Doors, Swinging- Wood - 1995	East 2-Story Classrooms (1995	Vestibule)	2020	Sent to Maintenance	Interior wood door in fair condition. C-wing south center vest.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$1,950	Each	\$1,950
5817	Batavia High School	1850 - Interior Doors, Swinging- Hollow Metal - 1995	East 2-Story Classrooms (1995	Vestibule)	2020	Sent to Maintenance	Interior HM door in fair condition. C-wing north center vest.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$75	Each	\$75
5818	Batavia High School	1763 - Exterior Entrance Doors, Hollow Metal - 1995	East 2-Story Classrooms (1995	Vestibule)	2020	Sent to Maintenance	Exterior HM door in fair condition. C-wing south vestibule	Shell	Exterior Vertical Enclosures	Exterior Doors and Grilles	Exterior Entrance Doors	2-Should Do	Fair	1	\$75	Each	\$75
5820	Batavia High School	1850 - Interior Doors, Swinging- Hollow Metal - 1995	East 2-Story Classrooms (1995	Vestibule)	2020	Sent to Maintenance	Interior HM doors in fair condition. C-wing south vestibule. C-wing south center vest. C-wing north center vest.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	6	\$75	Each	\$450
5821	Batavia High School	1763 - Exterior Entrance Doors, Hollow Metal - 1995	East 2-Story Classrooms (1995	Vestibule)	2020	Sent to Maintenance	Exterior HM frame in fair condition. C-wing south vestibule. C-wing south center vest.	Shell	Exterior Vertical Enclosures	Exterior Doors and Grilles	Exterior Entrance Doors	2-Should Do	Fair	2	\$60	Each	\$120
5823	Batavia High School	2116 - Ceilings, Acoustical Suspended Systems - 1995	East 2-Story Classrooms (1995	Vestibule)	2020	Sent to Maintenance	ACT ceiling in fair condition. C-wing north center vest.	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	2-Should Do	Fair	295	\$8	Square Foot	\$2,213
5824	Batavia High School	1910 - Flooring, VCT - 1995	East 2-Story Classrooms (1995	Vestibule)	2020	Sent to Maintenance	VCT flooring in fair condition. Cost to replace VCT with rubber flooring. C-wing south vestibule. C-wing south center vest.		Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	200	\$12	Square Foot	\$2,400
5825	Batavia High School	2117 - Flooring, Carpet - 1995	East 2-Story Classrooms (1995	Vestibule	2020	Sent to Maintenance	Carpet flooring in fair condition. C-wing south vestibule	Interiors	Interior Finishes	Flooring	Carpeting	2-Should Do	Fair	92	\$7	Square Foot	\$598
5829	Batavia High School	1921 - Interior Partitions, Fixed- CMU - 1995	East 2-Story Classrooms (1995	Vestibule)	2020	Sent to Maintenance	CMU wall (wide stair step crack at corner, continues behind lockers, see photo). C-wing south center vest.	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair	6	\$15	Linear Foot	\$90
5832	Batavia High School	1975 - Interior Wall Finishes, Wall Base - 1995	East 2-Story Classrooms (1995	Vestibule)	2020	Sent to Maintenance	Wall base in fair condition. C-wing south center vest. C-wing north center vest.	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	80	\$6	Square Foot	\$480
5833	Batavia High School	1991 - Interior Wall Finish, Paint 1995	East 2-Story - Classrooms (1995	Vestibule)	2020	Sent to Maintenance	Wall paint in fair condition. Quantity reflects total SF of all listed spaces. C-wing south center vest. C-wing north center vest.	y Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	190	\$2	Square Foot	\$428










Assessment	Campus	Linked Bldg	Addition	Room	Assessment	Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID		System	1100101011		Year	Status	2000	L1	L2	L3	L4		Tuestic, Condition	ζ,	5		
5837	Batavia High School	3395 - Equipment, Lockers - 1995	East 2-Story Classrooms (1995)	Vestibule	2020	Sent to Maintenance	Lockers in fair condition. See assessment item #7965 for quantity and pricing. C-wing south center vest. C-wing north center vest.	Equipment and Furnishings	Equipment	Institutional Equipment	Educational and Scientific Equipment	2-Should Do	Fair	0	\$0	Each	\$0
5838	Batavia High School	•	East 2-Story Classrooms (1995)	Vestibule	2020	Sent to Maintenance	Ceramic tile flooring in fair condition. Cost to clean grout. C-wing north center vest.	Interiors	Interior Finishes	Flooring	Tile Flooring	2-Should Do	Fair	90	\$5	Square Foot	\$450
5840	Batavia High School		East 2-Story Classrooms (1995)	Vestibule	2020	Sent to Maintenance	Exterior alum door in fair condition. Cost to replace door and hardware. C-wing north center vest.	Shell	Exterior Vertical Enclosures	Exterior Doors and Grilles	Exterior Entrance Doors	2-Should Do	Fair	1	\$7,500	Each	\$7,500
5842	Batavia High School		East 2-Story Classrooms (1995)	Vestibule	2020	Sent to Maintenance	ceramic wall tile in fair condition. Cost to clean grout. C-wing north center vest.	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	140	\$5	Square Foot	\$700
5845	Batavia High School		East 2-Story Classrooms (1995)	Stair	2020		Interior wood door in fair condition. Stair by C107 level 1. C-Wing South Stair. C-Wing North Stair	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	3	\$1,950	Each	\$5,850
5846	Batavia High School		East 2-Story Classrooms (1995)	Stair	2020		Exterior HM door in fair condition. Stair by C101 level 1. Stair by C107 level 1	Shell	Exterior Vertical Enclosures	Exterior Doors and Grilles	Exterior Entrance Doors	2-Should Do	Fair	2	\$75	Each	\$150
	Batavia High School		East 2-Story Classrooms (1995)	Stair	2020		Interior HM frame in fair condition. Stair by C101 level 1. Stair by C107 level 1. Stair by c122 level 1. C-Wing South Stair. C-Wing North Stair	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	5	\$60	Each	\$300
	Batavia High School		East 2-Story Classrooms (1995)	Stair	2020	Maintenance	Exterior HM frame in fair condition. Stair by C101 level 1. Stair by C107 level 1. Stair by c122 level 1.	Shell	Exterior Vertical Enclosures	Exterior Doors and Grilles	Exterior Entrance Doors	2-Should Do	Fair	3	\$60	Each	\$180
5852	Batavia High School		East 2-Story Classrooms (1995)	Stair	2020		ACT ceiling in fair condition. Stair by C107 level 1. C-Wing South Stair. C-Wing North Stair.	Interiors	Interior Construction	Suspended Ceiling Construction	g Acoustical Suspended Ceilings	2-Should Do	Fair	639	\$8	Square Foot	\$4,793
5855	Batavia High School	0.	East 2-Story Classrooms (1995)	Stair	2020		VCT flooring in fair condition. Cost to replace VCT with rubber flooring. Stair by C101 level 1. Stair by c122 level 1.	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	950	\$12	Square Foot	\$11,400
	Batavia High School		East 2-Story Classrooms (1995)	Stair	2020	Maintenance	CMU wall in fair condition. Cost to repair cracking, confirm quantity. Stair by C101 level 1 Stair by C107 level 1 Stair by c122 level 1	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair	0	\$15	Linear Foot	\$0
	Batavia High School	Partitions, Fixed- GWB - 1995	Classrooms (1995)	Stair	2020	Sent to	GWB wall in fair condition. Stair by c122 level 1	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair	0	\$15	Square Foot	\$0
	Batavia High School	1991 - Interior Wall Finish, Paint - 1995	Classrooms (1995)		2020	Maintenance	Wall paint in fair condition. Quantity reflects total SF of all listed spaces. Stair by C101 level 1. Stair by C107 level 1. Stair by c122 level 1.	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	2000	\$2	Square Foot	\$4,500
	Batavia High School		East 2-Story Classrooms (1995)	Stair	2020		Treads and risers in fair condition. Stair by C107 level 1. C-Wing North Stair.	Interiors	Interior Finishes	Stair Finishes	Resilient Stair Finish	2-Should Do	Fair	36	\$90	Each	\$3,240









Assessment ID	t Campus	Linked Bldg System	Addition Room	Assessmen Year	t Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System Priority L4	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
5866	Batavia High School	1813 - Interior Railings and Handrails - 1995	East 2-Story Stair Classrooms (1995)	2020	Sent to Maintenance	Stair pipe rails in fair condition. Cost to repaint. Stair by C101 level 1,2. Stair by C107 level 1,2. Stair by c122 level 1,2.		Interior Construction	Interior Specialties	Interior Railings and Handrails 2-Should Do	Fair	225	\$20	Linear Foot	\$4,500
5870	Batavia High School	1991 - Interior Wall Finish, Paint 1995	East 2-Story Elevator Classrooms (1995)	2020	Sent to Maintenance	paint in fair condition. Quantity reflects total SF of all listed spaces. C-Wing Elevator	Interiors	Interior Finishes	Wall Finishes	Wall Painting and 2-Should Do Coating	Fair	50	\$2	Square Foot	\$113
5872	Batavia High School	1850 - Interior Doors, Swinging- Hollow Metal - 1995	East 2-Story Corridor Classrooms (1995)	2020	Sent to Maintenance	Interior HM door in fair condition . C-wing south corridor, level 1 (3 doors). C-wing north corridor	Interiors	Interior Construction	Interior Doors	Interior Swinging 2-Should Do Doors	Fair	4	\$75	Each	\$300
5875	Batavia High School	1850 - Interior Doors, Swinging- Hollow Metal - 1995	East 2-Story Corridor Classrooms (1995)	2020	Sent to Maintenance	Interior HM frame in fair condition. Cost to repaint. C-wing south corridor, level 1(rusted at base). C-wing north corridor.		Interior Construction	Interior Doors	Interior Swinging 2-Should Do Doors	Fair	2	\$60	Each	\$120
5878	Batavia High School	1899 - Ceilings, Acoustical Suspended Systems - 1995	East 2-Story Corridor Classrooms (1995)	2020	Sent to Maintenance	ACT ceiling in fair condition. C-wing south corridor, level 1. C-wing north corridor	Interiors	Interior Construction		Acoustical 2-Should Do Suspended Ceilings	Fair	3745	\$8	Square Foot	\$28,088
5884	Batavia High School	1910 - Flooring, VCT - 1995	East 2-Story Corridor Classrooms (1995)	2020	Sent to Maintenance	VCT flooring in fair condition. Cost to replace VCT with rubber flooring. C-wing south corridor, level 1 (C-wing south corridor, level 1). C-wing north corridor (cracked across hallway in several locations).	Interiors	Interior Finishes	Flooring	Resilient Flooring 2-Should Do	Fair	4200	\$12	Square Foot	\$50,400
5890	Batavia High School	1975 - Interior Wall Finishes, Wall Base - 1995	East 2-Story Corridor Classrooms (1995)	2020	Sent to Maintenance	Wall base in fair condition. C-wing south corridor, level 1 (tile wall base scuffed and marked up, but not chipped or damaged). C-wing north corridor.	Interiors	Interior Finishes	Wall Finishes	2-Should Do	Fair	550	\$6	Linear Foot	\$3,300
5893	Batavia High School	1991 - Interior Wall Finish, Paint 1995	East 2-Story Corridor -Classrooms (1995)	2020	Sent to Maintenance	Wall paint in fair condition. Quantity reflects total SF of all listed spaces. C-wing south corridor, level 1. C-wing north corridor.	Interiors	Interior Finishes	Wall Finishes	Wall Painting and 2-Should Do Coating	Fair	5200	\$2	Square Foot	\$11,700
5899	Batavia High School	3395 - Equipment Lockers - 1995	East 2-Story Corridor Classrooms (1995)	2020	Sent to Maintenance	•	Equipment and Furnishings	Equipment	Institutional Equipment	Educational and 2-Should Do Scientific Equipment	Fair	0	\$0	Each	\$0
5900	Batavia High School	1896 - Interior Doors, Swinging- Wood - 1995	East 2-Story Corridor Classrooms (1995)	2020	Sent to Maintenance	Interior wood door in fair condition. C-Wing 2nd Floor Corridor	Interiors	Interior Construction	Interior Doors	Interior Swinging 2-Should Do Doors	Fair	3	\$1,950	Each	\$5,850
5902	Batavia High School	1850 - Interior Doors, Swinging- Hollow Metal - 1995	East 2-Story Corridor Classrooms (1995)	2020	Sent to Maintenance		Interiors	Interior Construction	Interior Doors	Interior Swinging Doors 2-Should Do	Fair	1	\$75	Each	\$75
5904	Batavia High School	1850 - Interior Doors, Swinging- Hollow Metal - 1995	East 2-Story Corridor Classrooms (1995)	2020	Sent to Maintenance	Interior HM frame in fair condition. C-Wing 2nd Floor Corridor	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors 2-Should Do	Fair	1	\$60	Each	\$60
5905	Batavia High School	2116 - Ceilings, Acoustical Suspended Systems - 1995	East 2-Story Corridor Classrooms (1995)	2020	Sent to Maintenance	ACT ceiling in fair condition. C-Wing 2nd Floor Corridor	Interiors	Interior Construction		Acoustical 2-Should Do Suspended Ceilings	Fair	5534	\$8	Square Foot	\$41,505









Assessment	Campus	Linked Bldg	Addition	Room	Assessment	Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID 5906	Batavia High School	System 1900 - Ceilings, Gypsum - 1995	East 2-Story Classrooms (1999	Corridor 5)	Year 2020	Sent to Maintenance	GWB ceiling in fair condition. C-Wing 2nd Floor Corridor	L1 Interiors	Interior Construction	L3 Suspended Ceiling Construction	L4 Suspended Plaster and Gypsum Board	2-Should Do	Fair	5534	\$12	Square Foot	\$66,408
5908	Batavia High School	1910 - Flooring, VCT - 1995	East 2-Story Classrooms (1995	Corridor 5)	2020	Sent to Maintenance	VCT flooring in fair condition. Cost to replace VCT with rubber flooring. C-Wing 2nd Floor Corridor	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	4400	\$12	Square Foot	\$52,800
5912	Batavia High School	1991 - Interior Wall Finish, Paint 1995	East 2-Story - Classrooms (1995	Corridor 5)	2020	Sent to Maintenance	Wall paint in fair condition. Quantity reflects total SF of all listed spaces. C-Wing 2nd Floor Corridor	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	5200	\$2	Square Foot	\$11,700
5915	Batavia High School	1837 - Interior Stair Finishes, Resilient - 1995	East 2-Story Classrooms (1995	Corridor 5)	2020	Sent to Maintenance	Stair treads and risers in fair condition. C-Wing 2nd Floor Corridor	Interiors	Interior Finishes	Stair Finishes	Resilient Stair Finish	2-Should Do	Fair	2	\$90	Each	\$180
5916	Batavia High School	1813 - Interior Railings and Handrails - 1995	East 2-Story Classrooms (1995	Corridor 5)	2020	Sent to Maintenance	Stair pipe rails in fair condition. Cost to repaint. C-Wing 2nd Floor Corridor	Interiors	Interior Construction	Interior Specialties	Interior Railings and Handrails	2-Should Do	Fair	75	\$20	Linear Foot	\$1,500
5920	Batavia High School	1699 - Ceilings, Acoustical Suspended Systems - 1971	LRC, Classrooms (1971)	Corridor	2020	Sent to Maintenance	ACT ceiling in fair condition. Corridor btwn B122 + B109	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	2-Should Do	Fair	1974	\$8	Square Foot	\$14,805
5922	Batavia High School	716 - Flooring, VCT - 1971	LRC, Classrooms (1971)	Corridor	2020	Sent to Maintenance	VCT flooring in fair condition. Cost to replace VCT with rubber flooring. Corridor btwn B122 + B109	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	1000	\$12	Square Foot	\$12,000
5923	Batavia High School	1973 - Interior Wall Finishes, Wall Base - 1971	LRC, Classrooms (1971)	Corridor	2020	Sent to Maintenance	Wall base in fair condition. Corridor btwn B122 + B109	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	325	\$6	Linear Foot	\$1,950
5925	Batavia High School	3396 - Equipment Lockers - 1971	, LRC, Classrooms (1971)	Corridor	2020	Sent to Maintenance	Lockers in fair condition. See assessment item #7965 for quantity and pricing. Corridor btwn B122 + B109	Equipment and Furnishings	Equipment	Institutional Equipment	Educational and Scientific Equipment	2-Should Do	Fair	0	\$0	Each	\$0
5926	Batavia High School	2019 - Interior Wall Finish, Tile - 1971	LRC, Classrooms (1971)	Corridor	2020	Sent to Maintenance	Ceramic wall tile in fair condition. Cost to clean grout. Corridor btwn B122 + B109	Interiors	Interior Finishes	Wall Finishes	Tile Wall Finish	2-Should Do	Fair	400	\$5	Square Foot	\$2,000
5927	Batavia High School	1760 - Exterior Entrance Doors, Hollow Metal - 2011	BFAC, Fieldhouse (2011)	Vestibule	2020	Sent to Maintenance	Exterior HM door in fair condition. VESTIBULE SOUTH ADJACENT TO PARKING LOT	Shell	Exterior Vertical Enclosures	Exterior Doors and Grilles	Exterior Entrance Doors	2-Should Do	Fair	2	\$75	Each	\$150
5928	Batavia High School	1760 - Exterior Entrance Doors, Hollow Metal - 2011	BFAC, Fieldhouse (2011)	Vestibule	2020	Sent to Maintenance	Exterior HM frame in fair condition. VESTIBULE SOUTH ADJACENT TO PARKING LOT	Shell	Exterior Vertical Enclosures	Exterior Doors and Grilles	Exterior Entrance Doors	2-Should Do	Fair	1	\$60	Each	\$60
5929	Batavia High School	2029 - Flooring, Carpet - 2011	BFAC, Fieldhouse (2011)	Vestibule	2020	Sent to Maintenance	Carpet flooring in fair condition. VESTIBULE SOUTH ADJACENT TO PARKING LOT	Interiors	Interior Finishes	Flooring	Carpeting	2-Should Do	Fair	100	\$7	Square Foot	\$650
5944	Batavia High School	1799 - Interior Doors, Swinging- Wood - 2011	BFAC, Fieldhouse (2011)	Corridor	2020	Sent to Maintenance	Interior wood door in fair condition. Cost to replace door and hardware. Confirm quantity. Field house corridor	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	4	\$1,950	Each	\$7,800
5946	Batavia High School	1853 - Interior Doors, Swinging- Hollow Metal - 2011	BFAC, Fieldhouse (2011)	Corridor	2020	Sent to Maintenance	Interior HM door in fair condition. Field house corridor	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	2	\$75	Each	\$150
5949	Batavia High School	1853 - Interior Doors, Swinging- Hollow Metal - 2011	BFAC, Fieldhouse (2011)	Corridor	2020	Sent to Maintenance	Interior HM frame in fair condition. Field house corridor	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	2	\$60	Each	\$120










Assessment	Campus	Linked Bldg	Addition	Room	Assessment	Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID		System			Year	Status		L1	L2	L3	L4						
5953	Batavia High School	1807 - Ceilings, Acoustical Suspended Systems - 2011	BFAC, Fieldhouse (2011)	Corridor	2020	Sent to Maintenance	ACT ceiling in fair condition (HOLES IN SOME TILES, SOME STAINING). CORRIDOR SOUTH OF FIELD HOUSE	Interiors	Interior Construction		Acoustical Suspended Ceilings	2-Should Do	Fair	1615	\$8	Square Foot	\$12,113
5954	Batavia High School	1811 - Ceilings, Gypsum - 2011	BFAC, Fieldhouse (2011)	Corridor	2020	Sent to Maintenance	GWB ceiling in fair condition. Field house corridor (SOME NICKS AND CHIPS IN SOFFIT AT TROPHY AREA). CORRIDOR BETWEEN BFAC/FIELD HOUSE (SOFFITS HAVE DENTS AND NICKS WITH PAINT REMOVED).	Interiors	Interior Construction	Suspended Ceiling Construction	Suspended Plaster and Gypsum Board Ceilings	2-Should Do	Fair	6051	\$12	Square Foot	\$72,612
5960	Batavia High School	1994 - Interior Wall Finish, Paint 2011	BFAC, Fieldhouse - (2011)	Corridor	2020	Sent to Maintenance	Wall paint in fair condition. Quantity reflects total SF of all listed spaces. Field house corridor. CORRIDOR BETWEEN BFAC/FIELD HOUSE. CORRIDOR SOUTH OF FIELD HOUSE. CORRIDOR ADJACENT TO MECH.	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	10500	\$2	Square Foot	\$23,625
5965	Batavia High School	2032 - Flooring, Epoxy - 2011	BFAC, Fieldhouse (2011)	Corridor	2020	Sent to Maintenance	Epoxy/SC flooring in fair condition. NORTH CORRIDOR BFAC (MINOR CRACKING NEAR DOOR TO STAGE). CORRIDOR SOUTH OF FIELD HOUSE CORRIDOR ADJACENT TO MECH	Interiors	Interior Finishes	Flooring	Fluid-Applied Flooring	2-Should Do	Fair	5490	\$20	Square Foot	\$109,800
5974	Batavia High School	1974 - Interior Wall Finishes, Wall Base - 1995 Entry	Central Area, South Entrance (1995)	Corridor	2020	Sent to Maintenance	Wall base in fair condition. Corridor south of A103. E/W corridor between locker rooms and 120s classrooms (scuffs/stains throughout)	Interiors	Interior Finishes	Wall Finishes		2-Should Do		300	\$6	Linear Foot	\$1,800
5975	Batavia High School	1804 - Ceilings, Acoustical Suspended Systems - 1995 Entry	Central Area, South Entrance (1995)	corridor	2020	Sent to Maintenance	ACT Ceiling in fair condition. Corridor south of A103	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	2-Should Do	Fair	2812	\$8	Square Foot	\$21,090
5980	Batavia High School	1709 - Interior Doors, Swinging- Hollow Metal - Original		Vestibule	2020	Sent to Maintenance	Interior HM door (paint touch-up required) in fair condition.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$75	Each	\$75
5981	Batavia High School	1709 - Interior Doors, Swinging- Hollow Metal - Original		Vestibule	2020	Sent to Maintenance	Interior HM frame (paint touch-up required)	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$60	Each	\$60
5988	Batavia High School	1700 - Ceilings, Gypsum - Original		Corridor	2020	Sent to Maintenance	GWB ceiling in fair condition. Corridor north of main office. B-CORRIDOR BETWEEN MAIN OFFICE AND STUDENT SERVICES	Interiors	Interior Construction	Suspended Ceiling Construction	Suspended Plaster and Gypsum Board Ceilings	2-Should Do	Fair	6700	\$12	Square Foot	\$80,400
5991	Batavia High School	1743 - Interior Wall Finishes, Wall Base -		Corridor	2020	Sent to Maintenance	Wall base in fair condition. Corridor north of main office. Main corridor by gyms.	Interiors	Interior Finishes	Wall Finishes		2-Should Do		570	\$6	Linear Foot	\$3,420
5994	Batavia High School	1951 - Interior Wall Finish, Paint Original	-	Corridor	2020	Sent to Maintenance	Wall paint in fair condition. Quantity reflects total SF of all listed spaces. Main corridor by gyms. B-CORRIDOR BETWEEN MAIN OFFICE AND STUDENT SERVICES.		Interior Finishes	Wall Finishes	Wall Painting and Coating			5700	\$2	Square Foot	\$12,825
5999	Batavia High School	1705 - Flooring, Terrazzo - Original		Corridor	2020	Sent to Maintenance	Terrazzo flooring in fair condition. B-CORRIDOR	Interiors	Interior Finishes	Flooring	Terrazzo Flooring	2-Should Do	Fair	3000	\$5	Square Foot	\$15,000









ssessment ID	Campus	Linked Bldg System	Addition	Room	Assessmen Year	t Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
6013	Batavia High School	1695 - Interior Doors, Swinging- Wood - Original		Server room	2020	Sent to Maintenance	Interior HM Frame at corridor is rusting on the interior side. Cost to repaint. B105	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$60	Each	\$60
6015	Batavia High School	1704 - Flooring, VCT - Original		Server room	2020	Sent to Maintenance	VCT Scuffed and scratched throughout. Cost to replace VCT with rubber flooring. B105	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	672	\$12	Square Foot	\$8,064
6024	Batavia High School	1709 - Interior Doors, Swinging- Hollow Metal - Original		Fitness Center	2020	Sent to Maintenance	Interior HM frame paint touch-up required. A103	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$60	Each	\$60
6035	Batavia High School	1709 - Interior Doors, Swinging- Hollow Metal - Original		Locker Room	2020	Sent to Maintenance	Interior HM frame, paint touch-up required. A104W Locker Room A108Men's Locker Room	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	2	\$60	Each	\$120
6036	Batavia High School	1709 - Interior Doors, Swinging- Hollow Metal - Original		Locker Room	2020	Sent to Maintenance	Interior HM Doors are due for replacement, damaged throughout. Confirm quantity. A110 Mens' Team Locker Room	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$1,500	Each	\$1,500
6039	Batavia High School	1700 - Ceilings, Gypsum - Original		Locker Room	2020	Sent to Maintenance	GWB ceiling in fair condition. A110 Mens' Team Locker Room	Interiors	Interior Construction	Suspended Ceiling Construction	Suspended Plaster and Gypsum Board	2-Should Do	Fair	3119	\$12	Square Foot	\$37,428
6045	Batavia High School	1729 - Electrical, Lighting Fixtures - Original		Locker Room	2020	Sent to Maintenance	Lighting in fair condition A110 Mens' Team Locker Room	Services	Electrical	Lighting	· · ·	2-Should Do	Fair	0	\$8	Square Foot	\$0
6048	Batavia High School	3393 - Equipment, Lockers - Original	,	Locker Room	2020	Sent to Maintenance	Lockers in fair condition. Confirm quantity. A110 Mens' Team Locker Room	Equipment and Furnishings	Equipment	Institutional Equipment	Educational and Scientific Equipment	2-Should Do	Fair	0	\$200	Each	\$0
6050	Batavia High School	1670 - Slab on Grade - Original		Locker Room	2020	Sent to Maintenance	Epoxy flooring in fair condition. A110 Mens' Team Locker Room	Substructure	Slabs-On-Grade	Standard Slabs-on- Grade	-	2-Should Do	Fair	3119	\$20	Square Foot	\$62,380
6052	Batavia High School	1875 - Interior Doors, Swinging- Hollow Metal - 1995 Entry	Central Area, South Entrance (1995)	Cafeteria	2020	Sent to Maintenance	Interior HM frame in fair condition (paint touch-up required). A100	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	2	\$60	Each	\$120
6056	Batavia High School	1808 - Ceilings, Gypsum - 1995 Entry	Central Area, South Entrance (1995)	Cafeteria	2020	Sent to Maintenance	GWB ceiling in fair condition. A100	Interiors	Interior Construction	Suspended Ceiling Construction	Suspended Plaster and Gypsum Board	2-Should Do	Fair	9794	\$12	Square Foot	\$117,528
6058	Batavia High School	1855 - Interior Partitions, Fixed- CMU - 1995 Entry		Cafeteria	2020	Sent to Maintenance	Cracking in CMU; burnished block in good condition; split face CMU in good condition. Confirm quantity. A100	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair	0	\$15	Square Foot	\$0
6061	Batavia High School	1711 - Interior Doors, Swinging- Wood - 1995 Entry	Central Area, South Entrance (1995)	School store	2020	Sent to Maintenance	Interior wood door in fair condition (scuffs/stains in veneer). A100A	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$1,950	Each	\$1,950
6062	Batavia High School	1875 - Interior Doors, Swinging- Hollow Metal - 1995 Entry	Central Area, South Entrance (1995)	School store	2020	Sent to Maintenance	Interior HM frame in fair condition (paint touch-up required) A100A	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$60	Each	\$60
6065	Batavia High School	1825 - Flooring, VCT - 1995 Entry	Central Area, South Entrance (1995)	School store	2020	Sent to Maintenance	VCT flooring in fair condition. Cost to replace VCT with rubber flooring. A100A	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	1995	\$12	Square Foot	\$23,940







Assessmen ID	t Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cos
6077	Batavia High School	1875 - Interior Doors, Swinging- Hollow Metal - 1995 Entry	Central Area, South Entrance (1995)	W locker room	2020	Sent to Maintenance	Interior HM door in fair condition (paint touch-up required). A106	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$75	Each	\$75
6078	Batavia High School	1875 - Interior Doors, Swinging- Hollow Metal - 1995 Entry	Central Area, South Entrance (1995)	W locker room		Sent to Maintenance	Interior HM frame in fair condition (paint touch-up required). A106	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$60	Each	\$60
6101	Batavia High School	1984 - Electrical, Lighting Fixtures - 2009	North Classrooms, SW Mechanical (2009)	Dance Gym		Sent to Maintenance	Lighting in fair condition (one light does not turn on; lights make clicking/buzzing noise when on) A132	Services	Electrical	Lighting	Lighting Fixtures	2-Should Do	Fair	0	\$8	Square Foot	\$0
6104	Batavia High School	1799 - Interior Doors, Swinging- Wood - 2011	BFAC, Fieldhouse (2011)	Field House		Sent to Maintenance	Interior wood door in fair condition. F112	Interiors	Interior Construction		Interior Swinging Doors	2-Should Do	Fair	1	\$1,950	Each	\$1,950
6105	Batavia High School	1853 - Interior Doors, Swinging- Hollow Metal - 2011	BFAC, Fieldhouse (2011)	Field House		Sent to Maintenance	Interior HM door in fair condition. F112	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$75	Each	\$75
6106	Batavia High School	1853 - Interior Doors, Swinging- Hollow Metal - 2011	BFAC, Fieldhouse (2011)	Field House		Sent to Maintenance	Interior HM frame in fair condition. F112	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$60	Each	\$60
6107	Batavia High School	1760 - Exterior Entrance Doors, Hollow Metal - 2011	BFAC, Fieldhouse (2011)	Field House		Sent to Maintenance	Exterior door in fair condition (SCRATCHES, PAINT AND MINOR RUSTING AROUND LITE). Cost to replace. F112	Shell	Exterior Vertical Enclosures	Exterior Doors and Grilles	Exterior Entrance Doors	2-Should Do	Fair	1	\$2,000	Each	\$2,000
6109	Batavia High School	1760 - Exterior Entrance Doors, Hollow Metal - 2011	BFAC, Fieldhouse (2011)	Field House		Sent to Maintenance	Exterior frame in fair condition. F112	Shell	Exterior Vertical Enclosures	Exterior Doors and Grilles	Exterior Entrance Doors	2-Should Do	Fair	1	\$60	Each	\$60
6112	Batavia High School	1994 - Interior Wall Finish, Paint 2011	BFAC, Fieldhouse (2011)	Field House		Sent to Maintenance	Wall paint in fair condition. Quantity reflects total SF of all listed spaces. F112	y Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	51050	\$2	Square Foot	\$114,863
6116	Batavia High School	1853 - Interior Doors, Swinging- Hollow Metal - 2011	BFAC, Fieldhouse (2011)	Storage		Sent to Maintenance	Interior HM door in fair condition. F112BSTORAGE F112CSTORAGE	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	2	\$75	Each	\$150
6120	Batavia High School	1853 - Interior Doors, Swinging- Hollow Metal - 2011	BFAC, Fieldhouse (2011)	Storage		Sent to Maintenance	Interior HM frame in fair condition. F112JSTORAGE	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$60	Each	\$60
6122	Batavia High School	1858 - Interior Partitions, Fixed- CMU - 2011	BFAC, Fieldhouse (2011)	Storage		Sent to Maintenance	CMU wall in fair condition. Cost to repair cracking, confirm quantity. F112JSTORAGE	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair	0	\$15	Linear Foot	\$0
6125	Batavia High School	1994 - Interior Wall Finish, Paint 2011	BFAC, Fieldhouse (2011)	Storage		Sent to Maintenance	Wall paint in fair condition. Quantity reflects total SF of all listed spaces. F112jSTORAGE	y Interiors	Interior Finishes		Wall Painting and Coating	2-Should Do	Fair	100	\$2	Square Foot	\$225
6138	Batavia High School	1837 - Interior Stair Finishes, Resilient - 1995	East 2-Story Classrooms (1995)	Stairs		Sent to Maintenance	C-Wing south stair rubber treads and risers in good to fair condition	Interiors	Interior Finishes	Stair Finishes	Resilient Stair Finish	2-Should Do	Fair	0	\$90	Each	\$0
6139	Batavia High School	2025 - Flooring, Interior - Rubber - 1995	•	Ramp, Landing		Sent to Maintenance	C-Wing ramp and landing rubber flooring in fair condition.	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	150	\$12	Square Foot	\$1,800









Assessmen	t Campus	Linked Bldg	Addition	Room	Assessment	Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cos
ID		System			Year	Status		L1	L2	L3	L4						
6140	Batavia High School	3294 - Flooring, Interior - Rubber - 2009	North - Classrooms, SW Mechanical	Ramp, Landing	2020	Sent to Maintenance	D-Wing ramp and landing rubber flooring in fair condition.	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	160	\$12	Square Foot	\$1,920
6141	Batavia High School	2025 - Flooring, Interior - Rubber 1995	East 2-Story - Classrooms (1995	Stairs)	2020	Sent to Maintenance	C-Wing north and central stair rubber treads and risers in fair condition	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do		390	\$12	Linear Foot	\$4,680
6144	Batavia High School	1990 - Interior Wall Finish, Paint 1995 Entry	Central Area, - South Entrance (1995)	Corridor		Sent to Maintenance	Wall paint in fair condition. Quantity reflects total SF of all listed spaces. N/S Corridor, near A131 (stains/scuffs in paint). E/W Corridor, near A132 (scuffs throughout)	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	2500	\$2	Square Foot	\$5,625
6147	Batavia High School	1875 - Interior Doors, Swinging- Hollow Metal - 1995 Entry	Central Area, South Entrance (1995)	Corridor	2020	Sent to Maintenance	Interior HM frame in fair condition (paint touch-up required). E/W corridor between café and Gym	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$60	Each	\$60
6148	Batavia High School	1875 - Interior Doors, Swinging- Hollow Metal - 1995 Entry	Central Area, South Entrance (1995)	corridor	2020	Sent to Maintenance	Interior HM frame in fair condition (paint touch-up required). E/W corridor between café and Gym	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$60	Each	\$60
6157	Batavia High School	1823 - Flooring, Ceramic Tile - 2009	North Classrooms, SW Mechanical (2009)	Toilet	2020	Sent to Maintenance	Ceramic tile flooring's Grout is dirty throughout - tiles are in good shape. Cost to clean grout. Toilet in Kitchen		Interior Finishes	Flooring	Tile Flooring	2-Should Do	Fair	53	\$5	Square Foot	\$265
6163	Batavia High School	1748 - Exterior Face Brick - 1995 Entry	East 2-Story Classrooms (1995)	2020	Sent to Maintenance	Lintels above first floor windows this entire addition need to be scraped and painted; no visible signs of rust at this time.	Shell	Exterior Vertical Enclosures	Exterior Walls	Exterior Wall Veneer	2-Should Do	Fair	276	\$15	Linear Foot	\$4,140
6166	Batavia High School	1869 - Exterior Face Brick - 1995	East 2-Story Classrooms (1995)	2020	Sent to Maintenance	Clean and remove build-up at first floor masonry entire addition (all sides, including courtyard). Consider staining masonry that has been damaged by graffiti.	Shell	Exterior Vertical Enclosures	Exterior Walls	Exterior Wall Veneer	2-Should Do	Fair	10000	\$5	Square Foot	\$50,000
6167	Batavia High School	1749 - Exterior Face Brick - 2009	North Classrooms, SW Mechanical (2009)		2020	Sent to Maintenance	Clean and remove efflorescence from exterior face brick along east and north facades of additon; otherwise, face brick generally in good condition.	Shell	Exterior Vertical Enclosures	Exterior Walls	Exterior Wall Veneer	2-Should Do	Good	850	\$5	Square Foot	\$4,250
6168	Batavia High School	3884 - Exterior Limestone Sills - 1995	East 2-Story Classrooms (1995)		Sent to Maintenance	Limestone sills are generally in good condition. Clean and remove build-up at all sills and tuckpoint; entire addition (all sides, including courtyard).	Shell	Exterior Vertical Enclosures	Exterior Walls	Exterior Wall Veneer	2-Should Do	Good	540	\$5	Linear Foot	\$2,700
6170	Batavia High School	3883 - Exterior Precast - 1995	East 2-Story Classrooms (1995)	2020	Sent to Maintenance	Precast generally in good condition. Clean and remove build-up and paint exterior precast panels, entire addition (all sides, including courtyard). Cost to clean.		Exterior Vertical Enclosures	Exterior Walls	Exterior Wall Construction	2-Should Do	Good	16400	\$5	Square Foot	\$82,000









Assessmer	nt Campus	Linked Bldg	Addition	Room	Assessment	Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cos
ID		System			Year	Status	, , , , , , , , , , , , , , , , , , ,	L1	L2	L3	L4		, , , , , , , , , , , , , , , , , , , ,				
6171	Batavia High School	4148 - Exterior Precast - 2011	BFAC, Fieldhouse (2011)		2020	Sent to Maintenance	Precast generally in fair to good condition; various areas of cracking occurring at Fieldhouse panels. Clean and remove build-up, seal cracks and paint exterior precast panels, entire addition. CONFIRM	Shell	Exterior Vertical Enclosures	Exterior Walls	Exterior Wall Construction	2-Should Do	Fair	27400	\$15	Square Foot	\$411,000
							UNIT COST. Approx. 14,000 SF of BFAC flyspace;										
6173	Batavia High School	1749 - Exterior Face Brick - 2009	North Classrooms, SW Mechanical (2009)		2020	Sent to Maintenance	Weep vents missing at face brick above and/or below windows; currently gaps in mortar joints. Occurs throughout facades of this addition, includes courtyard windows as well. Cost to tuckpoint.	Shell	Exterior Vertical Enclosures	Exterior Walls	Exterior Wall Veneer	2-Should Do	Fair	580	\$12	Linear Foot	\$6,960
6174	Batavia High School	1751 - Exterior Face Brick - 2011	BFAC, Fieldhouse (2011)		2020	Sent to Maintenance	Exterior lintels at window openings into BFAC courtyard are showing rust; scrape, prime and paint.	Shell	Exterior Vertical Enclosures	Exterior Walls	Exterior Wall Veneer	2-Should Do	Fair	102	\$15	Linear Foot	\$1,530
6175	Batavia High School	1751 - Exterior Face Brick - 2011	BFAC, Fieldhouse (2011)		2020	Sent to Maintenance	Lintels above entryways this entire addition showing rust; scrape, prim and paint, includes overhead door lintel and lintels at exterior wall louvers.		Exterior Vertical Enclosures	Exterior Walls	Exterior Wall Veneer	2-Should Do	Fair	60	\$15	Linear Foot	\$900
6176	Batavia High School	1749 - Exterior Face Brick - 2009	North Classrooms, SW Mechanical (2009)		2020	Sent to Maintenance	Paint at lintels for small square clerestory windows peeling with rusting; scrape, prime and paint. Located at north student entrance (off Wilson St.)	Shell	Exterior Vertical Enclosures	Exterior Walls	Exterior Wall Veneer	2-Should Do	Fair	10	\$15	Linear Foot	\$150
6180	Batavia High School	4291 - Exterior Limestone Sills - 1971	LRC, Classrooms (1971)		2020	Sent to Maintenance	Clean and tuckpoint joints of and below limestone sills on east facade of south courtyard (directly east of LRC).		Exterior Vertical Enclosures	Exterior Walls	Exterior Wall Veneer	2-Should Do	Fair	50	\$12	Linear Foot	\$600
							North facade sills are in good condition.										
6181	Batavia High School	1763 - Exterior Entrance Doors, Hollow Metal - 1995	East 2-Story Classrooms (1995)		2020	Sent to Maintenance	Hollow metal entrance doors and frames to south, east, and north showing rust at base; 2 sets of doors, 3 doors each + 1 pair.	Shell	Exterior Vertical Enclosures	Exterior Doors and Grilles	Exterior Entrance Doors	2-Should Do	Fair	8	\$7,500	Each	\$60,000
							Cost to replace with aluminum										
6182	Batavia High School	4774 - Sitework, Site Grading				Sent to Maintenance	storefront entry system. Visible site drainage issues and water ponding at northwest corner of school outside entrance W4.	Sitework	Site Preparation	Site Earthwork	Grading	2-Should Do	Fair	400	\$2	Square Foot	\$900
							Regrade area and/or provide more durable permeable surfacing for pedestrian access/use.										
6183	Batavia High School	4148 - Exterior Precast - 2011	BFAC, Fieldhouse (2011)		2020	Sent to Maintenance	Perimeter metal enclosure plate adjacent to door openings at base of precast panels at fieldhouse showing rust; scrape, prime,	Shell	Exterior Vertical Enclosures	Exterior Walls	Exterior Wall Construction	2-Should Do	Fair	130	\$20	Linear Foot	\$2,600

Building Our Future TOGETHER BPS









Assessmen	Campus	Linked Bldg	Addition	Room	Assessment	Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID		System	710011011		Year	Status	2 330., p.10.1.	L1	L2	L3	L4	,		Quantity	J 3331		
6185	Batavia High	1721 - HVAC,			2020	Sent to	Per Capital Projects Plan - Replace	Services	Heating,	Heating Systems	Heat Generation	2-Should Do	Fair 1	L	\$700,000	Lump Sum	\$700,000
	School	Boiler Plant				Maintenance	main boiler plant (Bryan boilers)		Ventilation, and								
							installed in approx. 1991. Consists of	:	Air Conditioning								
							two gas-fired, forced-draft		(HVAC)								
							boilers, each with an input capacity										
							of approximately 12,600 MBH.										
							Per discussion w/District; entire										
							school can run off of new										
							condensing boilers.										
6189	Batavia High	1680 - Roofing,			2019	Sent to	Per 2019 Roof Assessment - roofing	Shell	Exterior	Roofing	Low-Slope	2-Should Do	Fair 7	75252	\$30	Square Foot	\$2,257,560
	School	Low Slope -				Maintenance	system to be in fair condition and		Horizontal		Roofing						
		Original					performing as designed. Found		Enclosures								
							minor blistering throughout the field	I									
							Membrane, this is typical on older										
							pitch roofs. Wall flashings seem to										
							be adhered with no major blistering.										
							Debris around drains. Found										
							deteriorating caulk throughout the										
							multiple levels of roofing. Reported										
							one leak while on site. No major										
							issues found.										
6190	Batavia High		LRC, Classrooms		2019	Sent to	Per 2019 Roof Assessment - roofing	Shell	Exterior	Roofing	Low-Slope	2-Should Do	Fair 3	37035	\$30	Square Foot	\$1,111,050
	School	Low Slope - 1971	(1971)			Maintenance	system to be in fair condition and		Horizontal		Roofing						
							performing as designed. Found		Enclosures								
							minor blistering throughout the field	I									
							Membrane, this is typical on older										
							pitch roofs. Wall flashings seem to										
							be adhered with no major blistering.										
							Debris around drains. Found										
							deteriorating caulk throughout the										
							multiple levels of roofing. Reported										
							one leak while on site. No major										
6101	Data da Histo	1777 Daafina	Fact 2 Ctam.		2019	Cambba	issues found.	Chall	Futorion	Dantina	Law Clana	2-Should Do	Fair 4	11125	\$30	Caucas Foot	¢4 222 750
6191	Batavia High	<u> </u>	East 2-Story	E)	2019	Sent to	Per 2019 Roof Assessment - roofing	Shell	Exterior	Roofing	Low-Slope	2-Should Do	Fair	1125	\$30	Square Foot	\$1,233,750
	School		Classrooms (199	5)		Maintenance	system to be in fair condition and		Horizontal		Roofing						
		(Entry)					performing as designed. Found		Enclosures								
							minor blistering throughout the field Membrane, this is typical on older	1									
							pitch roofs. Wall flashings seem to										
							be adhered with no major blistering.										
							Debris around drains. Found	•									
							deteriorating caulk throughout the										
							multiple levels of roofing. Reported										
							one leak while on site. No major										
							issues found.										
<u> </u>							issues iouilu.	1	1		1	1					


Building Our Future
TOGETHER
BPS
101





	Campus Batavia High School	Linked Bldg System 1884 - Roofing, Low Slope	Addition Room East 2-Story Classrooms (1995)	Assessment Year 2019	Sent to Maintenance	Description Per 2019 Roof Assessment - roofing system to be in fair condition and	L1	L2 Exterior	Building System L3	L4 Low-Slope	Priority 2-Should Do	Facility Condition	Quantity	S30	Square Foot	Estimated Cost
6192	_	1884 - Roofing,	,		Sent to						2 Should Do	Fair	24200	¢20	Square Foot	
	_	,	,	2019			Isneii									
	SCHOOL	Low Slope	Classrooms (1995)		Maintenance				Roofing		2-3110ulu D0	Fair	34300	330	Square Foot	\$1,029,000
						*		Horizontal		Roofing						
						performing as designed. Found		Enclosures								
						minor blistering throughout the field										
						Membrane, this is typical on older pitch roofs. Wall flashings seem to										
						be adhered with no major blistering.										
						Debris around drains. Found										
						deteriorating caulk throughout the										
						multiple levels of roofing. Reported										
						one leak while on site. No major										
						issues found.										
7826	Batavia High	1899 - Ceilings,	East 2-Story Stairs	2020	Sent to	2nd floor stairwell ceilings in fair	Interiors	Interior	Suspended Ceiling	Acoustical	2-Should Do	Fair	1497	\$8	Square Foot	\$11,228
	School	Acoustical	Classrooms (1995)		Maintenance	condition		Construction	Construction	Suspended						
		Suspended								Ceilings						
		Systems - 1995														
7828	Batavia High	1755 - Exterior	Central Area, Exterior, Cafeter	ia 2020	Sent to	Large exterior windows in fair	Shell	Exterior Vertical	Exterior Windows	Exterior	2-Should Do	Fair	324	\$100	Square Foot	\$32,400
	School	Windows,	South Entrance		Maintenance	condition; window wall with		Enclosures		Operating						
		Operating - 2009	(1995)			operable bottom sections. Approx.				Windows						
						108 SF each										
						Cost to replace.										1.
	Batavia High		BFAC, Fieldhouse	2020	Sent to	<u> </u>	Shell		Exterior Walls	Exterior Wall	2-Should Do	Fair	114	\$15	Linear Foot	\$1,710
	School	Face Brick - 2011	(2011)		Maintenance	and paired doors showing rust;		Enclosures		Veneer						
7020	Data da Hisb	1740 - Francisco	Control Augo	2020	Combbo	scrape, prime and paint.	Shell	Futonian Mantinal	Futorior Mallo	Futorior M/all	2 Chauld Da	Fair	28	¢10	Lincou Foot	\$280
	Batavia High School	1748 - Exterior Face Brick - 1995	Central Area, South Entrance	2020	Sent to Maintenance	Control joints starting to fail.	Sneii	Exterior Vertical Enclosures	Exterior Walls	Exterior Wall Veneer	2-Should Do	Fair	28	\$10	Linear Foot	\$280
	3011001	Entry	(1995)		ivialifice			Efficiosures		veneer						
7839	Batavia High	1748 - Exterior	Central Area,	2020	Sent to	Mortar joints need tuckpointing,	Shell	Exterior Vertical	Exterior Walls	Exterior Wall	2-Should Do	Fair	100	\$12	Linear Foot	\$1,200
	School		South Entrance	2020	Maintenance	various areas along south facade.	Sileii	Enclosures	Exterior Walls	Veneer	2-Siloulu Do	Tan	100	712	Linear root	71,200
	3011001	Entry	(1995)		Mantenance	various areas along south facade.		Enclosures		Veneer						
7907	Batavia High		BFAC, Fieldhouse BFAC Stage	2020	Sent to	Original floor; needs replacement by	Interiors	Interior Finishes	Flooring	Specialty Flooring	2-Should Do	Fair	5237	\$20	Square Foot	\$104,740
	School	Stage Floor	(2011)		Maintenance	2019 per BFAC replacement										
						schedule.										
7909	Batavia High	9255 - Equipment,	BFAC, Fieldhouse BFAC Stage	2020	Sent to	Cyc replacement in 2021, per	Equipment and	Equipment	Entertainment	Theater and Stage	2-Should Do	Fair	1	\$3,000	Each	\$3,000
	School	Theater Drapes	(2011)		Maintenance	replacement schedule.	Furnishings		and Recreational	Equipment						
									Equipment							
	Batavia High		BFAC, Fieldhouse BFAC Stage	2020	Sent to	Scrim replacement in 2021 per	Equipment and	Equipment	Entertainment	Theater and Stage	2-Should Do	Fair	1	\$2,500	Each	\$2,500
	School	Theater Drapes	(2011)		Maintenance	replacement schedule.	Furnishings		and Recreational	Equipment						
									Equipment					4-0		4.0
	Batavia High		BFAC, Fieldhouse BFAC Stage	2020	Sent to	Original. Needs replacement in 2020	Services	Communications		Audio-Video	2-Should Do	Fair	1	\$0	Each	\$0
	School	-	(2011)		Maintenance	per replacement schedule.			Communication	Systems						
7913	Batavia High	Sound Board 9260 - Theater	BFAC, Fieldhouse BFAC Stage	2020	Cont to	Original. Needs replacement in 2024	Comisos	Communications	Audio Vidoo	Audio Vidos	2-Should Do	Fair	1	\$0	Each	\$0
	School	Speakers	(2011)	2020	Sent to Maintenance	per replacement schedule.	Services	Communications	Communication	Audio-Video Systems	2-3110ulu D0	rdii	1	ŞU	EdCII	\$ 0
	Batavia High		BFAC, Fieldhouse BFAC Stage	2020	Sent to	Original. Needs replacement in 2031	Services	Electrical	Lighting	Lighting Fixtures	2-Should Do	Fair	<u> </u>	\$0	Each	\$0
	School		(2011)	2020	Maintenance	per replacement schedule.	JC: 11003	_iccci icui		-ibiiciiig i ixtui es	_ 5115414 50		~	70	Lucii	70
		Lighting				p = 1 - sp. asc. ment senedure.										
		Instruments														
7916	Batavia High		BFAC, Fieldhouse BFAC Stage	2020	Sent to	Original. Needs replacement in 2031	Services	Electrical	Lighting	Lighting Fixtures	2-Should Do	Fair	0	\$0	Each	\$0
	School		(2011)		Maintenance	per replacement schedule.										
		Instruments														
7919	Batavia High	9266 - LED MK2	BFAC, Fieldhouse BFAC Stage	2020	Sent to	Original. Needs replacement in 2025	Services	Electrical	Lighting	Lighting Fixtures	2-Should Do	Fair	0	\$0	Each	\$0
	School		(2011)		Maintenance	per replacement schedule.										
7920	Batavia High		BFAC, Fieldhouse BFAC, Black Box	2020	Sent to	Original with some purchased in	Interiors	Interior Finishes	Flooring	Specialty Flooring	2-Should Do	Good	1	\$30,000	Lump Sum	\$30,000
	School		(2011)		Maintenance	2018. Needs replacement in 2022										
		Lights				per replacement schedule.										










Assessment	Campus	Linked Bldg	Addition	Room	Assessment	Assessment	Description	Building System	.	Building System		Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID 7924	Batavia High	System 9271 - Interior	BFAC, Fieldhouse	REAC Stage	Year 2020	Status Sent to	Original. Scheduled repainting in	L1 Interiors	L2 Interior Finishes	L3 Wall Finishes	L4 Wall Painting and	2-Should Do	Good	0	\$2	Square Foot	\$0
7324	School	Wall Finish, Zolatone Paint	(2011)	DI AC Stage	2020	Maintenance	2020.	interiors	interior rinishes	wall i illisties	Coating	2-31100110 00	Good	O .	72	Square 100t	30
7925	Batavia High School	9677 - Sitework, Landscape Pavers	BFAC, Fieldhouse (2011)		2020	Sent to Maintenance	Original. Some disturbance due to tree roots and wear from weather and exterior elements.	Sitework	Site Improvements	Pedestrian Plazas and Walkways	Pedestrian Pavement	2-Should Do	Fair	3000	\$25	Square Foot	\$75,000
7965	Batavia High School	3393 - Equipment Lockers - Original	,	Corridors	2020	Sent to Maintenance	Lockers generally in good/fair condition throughout school. Potential plans to remove full-size lockers and replace with half-size lockers.	Equipment and Furnishings	Equipment	Institutional Equipment	Educational and Scientific Equipment	2-Should Do	Fair	1990	\$200	Each	\$398,000
17687	Batavia High School	4821 - Plumbing, Domestic Water Piping			2020	Sent to Maintenance	Per Capital Projects Plan - water softener was due for replacement in 2011 and in fair condition.	Services	Plumbing	Domestic Water Distribution	Domestic Water Piping	2-Should Do	Fair	1	\$70,000	Each	\$70,000
78140	Batavia High School	18948 - Sitework, Fields and Athletic Areas			2013	Sent to Maintenance	Per 2013 Site Master Plan - stadium upgrades (8-lane track, drainage, increase seating capacity, press box score board, concessions/toilet/storage, plaza improvements, field sports improvements); cost includes escalation from 2013.		Site Improvements	Athletic, Recreational, and Playfield Areas		2-Should Do	Fair	1	\$6,000,000	Lump Sum	\$6,000,000
4811	Batavia High School	1687 - Exterior Entrance Doors, Hollow Metal - 1971	LRC, Classrooms (1971)	Learning Center	2020	Sent to Maintenance	Learning Center - One pair of doors to courtyard are in good condition with slight paint chipping near the base	Shell	Exterior Vertical Enclosures	Exterior Doors and Grilles	Exterior Entrance Doors	3-Like To Do	Good	2	\$7,500	Each	\$15,000
4815	Batavia High School	1699 - Ceilings, Acoustical Suspended Systems - 1971	LRC, Classrooms (1971)	Learning Center	2020	Sent to Maintenance	Work Room (B119D) "The Back Room" Lounge Library Work Room	Interiors	Interior Construction		Acoustical Suspended Ceilings	3-Like To Do	Good	1505	\$8	Square Foot	\$11,288
4824	Batavia High School	1805 - Ceilings, Acoustical Suspended Systems - 2009	North Classrooms, SW Mechanical (2009)	Science Lab		Sent to Maintenance	ACT in good condition D201, D205, D209	Interiors	Interior Construction		Acoustical Suspended Ceilings	3-Like To Do	Good	3616	\$8	Square Foot	\$27,120
4829	Batavia High School	1827 - Flooring, VCT - 2009	North Classrooms, SW Mechanical	Science Lab	2020	Sent to Maintenance	VCT in good condition D201, and D209	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	2405	\$12	Square Foot	\$28,860
4838	Batavia High School	1951 - Interior Wall Finish, Paint Original		Learning Center	2020	Sent to Maintenance	Quantity reflects total SF of all listed spaces. Learning Center. Library Work Room.	Interiors	Interior Finishes		Wall Painting and Coating	3-Like To Do	Good	12335	\$2	Square Foot	\$27,754
4848	Batavia High School	1988 - Fixed Equipment, Casework - 1971	LRC, Classrooms (1971)	Learning Center		Sent to Maintenance	Casework and bookshelves show no sign of delamination and are overall in good condition. Overall aesthetic is dated and original to the space. Learning Center. Work Room. (B119D) "The Back Room" Lounge	Furnishings	Furnishings	Fixed Furnishings	Casework	3-Like To Do	Good	1000	\$800	Linear Foot	\$800,000

Building Our Future TOGETHER BPS









Assessmen	t Campus	Linked Bldg	Addition	Room	Assessmen	t Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID		System			Year	Status		L1	L2	L3	L4		-	•			
4967	Batavia High School	1698 - Ceilings, Acoustical Suspended Systems - Original		Toilet	2020	Sent to Maintenance	ACT ceiling in good condition Toilets in Locker Room - A108 and A104 TR in PE Office - A105B Toilets in W Locker Room - A104 Staff TR in W Locker Room Boys by B124 Nurse suite Boys toilet Nurse suite Girls Toilet Mens Faculty Center Womens Faculty Center	Interiors	Interior Construction	Suspended Ceiling Construction	Suspended Ceilings	3-Like To Do		1585	\$8	Square Foot	\$11,888
5002	Batavia High School	1898 - Ceilings, Acoustical Suspended Systems - 1969	North Central Classrooms (1969	Staff Toilet Room	n 2020	Sent to Maintenance	ACT ceiling in good condition A129A-T	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	58	\$8	Square Foot	\$435
5013	Batavia High School	1804 - Ceilings, Acoustical Suspended Systems - 1995 Entry	Central Area, South Entrance (1995)	Toilet	2020	Sent to Maintenance	ACT ceiling is in good condition Girls in C wing1 Staff in c wing 1 Girls by c119 Girls by Café 126D- Student TR	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	563	\$8	Square Foot	\$4,973
5018	Batavia High School	1825 - Flooring, VCT - 1995 Entry	Central Area, South Entrance (1995)	Toilet	2020	Sent to Maintenance	VCT flooring in good condition. Boys by cafe. Girls by cafe.	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	103	\$12	Square Foot	\$1,236
5032	Batavia High School	1991 - Interior Wall Finish, Paint - 1995	Central Area, South Entrance (1995)	Toilet	2020	Sent to Maintenance	Wall paint in good condition. Quantity reflects total SF of all listed spaces. 126D- Student TR	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	3-Like To Do	Good	109	\$2	Square Foot	\$245
5053	Batavia High School	1698 - Ceilings, Acoustical Suspended Systems - Original	LRC, Classrooms (1971)	Office / Pull-Out	2020	Sent to Maintenance	Career Counselor (In the Library)	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	100	\$8	Square Foot	\$750
5066	Batavia High School	1951 - Interior Wall Finish, Paint - Original		Office / Pull-Out	2020	Sent to Maintenance	Quantity reflects total SF of listed spaces. Career Counselor (In the Library).	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	3-Like To Do	Good	235	\$2	Square Foot	\$529
5069	Batavia High School	1991 - Interior Wall Finish, Paint · 1995	Central Area, South Entrance (1995)	Toilet	2020	Sent to Maintenance	Wall paint in a good condition. Quantity reflects total SF of listed spaces. C-Wing South, 2nd Floor - Girls Toilet. C-Wing South, 2nd Floor - boys Toilet. C-Wing South, 2nd Floor - staff Toilet. C-Wing North, 2nd Floor - Girls Toilet. C-Wing North, 2nd Floor - boys Toilet. C-Wing North, 2nd Floor - boys Toilet.	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	3-Like To Do	Good	1100	\$2	Square Foot	\$2,475









ssessmen	nt Campus	Linked Bldg	Addition	Room	Assessment		Description	Building System		Building System		Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Co
ID		System			Year	Status		L1	L2	L3	L4						
5089	Batavia High School	1805 - Ceilings, Acoustical Suspended Systems - 2009	North Classrooms, SW Mechanical (2009)	Toilet	2020	Sent to Maintenance	ACT ceilings are in a good condition Girls by d100 Boys by d100 Toilet in d102	Interiors	Interior Construction		Acoustical Suspended Ceilings	3-Like To Do	Good	1695	\$8	Square Foot	\$12,713
							Mens in Office Womens in Office TR in kitchen E CORRIDOR TOILET E CORRIDOR MENS E CORRIDOR WOMENS E CORRIDOR TOILET										
5097	Batavia High	1993 - Interior	North	Toilet	2020	Sent to	Wall paint in good condition.	Interiors	Interior Finishes	Wall Finishes	Wall Painting and	3-Like To Do	Good	53	\$2	Square Foot	\$119
3037	School	Wall Finish, Paint 2009	- Classrooms, SW Mechanical (2009)	ronet		Maintenance	Quantity reflects total SF of listed spaces. TR in Kitchen	interiors			Coating	S LINE TO BU	Coou		42	Squareroot	7113
5108	Batavia High School	1827 - Flooring, VCT - 2009	North Classrooms, SW Mechanical	Toilet		Sent to Maintenance	VCT flooring in good condition. D-Wing 2nd Floor- Girls Toilet.	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	135	\$12	Square Foot	\$1,620
			(2009)				D-Wing 2nd Floor- boys Toilet								40		40 - 40
5131	Batavia High School	1807 - Ceilings, Acoustical Suspended	BFAC, Fieldhouse (2011)	Toilet		Sent to Maintenance	ACT ceiling in good condition. FIELDHOUSE GIRLS FIELDHOUSE BOYS	Interiors	Interior Construction		Suspended Ceilings	3-Like To Do	Good	472	\$8	Square Foot	\$3,540
5160	Batavia High	Systems - 2011 1698 - Ceilings,		Classrooms	2020	Sent to	ACT in good condition.	Interiors	Interior	Suspended Ceiling	Acquetical	3-Like To Do	Good	4522	\$8	Square Foot	\$33,915
3100	School	Acoustical Suspended Systems - Original	1	Classioonis		Maintenance	B106. B107. B113. B125. A109	interiors	Construction	Construction	Suspended Ceilings	3-Like 10 DO	0000	7,722	30	Squareroot	733,313
5163	Batavia High School	1704 - Flooring, VCT - Original		Classrooms	2020	Sent to Maintenance	VCT in good condition - older tile but in good condition. B109. B125. A109	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	2958	\$12	Square Foot	\$35,496
5173	Batavia High School	1951 - Interior Wall Finish, Paint Original	-	Classrooms		Sent to Maintenance	Paint in good condition. Quantity reflects total SF of listed spaces. B109, A109	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	3-Like To Do	Good	1660	\$2	Square Foot	\$3,735
5177	Batavia High School	1732 - Fixed Equipment, Casework - Original		Classrooms		Sent to Maintenance	Casework in good condition. B125	Equipment and Furnishings	Furnishings	Fixed Furnishings	Casework	3-Like To Do	Good	76	\$800	Linear Foot	\$60,800
5194	Batavia High School	1898 - Ceilings, Acoustical Suspended Systems - 1969	North Central Classrooms (1969	Classrooms 9)		Sent to Maintenance	ACT in good condition. A121. A126. A128.	Interiors	Interior Construction		Acoustical Suspended Ceilings	3-Like To Do	Good	2641	\$8	Square Foot	\$19,808
5195	Batavia High School	1901 - Ceilings, Gypsum - 1969	North Central Classrooms (1969	Classrooms	2020	Sent to Maintenance	GWB soffit in good condition. A121	Interiors	Interior Construction		Suspended Plaster and Gypsum Board	3-Like To Do	Good	1140	\$1	Square Foot	\$1,140









Assessment	Campus	Linked Bldg	Addition	Room	Assessment	Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID		System			Year	Status		L1	L2	L3	L4						
5199	Batavia High School	1909 - Flooring, VCT - 1969	North Central Classrooms (1969	(Classrooms	2020	Sent to Maintenance	VCT in good condition. A121. A126. A128.	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	2641	\$12	Square Foot	\$31,692
	Batavia High School	1698 - Ceilings, Acoustical Suspended Systems - Original		Office / Pull-Out	2020	Sent to Maintenance	ACT is in Good Condition A104B, A106, A108B, B108, B118, B118A, B118F, B118G, B118H, B119A, B119B, B120, B121, B122 (Faculty Center South), B122 (Faculty Center North), B122A, B122B, B122C, B122B, B122C, B124A, B124A, B124A, B124B, B124C, B124C, B124C, B124D	Interiors	Interior Construction		Acoustical Suspended Ceilings	3-Like To Do	Good	12986	\$8	Square Foot	\$97,395
5204	Batavia High School		North Central Classrooms (1969		2020	Sent to Maintenance	ACT is in Good Condition A123A A125A A129A	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	1101	\$8	Square Foot	\$8,258
	Batavia High School	Wall Base - 1969	North Central Classrooms (1969		2020	Sent to Maintenance	Wall base in good condition. A121. A126. A127. A128.	Interiors	Interior Finishes			3-Like To Do		562	\$6		\$3,372
5211	Batavia High School Batavia High School	Acoustical Suspended Systems - 1995 Entry	Central Area, South Entrance (1995) North Central Classrooms (1965)	Office / Pull-Out Classrooms	2020	Sent to Maintenance Sent to Maintenance	ACT is in Good Condition A101A A101B A134A B100M Paint in good condition. Quantity reflects total SF of listed spaces.	Interiors	Interior Construction Interior Finishes	Wall Finishes	Acoustical Suspended Ceilings Wall Painting and Coating	3-Like To Do 3-Like To Do		3300			\$7,425
							A121. A126. A127. A128.										









Assessmen	nt Campus	Linked Bldg	Addition	Room	Assessment	Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cos
ID		System			Year	Status		L1	L2	L3	L4						
5214	Batavia High	1929 - Fixed	North Central	Classrooms	2020	Sent to	Casework in good condition.	Equipment and	Furnishings	Fixed Furnishings	Casework	3-Like To Do	Good	75	\$800	Linear Foot	\$60,000
	School	Equipment,	Classrooms (1969))		Maintenance		Furnishings									
		Casework - 1969					A126, A128										
5216	Batavia High	1805 - Ceilings,	South Admin	Office / Pull-Out		Sent to	ACT is in Good Condition	Interiors	Interior	Suspended Ceiling		3-Like To Do	Good	3708	\$8	Square Foot	\$27,810
	School	Acoustical	Addition (2009)			Maintenance	A102C,		Construction		Suspended						
		Suspended					B100B,				Ceilings						
		Systems - 2009					B100C,										
							B100D,										
							B100E,										
							B100F,										
							B100G,										
							B100H, B100J,										
							B100J, B100K,										
							B100K,										
							B101,										
							B101A,										
							B101B,										
							B101C,										
							B101D,										
							B101E,										
							B102,										
							B102A,										
							D211										
5218	Batavia High	1807 - Ceilings,	BFAC, Fieldhouse	Office / Pull-Out	2020	Sent to	ACT is in Fair Condition	Interiors	Interior	Suspended Ceiling	Acoustical	3-Like To Do	Good	295	\$8	Square Foot	\$2,213
	School	Acoustical	(2011)			Maintenance	F111 (Building Trades Office)		Construction	Construction	Suspended						
		Suspended									Ceilings						
		Systems - 2011															
5220	Batavia High	1804 - Ceilings,	Central Area,	Office / Pull-Out		Sent to	ACT is in Good Condition	Interiors	Interior	Suspended Ceiling		3-Like To Do	Good	1686	\$8	Square Foot	\$12,645
	School	Acoustical	South Entrance			Maintenance	A101A		Construction		Suspended						
		Suspended	(1995)				A101B				Ceilings						
		Systems - 1995															
		Entry													10		***
5225	Batavia High	1699 - Ceilings,	LRC, Classrooms	Classrooms	2020	Sent to	ACT in good condition.	Interiors	Interior	Suspended Ceiling		3-Like To Do	Good	1520	\$8	Square Foot	\$11,400
	School	Acoustical	(1971)			Maintenance	D404 D4044		Construction		Suspended						
		Suspended					B104, B104A				Ceilings						
5226	Ratavia ⊔iah	Systems - 1971 1809 - Ceilings,	South Admin	Office / Pull-Out	2020	Sent to	ACT is in Good Condition	Interiors	Interior	Suspended Cailing	Suspended	3-Like To Do	Good	626	\$1	Square Foot	\$626
3220	Batavia High School	Gypsum - 2009	Addition (2009)	Office / Pull-Out			B101 (Dean Reception)	interiors	Interior Construction	Suspended Ceiling Construction		3-LIKE TO DO	3000	020	31	Square Foot	J020
	3011001	Admin	Addition (2003)			ivianite nance	bioi (bean neception)		Construction		Gypsum Board						
5227	Batavia High	1811 - Ceilings,	BFAC. Fieldhouse	Office / Pull-Out	2020	Sent to	ACT is in Good Condition	Interiors	Interior	Suspended Ceiling		3-Like To Do	Good	170	\$1	Square Foot	\$170
5221	School	Gypsum - 2011	(2011)	Since / Full-Out			F102 (Auditorium Manager)	interior3	Construction		Plaster and	S LIKE TO DO	3000	1,0	71	Square 100t	71,0
	3611001	3 y p 3 u 11 - 2 0 1 1	(2011)			amicenance	1 202 (Additorial Manager)		Constituction		Gypsum Board						
5229	Batavia High	1716 - Flooring,	LRC, Classrooms	Classrooms		Sent to	VCT in good condition.	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	2574	\$12	Square Foot	\$30,888
	School	VCT - 1971	(1971)			Maintenance											
							B115.										
							B116.										
							B117										










Assessmen	t Campus	Linked Bldg	Addition Room	Assessmen	t Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID		System		Year	Status		L1	L2	L3	L4		, , , , , , , , , , , , , , , , , , , ,				
5233	Batavia High	1704 - Flooring,	Office / Pull-Out	2020	Sent to	VCT is in Good Condition	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	1854	\$12	Square Foot	\$22,248
	School	VCT - Original			Maintenance	A104B,								·		
						A106,										
						A108B,										
						B118A,										
						B119C - Mostly covered by a large										
						carpet,										
						B119D - Some minor scuffs										
						throughout,										
						B124,										
						B124A,										
						B124B,										
						B124C,										
						B124D,										
						B124E,										
						B124F,										
						B124G										
5234	Batavia High	1973 - Interior	LRC, Classrooms Classrooms	2020	Sent to	Wall base in good condition.	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	362	\$6	Linear Foot	\$2,172
	School	Wall Finishes,	(1971)		Maintenance	2400										
		Wall Base - 1971				B103.										
						B104. B104A.										
5235	Datavia High	1989 - Interior	LRC, Classrooms Classrooms	2020	Sent to		Intoriors	Interior Finishes	Wall Finishes	Wall Painting and	2 Like Te De	Good	2600	\$2	Square Foot	\$5,850
5235	Batavia High School	Wall Finish, Paint -		2020	Maintenance	Paint in good condition. Quantity reflects total SF of all listed spaces.	Interiors	interior rinishes	wall rillisties	Coating	3-LIKE 10 D0	Good	2600	\$2	Square Foot	\$5,650
	3011001	1971	(1971)		iviaiiiteiiaiice	reflects total 31 of all listed spaces.				Coating						
		1371				B103.										
						B104.										
						B104A.										
5238	Batavia High	1988 - Fixed	LRC, Classrooms Classrooms	2020	Sent to	Casework in good condition. Verify	Equipment and	Furnishings	Fixed Furnishings	Casework	3-Like To Do	Good	40	\$800	Square Foot	\$32,000
	School	Equipment,	(1971)		Maintenance	quantity in field, not shown in plan.										
		Casework - 1971														
						B104, B104A										
5249	Batavia High	1899 - Ceilings,	East 2-Story Classrooms	2020	Sent to	ACT in good condition.	Interiors	Interior	Suspended Ceiling	Acoustical	3-Like To Do	Good	13706	\$8	Square Foot	\$102,795
	School	Acoustical	Classrooms (1995)		Maintenance			Construction	Construction	Suspended						
		Suspended				C101.				Ceilings						
		Systems - 1995				C102.										
						C103.										
						C105.										
						C107.										
						C109.										
						C110.										
						C111.										
						C112 - borderline fair, 3 damaged										
						tiles.										
						C113. C114.										
						C114. C116.										
						C117 - large water stain on 2 tiles.										
						C117 - large water stall on 2 tiles.										
						C120.										
						C120. C121.										
						C122.										
						C123.										
5251	Batavia High	1909 - Flooring,	North Central Office / Pull-Out	2020	Sent to	VCT is in Poor Condition	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	100	\$12	Square Foot	\$1,200
	School	VCT - 1969	Classrooms (1969)			A125A (Pull-Out)			J							
	- 555.	1.0. 2000						l	1	1				_1		









Assessmen	t Campus	Linked Bldg	Addition	Room	Assessmen	t Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID 5253	Batavia High School	System 1932 - Interiors, Flooring-LVT -	East 2-Story Classrooms (1995)	Classrooms	Year 2020	Sent to Maintenance	LVT in good condition.	L1 Interiors	L2 Interior Finishes	L3 Flooring	L4 Resilient Flooring	3-Like To Do	Good	801	\$10	Square Foot	\$8,010
5264	Batavia High School	1995 1986 - Fixed Equipment, Casework - 1995	East 2-Story Classrooms (1995)	Classrooms	2020	Sent to Maintenance	C118 Casework in good condition. C119. C120. C122. C123. C106.	Equipment and Furnishings	Furnishings	Fixed Furnishings	Casework	3-Like To Do	Good	100	\$800	Linear Foot	\$80,000
5273	Batavia High School	1805 - Ceilings, Acoustical Suspended Systems - 2009	North Classrooms, SW Mechanical (2009)	Classrooms	2020	Sent to Maintenance	ACT in good condition. D101. D102. D103. D104. D105. D106. D107. D108. D109.	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	7844	\$8	Square Foot	\$58,830
5275	Batavia High School	1827 - Flooring, VCT - 2009	North Classrooms, SW Mechanical	Classrooms	2020	Sent to Maintenance	VCT in good condition. D101, D103	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	1711	\$12	Square Foot	\$20,532
5280	Batavia High School	1977 - Interior Wall Finishes, Wall Base - 2009	North Classrooms, SW Mechanical (2009)	Classrooms	2020	Sent to Maintenance	Wall base in good condition. D101. D102. D103. D104. D105. D106. D107. D108. D109.	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	1050	\$6	Linear Foot	\$6,300
5302	Batavia High	1704 - Flooring,		Storage/Mecha	nic 2020	Sent to	VCT flooring is in good condition.	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good !	589	\$12	Square Foot	\$7,068
5311	School Batavia High School	VCT - Original 1743 - Interior Wall Finishes, Wall Base - Original		al Storage/Mechal al	nic 2020	Maintenance Sent to Maintenance	A104D, B125B, B110B Wall base in good condition B122D, A104D, A105B, A105D, A109B, A109A, B125B, B126A, B126D, B110B	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	750	\$6	Linear Foot	\$4,500
5312	Batavia High School	1951 - Interior Wall Finish, Paint Original		Storage/Mechai al	nic 2020	Sent to Maintenance	Wall paint in good condition. Quantity reflects total SF of all listed spaces. B122D, A104D, A105B, A105D, A109B, A109A. B125B, B126D, B110B		Interior Finishes	Wall Finishes	Wall Painting and Coating	3-Like To Do	Good	3631	\$2	Square Foot	\$8,170
5315	Batavia High School	1698 - Ceilings, Acoustical Suspended Systems - Original		Storage/Mechal			ACT ceiling in good condition B125B, B111, B110B	Interiors	Interior Construction		Suspended Ceilings	3-Like To Do		361	\$8	Square Foot	\$2,708
5318	Batavia High School	1732 - Fixed Equipment, Casework - Original		Storage/Mechal	nic 2020	Sent to Maintenance	Casework is in good condition. B110B	Equipment and Furnishings	Furnishings	Fixed Furnishings	Casework	3-Like To Do	Good	28	\$800	Linear Foot	\$22,400









Assessment	Campus	Linked Bldg	Addition	Room	Assessmen		Description			Building System		n Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cos
5322	Batavia High School	System 1898 - Ceilings, Acoustical Suspended Systems - 1969	North Central Classrooms (1969	Storage)	2020	Status Sent to Maintenance	ACT ceiling in good condition Elec Room - located in A125, also being used as storage Storage located between A122 and A121	L1 Interiors	Interior Construction	L3 Suspended Ceiling Construction	L4 Acoustical Suspended Ceilings	3-Like To Do	Good	288	\$8	Square Foot	\$2,160
5324	Batavia High School	1901 - Ceilings, Gypsum - 1969	North Central Classrooms (1969	Storage)	2020	Sent to Maintenance	GWB ceiling in good condition	Interiors	Interior Construction	Suspended Ceiling Construction	Suspended Plaster and Gypsum Board	3-Like To Do	Good	117	\$1		\$117
5325	Batavia High School	1909 - Flooring, VCT - 1969	North Central Classrooms (1969	Storage)	2020	Sent to Maintenance	VCT in good condition. Elec Room - located in A125, also being used as storage (102SF). Drying Room - located between A123 and A124 (185SF). Storage -located between A122 and A121 (318SF)	Interiors	Interior Finishes	Flooring	Resilient Flooring	g 3-Like To Do	Good	605	\$12	Square Foot	\$7,260
5328	Batavia High School	1972 - Interior Wall Finishes, Wall Base - 1969	North Central Classrooms (1969	Storage)	2020	Sent to Maintenance	Wall base in good condition Elec Room in A126A Drying Room located between A123 and A124 Storage located between A122 and A121 Storage in A124	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	200	\$6	Linear Foot	\$1,200
5329	Batavia High School	1971 - Interior Wall Finish, Paint 1969	North Central - Classrooms (1969	Storage)	2020	Sent to Maintenance	Wall paint in good condition. Quantity reflects total SF of all listed spaces. Elec Room in A126A. Elec Room located in A125, also being used as storage. Drying Room located between A123 and A124. Storage Room limited lighting due to activities in room; located in A124. Storage located between A122 and A121.		Interior Finishes	Wall Finishes	Wall Painting and Coating	d 3-Like To Do	Good	624	\$2	Square Foot	\$1,404
5347	Batavia High School	1899 - Ceilings, Acoustical Suspended Systems - 1995	Central Area, South Entrance (1995)	Storage	2020	Sent to Maintenance	Act ceiling in good condition C115B	Interiors	Interior Construction		Acoustical Suspended Ceilings	3-Like To Do	Good	670	\$8	Square Foot	\$5,025
5361	Batavia High School	1990 - Interior Wall Finish, Paint 1995 Entry	Central Area, - South Entrance (1995)	Storage	2020	Sent to Maintenance	Wall paint in good condition. Quantity reflects total SF of all listed spaces. Storage near Café TR	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	d 3-Like To Do	Good	83	\$2	Square Foot	\$187
5374	Batavia High School	1806 - Ceilings, Acoustical Suspended Systems - 2009 Admin	South Admin Addition (2009)	Storage	2020	Sent to Maintenance	ACt ceiling in good condition B102B	Interiors	Interior Construction		Acoustical Suspended Ceilings	3-Like To Do	Good	109	\$8	Square Foot	\$818
5377	Batavia High School	1976 - Interior Wall Finishes, Wall Base - 2009	Addition (2009)	Storage	2020	Sent to Maintenance	Wall base in good condition B102B	Interiors	Interior Finishes	Wall Finishes		3-Like To Do		33	\$6	Linear Foot	\$198
5390	Batavia High School	1807 - Ceilings, Acoustical Suspended Systems - 2011	BFAC, Fieldhouse (2011)	BFAC Spaces	2020	Sent to Maintenance	Room #: F100 Lobby, F100 Vestibule, F109 , F109C, F109D, Women's RR, Mens RR Cost is to replace system in its entirety.	Interiors	Interior Construction		Acoustical Suspended Ceilings	3-Like To Do	Good	6000	\$8	Square Foot	\$45,000









ssessment	Campus	Linked Bldg	Addition	Room	Assessment	Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID		System			Year	Status		L1	L2	L3	L4						
5392	Batavia High	1898 - Ceilings,	North Central	Art Rooms	2020	Sent to	ACT in good condition.	Interiors	Interior	Suspended Ceiling	Acoustical	3-Like To Do	Good	2818	\$8	Square Foot	\$21,135
	School	Acoustical	Classrooms (1969)		Maintenance	Room #: A123, A125, A131, A131A,		Construction	Construction	Suspended						
		Suspended					A133,				Ceilings						
		Systems - 1969															
5394	Batavia High	1805 - Ceilings,	North	Art Rooms	2020	Sent to	Room #: D110, D114, D116	Interiors	Interior	Suspended Ceiling		3-Like To Do	Good	3579	\$8	Square Foot	\$26,843
	School	Acoustical	Classrooms, SW			Maintenance			Construction	Construction	Suspended						
		Suspended	Mechanical								Ceilings						
		Systems - 2009	(2009)												4.		+= 00
5395	Batavia High	1901 - Ceilings,	North Central	Video	2020	Sent to	Room #: A131	Interiors	Interior	Suspended Ceiling		3-Like To Do	Good	768	\$1	Square Foot	\$768
	School	Gypsum - 1969	Classrooms (1969)		Maintenance			Construction	Construction	Plaster and						
5396	Batavia High	1808 - Ceilings,	East 2-Story	Video Room	2020	Sent to	Room #: A133	Interiors	Interior	Suspended Ceiling	Gypsum Board	3-Like To Do	Good	419	\$1	Square Foot	\$419
3330	School	Gypsum - 1995	Classrooms (1995		2020	Maintenance	100111 #. A133	interiors	Construction	Construction	Plaster and	3-LIKE TO DO	Good	413	71	Square 100t	5419
	3011001	Entry	Classi 001115 (1555	,		Walliterlance			Construction	Construction	Gypsum Board						
5397	Batavia High	1808 - Ceilings,	North	CS, Eng, 2D Art	2020	Sent to	Room #: D110, D114, D116	Interiors	Interior	Suspended Ceiling		3-Like To Do	Good	3579	\$1	Square Foot	\$3,579
	School	Gypsum - 1995	Classrooms, SW	20, 20, 20		Maintenance			Construction	Construction	Plaster and				7-	- 4	7-7-1-5
		Entry	Mechanical								Gypsum Board						
5399	Batavia High	1811 - Ceilings,	BFAC, Fieldhouse	Aud. Rooms	2020	Sent to	Room #: F103A, F103B, F200B, BFAC	Interiors	Interior	Suspended Ceiling		3-Like To Do	Good	500	\$1	Square Foot	\$500
	School	Gypsum - 2011	(2011)			Maintenance	2nd Level Lobby		Construction	Construction	Plaster and					-	
											Gypsum Board						
5405	Batavia High	1810 - Ceilings,	North	Storage	2020	Sent to	ACT ceiling in good condition	Interiors	Interior	Suspended Ceiling	Suspended	3-Like To Do	Good	65	\$1	Square Foot	\$65
	School	Gypsum - 2009	Classrooms, SW			Maintenance	D113		Construction	Construction	Plaster and						
			Mechanical								Gypsum Board						
5412	Batavia High	1977 - Interior	North	Storage	2020	Sent to	Wall base in good condition	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	140	\$6	Linear Foot	\$840
	School	Wall Finishes,	Classrooms, SW			Maintenance	D113, A102B										
		Wall Base - 2009	Mechanical														
5416	Batavia High	1993 - Interior	North	Storage	2020	Sent to	Wall paint is in good condition.	Interiors	Interior Finishes	Wall Finishes	Wall Painting and	3-Like To Do	Good	278	\$2	Square Foot	\$626
	School	Wall Finish, Paint -	Classrooms, SW			Maintenance	Quantity reflects total SF of all listed				Coating						
		2009	Mechanical				spaces.										
			(2009)				Janitor in Kitchen. A102B, E114, E116.										
5424	Batavia High	1805 - Ceilings,	North	Science Prep.	2020	Sent to	ACT ceiling is in a good condition	Interiors	Interior	Suspended Ceiling	Acquetical	3-Like To Do	Good	351	\$8	Square Foot	\$2,633
3424	School	Acoustical	Classrooms, SW	Science Frep.	2020	Maintenance	D203	interiors	Construction		Suspended	3-LIKE TO DO	Good	331	70	Square 100t	72,033
	30.1001	Suspended	Mechanical							551.561.4561.511	Ceilings						
		Systems - 2009	(2009)								85						
5427	Batavia High	1827 - Flooring,	North	Science Prep.	2020	Sent to	VCT flooring is in a good condition	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	351	\$12	Square Foot	\$4,212
	School	VCT - 2009	Classrooms, SW			Maintenance	D207									•	
			Mechanical														
5429	Batavia High	1977 - Interior	North	Science Prep.	2020	Sent to	Wall base is in a good condition	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	90	\$6	Linear Foot	\$540
	School	Wall Finishes,	Classrooms, SW			Maintenance	D203, D207										
		Wall Base - 2009	Mechanical														
5437	Batavia High		East 2-Story	Classrooms	2020	Sent to	ACT in good condition, room	Interiors	Interior	Suspended Ceiling		3-Like To Do	Good	807	\$8	Square Foot	\$6,053
	School		Classrooms (1995)		Maintenance	recently renovated.		Construction		Suspended						
		Suspended					C219				Ceilings						
F 420	Deterrie III-li	Systems - 1995	Nambh Cairtin	Ant Decision	2020	Combine	Danie #, A120, A124, A125, A120	lataria va	Interior State	Flagring	Desilient Floor	2 Libe T- D-	Cood	5200	ć12	Caucana Front	¢CA 77C
5439	Batavia High School	1909 - Flooring, VCT - 1969	North Central Classrooms (1969	Art Rooms	2020	Sent to Maintenance	Room #: A120, A124, A125, A129,	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-rike 10 D0	Good	5398	\$12	Square Foot	\$64,776
5446	Batavia High		BFAC, Fieldhouse		ic 2020	Sent to	A131A ACt ceiling in good condition	Interiors	Interior	Suspended Ceiling	Acquetical	3-Like To Do	Good	8729	\$8	Square Foot	\$65,468
J -14 0	School	Acoustical	(2011)	al/IT	10/2020		F111A (3723 sf)	THE HOLD	Construction		Suspended	J-LINE TO DU	3000	0/23	γo	Square 100t	700,700
	3011001	Suspended	(2011)	ai, ii		Walliteriance	F106A (2145 sf)		Construction	Construction	Ceilings						
		Systems - 2011					F112M				55111185						
		_,					F112K (58 sf)										
							F112L										
							F114 (2803 sf)										
	i e	i i	Ì	1		1	F114A	1	1	1	1	1	1	I .	1	1	









ssessment	Campus	Linked Bldg	Addition	Room	Assessmen	Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID		System			Year	Status		L1	L2	L3	L4						
5447	Batavia High School	1909 - Flooring, VCT - 1969	North Central Classrooms (1969	Art Rooms	2020	Sent to Maintenance	Room #: A120, A124, A125, A129, A131A	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	5398	\$12	Square Foot	\$64,776
5455	Batavia High School	1827 - Flooring, VCT - 2009	North Classrooms, SW Mechanical	Exploratories	2020	Sent to Maintenance	Room #: D111	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	1099	\$12	Square Foot	\$13,188
5456	Batavia High School	1811 - Ceilings, Gypsum - 2011	BFAC, Fieldhouse (2011)	Storage/Mechan al/IT	ic 2020	Sent to Maintenance	GWB ceiling in good condition F103B	Interiors	Interior Construction	Suspended Ceiling Construction	Suspended Plaster and Gypsum Board	3-Like To Do	Good	236	\$1	Square Foot	\$236
5461	Batavia High School	1986 - Fixed Equipment, Casework - 1995	East 2-Story Classrooms (1995	Classrooms)	2020	Sent to Maintenance	Casework in good condition. C219	Equipment and Furnishings	Furnishings	Fixed Furnishings	Casework	3-Like To Do	Good	20	\$800	Linear Foot	\$16,000
5466	Batavia High School	1978 - Interior Wall Finishes, Wall Base - 2011	BFAC, Fieldhouse (2011)	Storage/Mechan al/IT	ic 2020	Sent to Maintenance	Wall base in good condition F111A F101 F103B F103C F105 F107A	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	100	\$6	Linear Foot	\$600
5468	Batavia High School	1994 - Interior Wall Finish, Paint 2011	BFAC, Fieldhouse (2011)	Storage/Mechan al/IT	ic 2020	Sent to Maintenance	Wall paint in good condition. Quantity reflects total SF of all listed spaces. F111A. F101. F103B. F103C. F107A. F112M. F112K. F112L. F114. F115.	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	3-Like To Do	Good	6100	\$2	Square Foot	\$13,725
5471	Batavia High School	1827 - Flooring, VCT - 2009	North Classrooms, SW Mechanical	Music Rooms	2020	Sent to Maintenance	Room #: E101A, E105, E106B, E06C, E106D, E106E, E106F, E106G, E106H, E106J, E106K, E107	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	6865	\$12	Square Foot	\$82,380
5476	Batavia High School	1805 - Ceilings, Acoustical Suspended Systems - 2009	North Classrooms, SW Mechanical (2009)	Science Classrooms	2020	Sent to Maintenance	ACT in good condition. D202. D204. D206. D208.	Interiors	Interior Construction		Acoustical Suspended Ceilings	3-Like To Do	Good	3534	\$8	Square Foot	\$26,505
5479	Batavia High School	1977 - Interior Wall Finishes, Wall Base - 2009	North Classrooms, SW Mechanical (2009)	Science Classrooms	2020	Sent to Maintenance	Wall base in good condition. D202. D204. D206. D208.	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	480	\$6	Linear Foot	\$2,880
5485	Batavia High School	1933 - Interiors, Flooring-LVT	BFAC, Fieldhouse (2011)	BFAC Support Space	2020	Sent to Maintenance	Room #: F103B, F109, F109C, F109D, F109 Mens and Women's RR	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	2316	\$10	Square Foot	\$23,160
5486	Batavia High School	2029 - Flooring, Carpet - 2011	BFAC, Fieldhouse (2011)	BFAC Spaces	2020	Sent to Maintenance	Cost is to replace LVT in kind. F100: Auditorium, Lobby, 2nd Level Lobby, F103A, F200B	Interiors	Interior Finishes	Flooring	Carpeting	3-Like To Do	Good	5000	\$7	Square Foot	\$32,500
							Cost is to replace with carpet tile.										









T									T	T	1					
Assessment	Campus	Linked Bldg	Addition Room		t Assessment	Description			Building System		Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID 5407	Potovio High	System	North Central Art Rooms	Year	Status	Doom #	L1	L2	L3 Wall Finishes	L4	2 Like To Do	Good	950	\$6	Linear Foot	¢F 700
5497	Batavia High School	1978 - Interior Wall Finishes,	North Central Art Rooms Classrooms (1969)	2020	Sent to Maintenance	Room #: A120	Interiors	Interior Finishes	wall fillishes		3-Like To Do	Good	950	\$6	Linear Foot	\$5,700
	3011001	Wall Base - 2011	Classicollis (1909)		ivialiteilalice	A123										
		Wali base - 2011				A124										
						A125										
						A129										
						A131										
						A131A										
5498	Batavia High	1975 - Interior	East 2-Story Art Rooms	2020	Sent to	Room #: A133	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	88	\$6	Linear Foot	\$528
	School		Classrooms (1995)		Maintenance											
		Wall Base - 1995														
5499	Batavia High	1977 - Interior	North Exploratories	2020	Sent to	Room #:	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	714	\$6	Linear Foot	\$4,284
	School		Classrooms, SW		Maintenance	D110										
		Wall Base - 2009	Mechanical (2009)			D111										
			(2009)			D114 D115										
						D116										
5500	Batavia High	1977 - Interior	North Music Rooms	2020	Sent to	Room #:	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	1900	\$6	Linear Foot	\$11,400
	School	Wall Finishes,	Classrooms, SW	1020	Maintenance	E101					5 2.me 15 25		1500	75	264. 1.000	ψ±±, 100
			Mechanical			E101A										
			(2009)			E103										
						E105										
						E106A										
						E106B										
						E106C										
						E106D										
						E106E										
						E106F										
						E106G E106H										
						E106J										
						E106K										
						E107										
						E107A										
						E107B										
						E108										
						E109										
						E109A										
						E109B										
						E109C										
5500	D	1070	D540 5: 1 II D5406	2020	6	E110) A (211 7 2		2400	A.C.		411100
5503	Batavia High		BFAC, Fieldhouse BFAC Spaces	2020	Sent to	Room #:	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	2400	\$6	Linear Foot	\$14,400
	School	Wall Finishes, Wall Base - 2011	(2011)		Maintenance	F100. F100 Lobby.										
		Wali Base - 2011				F100 L000y. F103A.										
						F103B.										
						F106.										
						F107.										
						F109.										
						F109C.										
						F109D.										
						F110.										
						F111.										
						F200B.										
						men's women's RR (F109).										
						2nd level lobby										









Assessment	t Campus	Linked Bldg	Addition Room	Assessmen	t Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cos
ID	Campus	System	Addition	Year	Status	Description	L1	L2	L3	L4	rionty	racinty condition	Quantity	Onit cost	Offic Of Wieasure	Littliated Cos
5504	Batavia High	1971 - Interior	North Central Art Rooms	2020	Sent to	Paint in good condition. Quantity	Interiors		Wall Finishes	Wall Painting and	3-Like To Do	Good	7657	\$2	Square Foot	\$17,228
	School	1969	-Classrooms (1969)		Maintenance	reflects total SF of all listed spaces.				Coating						
						A120. A123.										
						A124.										
						A125.										
						A129.										
						A131.										
						A131A.										
						A133.										
5508	Batavia High	1993 - Interior	North Music Rooms	2020	Sent to	Paint in good condition. Quantity	Interiors	Interior Finishes	Wall Finishes	Wall Painting and	3-Like To Do	Good	3800	\$2	Square Foot	\$8,550
3300	School		- Classrooms, SW	2020	Maintenance	reflects total SF of all listed spaces.	meeriors	interior rimanes	vvan i mones	Coating	5 Line 10 Bo	3000	3000	72	Square 100t	40,330
	3611001	2009	Mechanical		Widirectionec	E101A.				Couring						
		2003	(2009)			E105.										
			(2003)			E106A.										
						E106B.										
						E106C.										
						E106D.										
						E106E.										
						E106F.										
						E106G.										
						E106H.										
						E106J.										
						E106K.										
						E107A.										
						E107B.										
						E109A.										
						E109C.										
5509	Batavia High	1994 - Interior	BFAC, Fieldhouse BFAC Spaces	2020	Sent to	Paint in good condition. Quantity	Interiors	Interior Finishes	Wall Finishes	Wall Painting and	3-Like To Do	Good	24800	\$2	Square Foot	\$55,800
	School	Wall Finish, Paint			Maintenance	reflects total SF of all listed spaces.				Coating						
		2011				F100 Lobby.										
						F100.										
						F103A.										
						F103B.										
						F106.										
						F107.										
						F109.										
						F109C.										
						F109D.										
						F110.										
						F111.										
						F200B.										
5511	Batavia High		Central Area, Office / Pull-	Out 2020	Sent to	VCT is in Good Condition	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	113	\$12	Square Foot	\$1,356
	School	VCT - 1995	South Entrance		Maintenance	A134A (Trainer Office)										
1	Ì		(1995)								1					

Building Our Future
TOGETHER
BPS
101

57 of 96 Print Date: 2/22/2021









ssessment ID	Campus	Linked Bldg	Addition	Room	Assessmen	t Assessment Status	Description	Building System L1	Building System L2	Building System L3		Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cos
	Datavia High	System	Control Area	Office / Dull Out		-	VCT is in Cood Condition				L4	2 Like To Do	Cood	2201	¢12	Causes Foot	¢27.402
5513	Batavia High School	1827 - Flooring, VCT - 2009	Central Area, South Entrance (1995)	Office / Pull-Out	2020	Sent to Maintenance	VCT is in Good Condition A102C, B100 - Covered mostly by a walk-off mat, B100G, B100H, B100J, B101A, B101B, B101C, B101D, B101E, B102A, D110A, D112,	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	2291	\$12	Square Foot	\$27,492
							D112, D117,										
5520	Batavia High School	1929 - Fixed Equipment,	North Central Classrooms (1969)	Art Rooms	2020	Sent to Maintenance	D211 Room #: A125 A131	Equipment and Furnishings	Furnishings	Fixed Furnishings	Casework	3-Like To Do	Good	27	\$800	Linear Foot	\$21,600
5541	Batavia High	Casework - 1969 1840 - Interior	BFAC, Fieldhouse	Stairs	2020	Sent to	F100 Stairs	Interiors	Interior Finishes	Stair Finishes	Resilient Stair	3-Like To Do	Good	<u> </u>	\$90	Each	\$0
3341	School	Stair Finishes, Resilient - 2011	(2011)	Stalls	2020	Maintenance	1 100 Stalls	interiors	interior rinishes	Stail Fillishes	Finish	3-LIKE TO DO	Good	J	390	Lacii	3 0
5552	Batavia High	1698 - Ceilings,		FACS	2020	Sent to	ACT in good condition.	Interiors	Interior	Suspended Ceiling	Acoustical	3-Like To Do	Good	1180	\$8	Square Foot	\$8,850
	School	Acoustical Suspended Systems - Original				Maintenance	B110		Construction	Construction	Suspended Ceilings					·	
5555	Batavia High School	1743 - Interior Wall Finishes, Wall Base -		FACS	2020	Sent to Maintenance	Wall base in good condition. B110	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	280	\$6	Linear Foot	\$1,680
5556	Batavia High	1951 - Interior		FACS	2020	Sent to	Paint in good condition. Quantity	Interiors	Interior Finishes	Wall Finishes	Wall Painting and	3-Like To Do	Good	1180	\$2	Square Foot	\$2,655
	School	Wall Finish, Paint Original				Maintenance	reflects total SF of all listed spaces. B110				Coating				ľ		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
5557	Batavia High School	1732 - Fixed Equipment, Casework - Original		FACS	2020	Sent to Maintenance	Casework in good condition. B110	Equipment and Furnishings	Furnishings	Fixed Furnishings	Casework	3-Like To Do	Good	57	\$800	Linear Foot	\$45,600
5561	Batavia High School	1898 - Ceilings, Acoustical Suspended Systems - 1969	North Central Classrooms (1969)	Culinary Arts A122	2020	Sent to Maintenance	ACT in good condition. A122	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	1843	\$8	Square Foot	\$13,823
5562	Batavia High School	1909 - Flooring, VCT - 1969	North Central Classrooms (1969)	Culinary Arts A122	2020	Sent to Maintenance	VCT in good condition. A122	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	1843	\$12	Square Foot	\$22,116
5563	Batavia High	1901 - Ceilings,	North Central	Culinary Arts	2020	Sent to	GWB ceiling in good condition.	Interiors	Interior	Suspended Ceiling	Suspended	3-Like To Do	Good	5823	\$1	Square Foot	\$5,823
-	School	Gypsum - 1969	Classrooms (1969)	1 -		Maintenance	A122		Construction	Construction	Plaster and Gypsum Board			-	·	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
5565	Batavia High School	1972 - Interior Wall Finishes, Wall Base - 1969	North Central Classrooms (1969)	Culinary Arts A122	2020	Sent to Maintenance	Wall base in good condition. A122	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	340	\$6	Linear Foot	\$2,040
5566	Batavia High School	1971 - Interior Wall Finish, Paint	North Central Classrooms (1969)	Culinary Arts A122	2020	Sent to Maintenance	Paint in good condition. Quantity reflects total SF of all listed spaces.	Interiors	Interior Finishes		Wall Painting and Coating	3-Like To Do	Good	1850	\$2	Square Foot	\$4,163
		1505					A122										




2020 Facility Condition Assessments





Assessmen	t Campus	Linked Bldg	Addition	Room	Assessment	Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID		System			Year	Status	·	L1	L2	L3	L4	•					
5567	Batavia High	1929 - Fixed	North Central	Culinary Arts	2020	Sent to	Casework in good condition.	Equipment and	Furnishings	Fixed Furnishings	Casework	3-Like To Do	Good	150	\$800	Linear Foot	\$120,000
	School	Equipment,	Classrooms (1969	9) A122		Maintenance		Furnishings									
		Casework - 1969					A122										
5572	Batavia High	1978 - Interior		Building Trades	2020	Sent to	Wall base in good condition.	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	266	\$6	Linear Foot	\$1,596
	School	Wall Finishes,	(2011)	F111		Maintenance											
		Wall Base - 2011					F111										
5573	Batavia High	1994 - Interior	BFAC, Fieldhouse	_	2020	Sent to	Wall and ceiling paint in good	Interiors	Interior Finishes	Wall Finishes	Wall Painting and	3-Like To Do	Good	3723	\$2	Square Foot	\$8,377
	School	Wall Finish, Paint	(2011)	F111		Maintenance	condition. Quantity reflects total SF				Coating						
		2011					of all listed spaces.										
							F111										
5593	Batavia High	1740 - Interiors,		Office / Pull-Out	2020	Sent to	Flooring is in Good Conditoin	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	130	\$10	Square Foot	\$1.300
3333	School	Flooring-LVT -		office / Tall out	2020	Maintenance	B118B (Champion's Room)	III CIIOI3	interior rimanes	Tioornig	incoment rooming	5 LIKE TO DO	Good	130	710	Square root	71,500
	3011001	Original				Manremance	bries (champion s neom)										
5595	Batavia High	1970 - Flooring,		Office / Pull-Out	2020	Sent to	Carpet is in Good Condition	Interiors	Interior Finishes	Flooring	Carpeting	3-Like To Do	Good	10108	\$7	Square Foot	\$65,702
	School	Carpet - Original		,		Maintenance	B108 - Original carpet but overall in								·		. ,
							good condition,										
							B118, B118F, B118G, B118H, B122,										
							B122B, B122C, B122E - Carpet is the										
							original 2x2 tile but it is above										
							average condition throughout.										
							B123										
5597	Batavia High	1717 - Flooring,	North Central	Office / Pull-Out		Sent to	Carpet is in Good Condition	Interiors	Interior Finishes	Flooring	Carpeting	3-Like To Do	Good	921	\$7	Square Foot	\$5,987
5500	School	Carpet - 1971	Classrooms (1969			Maintenance	Council in its Cound Coundition	Later of a sec	to to also electrica	Eleccione	C	2 Libe Te De	Caral	2405	\$7	C	Ć4.4.202
5599	Batavia High School	2036 - Flooring, Carpet - 1995	Central Area, South Entrance	Office / Pull-Out	2020	Sent to Maintenance	Carpet is in Good Condition A101A,	Interiors	Interior Finishes	Flooring	Carpeting	3-Like To Do	Good	2185	\$7	Square Foot	\$14,203
	SCHOOL	Entry	(1995)			Maintenance	A101A, A101B,										
		Littiy	(1993)				B100M - Carpet is the same as 2009										
							addition although this area was a										
							part of the 1995 space										
5600	Batavia High	2037 - Flooring,	South Admin	Office / Pull-Out	2020	Sent to	Carpet is in Good Condition	Interiors	Interior Finishes	Flooring	Carpeting	3-Like To Do	Good	1079	\$7	Square Foot	\$7,014
	School	Carpet - 2009	Addition (2009)			Maintenance	B100 - Walk-off carpet,										
							B100B,										
							B100C,										
							B100D,										
							B100E,										
							B100F,										
	1						B100K										
5602	Batavia High	2029 - Flooring,	,	Office / Pull-Out		Sent to	Carpet is in Good Condition	Interiors	Interior Finishes	Flooring	Carpeting	3-Like To Do	Good	170	\$7	Square Foot	\$1,105
FCFC	School	Carpet - 2011	(2011)	Office / Pull Oct		Maintenance	F102 (Auditorium Manager)	lata di a da	Interior State	Mall Fig		2 Libe T- D-	Cand	175	¢c.	Linnan Front	Ć1 050
5656	Batavia High School	1972 - Interior	North Central	Office / Pull-Out		Sent to	Wall base is in Good condition A123A,	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	175	\$6	Linear Foot	\$1,050
	SC11001	Wall Finishes, Wall Base - 1969	Classrooms (1969	7)		Maintenance	A123A, A125A,										
		vvali base - 1909					A129A										
<u> </u>							MIZJA	1	1		1				1	1	1










Assessmen	t Campus	Linked Bldg	Addition	Room	Assessmen	t Assessment	Description	Ruilding System	Ruilding System	Building System	Ruilding System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
	Campus		Addition	KOOIII			Description					Priority	racinty Condition	Quantity	Onit Cost	Offic Of Measure	Estimated Cost
1D 5657	Batavia High School	System 1743 - Interior Wall Finishes, Wall Base - Original		Office / Pull-Out	Year 2020	Sent to Maintenance	Wall base is in Good condition A104B, A106, A108B, B107A, B108, B114, B114A, B118B, B118B, B118B, B118B, B118B, B119D, B118F, B119A, B119B, B119C, B119D, B122, B122, B122, B122A, B122B, B122B, B122C, B122E, B123,	Interiors	L2 Interior Finishes	L3 Wall Finishes	14	3-Like To Do	Good	2500	\$6	Linear Foot	\$15,000
							B123,										
FCFO	Data da Hisb	1075 Interior	Combuel Area	Office / Pull-Out	2020	Combine	B124.	lataria ra	Interior Finishes	Mall Finish on		2 Libe Te De	Cand	375	¢c.	LinconFoot	ć2 250
5659	Batavia High School	Wall Finishes,	Central Area, South Entrance (1995)	Office / Pull-Out	2020	Sent to Maintenance	Wall base is in Good condition A101A, A101B, A134A, B100M	Interiors	Interior Finishes	wall Finisnes		3-Like To Do	Good	3/5	\$6	Linear Foot	\$2,250
5661	Batavia High School		South Admin Addition (2009)	Office / Pull-Out	2020	Sent to Maintenance	Wall base is in Good condition B100, B100B, B100C, B100D, B100F, B100F, B100G, B100H, B100J, B100I, B101A, B101A, B101B, B101C, B101D, B101C, B101D, B101E, B101C, B101A, B101A,	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	1200	\$6	Linear Foot	\$7,200









Accoccmon	Campus	Linked Bldg	Addition	Room	Assessment	Assessment	Description	Building Systom	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Massura	Estimated Cost
Assessment ID	Campus	System	Addition	Koom	Year	Status	Description	L1	L2	L3	L4	Priority	racility Condition	Quantity	Unit Cost	Onit Of Measure	Estimated Cost
5663	Batavia High	1978 - Interior	BFAC. Fieldhouse	Office / Pull-Out	2020	Sent to	Wall base is in Good condition	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	120	\$6	Linear Foot	\$720
3000	School	Wall Finishes,	(2011)	oee y . a eac	2020	Maintenance	F102 (Auditorium Manager).					5 Line 10 De	3334		70		7.20
		Wall Base - 2011	,				F111 (Building Trades Office).										
5745	Batavia High	1698 - Ceilings,		Corridor	2020	Sent to	ACT in good condition.	Interiors	Interior	Suspended Ceiling	g Acoustical	3-Like To Do	Good	5700	\$8	Square Foot	\$42,750
	School	Acoustical				Maintenance			Construction	Construction	Suspended						
		Suspended					Corridor north of main office.				Ceilings						
		Systems - Original					B-CORRIDOR BETWEEN MAIN										
							OFFICE AND STUDENT SERVICES.										
5751	Batavia High	1805 - Ceilings,	North	Corridor	2020	Sent to	ACT ceiling in good condition.	Interiors	Interior	Suspended Ceiling	-	3-Like To Do	Good	10100	\$8	Square Foot	\$75,750
	School	Acoustical	Classrooms, SW			Maintenance	D-wing corridors level 1.		Construction	Construction	Suspended						
		Suspended Systems - 2009	Mechanical (2009)				PRACTICE CORRIDOR.				Ceilings						
5753	Batavia High	1810 - Ceilings,	North	Corridor	2020	Sent to	GWB ceiling in good condition	Interiors	Interior	Suspended Ceiling	Suspended	3-Like To Do	Good	2200	\$1	Square Foot	\$2,200
3733	School	Gypsum - 2009	Classrooms, SW	Corridor	2020	Maintenance	D-wing corridors level 1 (soffits)	interiors	Construction	Construction	Plaster and	3-LIKE TO DO	Good	2200	71	Square root	\$2,200
	30.1001	C, psu 2005	Mechanical			ae	E CORRIDOR			001100110011011	Gypsum Board						
5754	Batavia High	1827 - Flooring,	North	Corridor	2020	Sent to	VCT flooring in good condition	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	5700	\$12	Square Foot	\$68,400
	School	VCT - 2009	Classrooms, SW			Maintenance	PRACTICE CORRIDOR										
			Mechanical				E CORRIDOR										
5759	Batavia High	1977 - Interior	North	Corridor	2020	Sent to	Wall base in good condition.	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	1000	\$6	Linear Foot	\$6,000
	School	Wall Finishes,	Classrooms, SW			Maintenance	E CORRIDOR.										
		Wall Base - 2009	Mechanical				PRACTICE CORRIDOR.										
5760	Batavia High	1993 - Interior	North	Corridor	2020	Sent to	Paint in good condition. Quantity	Interiors	Interior Finishes	Wall Finishes	Wall Painting and	3-Like To Do	Good	350	\$2	Square Foot	\$788
	School	Wall Finish, Paint - 2009	Classrooms, SW			Maintenance	reflects total SF of all listed spaces. PRACTICE CORRIDOR				Coating						
5764	Batavia High		Mechanical North	Corridor	2020	Sent to		Equipment and	Equipment	Institutional	Educational and	3-Like To Do	Good	0	\$200	Each	\$0
3704	School	3394 - Equipment, Lockers - 2009	Classrooms, SW	Corridor	2020	Maintenance	Lockers in good condition. See assessment item #7965 for quantity		Equipment	Equipment	Scientific	3-LIKE 10 D0	Good	U	\$200	EdCII	ŞU
	3011001	LOCKETS - 2005	Mechanical			Wallitellance	and pricing.	i uriiisiiiigs		Equipment	Equipment						
			(2009)				D-wing corridors level 1.										
			,				E CORRIDOR										
5773	Batavia High	1805 - Ceilings,	North	Stair	2020	Sent to	Act ceiling in good condition.	Interiors	Interior	Suspended Ceiling	g Acoustical	3-Like To Do	Good	660	\$8	Square Foot	\$4,950
	School	Acoustical	Classrooms, SW			Maintenance	Stair by d110 level 1.		Construction	Construction	Suspended						
		Suspended	Mechanical				Stair by d110 level 2				Ceilings						
		Systems - 2009	(2009)														
5774	Batavia High	1827 - Flooring,	North	Stair	2020	Sent to	VCT flooring in good condition.	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	250	\$12	Square Foot	\$3,000
	School	VCT - 2009	Classrooms, SW			Maintenance	Stair by d110 level 1. Stair by d110 level 2.										
5778	Batavia High	1977 - Interior	Mechanical North	Stair	2020	Sent to	Wall base in good condition	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	100	\$6	Linear Foot	\$600
3776	School	Wall Finishes,	Classrooms, SW	Stan	2020	Maintenance	Stair by d110 level 1	interiors	interior rinishes	vvaii i iiiisiies		3-LIKE TO DO	Good	100	70	Linear root	3000
	3611001	Wall Base - 2009				- Iviairie	Stair by d110 level 2										
5782	Batavia High	1839 - Interior	North	Stair	2020	Sent to	stairs treads are risers in good	Interiors	Interior Finishes	Stair Finishes	Resilient Stair	3-Like To Do	Good	0	\$90	Each	\$0
	School	Stair Finishes,	Classrooms, SW			Maintenance	condition.				Finish						
		Resilient - 2009	Mechanical				Stair by d110 level 1.										
			(2009)				Stair by d110 level 2.										
5788	Batavia High	1805 - Ceilings,	North	Vestibule	2020	Sent to	ACT ceiling in good condition.	Interiors	Interior	Suspended Ceiling		3-Like To Do	Good	90	\$8	Square Foot	\$675
	School	Acoustical	Classrooms, SW			Maintenance	D-wing middle vestibule		Construction	Construction	Suspended						
		Suspended	Mechanical								Ceilings						
F70 <i>C</i>	Data da Hilab	Systems - 2009	(2009)	Ci-l	2020	C 1 1 -	ACT as the plants and a solution	Laborita na	Late of an	Commented Calling	- 4	2 Libe Te De	Caral	CE0.	ćo	Carrage Front	Ć4 025
5796	Batavia High	1806 - Ceilings,	South Admin Addition (2009)	Corridor	2020	Sent to Maintenance	ACT ceiling in good condition 2009 office	Interiors	Interior	Suspended Ceiling	g Acoustical Suspended	3-Like To Do	Good	658	\$8	Square Foot	\$4,935
	School	Acoustical Suspended	Audition (2009)			iviaiiiteriance	2009 Office		Construction	Construction	Ceilings						
		Systems - 2009									Cennigs						
		Admin															
5797	Batavia High	2037 - Flooring,	South Admin	Corridor	2020	Sent to	Carpet flooring in good condition	Interiors	Interior Finishes	Flooring	Carpeting	3-Like To Do	Good	975	\$7	Square Foot	\$6,338
	School	Carpet - 2009	Addition (2009)			Maintenance	(Slightly worn 2x2 Carpet tiles			_							
							throughout)										
	1	1		I			2009 office		1	1		1	i l		1	1	I.









sessment	Campus	Linked Bldg	Addition	Room	Assessment	Assessment	Description	Building System				Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cos
ID 5822	Batavia High School	System 2116 - Ceilings, Acoustical Suspended Systems - 1995	East 2-Story Classrooms (1995)	Vestibule	Year 2020	Sent to Maintenance	ACT ceiling in good condition C-wing south vestibule C-wing south center vest.	L1 Interiors	Interior Construction	L3 Suspended Ceiling Construction	L4 Acoustical Suspended Ceilings	3-Like To Do	Good	380	\$8	Square Foot	\$2,850
5830	Batavia High School	1975 - Interior Wall Finishes, Wall Base - 1995	Classrooms (1995)	Vestibule		Sent to Maintenance	Wall base in good condition. C-wing south vestibule	Interiors	Interior Finishes	Wall Finishes		3-Like To Do		16	\$6	Linear Foot	\$96
5834	Batavia High School	1991 - Interior Wall Finish, Paint 1995	East 2-Story - Classrooms (1995)	Vestibule	2020	Sent to Maintenance	Wall paint in good condition. Quantity reflects total SF of all listed spaces. C-wing south vestibule	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	d 3-Like To Do	Good	90	\$2	Square Foot	\$203
5850	Batavia High School	1899 - Ceilings, Acoustical Suspended Systems - 1995	East 2-Story Classrooms (1995)	Stair	2020	Sent to Maintenance	ACT ceiling in good condition Stair by C101 level 1 Stair by c122 level 1	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	1355	\$8	Square Foot	\$10,163
5860	Batavia High School	1975 - Interior Wall Finishes, Wall Base - 1995	East 2-Story Classrooms (1995)	Stair	2020	Sent to Maintenance	Wall base in good condition. Stair by C101 level 1. Stair by C107 level 1. Stair by c122 level 1.	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	220	\$6	Linear Foot	\$1,320
5863	Batavia High School	1837 - Interior Stair Finishes, Resilient - 1995	East 2-Story S Classrooms (1995)	Stair	2020	Sent to Maintenance	Treads and risers in good condition. Stair by C101 level 1. Stair by c122 level 1.	Interiors	Interior Finishes	Stair Finishes	Resilient Stair Finish	3-Like To Do	Good	0	\$90	Each	\$0
5881	Batavia High School	1805 - Ceilings, Acoustical Suspended Systems - 2009	North Classrooms, SW Mechanical (2009)	Corridor	2020	Sent to Maintenance	ACT ceiling in good condition. N/S Corridor, near A131 . E/W Corridor, near A132.	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	2500	\$8	Square Foot	\$18,750
5882	Batavia High School	1900 - Ceilings, Gypsum - 1995		Corridor	2020	Sent to Maintenance	GWB ceiling in good condition C-wing south corridor, level 1	Interiors	Interior Construction	Suspended Ceiling Construction	Suspended Plaster and Gypsum Board	3-Like To Do	Good	1400	\$1	Square Foot	\$1,400
5885	Batavia High School	1827 - Flooring, VCT - 2009	North Classrooms, SW Mechanical (2009)	Corridor	2020	Sent to Maintenance	VCT flooring in good condition. N/S Corridor, near A131. E/W Corridor, near A132.	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	2500	\$12	Square Foot	\$30,000
5891	Batavia High School	1977 - Interior Wall Finishes, Wall Base - 2009	North Classrooms, SW Mechanical	Corridor	2020	Sent to Maintenance	Wall base in good condition. N/S Corridor, near A131. E/W Corridor, near A132.	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	525	\$6	Linear Foot	\$3,150
5898	Batavia High School	3395 - Equipment, Lockers - 1995	Classrooms (1995)	Corridor	2020	Sent to Maintenance	Lockers in good condition. See assessment item #7965 for quantity and pricing. C-wing south corridor, level 1 (some fair, most good, all could use new paint, few dented).		Equipment	Institutional Equipment	Educational and Scientific Equipment	3-Like To Do	Good	0	\$200	Each	\$0
5911	Batavia High School	1975 - Interior Wall Finishes, Wall Base - 1995	East 2-Story Classrooms (1995)	Corridor	2020	Sent to Maintenance	Wall base in good condition C-Wing 2nd Floor Corridor	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	850	\$6	Linear Foot	\$5,100
5914	Batavia High School	3395 - Equipment, Lockers - 1995	East 2-Story Classrooms (1995)	Corridor	2020	Sent to Maintenance	Lockers in good condition. See assessment item #7965 for quantity and pricing. C-Wing 2nd Floor Corridor	Equipment and Furnishings	Equipment	Institutional Equipment	Educational and Scientific Equipment	3-Like To Do	Good	0	\$200	Each	\$0
5936	Batavia High School	1807 - Ceilings, Acoustical Suspended Systems - 2011	BFAC, Fieldhouse (2011)	Stair/Corridor	2020	Sent to Maintenance	ACT ceiling in good condition Stair 4	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	343	\$8	Square Foot	\$2,573
5937	Batavia High School	2029 - Flooring, Carpet - 2011	BFAC, Fieldhouse (2011)	Stair/Corridor	2020	Sent to Maintenance	Carpet flooring in good condition Stair 4	Interiors	Interior Finishes	Flooring	Carpeting	3-Like To Do	Good	343	\$7	Square Foot	\$2,230









Assessmen	t Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
5939	Batavia High School	1978 - Interior Wall Finishes, Wall Base - 2011	BFAC, Fieldhouse (2011)	Stair/Corridor		Sent to Maintenance	Wall base in good condition Stair 4	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	50	\$6	Linear Foot	\$300
5940	Batavia High School	1994 - Interior Wall Finish, Paint 2011	BFAC, Fieldhouse - (2011)	Stair/Corridor		Sent to Maintenance	Wall paint in good condition. Quantity reflects total SF of all listed spaces. Stair 4	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	3-Like To Do	Good	500	\$2	Square Foot	\$1,125
5942	Batavia High School	3398 - Interior Stair Finishes, Carpet - 2011	BFAC, Fieldhouse (2011)	Stair/Corridor	2020	Sent to Maintenance	stairs treads and risers (CARPET) in good condition Stair 4	Interiors	Interior Finishes	Stair Finishes	Carpeted Stair Finish	3-Like To Do	Good	100	\$7	Square Foot	\$650
5952	Batavia High School	1807 - Ceilings, Acoustical Suspended Systems - 2011	BFAC, Fieldhouse (2011)	Corridor		Sent to Maintenance	ACT ceiling in good condition Field house corridor CORRIDOR BETWEEN BFAC/FIELD HOUSE NORTH CORRIDOR BFAC CORRIDOR ADJACENT TO MECH	Interiors	Interior Construction		Acoustical Suspended Ceilings	3-Like To Do	Good	10427	\$8	Square Foot	\$78,203
5956	Batavia High School	1811 - Ceilings, Gypsum - 2011	BFAC, Fieldhouse (2011)	Corridor	2020	Sent to Maintenance	GWB ceiling in good condition CORRIDOR ADJACENT TO MECH	Interiors	Interior Construction	Suspended Ceiling Construction	Suspended Plaster and Gypsum Board	3-Like To Do	Good	3980	\$1	Square Foot	\$3,980
5958	Batavia High School	1978 - Interior Wall Finishes, Wall Base - 2011	BFAC, Fieldhouse (2011)	Corridor		Sent to Maintenance	Wall base in good condition. Field house corridor. CORRIDOR BETWEEN BFAC/FIELD HOUSE. NORTH CORRIDOR BFAC. CORRIDOR ADJACENT TO MECH.	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	1100	\$6	Linear Foot	\$6,600
5959	Batavia High School	1994 - Interior Wall Finish, Paint 2011	BFAC, Fieldhouse - (2011)	Corridor	2020	Sent to Maintenance	Wall paint in good condition. Quantity reflects total SF of all listed spaces. NORTH CORRIDOR BFAC	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	3-Like To Do	Good	1500	\$2	Square Foot	\$3,375
5968	Batavia High School	1898 - Ceilings, Acoustical Suspended Systems - 1969	North Central Classrooms (1969)	Corridor		Sent to Maintenance	ACT ceiling in good condition N/S Corridor	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	142	\$8	Square Foot	\$1,065
5969	Batavia High School	1909 - Flooring, VCT - 1969	North Central Classrooms (1969)	Corridor	2020	Sent to Maintenance	VCT flooring in good condition N/S Corridor	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	142	\$12	Square Foot	\$1,704
5971	Batavia High School	1972 - Interior Wall Finishes, Wall Base - 1969	` '	Corridor		Sent to Maintenance	Wall base in good condition N/S Corridor	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	275	\$6	Linear Foot	\$1,650
5972	Batavia High School	1971 - Interior Wall Finish, Paint 1969	North Central - Classrooms (1969)	Corridor		Sent to Maintenance	Wall paint in good condition. Quantity reflects total SF of all listed spaces. N/S Corridor		Interior Finishes	Wall Finishes	Wall Painting and Coating	3-Like To Do	Good	900	\$2	Square Foot	\$2,025
5987	Batavia High School	1700 - Ceilings, Gypsum - Original		Corridor		Sent to Maintenance	GWB ceiling in good condition. Corridor north of main office	Interiors	Interior Construction		Suspended Plaster and Gypsum Board	3-Like To Do	Good	2700	\$1	Square Foot	\$2,700
5989	Batavia High School	1704 - Flooring, VCT - Original		Corridor		Sent to Maintenance	VCT flooring in good condition. B-CORRIDOR NORTH OF FAC CENTER (TEAL LOCKERS)		Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	1100	\$12	Square Foot	\$13,200
5992	Batavia High School	1743 - Interior Wall Finishes, Wall Base - Original		Corridor		Sent to Maintenance	Wall base in good condition. B-CORRIDOR NORTH OF FAC CENTER (TEAL LOCKERS) (MISMATCHED BASE.)		Interior Finishes	Wall Finishes		3-Like To Do	Good	225	\$6	Linear Foot	\$1,350









Assessmen	t Campus	Linked Bldg	Addition	Room	Assessmen	Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cos
ID		System			Year	Status	·	L1	L2	L3	L4		•	, ,			
5993	Batavia High School	1951 - Interior Wall Finish, Paint - Original		Corridor	2020	Sent to Maintenance	Wall paint in good condition. Quantity reflects total SF of all listed spaces. B-CORRIDOR. B-CORRIDOR NORTH OF FACULTY CENTER (TEAL LOCKERS).	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	3-Like To Do	Good	2800	\$2	Square Foot	\$6,300
5997	Batavia High School	3393 - Equipment, Lockers - Original		Corridor	2020	Sent to Maintenance	Lockers in good condition. See assessment item #7965 for quantity and pricing. B-CORRIDOR NORTH OF FAC CENTER (TEAL LOCKERS)		Equipment	Institutional Equipment	Educational and Scientific Equipment	3-Like To Do	Good	0	\$200	Each	\$0
6014	Batavia High School	1698 - Ceilings, Acoustical Suspended Systems - Original		Server room	2020	Sent to Maintenance	ACT ceiling is in good condition B105	Interiors	Interior Construction	Suspended Ceiling Construction	g Acoustical Suspended Ceilings	3-Like To Do	Good	672	\$8	Square Foot	\$5,040
6017	Batavia High School	1743 - Interior Wall Finishes, Wall Base -		Server room	2020	Sent to Maintenance	Wall base is in a good condition. B105	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	106	\$6	Linear Foot	\$636
6018	Batavia High School	1951 - Interior Wall Finish, Paint - Original		Server room	2020	Sent to Maintenance	Wall paint is in a good condition. Quantity reflects total SF of all listed spaces. B105	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	3-Like To Do	Good	672	\$2	Square Foot	\$1,512
6025	Batavia High School	1698 - Ceilings, Acoustical Suspended Systems - Original		Fitness Center	2020	Sent to Maintenance	ACT ceiling in good condition A103	Interiors	Interior Construction	Suspended Ceiling Construction	g Acoustical Suspended Ceilings	3-Like To Do	Good	3906	\$8	Square Foot	\$29,295
6026	Batavia High School	1704 - Flooring, VCT - Original		Fitness Center	2020	Sent to Maintenance	VCT flooring in good condition A103	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	3906	\$12	Square Foot	\$46,872
6028	Batavia High School	1743 - Interior Wall Finishes, Wall Base -		Fitness Center	2020	Sent to Maintenance	Wall base in good condition. A103	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	350	\$6	Linear Foot	\$2,100
6029	Batavia High School	1951 - Interior Wall Finish, Paint - Original		Fitness Center	2020	Sent to Maintenance	Wall paint in good condition. Quantity reflects total SF of all listed spaces. A103	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	3-Like To Do	Good	3900	\$2	Square Foot	\$8,775
6037	Batavia High School	1698 - Ceilings, Acoustical Suspended Systems - Original		Locker Room	2020	Sent to Maintenance	ACT ceiling in good condition A105AStaff Locker Room	Interiors	Interior Construction	Suspended Ceiling Construction	g Acoustical Suspended Ceilings	3-Like To Do	Good	255	\$8	Square Foot	\$1,913
6038	Batavia High School	1700 - Ceilings, Gypsum - Original		Locker Room	2020	Sent to Maintenance	GWB ceiling in good condition A104W Locker Room1670 sf A108Men's Locker Room 1238 sf	Interiors	Interior Construction	Suspended Ceiling Construction	Suspended Plaster and Gypsum Board	3-Like To Do	Good	2908	\$1	Square Foot	\$2,908
6042	Batavia High School	1743 - Interior Wall Finishes, Wall Base - Original		Locker Room	2020	Sent to Maintenance	wall base in good condition. A104W Locker Room. A105AStaff Locker Room. A108Men's Locker Room.	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	350	\$6	Linear Foot	\$2,100
6046	Batavia High School	3393 - Equipment, Lockers - Original		Locker Room	2020	Sent to Maintenance	Lockers in good condition. Verify quantity with District. A104W Locker Room. A105AStaff Locker Room. A108Men's Locker Room.	Equipment and Furnishings	Equipment	Institutional Equipment	Educational and Scientific Equipment	3-Like To Do	Good	0	\$200	Each	\$0
6055	Batavia High School		Central Area, South Entrance (1995)	Cafeteria	2020	Sent to Maintenance	ACT ceiling in good condition A100	Interiors	Interior Construction	Suspended Ceiling Construction	g Acoustical Suspended Ceilings	3-Like To Do	Good	9794	\$8	Square Foot	\$73,455

Building Our Future TOGETHER

BPS
101










ssessment	Campus	Linked Bldg	Addition	Room	Assessment	Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cos
ID 6057	Batavia High	System 1825 - Flooring,	Central Area,	Cafeteria	Year 2020	Status Sent to	VCT flooring in good condition	L1 Interiors	L2 Interior Finishes	L3 Flooring	L4 Resilient Flooring	3-Like To Do	Good	9794	\$12	Square Foot	\$117,528
	School	VCT - 1995 Entry	South Entrance (1995)			Maintenance	A100										
6063	Batavia High School	1804 - Ceilings, Acoustical Suspended Systems - 1995 Entry	Central Area, South Entrance (1995)	School store	2020	Sent to Maintenance	ACT ceiling in good condition A100A	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	1995	\$8	Square Foot	\$14,963
6067	Batavia High School	1974 - Interior Wall Finishes, Wall Base - 1995	Central Area, South Entrance (1995)	School store	2020	Sent to Maintenance	Wall base in good condition. A100A	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	88	\$6	Linear Foot	\$528
6068	Batavia High School	1990 - Interior Wall Finish, Paint - 1995 Entry	Central Area, South Entrance (1995)	School store	2020	Sent to Maintenance	Wall paint in good condition. Quantity reflects total SF of all listed spaces. A100A	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	3-Like To Do	Good	375	\$2	Square Foot	\$844
6071	Batavia High School		North Classrooms, SW Mechanical	Training	2020	Sent to Maintenance	ACT ceiling in good condition A134	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	535	\$8	Square Foot	\$4,013
6072	Batavia High School	1827 - Flooring, VCT - 2009	Central Area, South Entrance (1995)	Training	2020	Sent to Maintenance	VCT flooring in good condition A134	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	535	\$12	Square Foot	\$6,420
6074	Batavia High School	1977 - Interior Wall Finishes, Wall Base - 2009	North Classrooms, SW Mechanical	Training	2020	Sent to Maintenance	Wall base in good condition. A134	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	93	\$6	Linear Foot	\$558
6075	Batavia High School	1993 - Interior Wall Finish, Paint - 2009	North Classrooms, SW Mechanical (2009)	Training	2020	Sent to Maintenance	Wall paint in good condition. Quantity reflects total SF of all listed spaces. A134	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	3-Like To Do	Good	535	\$2	Square Foot	\$1,204
6079	Batavia High School	1808 - Ceilings, Gypsum - 1995 Entry	Central Area, South Entrance (1995)	W locker room	2020	Sent to Maintenance	GWB ceiling in good condition A106	Interiors	Interior Construction	Suspended Ceiling Construction	Suspended Plaster and Gypsum Board	3-Like To Do	Good	2706	\$1	Square Foot	\$2,706
6081	Batavia High School	1974 - Interior Wall Finishes, Wall Base - 1995	Central Area, South Entrance (1995)	W locker room	2020	Sent to Maintenance	Wall Base in good condition. A106	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	260	\$6	Linear Foot	\$1,560
6082	Batavia High School	1990 - Interior Wall Finish, Paint - 1995 Entry	Central Area, South Entrance (1995)	W locker room	2020	Sent to Maintenance	Wall paint in good condition. Quantity reflects total SF of all listed spaces. A106	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	3-Like To Do	Good	2700	\$2	Square Foot	\$6,075
6084	Batavia High School	3397 - Equipment, Lockers - 1995 Entry	Central Area, South Entrance (1995)	W locker room	2020	Sent to Maintenance		Equipment and Furnishings	Equipment	Institutional Equipment	Educational and Scientific Equipment	3-Like To Do	Good	0	\$200	Each	\$0
6091	Batavia High School	1974 - Interior Wall Finishes, Wall Base - 1995	Central Area, South Entrance (1995)	Wrestling	2020	Sent to Maintenance	Wall base in good condition A107A	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	325	\$6	Linear Foot	\$1,950
6092	Batavia High School	1990 - Interior Wall Finish, Paint - 1995 Entry	Central Area, South Entrance (1995)	Wrestling	2020	Sent to Maintenance	Wall paint in good condition. Quantity reflects total SF of all listed spaces. A107A	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	3-Like To Do	Good	5950	\$2	Square Foot	\$13,388
6099	Batavia High School	1977 - Interior Wall Finishes, Wall Base - 2009	North Classrooms, SW Mechanical	Dance Gym	2020	Sent to Maintenance	Wall base in good condition A132	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	175	\$6	Linear Foot	\$1,050
6100	Batavia High School	1993 - Interior Wall Finish, Paint - 2009	North Classrooms, SW Mechanical (2009)	Dance Gym	2020	Sent to Maintenance	Wall paint in good condition. Quantity reflects total SF of all listed spaces. A132	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	3-Like To Do	Good	1540	\$2	Square Foot	\$3,465









A	Ca	Linked Bldg	Addition Dr	A a c = = = = = =	Λοοο	Description	Duilding Cost	Duilding Coate	Duilding Cost	Duilding Costs	Dul a ultu	Facility Canadist	O	Heir Carr	Unit Of Measure	Fotimeted C
Assessment	Campus	J	Addition Room	Assessmen		Description			Building System		Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID C111	Data da High	System	BFAC, Fieldhouse Field House	Year	Status	Mall bass in as ad soudition	L1	L2	L3 Wall Finishes	L4	3-Like To Do	Good	950	\$6	Linnau Fant	ĆE 700
6111	Batavia High	1978 - Interior	,	2020	Sent to	Wall base in good condition.	Interiors	Interior Finishes	wall Finishes		3-LIKE 10 DO	G000	950	\$6	Linear Foot	\$5,700
	School	Wall Finishes,	(2011)		Maintenance	F112										
C422	Data da Ulab	Wall Base - 2011	DEAC Fieldhause Chanasa	2020	C t - t -	MALL have to see all and distant	lataria.	Intenies Bioteless	Marill Etailahaa		2 L'I T- D-	Carad		¢c.	Lineau Frank	¢220
6123	Batavia High	1978 - Interior	BFAC, Fieldhouse Storage	2020	Sent to	Wall base in good condition.	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	55	\$6	Linear Foot	\$330
	School	Wall Finishes,	(2011)		Maintenance	F112BSTORAGE.										
		Wall Base - 2011				F112CSTORAGE										
6124	Batavia High	1994 - Interior	BFAC, Fieldhouse Storage	2020	Sent to	Wall paint in good condition.	Interiors	Interior Finishes	Wall Finishes	Wall Painting and	3-Like To Do	Good	250	\$2	Square Foot	\$563
	School	-	(2011)		Maintenance	Quantity reflects total SF of all listed				Coating						
		2011				spaces.										
						F112BSTORAGE.										
						F112CSTORAGE.										
6153	Batavia High	3394 - Equipment,		2020	Sent to	Locker in good condition. See	Equipment and	Equipment	Institutional	Educational and	3-Like To Do	Good	0	\$200	Each	\$0
	School	Lockers - 2009	Classrooms, SW		Maintenance	assessment item #7965 for quantity	Furnishings		Equipment	Scientific						
			Mechanical			and pricing.				Equipment						
			(2009)													
						N/S corridor near A131										
6154	Batavia High	1910 - Flooring,	East 2-Story Toilet	2020	Sent to	VCT flooring in good condition.	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	41	\$12	Square Foot	\$492
	School	VCT - 1995	Classrooms (1995)		Maintenance	Girls by c119										
6186	Batavia High	1723 - HVAC,		2020	Sent to	Per Capital Projects Plan - AHU 3, 4,	Services	Heating,	Ventilation	Supply Air	3-Like To Do	Good	1	\$675,000	Lump Sum	\$675,000
	School	Ventilation-AHU			Maintenance	5, 6, & 7 in good condition		Ventilation, and								
								Air Conditioning								
								(HVAC)								
6193	Batavia High	1965 - Flooring,	BFAC, Fieldhouse Fieldhouse	2020	Sent to	Per Capital Projects Plan - replace	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	51047	\$15	Square Foot	\$765,705
	School	<u> </u>	(2011)		Maintenance	fieldhouse rubber flooring in 2023.				0				, -	1	, , , , ,
		2011	(
6231	Batavia High	1724 - HVAC,		2020	Sent to	Per Capital Projects Plan -	Services	Heating,	Cooling Systems	Central Cooling	3-Like To Do	Good	2	\$80,000	Each	\$160,000
0231	School	Cooling-Chiller		2020	Maintenance	Chiller #1 overhaul in 2016	Services	Ventilation, and	cooming systems	central cooming	5 Like 10 Do	Good	-	700,000	Lacii	7100,000
	3011001	cooming crimer			Wantenance	(scheduled replacement in 2026)		Air Conditioning								
						Chiller #2 overhaul in 2018		(HVAC)								
						(scheduled replacement in 2028)		(IIVAC)								
7908	Batavia High	02EE Fauinment	BFAC, Fieldhouse BFAC Stage	2020	Sent to	, , ,	Fauinment and	Fauinment	Entertainment	Theater and Stage	2 Like To Do	Fair	1	\$80,000	Lump Sum	\$80,000
7908			_	2020		Needs replacement in 2025 per	Equipment and	Equipment			3-LIKE TO DO	raii	1	\$80,000	Lump Sum	\$80,000
	School	Theater Drapes	(2011)		Maintenance	BFAC replacement schedule.	Furnishings		and Recreational	Equipment						
									Equipment					4		4.0.000
7914	Batavia High		BFAC, Fieldhouse BFAC Stage	2020	Sent to	Original. Received maintenance in	Special	Special	Special Facility		3-Like To Do	Good	1	\$10,000	Each	\$10,000
	School	Theater Handline	(2011)		Maintenance	2017. Needs replacement in 2025	Construction and	Construction	Components							
		Ropes				per replacement schedule.	Demolition									
7917	Batavia High	9264 - LED PAR	BFAC, Fieldhouse BFAC Stage	2020	Sent to	Purchased in 2014. Needs	Services	Electrical	Lighting	Lighting Fixtures	3-Like To Do	Good	1	\$25,000	Each	\$25,000
	School		(2011)		Maintenance	replacement in 2022 per										
						replacement schedule.										
7918	Batavia High	9265 - LED R2	BFAC, Fieldhouse BFAC Stage	2020	Sent to	Purchased in 2017-2018. Needs	Services	Electrical	Lighting	Lighting Fixtures	3-Like To Do	Good	1	\$25,000	Each	\$25,000
	School		(2011)		Maintenance	replacement in 2025 per										
						replacement schedule.										
7922	Batavia High	9269 - Equipment,	BFAC, Fieldhouse BFAC Stage	2020	Sent to	Purchased between 2017-2019.	Equipment and	Equipment	Entertainment	Theater and Stage	3-Like To Do	Good	1	\$32,500	Each	\$32,500
	School	Digital Theater	(2011)		Maintenance	Needs replacement in 2024 per	Furnishings		and Recreational	Equipment						
		Signage				replacement schedule.			Equipment							
7926	Batavia High	1976 - Interior	South Admin Toilet	2020	Sent to	Ceramic tile base is in good	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	64	\$6	Linear Foot	\$384
	School	Wall Finishes,	Addition (2009)		Maintenance	condition - grout is slightly dirty at										
		Wall Base - 2009				coved transition to floor										
		Admin				Mens in Office										
						Womens in Office										
7927	Batavia High	1965 - Flooring,	BFAC, Fieldhouse Corridor	2020	Sent to	Rubber flooring in good condition.	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	3100	\$12	Square Foot	\$37,200
	School	Interior - Rubber -			Maintenance	a see a see										,,
	3311001	2011	(/		amtenance	Corridor east of Fieldhouse										
	1	2011				COTTIGOT COST OF FICIALIDUSE	1	1		1	1	1	l .	i i	1	

Building Our Future TOGETHER

BPS
101









ssessment	Campus	Linked Bldg	Addition	Room	Assessmen	t Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID	·	System			Year	Status	·	L1	L2	L3	L4	•		•			
7928	Batavia High School	1977 - Interior Wall Finishes, Wall Base - 2009	North Classrooms, SW Mechanical (2009)	Office / Pull-Out	2020	Sent to Maintenance	Wall base is in Good condition A102C, D110A, D112, D117,	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	180	\$6	Linear Foot	\$1,080
7929	Batavia High	1977 - Interior	North	Office / Pull-Out	2020	Sent to	D211 Wall base is in Good condition.	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	86	\$6	Linear Foot	\$516
7929	School	Wall Finishes, Wall Base - 2009	Classrooms, SW Mechanical	Office / Pull-Out	2020	Maintenance	D211	interiors	interior Finishes	wall Fillisties		5-LIKE TO DO	Good	00	50	Linear Foot	3310
7935	Batavia High School	1698 - Ceilings, Acoustical Suspended Systems - Original		Corridor	2020	Sent to Maintenance	ACT in good condition. E/W Corridor between locker rooms and 120s classrooms	Interiors	Interior Construction		Acoustical Suspended Ceilings	3-Like To Do	Good	1300	\$8	Square Foot	\$9,750
7936	Batavia High School	1704 - Flooring, VCT - Original		Corridor	2020	Sent to Maintenance	VCT flooring in good condition. E/W Corridor between locker rooms and 120s classrooms Cost is to replace with rubber	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	1300	\$12	Square Foot	\$15,600
7937	Batavia High School	1951 - Interior Wall Finish, Paint Original	-	Corridor	2020	Sent to Maintenance	flooring. Wall paint in good condition. Quantity reflects total SF of all listed spaces. E/W Corridor between locker rooms and 120s classrooms		Interior Finishes	Wall Finishes	Wall Painting and Coating	3-Like To Do	Good	1300	\$2	Square Foot	\$2,925
11698	Batavia High School	3393 - Equipment, Lockers - Original			2020	Sent to Maintenance	Athletic lockers, both varsity locker rooms: Girls varsity - Large - 152 1/2 size - 180 Boys varsity - Large - 206	Equipment and Furnishings	Equipment		Educational and Scientific Equipment	3-Like To Do	Good	537	\$200	Each	\$107,400
11699	Batavia High School	3395 - Equipment, Lockers - 1995	Central Area, South Entrance (1995)		2020	Sent to Maintenance	1/2 size - 178 Athletic lockers, both varsity locker rooms: Girls PE - 1/2 size - 480 1/4 size - 30 Boys PE - 1/2 size - 474 1/4 size - 35	Equipment and Furnishings	Equipment	Institutional Equipment	Educational and Scientific Equipment	3-Like To Do	Good	494	\$200	Each	\$98,800
78141	Batavia High School	18948 - Sitework, Fields and Athletic Areas			2020	Sent to Maintenance	Counts tallied as full-height lockers. Per 2013 Site Master Plan - provide synthetic turf fields, underground stormwater detention, perimeter fence, sports field lighting, observation tower; cost includes escalation from 2013.		Site Improvements	Athletic, Recreational, and Playfield Areas		3-Like To Do	Fair	1	\$5,600,000	Lump Sum	\$5,600,000
78142	Batavia High School	18948 - Sitework, Fields and Athletic Areas			2013	Sent to Maintenance	Per 2013 Site Master Plan - add press box to softball/baseball diamonds; district has indicated desire for double-sided press box with storage below.	Sitework	Site Improvements	Athletic, Recreational, and Playfield Areas		3-Like To Do		1	\$675,000	Lump Sum	\$675,000









Assessment	Campus	Linked Bldg	Addition	Room	Assessment		Description		Building System			Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cos
78143	Batavia High School	System 18948 - Sitework, Fields and			Year 2013	Sent to Maintenance	Per 2013 Site Master Plan - demolish existing bus maintenance garage;	L1 Sitework	Site Improvements	L3 Athletic, Recreational, and	L4	3-Like To Do	Poor	1	\$2,000,000	Lump Sum	\$2,000,000
		Athletic Areas					construct new storage/concessions/toilet facility with parking. Cost includes addition			Playfield Areas							
78144	Batavia High School				2013	Sent to Maintenance	of scope and escalation from 2013. Per 2013 Site Master Plan - add 2 monument signs. Cost includes escalation from 2013.					3-Like To Do		1	\$105,000	Lump Sum	\$105,000
4807	Batavia High School	1895 - Interior Doors, Swinging- Wood - 1971	LRC, Classrooms (1971)	Learning Center	2020	Sent to Maintenance	Learning Center - Doors to corridors have narrow lites Work Room B119D - "The Back Room" Lounge Library Work Room	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	12	\$2,400	Each	\$28,800
4809	Batavia High School	1895 - Interior Doors, Swinging- Wood - 1971	LRC, Classrooms (1971)	Learning Center		Sent to Maintenance	HM Frames are in good condition throughout Learning Center - Frames into the library are part of a larger storefront system Work Room B119D - "The Back Room" Lounge Library Work Room	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	10	\$2,400	Each	\$24,000
4812	Batavia High School	1896 - Interior Doors, Swinging- Wood - 1995	East 2-Story Classrooms (1995)	Science Lab	2020	Sent to Maintenance	Interior wood doors in good condition C202,C204, C209, C211, C215, and C217	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	14	\$2,400	Each	\$33,600
4819	Batavia High School	1797 - Interior Doors, Swinging- Wood - 2009	North Classrooms, SW Mechanical	Science Lab	2020	Sent to Maintenance	Interior wood doors are in good condition D201, D205, and D209	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	12	\$2,400	Each	\$28,800
4820	Batavia High School	1852 - Interior Doors, Swinging- Hollow Metal - 2009	North Classrooms, SW Mechanical (2009)	Science Lab	2020	Sent to Maintenance	Interior HM frames are in good condition D201, D205, and D209	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	12	\$1,950	Each	\$23,400
4828	Batavia High School	1743 - Interior Wall Finishes, Wall Base - Original	LRC, Classrooms (1971)	Learning Center	2020	Sent to Maintenance	Learning Center Work Room (B119D) "The Back Room" Lounge Library Work Room	Interiors	Interior Finishes	Wall Finishes		4-Future	Good	862	\$6	Linear Foot	\$5,172
4831	Batavia High School	1921 - Interior Partitions, Fixed- CMU - 1995	East 2-Story Classrooms (1995)	Science Lab	2020	Sent to Maintenance	CMU walls in good condition C202, C204, C209, C211, C215, and C217	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Each	\$0
	Batavia High School	CMU - 1971	LRC, Classrooms (1971)			Sent to Maintenance	Work Room (B119D) "The Back Room" Lounge Library Work Room	Interiors	Interior Construction	Interior Partitions	Partitions	4-Future	Coou	0	\$0		\$0
4839	Batavia High School	1951 - Interior Wall Finish, Paint - Original	LRC, Classrooms (1971)	Learning Center		Sent to Maintenance	(B119D) "The Back Room" Lounge - Recently re-painted with two custom murals	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	4-Future	Excellent	559	\$2	Square Foot	\$1,258
4841	Batavia High School	1857 - Interior Partitions, Fixed- CMU - 2009	North Classrooms, SW Mechanical	Science Lab	2020	Sent to Maintenance	CMU walls in good condition D201, D205, and D209	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Each	\$0
4846	Batavia High School	1987 - Fixed Equipment,	North Classrooms, SW Mechanical	Science Lab	2020	Sent to Maintenance	Caswork in good condition. D201, D205, and D209	Equipment and Furnishings	Furnishings	Fixed Furnishings	Casework	4-Future	Good	360	\$0	Linear Foot	\$0

Building Our Future TOGETHER BPS









Assessment	Campus	Linked Bldg	Addition	Room	Assessmen	t Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID	Campus	System	, taution	, noon	Year	Status	Description	L1	L2	L3	L4	· · · · · · · · · · · · · · · · · · ·	ruemey condition	Quartity	ome cost	Ome of Measure	Estimated cost
4851	Batavia High School	1694 - Interior Windows, Fixed - Original	LRC, Classrooms (1971)	Learning Center	2020	Sent to Maintenance	Interior storefronts are in good condition with no visible damage to glazing. Learning Center. (B119D) "The Back Room" Lounge	Interiors	Interior Construction	Interior Windows		4-Future	Good	200	\$45	Square Foot	\$9,000
4852	Batavia High School	1755 - Exterior Windows, Operating - 2009	North Classrooms, SW Mechanical	Science Lab	2020	Sent to Maintenance	Exterior window in good condition. Verify size in field. D201, D205, and D209	Shell	Exterior Vertical Enclosures	Exterior Windows	Exterior Operating Windows	4-Future	Good	252	\$100	Square Foot	\$25,200
4863	Batavia High School	1695 - Interior Doors, Swinging- Wood - Original		Toilet	2020	Sent to Maintenance	Interior wood door in good condition Girls Toilet - Nurse suite	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	2	\$2,400	Each	\$4,800
4866	Batavia High School	1709 - Interior Doors, Swinging- Hollow Metal - Original		Toilet	2020	Sent to Maintenance	Interior HM frame in good condition Girls by B124 Boys Toilet-B-Wing South 1st Floor Girls Toilet - B-Wing South 1st Floor Girls Toilet - Nurse Suite Boys Toilet - Nurse Suite Mens Faculty Center Womens Faculty Center	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	7	\$1,950	Each	\$13,650
4972	Batavia High School	1703 - Flooring, Ceramic Tile - Original		Toilet	2020	Sent to Maintenance	Ceramic tile flooring in good condition. Boys by B124 (192sf). Girls by B124 (204sf). Nurse Suite - Boys Toilet (78.5sf). Nurse Suite - Girls Toilet (78.5sf).	Interiors	Interior Finishes	Flooring	Tile Flooring	4-Future	Good	483	\$30	Square Foot	\$14,490
4982	Batavia High School	1710 - Interior Partitions, Fixed- CMU - Original		Toilet	2020	Sent to Maintenance	CMU wall in good condition A108 - Toilets in Locker Room A104 - Toilets in Locker Room A105B - TR in PE Office A104 - Toilets in W Locker Room Toilets in A110 - Mens' Team Locker	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0		\$0
4987	Batavia High School	1743 - Interior Wall Finishes, Wall Base - Original		Toilet	2020	Sent to Maintenance	Wall base in good condition A108 - Toilets in Locker Room A104 - Toilets in Locker Room A105B - TR in PE Office Boys by B124 Girls by B124 Mens Faculty Center Womens Faculty Center	Interiors	Interior Finishes	Wall Finishes		4-Future	Good	531	\$6	Linear Foot	\$3,186
4988	Batavia High School	1951 - Interior Wall Finish, Paint Original	-	Toilet	2020	Sent to Maintenance	Wall paint in good condition. Quantity reflects the total SF in all listed spaces. A108 - Toilets in Locker Room. A104 - Toilets in Locker Room. A105B - TR in PE Office.	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	4-Future	Good	850	\$2	Square Foot	\$1,913









Accoccmon	Campus	Linked Bldg	Addition Room	Accordment	Assassment	Description	Puilding System	Building System	Puilding System	Puilding System	Priority	Eacility Condition	Quantity	Unit Cost	Unit Of Massura	Estimated Cost
Assessment	Campus	System	Addition Room	Assessment Year	Assessment Status	Description	L1	L2	L3	L4	Priority	Facility Condition	Quantity	Unit Cost	Onit Of Weasure	Estimated Cost
4992	Batavia High	1728 - Plumbing,	Toilet	2014	Sent to	Fixtures in good condition	Services	Plumbing	Domestic Water	Plumbing Fixtures	1-Euturo	Good	n	\$2,000	Each	\$0
4992	School	Plumbing Fixtures		2014	Maintenance	A108 - Toilets in Locker Room	Sel vices	Fidilibilig	Distribution	Fiumbing rixtures	4-1 utule	dood	U	\$2,000	Lacii	ÇÜ
	3011001	- Original			iviaiiiteilaiice	A104 - Toilets in Locker Room			Distribution							
		- Original				A105B - TR in PE Office										
						Staff TR in W Locker Room										
						Toilets in A110 - Mens' Team Locker										
						Room										
						B-Wing South 1st Floor - Boys Toilet B-Wing South 1st Floor - Girls Toilet										
						Nurse suite - Girls Toilet										
						Nurse suite - Giris Toilet										
						Mens Faculty Center										
						Womens Faculty Center										
4993	Batavia High	1914 - Interior	Toilet	2020	Sent to	interior Partition is in good	Interiors	Interior	Interior	Toilet, Bath, and	1-Future	Good	7	\$1,800	Each	\$12,600
4555	School	Specialties, Toilet	Tonet	2020	Maintenance	condition	interiors	Construction	Specialties	Laundry	4-1 utule	Good	,	\$1,000	Lacii	712,000
	3011001	Compartments -			iviairiteriarice	A108 - Toilets in Locker Room		Construction	Specialties	Accessories						
		Original				A105B - TR in PE Office				Accessories						
		Original				A104 - Toilets in W Locker Room										
						Boys by B124										
						Toilets in A110 - Mens' Team Locker										
						Room										
						Mens Faculty Center										
4999	Batavia High	1741 - Interior	Toilet	2020	Sent to	wall tile in good condition	Interiors	Interior Finishes	Wall Finishes	Tile Wall Finish	4-Future	Good	852	\$30	Square Foot	\$25,560
	School	Wall Finish, Tile -			Maintenance	A105B- TR in PE Office								755		7-3,555
		Original				A110 - Mens' Team Locker Room										
						Boys by B124										
						Girls by B124										
5000	Batavia High	1894 - Interior	North Central Staff Toilet Room	2020	Sent to	Interior wood door in good	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good	1	\$2,400	Each	\$2,400
	School	Doors, Swinging-	Classrooms (1969)		Maintenance	condition		Construction		Doors						
		Wood - 1969				A129A-T										
5001	Batavia High	1873 - Interior	North Central Staff Toilet Room	2020	Sent to	Interior HM door frame in good	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good	1	\$1,950	Each	\$1,950
	School	Doors, Swinging-	Classrooms (1969)		Maintenance	condition		Construction		Doors						
		Hollow Metal -				A129A-T										
		1969														
5003	Batavia High	1907 - Flooring,	North Central Staff Toilet Room	2020	Sent to	Flooring ceramic tile in good	Interiors	Interior Finishes	Flooring	Tile Flooring	4-Future	Good	58	\$30	Square Foot	\$1,740
	School	Ceramic Tile -	Classrooms (1969)		Maintenance	condition, one stained tile										
		1969				A129A-T										
5004	Batavia High	2007 - Plumbing,		2014	Sent to		Services	Plumbing		Plumbing Fixtures	4-Future	Good	0	\$2,000	Each	\$0
	School		Classrooms (1969)		Maintenance	A129A-T			Distribution							
		- 1969														
5006	Batavia High	1935 - Interior	North Central Staff Toilet Room	2020	Sent to	Wall tile in good condition	Interiors	Interior Finishes	Wall Finishes	Tile Wall Finish	4-Future	Good	132	\$30	Square Foot	\$3,960
	School		Classrooms (1969)		Maintenance	A129A-T										
		1969														
5009	Batavia High	1896 - Interior	Central Area, Toilet	2020	Sent to	interior wood door in good	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good	4	\$2,400	Each	\$9,600
	School		South Entrance		Maintenance			Construction		Doors						
		Wood - 1995	(1995)			Boys in c wing 1										
						Staff in c wing 1										
						Girls by c119										
						Girls by Café										
						126D										
5011	Batavia High		Central Area, Toilet	2020	Sent to	interior HM frames in good	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good	3	\$1,950	Each	\$5,850
	School		South Entrance		Maintenance	condition		Construction		Doors						
		Hollow Metal -	(1995)			Boys by Café										
<u> </u>		1995				Girls by Café										









Assessmen	nt Campus	Linked Bldg	Addition	Room	Assessment	Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID		System			Year	Status		L1	L2	L3	L4						
5021	Batavia High School	1908 - Flooring, Ceramic Tile - 1995	East 2-Story Classrooms (1995	Toilet	2020	Sent to Maintenance	ceramic floor tile in good condition Girls in C wing1 (215sf). Boys in c wing 1 (217sf). Staff in c wing 1 (70sf) Girls by c119 (292sf). Boys by c119 (287sf)	Interiors	Interior Finishes	Flooring	Tile Flooring	4-Future	Good	1081	\$30	Square Foot	\$32,430
5025	Batavia High School	1855 - Interior Partitions, Fixed- CMU - 1995 Entry		Toilet		Sent to Maintenance	CMU wall is in good condition Girls in C wing1 Boys in c wing 1 Staff in c wing 1 Boys by Café Girls by Café 126D- Student TR	Interiors	Interior Construction	Interior Partitions	Partitions	4-Future	Good	0	\$0		\$0
5027	Batavia High School	1975 - Interior Wall Finishes, Wall Base - 1995	Central Area, South Entrance (1995)	Toilet	2020	Sent to Maintenance	Wall base in good condition Girls in C wing1 Boys in c wing 1 Staff in c wing 1 Girls by c119 126D- Student TR	Interiors	Interior Finishes	Wall Finishes		4-Future	Good	300	\$6	Linear Foot	\$1,800
5038	Batavia High School	2010 - Plumbing, Plumbing Fixtures - 1995		Toilet	2014	Sent to Maintenance	plumbing fixtures are in good condition Girls in C wing1 Staff in c wing 1 Girls by c119 Boys by Café 126D - student TR	Services	Plumbing	Domestic Water Distribution	Plumbing Fixtures	4-Future	Good	0	\$2,000	Each	\$0
5042	Batavia High School	1841 - Interior Specialties, Toilet Compartments - 1995 Entry	Central Area, South Entrance (1995)	Toilet	2020	Sent to Maintenance	Interior partition in good condition Boys by Café Girls by Café	Interiors	Interior Construction		Toilet, Bath, and Laundry Accessories	4-Future	Good	2	\$1,800	Each	\$3,600
5043	Batavia High School	1711 - Interior Doors, Swinging- Wood - 1995 Entry	East 2-Story Classrooms (1995	Toilet		Sent to Maintenance	Interior wood doors in good condition C-Wing South, 2nd Floor - Girls Toilet C-Wing South, 2nd Floor - boys Toilet C-Wing South, 2nd Floor - staff	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	6	\$2,400	Each	\$14,400
5048	Batavia High School	1908 - Flooring, Ceramic Tile - 1995	East 2-Story Classrooms (1995	Toilet	2020	Sent to Maintenance	Ceramic tile flooring in a good condition. C-Wing South, 2nd Floor - Girls Toilet. C-Wing South, 2nd Floor - boys Toilet. C-Wing South, 2nd Floor - staff Toilet. C-Wing North, 2nd Floor - Girls Toilet. C-Wing North, 2nd Floor - boys Toilet.	Interiors	Interior Finishes	Flooring	Tile Flooring	4-Future	Good	1087	\$30	Square Foot	\$32,610









Assessmer ID	nt Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cos
5049	Batavia High	1695 - Interior		Office / Pull-Out	2020	Sent to	A104B,	Interiors	Interior		Interior Swinging	A-Euturo	Good	29	\$2,400	Each	\$69,600
3043	School	Doors, Swinging-		Office / Full-Out	2020	Maintenance	A1046,	interiors	Construction	interior boors	Doors	4-1 uture	doou	29	\$2,400	Lacii	\$09,000
	301001	Wood - Original				iviairiteriarite	B107A,		Construction		D0013						
		Wood - Original					B108,										
							B115,										
							B116,										
							B117,										
							B118,										
							B118A,										
							B118B,										
							B118D,										
							B118F,										
							B118G,										
							B118H,										
							B119A,										
							B119B,										
							B119C,										
							B119D,										
							B120,										
							B121,										
							B122,										
							B122A,										
							B122B,										
							B122E,										
							B123,										
							B123,										
							B124,										
							B124A, B124B.										
5050	Batavia High	1695 - Interior	LRC. Classrooms	Office / Pull-Out	2020	Sent to	Career Counselor Office (In the	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good	1	\$2,400	Each	\$2,400
	School		(1971)	,		Maintenance	Library) Door is in Good condition		Construction		Doors				, ,		, ,
		Wood - Original	,				,,										
5051	Batavia High		LRC, Classrooms	Office / Pull-Out	2020	Sent to	Career Counselor Office (In the	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good	1	\$2,400	Each	\$2,400
	School		(1971)			Maintenance	Library) - HM Frame is in Good		Construction		Doors						
		Wood - Original					condition										
5063	Batavia High	1855 - Interior	East 2-Story	Toilet	2020	Sent to	CMU walls in a good condition	Interiors	Interior	Interior Partitions	Interior Fixed	4-Future	Good	0	\$0		\$0
	School	Partitions, Fixed-	Classrooms (1995))		Maintenance	C-Wing South, 2nd Floor - Girls		Construction		Partitions						
		CMU - 1995 Entry					Toilet										
							C-Wing South, 2nd Floor - boys										
							Toilet										
							C-Wing South, 2nd Floor - staff										
5064	Batavia High			Office / Pull-Out		Sent to	Career Counselor (In the Library)	Interiors	Interior Finishes	Wall Finishes		4-Future	Good	30	\$6	Linear Foot	\$180
	School		(1971)			Maintenance											
F.C.C.		Wall Base -	1.00.01	0.00	2020									40	645		44.000
5068	Batavia High			Office / Pull-Out		Sent to	Career Counselor (In the Library) -	Interiors	Interior	Interior Windows		4-Future	Good	42	\$45	Square Foot	\$1,890
	School		(1971)			Maintenance	Side lite adjacent to wood dooor		Construction		Windows						
F070	Determent 111-1-	1971	Fact 2 Ct	Tailet	2014	Cantta	alonghian finance to a second section	n Comileas	Discondina -	Damasti - Mi-ti	Disambin - First	4 F	Cand	0	ć2.000	Face	ćo
5070	Batavia High	2010 - Plumbing, Plumbing Fixtures		Toilet		Sent to Maintenance	plumbing fixture in a good condition	Services	Plumbing		Plumbing Fixtures	4-Future	Good	U	\$2,000	Each	\$0
	School		Ciassi 00fffs (1995)	,		iviaintenance	C-Wing South, 2nd Floor - Girls			Distribution							
		- 1995					Toilet C-Wing South, 2nd Floor - boys										
							Toilet C-Wing South, 2nd Floor - staff										
			1				C- Willig South, Allu Floor - Stall		1		1	1				1	










Assessmer	nt Campus	Linked Bldg	Addition	Room	Assessment	Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID	•	System			Year	Status	·	L1	L2	L3	L4	,	•	•			
5071	Batavia High School	1695 - Interior Doors, Swinging- Wood - Original	Central Area, South Entrance (1995)	Office / Pull-Out		Sent to Maintenance	A101A A101B A110A A134A B100M - Door lite has a half lite that		Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	5	\$2,400	Each	\$12,000
5074	Batavia High School	1695 - Interior Doors, Swinging- Wood - Original	South Admin Addition (2009)	Office / Pull-Out		Sent to Maintenance	is in Good condtion Offices almost all contain Narrow lites that are in Good condition A102C, A102D, B100, B100B, B100C, B100D, B100E, B100F, B100G, B100H, B100J, B100J, B100L, B101D, B101D, B101D, B101A, B101B, B101C, B101D, B101C, B101D, B101E, B101C, B101D, B101E, B101C, B101D, B101E, B101C, B101D, B101E, B102A, D110A, D112,	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	23	\$2,400	Each	\$55,200
							D112, D117, D211										
5078	Batavia High School	1695 - Interior Doors, Swinging- Wood - Original	South Admin Addition (2009)	Office / Pull-Out		Sent to Maintenance	F102 Auditorium Manager	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$2,400	Each	\$2,400
5082	Batavia High School	1797 - Interior Doors, Swinging- Wood - 2009	North Classrooms, SW Mechanical (2009)	Toilet	2020	Sent to Maintenance	Interior wood door in good condition Womens in Office TR in kitchen Kick plate on corridor side is dirty Mens in Office E CORRIDOR TOILET E CORRIDOR MENS E CORRIDOR WOMENS	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	7	\$2,400	Each	\$16,800
5087	Batavia High School	1797 - Interior Doors, Swinging- Wood - 2009	North Classrooms, SW Mechanical (2009)	Toilet		Sent to Maintenance	Interior wood door in good condition Womens in Office TR in kitchen Mens in Office E CORRIDOR TOILET E CORRIDOR MENS E CORRIDOR WOMENS		Interior Construction		Interior Swinging Doors	4-Future	Good	7	\$2,400	Each	\$16,800









Assessmen	t Campus	Linked Bldg	Addition	Room	Assessmen	t Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID	•	System			Year	Status		L1	L2	L3	L4	,	,	- · · · · ·			
5090	Batavia High School	1823 - Flooring, Ceramic Tile - 2009	North Classrooms, SW Mechanical (2009)	Toilet	2020	Sent to Maintenance	Ceramic tile flooring in a good condition Girls by d100 Boys by d100' Toilet in d102 E CORRIDOR MENS E CORRIDOR WOMENS E CORRIDOR TOILET	Interiors	Interior Finishes	Flooring	Tile Flooring	4-Future	Good	2710	\$30	Square Foot	\$81,300
5093	Batavia High	1857 - Interior	North	Toilet	2020	Sent to	CMU walls are in good condition	Interiors	Interior	Interior Partitions	Interior Fixed	4-Future	Good	0	\$0		\$0
	School	Partitions, Fixed- CMU - 2009	Classrooms, SW Mechanical			Maintenance	TR in Kitchen		Construction		Partitions						
5094	Batavia High School	1695 - Interior Doors, Swinging- Wood - Original		Office / Pull-Out	2020	Sent to Maintenance	HM Frames are in Good condition B107A, B118, B118A, B118B, B118D, B118G, B118H, B119A, B119C, B119D, B122B, B122C, B122E, B123 (Conference), B123 (Office), B124, B124A, B124A, B124C, B124C, B124C, B124C, B124C, B124E, B124E, B124E,	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	24	\$2,400	Each	\$57,600
5095	Batavia High School	1977 - Interior Wall Finishes, Wall Base - 2009	North Classrooms, SW Mechanical	Toilet	2020	Sent to Maintenance	B124G, Wall base in good condition Toilet in d102	Interiors	Interior Finishes	Wall Finishes		4-Future	Good	30	\$6	Linear Foot	\$180
5098	Batavia High School	2011 - Plumbing, Plumbing Fixtures - 2009	North	Toilet	2014	Sent to Maintenance	plumbing fixtures are in good condition. Girls by d100 Boys by d100 Toilet in d102 Mens in Office Womens in Office TR in Kitchen E CORRIDOR TOILET E CORRIDOR MENS E CORRIDOR WOMENS	Services	Plumbing	Domestic Water Distribution	Plumbing Fixtures	4-Future	Good	0	\$2,000	Each	\$0









Assessme	nt Campus	Linked Bldg	Addition	Room	Assessment	Assessment	Description	Building System	Ruilding System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID	Campus	System	Addition	Koom	Year	Status	Description	L1	L2	L3	L4	Filolity	racinty Condition	Qualitity	Onit Cost	Offic Of Wieasure	Littillated Cost
5104	Batavia High School	2023 - Interior Wall Finish, Tile - 2009	North Classrooms, SW Mechanical (2009)	Toilet	2020	Sent to Maintenance	Wall tiles are in good condition. Girls by d100 Boys by d100 Toilet in d102 E CORRIDOR TOILET E CORRIDOR MENS E CORRIDOR WOMENS	Interiors	Interior Finishes			4-Future	Good	1700	\$30	Square Foot	\$51,000
5110	Batavia High School	1823 - Flooring, Ceramic Tile - 2009	North Classrooms, SW Mechanical (2009)	Toilet	2020	Sent to Maintenance	Ceramic tile flooring in good condition. D-Wing 2nd Floor- Girls Toilet D-Wing 2nd Floor- boys Toilet	Interiors	Interior Finishes	Flooring	Tile Flooring	4-Future	Good	350	\$30	Square Foot	\$10,500
5113	Batavia High School	2011 - Plumbing, Plumbing Fixtures - 2009	North Classrooms, SW Mechanical (2009)	Toilet	2014	Sent to Maintenance	Plumbing fixtures are in good condition. D-Wing 2nd Floor- Girls Toilet D-Wing 2nd Floor- boys Toilet D-Wing 2nd Floor	Services	Plumbing	Domestic Water Distribution	Plumbing Fixtures	4-Future	Good	0	\$2,000	Each	\$0
5116	Batavia High School	1843 - Interior Specialties, Toilet Compartments - 2009	North Classrooms, SW Mechanical (2009)	Toilet	2020	Sent to Maintenance	Toilet partitions in good condition. D-Wing 2nd Floor- Girls Toilet. D-Wing 2nd Floor- boys Toilet.	Interiors	Interior Construction		Toilet, Bath, and Laundry Accessories	4-Future	Good	7	\$1,800	Each	\$12,600
5134	Batavia High School	1896 - Interior Doors, Swinging- Wood - 1995	Central Area, South Entrance (1995)	Office / Pull-Out		Sent to Maintenance	B100M (Counselor Reception) - Good Condition Overall	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$2,400	Each	\$2,400
5136	Batavia High School	2013 - Plumbing, Plumbing Fixtures - 2011	BFAC, Fieldhouse (2011)	Toilet	2014	Sent to Maintenance	Plumbing fixtures in good condition FIELDHOUSE GIRLS FIELDHOUSE BOYS	n. Services	Plumbing	Domestic Water Distribution	Plumbing Fixtures	4-Future	Good	0	\$2,000	Each	\$0
5138	Batavia High School	1695 - Interior Doors, Swinging- Wood - Original	Central Area, South Entrance (1995)	Office / Pull-Out	2020	Sent to Maintenance	HM Frames are in Good Condition Overall A102C, B100, B100B - Edges on corridor side need to be repainted, B100C - Edges on corridor side need to be repainted, B100D - Edges on corridor side need to be repainted, B100E - Edges on corridor side need to be repainted, B100F - Edges on corridor side need to be repainted, B100F - Edges on corridor side need to be repainted, B100G, B100H, B100J, B100L, B101A, B101C, B101D, B101E, B102A, D110A, D112, D211,	d d	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	20	\$2,400	Each	\$48,000









Assessmen	nt Campus	Linked Bldg	Addition	Room	Assessment		Description	Building System		Building System		Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
I D 5144	Batavia High School	System 1843 - Interior Specialties, Toilet Compartments - 2009	North Classrooms, SW Mechanical (2009)	Toilet	Year 2020	Status Sent to Maintenance	Toilet partition is in good condition. Girls by d100. Boys by d100. E CORRIDOR MENS.	L1 Interiors	L2 Interior Construction	L3 Interior Specialties	Toilet, Bath, and Laundry Accessories	4-Future	Good	15	\$1,800	Each	\$27,000
5147	Batavia High School	1797 - Interior Doors, Swinging- Wood - 2009	North Classrooms, SW Mechanical	Toilet		Sent to Maintenance	E CORRIDOR WOMENS. Interior wood door in a good condition D-Wing 2nd Floor	Interiors	Interior Construction		Interior Swinging Doors	4-Future	Good	1	\$2,400	Each	\$2,400
5148	Batavia High School	1852 - Interior Doors, Swinging- Hollow Metal - 2009	North Classrooms, SW Mechanical (2009)	Toilet	2020	Sent to Maintenance	Interior HM frame in a good condition D-Wing 2nd Floor	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$1,950		\$1,950
5149	Batavia High School	2023 - Interior Wall Finish, Tile - 2009	North Classrooms, SW Mechanical	Toilet	2020	Sent to Maintenance	wall tile frame in good condition D-Wing 2nd Floor	Interiors	Interior Finishes	Wall Finishes	Tile Wall Finish	4-Future	Good	50	\$30	Square Foot	\$1,500
5151	Batavia High School	1695 - Interior Doors, Swinging- Wood - Original		Classrooms	2020	Sent to Maintenance	Wood door in good condition. B106. B107. B109. A109	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	3	\$2,400	Each	\$7,200
5154	Batavia High School	1695 - Interior Doors, Swinging- Wood - Original		Classrooms	2020	Sent to Maintenance	HM door frame in good condition. B106. A109	Interiors	Interior Construction		Interior Swinging Doors	4-Future	Good	1	\$2,400	Each	\$2,400
5155	Batavia High School	1709 - Interior Doors, Swinging- Hollow Metal - Original		Classrooms	2020	Sent to Maintenance	HM door in good condition. B113, B125, B114	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	3	\$1,950		\$5,850
5156	Batavia High School	1695 - Interior Doors, Swinging- Wood - Original	BFAC, Fieldhouse (2011)	Office / Pull-Out		Sent to Maintenance	HM Frames are in Good Condition Overall F102 (Auditorium Manager) F111 (Building Trades Office)	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	2	\$2,400	Each	\$4,800
5157	Batavia High School	1709 - Interior Doors, Swinging- Hollow Metal - Original		Classrooms		Sent to Maintenance	HM door in good condition. B112	Interiors	Interior Construction		Interior Swinging Doors	4-Future	Good	1	\$1,950		\$1,950
5167	Batavia High School	1710 - Interior Partitions, Fixed- CMU - Original		Classrooms		Sent to Maintenance	CMU in good condition. B109, B125, A109, B114	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Square Foot	\$0
5170	Batavia High School	1708 - Interior Partitions, Fixed - GWB - Original		Classrooms		Sent to Maintenance	GWB in good condition. B125	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Square Foot	\$0
5171	Batavia High School	1743 - Interior Wall Finishes, Wall Base - Original		Classrooms		Sent to Maintenance	Wall base in good condition. B106. B107. B109. B112. B113. B125. A109. B114	Interiors	Interior Finishes	Wall Finishes		4-Future	Good	1000	\$6	Linear Foot	\$6,000









Assessment	t Campus	Linked Bldg System	Addition	Room	Assessmen Year	t Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
5174	Batavia High School	1709 - Interior Doors, Swinging- Hollow Metal - Original		Office / Pull-Out	2020	Sent to Maintenance	HM Doors are in Good Condition A104B B122B	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	2	\$1,950	Each	\$3,900
5176	Batavia High School	1873 - Interior Doors, Swinging- Hollow Metal - 1969	North Central Classrooms (1969	Office / Pull-Out	2020	Sent to Maintenance	HM Doors are in Good Condition, A123A, A129A	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	2	\$1,950	Each	\$3,900
5183	Batavia High School	1694 - Interior Windows, Fixed - Original		Classrooms	2020	Sent to Maintenance	Interior windows in good condition. B106. B107. B109. B114.	Interiors	Interior Construction	Interior Windows	Interior Fixed Windows	4-Future	Good	80	\$45	Square Foot	\$3,600
5184	Batavia High School	1850 - Interior Doors, Swinging- Hollow Metal - 1995	Central Area, South Entrance (1995)	Office / Pull-Out	2020	Sent to Maintenance	HM Doors are in Good Condition, A101A, A101B, A134A	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors		Good	3	\$1,950	Each	\$5,850
5186	Batavia High School	1851 - Interior Doors, Swinging- Hollow Metal - 2009 Admin	South Admin Addition (2009)	Office / Pull-Out	2020	Sent to Maintenance	HM Doors are in Good Condition, B100, B102	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	2	\$1,950	Each	\$3,900
5187	Batavia High School	1675 - Exterior Entrance Doors, Hollow Metal - Original		Classrooms	2020	Sent to Maintenance	Exterior HM doors and frame in good condition. B112, B125	Shell	Exterior Vertical Enclosures	Exterior Doors and Grilles	Exterior Entrance Doors	4-Future	Good	3	\$7,500	Each	\$22,500
5189	Batavia High School	1853 - Interior Doors, Swinging- Hollow Metal - 2011	BFAC, Fieldhouse (2011)	Office / Pull-Out	2020	Sent to Maintenance	HM Doors are in Good Condition, F111 (Building Trades Office)	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$1,950	Each	\$1,950
5205	Batavia High School	1920 - Interior Partitions, Fixed- CMU - 1969	North Central Classrooms (1969	Classrooms)	2020	Sent to Maintenance	CMU in good condition. A121. A126. A128.	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Square Foot	\$0
5215	Batavia High School	1805 - Ceilings, Acoustical Suspended Systems - 2009	South Admin Addition (2009)	Office / Pull-Out	2020	Sent to Maintenance	ACT is in Excellent Condition D112 (Mother's Room)	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	4-Future	Excellent	65	\$8	Square Foot	\$488
5230	Batavia High School	1717 - Flooring, Carpet - 1971	LRC, Classrooms (1971)	Classrooms	2020	Sent to Maintenance	Carpet in excellent condition, recent renovation. B104, B104A	Interiors	Interior Finishes	Flooring	Carpeting	4-Future	Excellent	1520	\$7	Square Foot	\$9,880
5231	Batavia High School	1854 - Interior Partitions, Fixed- CMU - 1971	LRC, Classrooms (1971)	Classrooms	2020	Sent to Maintenance	CMU in good condition. B103. B104. B104A.	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Square Foot	\$0
5244	Batavia High School	1896 - Interior Doors, Swinging- Wood - 1995	East 2-Story Classrooms (1995	Classrooms)	2020	Sent to Maintenance	Wood door in good condition. C100. C106. C109. C115.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	4	\$2,400	Each	\$9,600









Assessment	Campus	Linked Bldg	Addition	Room	Assessmei	nt Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cos
ID	Campus	System	Addition	Koom	Year	Status	Description	L1	L2	L3	L4	Priority	racinty Condition	Quantity	Unit Cost	Onit Of Measure	e Estimated Cos
5246	Batavia High	1896 - Interior	East 2-Story	Classrooms	2020	Sent to	HM door frame in good condition.	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good	1	\$2,400	Each	\$2,400
	School	Doors, Swinging-	Classrooms (19			Maintenance			Construction		Doors				7-7:00		7-7.55
		Wood - 1995	,				C106										
5247	Batavia High	1804 - Ceilings,	East 2-Story	Classrooms	2020	Sent to	ACT excellent - looks brand new.	Interiors	Interior	Suspended Ceiling	Acoustical	4-Future	Excellent	801	\$8	Square Foot	\$6,008
	School	Acoustical	Classrooms (19	95)		Maintenance			Construction	Construction	Suspended						
		Suspended					C118				Ceilings						
		Systems - 1995															
		Entry													4.0		4.0
5257	Batavia High	1921 - Interior	East 2-Story	Classrooms	2020	Sent to	CMU in overall good condition -	Interiors	Interior	Interior Partitions		4-Future	Good	30	\$0	Linear Foot	\$0
	School	Partitions, Fixed- CMU - 1995	Classrooms (19	195)		Maintenance	small stair step crack at window sills.		Construction		Partitions						
		CIVIO - 1995					SIIIS.										
							C102.										
							C111.										
							C112.										
							C113.										
							C114.										
							C116.										
							C117.										
							C119.										
							C122.										
							C100.										
							C104. C106.										
							C106. C110.										
							C110.										
5260	Batavia High	1845 - Interior	East 2-Story	Classrooms	2020	Sent to	GWB wall in good condition.	Interiors	Interior	Interior Partitions	Interior Fixed	4-Future	Good	0	\$0	Square Foot	\$0
	School	Partitions, Fixed-	Classrooms (19			Maintenance	S .		Construction		Partitions				·		ľ
		GWB - 1995					C101.										
							C102.										
							C103.										
							C104.										
							C106.										
							C105.										
							C107.										
							C109. C110.										
							C110. C111.										
							C111. C112.										
							C113.										
							C114.										
							C116.										
							C117.										
							C121.										
							C122.										
							C123.										
							C115.										1.
5271	Batavia High	1797 - Interior	North	Classrooms	2020	Sent to	Wood door in good condition.	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good	3	\$2,400	Each	\$7,200
	School	Doors, Swinging-	Classrooms, SV	V		Maintenance			Construction		Doors						
		Wood - 2009	Mechanical				D101.										
			(2009)				D104. D109.										
							ען 109.										











ssessmen	nt Campus	Linked Bldg	Addition	Room	Assessment	Assessment	Description	Building System	Building System	Building System		Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated C
ID 5276	Batavia High School	System 1857 - Interior Partitions, Fixed- CMU - 2009	North Classrooms, SW Mechanical	Classrooms		Sent to Maintenance	CMU in good condition. D101.	L1 Interiors	Interior Construction	L3 Interior Partitions	L4 Interior Fixed Partitions	4-Future	Good	0	\$0	Square Foot	\$0
			(2009)				D102. D103. D104. D105. D106. D107. D108. D109.										
5282	Batavia High School	2017 - Interior Specialties, Toilet Compartments - 1995	East 2-Story Classrooms (1995	Toilet)		Sent to Maintenance	Toilet partition in good condition Girls by C109 Boys by C109 Cost to replace with solid phenolic partitions.	Interiors	Interior Construction	Specialties	Toilet, Bath, and Laundry Accessories	4-Future	Good	0	\$1,800	Each	\$0
5285	Batavia High School	2022 - Interior Wall Finish, Tile - 2009 Admin	South Admin Addition (2009)	Toilet		Sent to Maintenance	Wall tiles in good condition. Men in admin Women in admin	Interiors	Interior Finishes	Wall Finishes	Tile Wall Finish	4-Future	Good	250	\$30	Square Foot	\$7,500
5286	Batavia High School	1709 - Interior Doors, Swinging- Hollow Metal - Original		Storage/Mechanical		Sent to Maintenance	Interior HM door in a good condition B112D Maintenance office by b124	Interiors	Interior Construction		Interior Swinging Doors	4-Future	Good	1	\$1,950		\$1,950
5290	Batavia High School	1987 - Fixed Equipment, Casework - 2009	North Classrooms, SW Mechanical (2009)	Classrooms		Sent to Maintenance	Casework in good condition. Verify quantity in field, not shown in plan. D101. D102. D103. D104. D105. D106. D107. D108. D109.	Furnishings	Furnishings	Fixed Furnishings	Casework	4-Future		200	\$1,200	Linear Foot	\$240,000
5292	Batavia High School	1755 - Exterior Windows, Operating - 2009	North Classrooms, SW Mechanical (2009)	Classrooms		Sent to Maintenance	Exterior windows in good condition D101. D102. D103. D104. D105. D106. D107. D108. D109.	. Shell	Exterior Vertical Enclosures	Exterior Windows	Exterior Operating Windows	4-Future	Good	532	\$100	Square Foot	\$53,200
5304	Batavia High School	1670 - Slab on Grade - Original		Storage/Mechanical		Sent to Maintenance	Concrete is mostly in good condition. Concrete near drain has visible water damage on the surface		Slabs-On-Grade	Standard Slabs-on- Grade		4-Future	Good	152	\$0	Square Foot	\$0
5307	Batavia High School	1709 - Interior Doors, Swinging- Hollow Metal - Original		Storage/Mechanical		Sent to Maintenance	B112D Interior HM frame in good condition B122D, Maintenance office by b124	n Interiors	Interior Construction		Interior Swinging Doors	4-Future	Good	2	\$1,950		\$3,900









Assessment	Campus	Linked Bldg	Addition	Room	Assessment Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID	Campus	System	/ taution	1100111	Year Status	Description	L1	L2	L3	L4	11101110	radiney condition	Quantity	Oint cost	ome or measure	Lotimated Coot
5310	Batavia High	1710 - Interior		Storage/Mechani		CMU wall in good condition	Interiors	Interior	Interior Partitions	Interior Fixed	4-Future	Good	0	\$0		\$0
	School	Partitions, Fixed-		al	Maintenance	A110C, B112D, A104D, A105B,		Construction		Partitions				ľ		,
		CMU - Original				A105D, A109B, A109A, B126D,										
						B110B										
5316	Batavia High	1695 - Interior		Storage/Mechani	c 2020 Sent to	Interior wood door in good	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good	4	\$2,400	Each	\$9,600
	School	Doors, Swinging-		al	Maintenance	condition		Construction		Doors						
		Wood - Original				B105, E116, B125B, B110B										
5319	Batavia High	1894 - Interior	North Central	Storage	2020 Sent to	Interior wood door in good	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good	2	\$2,400	Each	\$4,800
	School	Doors, Swinging-	Classrooms (1969)		Maintenance	condition		Construction		Doors						
		Wood - 1969	, ,			Storage near Café TR - near Café										
						toilet rooms, has beverage storage										
5320	Batavia High	1873 - Interior	North Central	Storage	2020 Sent to	Interior HM door in good condition	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good	3	\$1,950		\$5,850
	School		Classrooms (1969)		Maintenance	electrical room located in A125, also		Construction		Doors				, , , , , , , , , , , , , , , , , , , ,		, , , , , , , , , , , , , , , , , , , ,
		Hollow Metal -	(====,			being used as storage										
		1969				Drying room located between A123										
		1303				and A124										
						Storage located between A122 and										
						A121										
5327	Batavia High	1920 - Interior	North Central	Storage	2020 Sent to	CMU walls in good condition	Interiors	Interior	Interior Partitions	Interior Fixed	4-Future	Good	0	\$0		\$0
3327	School	Partitions, Fixed-	Classrooms (1969)		Maintenance	Elec Room in A126A	interiors	Construction	interior rantitions	Partitions	4-1 uture	Good	O	ÇÜ		70
	3011001	CMU - 1969	Classi 001113 (1303)		Walltellance	Elec Room located in A125, also		Construction		i ai titions						
		CIVIO - 1909				being used as storage										
						Drying Room located between A123										
						and A124										
						Storage Room limited lighting due to										
						activities in room; portion of ceiling										
						is painted concrete; located in A124										
						Storage located between A122 and										
5341	Batavia High	1896 - Interior	Central Area,	Storage	2020 Sent to	A121 Interior wood door in good	Interiore	Intorior	Interior Doors	Interior Swinging	4 Futuro	Good	2	\$2,400	Each	\$4,800
5341				Storage	2020 Sent to Maintenance	condition	Interiors	Interior	Interior Doors	0 0	4-ruture	Good	2	\$2,400	Each	\$4,800
	School	Doors, Swinging-	South Entrance		ivialiteilailee			Construction		Doors						
5346	Batavia High	Wood - 1995 1850 - Interior	(1995) Central Area,	Storage	2020 Sent to	Electrical in c wing 1 Interior HM frame in good condition	lukovi ovo	lataria a	Interior Doors	Interior Swinging	4 5	Good	2	\$1,950		\$3,900
5540	_			Storage			interiors	Interior	interior Doors	0 0	4-ruture	Good	2	\$1,950		\$3,900
	School	Doors, Swinging-	South Entrance		Maintenance	Café Storage		Construction		Doors						
		Hollow Metal -	(1995)			Storage near Café TR										
	B	1995	0 1 14	C:	2020	0.41.					4.5.	0 1	•	40		40
5354	Batavia High	1855 - Interior	Central Area,	Storage	2020 Sent to	CMU wall in good condition	Interiors	Interior	Interior Partitions		4-Future	Good	0	\$0		\$0
	School	Partitions, Fixed-			Maintenance	_		Construction		Partitions						
		CMU - 1995 Entry	(1995)			Café Storage										
						Storage near Café TR										
5364	Batavia High		-	Storage	2020 Sent to	Interior HM door in good condition	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good	1	\$1,950		\$1,950
	School		South Entrance		Maintenance	A146B		Construction		Doors						
		Hollow Metal -	(1995)													
		1995														
5365	Batavia High	1850 - Interior		Storage	2020 Sent to	Interior HM frame in good condition	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good	1	\$1,950		\$1,950
	School		South Entrance		Maintenance	A146B		Construction		Doors						
		Hollow Metal -	(1995)													
		1995														
5368	Batavia High		Central Area,	Storage	2020 Sent to	CMU wall in good condition	Interiors	Interior	Interior Partitions	Interior Fixed	4-Future	Good	0	\$0		\$0
	School		South Entrance		Maintenance	A146B		Construction		Partitions						
		CMU - 1995 Entry	(1995)													
5373	Batavia High	1851 - Interior	South Admin	Storage	2020 Sent to	Interior HM frame in good condition	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good	1	\$1,950		\$1,950
	School	Doors, Swinging-	Addition (2009)		Maintenance			Construction		Doors						
		Hollow Metal -														
		2009 Admin														
	1		1	1	I I	1	1	1	_ I	- 0	1				1	- (

Building Our Future
TOGETHER
BPS
101










Assessment	t Campus	Linked Bldg	Addition	Room	Assessment	Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID		System			Year	Status		L1	L2	L3	L4						
5375	Batavia High School	1745 - Slab on Grade - 2009	South Admin Addition (2009)	Storage	2020	Sent to Maintenance	slight cracking near door, but overal in good condition	Substructure	Slabs-On-Grade	Standard Slabs-on- Grade		4-Future	Good	60	\$0	Square Foot	\$0
		Admin					B102B										
5376	Batavia High	1856 - Interior	South Admin	Storage	2020	Sent to	CMU wall in good condition	Interiors	Interior	Interior Partitions		4-Future	Good	0	\$0		\$0
	School	Partitions, Fixed-	Addition (2009)			Maintenance	B102B		Construction		Partitions						
		CMU - 2009 Admin															
5381	Batavia High	1695 - Interior	North Central	Art Rooms	2020	Sent to	Room #: A129, A131, A131A	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good	3	\$2,400	Each	\$7,200
	School	Doors, Swinging-	Classrooms (1969	9)		Maintenance			Construction		Doors						
		Wood - Original															
5382	Batavia High	1711 - Interior	Central Area,	Video Room	2020	Sent to	Room #: A133	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good	1	\$2,400	Each	\$2,400
	School	Doors, Swinging- Wood - 1995	South Entrance (1995)			Maintenance			Construction		Doors						
		Entry	(1333)														
5383	Batavia High	1797 - Interior	North	CS, 2D Art, 3D Art	, 2020	Sent to	Room #: D110, D111, D114, D115,	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good	5	\$2,400	Each	\$12,000
	School	Doors, Swinging-	Classrooms, SW	Eng.		Maintenance	D116		Construction		Doors						
5205		Wood - 2009	Mechanical		2020	6				5			0 1	40	42.400		420.000
5385	Batavia High	1797 - Interior	North Classrooms, SW	Music Rooms	2020	Sent to Maintenance	Room #: E101A, E105, E106A, E106C E106D, E106E, E106F, E106G, E106H		Interior	Interior Doors	Interior Swinging	4-Future	Good	12	\$2,400	Each	\$28,800
	School	Doors, Swinging- Wood - 2009	Mechanical			Maintenance	E106D, E106E, E106F, E106G, E106H	,	Construction		Doors						
5387	Batavia High	1709 - Interior	North Central	Video	2020	Sent to	Room #: A131	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good	1	\$1,950		\$1,950
	School	Doors, Swinging-	Classrooms (1969	9)		Maintenance			Construction		Doors						
		Hollow Metal -															
5200	Data da Ulab	Original	DEAC Fieldhama	Lable Ataski e	2020	Countries	5400	Ch - II	Estada Nautical	F. A. oi e o De e o o	F. A. S. F. B. L.	A. Frankrick	Cl		67.500	E. d.	627 500
5388	Batavia High School	1764 - Exterior Entrance Doors,	(2011)	Lobby, Vestibule	2020	Sent to Maintenance	F100	Shell	Exterior Vertical Enclosures	Exterior Doors and Grilles	Exterior Entrance Doors	4-Future	Good	5	\$7,500	Each	\$37,500
	3011001	Aluminum - 2011	(2011)			Wantenance			Liiciosures	and offiles	D0013						
5400	Batavia High	1797 - Interior	North	Storage	2020	Sent to	Interior wood door in good	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good	3	\$2,400	Each	\$7,200
	School	Doors, Swinging-	Classrooms, SW			Maintenance	condition		Construction		Doors						
		Wood - 2009	Mechanical				D100A										
5402	Batavia High	1852 - Interior	(2009) North	Storage	2020	Sent to	D113 Interior HM door in good condition	Interiors	Interior	Interior Doors	Interior Swinging	4-Euturo	Good	1	\$1,950		\$1,950
3402	School	Doors, Swinging-	Classrooms, SW	Storage	2020	Maintenance	Janitor in Kitchen, A102B	interiors	Construction	interior boors	Doors	4-i uture	Good	_	\$1,550		71,550
		Hollow Metal -	Mechanical				,										
		2009	(2009)														
5403	Batavia High	1852 - Interior	North	Storage	2020	Sent to	Interior HM frame in good condition	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good	5	\$1,950		\$9,750
	School	Doors, Swinging- Hollow Metal -	Classrooms, SW Mechanical			Maintenance	D116A, Janitor in kitchen, A102B, E114,		Construction		Doors						
		2009	(2009)				E116										
5409	Batavia High	1745 - Slab on	North	Storage	2020	Sent to	Epoxy flooring in good condition	Substructure	Slabs-On-Grade	Standard Slabs-on-		4-Future	Good	106	\$18	Square Foot	\$1,908
	School	Grade - 2009	Classrooms, SW			Maintenance	D116A			Grade							
		Admin	Mechanical														
E 411	Potovio High	1957 Interior	(2009)	Storage	2020	Cont to	Cost to replace in kind.	Intoriors	Interior	Interior Partitions	Interior Fixed	4 Futuro	Cood	0	ćo		¢0
5411	Batavia High School	1857 - Interior Partitions, Fixed-	North Classrooms, SW	Storage	2020	Sent to Maintenance	CMU walls in good condition D113, D116A, Janitor in Kitchen,	Interiors	Interior Construction	Interior Partitions	Partitions	4-Future	Good	U	\$0		\$0
	0000.	CMU - 2009	Mechanical			aee	E114, E116										
			(2009)				tile wall base in good condition										
							A102B								1		
5422	Batavia High	1797 - Interior	North	Science Prep.	2020	Sent to	Interior wood door are in good	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good	6	\$2,400	Each	\$14,400
	School	Doors, Swinging- Wood - 2009	Classrooms, SW Mechanical			Maintenance	condition D203, D207		Construction		Doors						
5423	Batavia High	1852 - Interior	North	Science Prep.	2020	Sent to	Interior HM frame is in a good	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good	6	\$1,950	Each	\$11,700
-	School	Doors, Swinging-	Classrooms, SW			Maintenance	condition		Construction		Doors				. ,		,
		Hollow Metal -	Mechanical				D203, D207										
		2009	(2009)														










Assessment	t Campus	Linked Bldg	Addition	Room	Assessment	Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID		System			Year	Status		L1	L2	L3	L4						
5428	Batavia High School	1857 - Interior Partitions, Fixed- CMU - 2009	North Classrooms, SW Mechanical	Science Prep.	2020	Sent to Maintenance	CMU walls are in a good condition D203.	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good)	\$0	Each	\$0
5433	Batavia High School	1896 - Interior	East 2-Story Classrooms (1995	Classrooms)	2020	Sent to Maintenance	Wood door in good condition. C200. C201. C203. C205. C206. C207. C208. C210. C212. C213. C214. C218. C219. C220.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	15	\$2,400	Each	\$36,000
							C221.										
5436	Batavia High School	1799 - Interior Doors, Swinging- Wood - 2011	BFAC, Fieldhouse (2011)	Storage/Mechani al/IT	c 2020	Sent to Maintenance	Interior wood door in good condition storage between A122 and A121	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$2,400	Each	\$2,400
5441	Batavia High School	1932 - Interiors, Flooring-LVT - 1995	East 2-Story Classrooms (1995	Classrooms	2020	Sent to Maintenance	LVT in excellent condition, looks brand new. C219	Interiors	Interior Finishes	Flooring	Resilient Flooring	4-Future	Excellent 8	807	\$10	Square Foot	\$8,070
5442	Batavia High School	1853 - Interior Doors, Swinging- Hollow Metal - 2011	BFAC, Fieldhouse (2011)	Storage/Mechani al/IT		Sent to Maintenance	Interior HM frame in good condition F101 F105 F107A	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	3	\$1,950	Each	\$5,850
5445	Batavia High School	1921 - Interior	East 2-Story Classrooms (1995	Classrooms		Sent to Maintenance	CMU in good condition. C201. C203. C205. C206. C207. C208. C210. C212. C213. C214. C216. C218. C219. C220. C221.	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good		\$0	Square Foot	\$0









Assessmen	t Campus	Linked Bldg	Addition	Room	Assessment		Description	Building System		Building System		Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cos
ID		System		1	Year	Status		L1	L2	L3	L4						1.
5448	Batavia High School	1845 - Interior Partitions, Fixed- GWB - 1995	East 2-Story Classrooms (1995	Classrooms	2020	Sent to Maintenance	GWB in overall good condition - wal patched by door, but otherwise good condition.	II Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Square Foot	\$0
							C208. C210. C212.										
							C214. C216. C218. C220.										
5450	Batavia High School	1975 - Interior Wall Finishes, Wall Base - 1995	East 2-Story Classrooms (1995	Classrooms	2020	Sent to Maintenance	Wall base in excellent condition. C219	Interiors	Interior Finishes	Wall Finishes		4-Future	Excellent	88	\$6	Linear Foot	\$528
5458	Batavia High School	1747 - Slab on Grade - 2011	BFAC, Fieldhouse (2011)	Storage/Mechani al/IT		Sent to Maintenance	Epoxy flooring in good condition F11A Cost to replace in kind.	Substructure	Slabs-On-Grade	Standard Slabs-on- Grade		4-Future	Good	3723	\$18	Square Foot	\$67,014
5464	Batavia High School	1858 - Interior Partitions, Fixed- CMU - 2011		Storage/Mechani al/IT		Sent to Maintenance	CMU walls in good condition F111A F103B F103C F105	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Square Foot	\$0
							F107A F112M F112K F112L F114 F114A										
5474	Batavia High School	1797 - Interior Doors, Swinging- Wood - 2009	North Classrooms, SW Mechanical (2009)	Science Classrooms		Sent to Maintenance	F115 Wood door in good condition. D202. D204. D206. D208.	Interiors	Interior Construction		Interior Swinging Doors	4-Future	Good	4	\$2,400	Each	\$9,600
5478	Batavia High School	1857 - Interior Partitions, Fixed- CMU - 2009	North Classrooms, SW Mechanical (2009)	Science Classrooms		Sent to Maintenance	D202. D204. D206. D208.	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Linear Foot	\$0
5481	Batavia High School	1987 - Fixed Equipment, Casework - 2009	North Classrooms, SW Mechanical (2009)	Science Classrooms	2020	Sent to Maintenance	Casework in good condition. D202. D204. D206. D208.	Equipment and Furnishings	Furnishings	Fixed Furnishings	Casework	4-Future	Good	137	\$1,200	Linear Foot	\$164,400
5484	Batavia High School	1755 - Exterior Windows, Operating - 2009	North Classrooms, SW Mechanical (2009)	Science Classrooms	2020	Sent to Maintenance	Exterior windows in good condition Verify size in field. D202. D204. D206. D208.	. Shell	Exterior Vertical Enclosures	Exterior Windows	Exterior Operating Windows	4-Future	Good	224	\$100	Square Foot	\$22,400









ssessment	Campus	Linked Bldg	Addition Ro	oom Assessr	nent Assessment	Description	Building System	Building System	Building System	Building System	n Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID	-	System		Yea	r Status		L1	L2	L3	L4	-	,	•			
5488	Batavia High School	1920 - Interior Partitions, Fixed- CMU - 1969	North Central Classrooms (1969)	ms 2020	Sent to Maintenance	Room #: A120, A123 A124 A125 A129 A131 A131A	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Square Foot	\$0
5489	Batavia High School	1921 - Interior Partitions, Fixed- CMU - 1995	East 2-Story Storage Classrooms (1995)	2020	Sent to Maintenance	Room #: A133	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Square Foot	\$0
5490	Batavia High School	1857 - Interior Partitions, Fixed- CMU - 2009	North Explorate Classrooms, SW Mechanical	ories 2020	Sent to Maintenance	Room #: D110 D111 D114 D115 D116	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Square Foot	\$0
5491	Batavia High School	1857 - Interior Partitions, Fixed- CMU - 2009	North Classrooms, SW Mechanical (2009)	2020	Sent to Maintenance	Room #: E101 E101A E103 E105 E106A E106B E106C E106D E106E E106F E106G E106H E106J E107 E107A E107A E107B E108 E109 E109A E109B E109C E110	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Square Foot	\$0
	Batavia High School Batavia High	1858 - Interior Partitions, Fixed- CMU - 2011	BFAC, Fieldhouse (2011) North Central Art Room		Sent to Maintenance	Room #: F100 F100 F100 F103A F103B F106 F107 F109 F109C F109D F110 F111 F200B Women's & Men's RR at F109 Room #: A120	Interiors	Interior Construction	Interior Partitions Interior Partitions	Partitions Interior Fixed	4-Future		0	\$0	Square Foot	\$0
5495	School Batavia High	Partitions, Fixed- GWB 1848 - Interior	Classrooms (1969) BFAC, Fieldhouse	2020	Maintenance Sent to	Room #: F100 Auditorium and Lob	hy Interiors	Construction	Interior Partitions	Partitions Interior Fixed	4-Future	Good	0	\$0	Square Foot	\$0
J 4 J3	School	Partitions, Fixed- GWB - 2011		2020	Maintenance		interiors	Construction		Partitions	 utule	3000	O	U	Square root	, , , , , , , , , , , , , , , , , , ,

Building Our Future TOGETHER

BPS
101










Assessmen ID	t Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cos
5523	Batavia High School	1987 - Fixed Equipment, Casework - 2009	North Classrooms, SW Mechanical (2009)	Exploratories	2020	Sent to Maintenance	Room #: D110. D111. D114. D116.		Furnishings	Fixed Furnishings		4-Future	Good	140	\$1,200	Linear Foot	\$168,000
5534	Batavia High School	1757 - Exterior Windows, Fixed - 2009	North Classrooms, SW Mechanical (2009)	Music Rooms	2020	Sent to Maintenance	Verify size of windows in field. E101A. E107. E107A. E109. E109A.	Shell	Exterior Vertical Enclosures	Exterior Windows	Exterior Fixed Windows	4-Future	Good	950	\$90	Square Foot	\$85,500
5535	Batavia High School	1794 - Interior Windows, Fixed - 2009	North Classrooms, SW Mechanical (2009)	Exploratories	2020	Sent to Maintenance	Verify window size in field. D110. D111. D114. D115.	Interiors	Interior Construction	Interior Windows	Interior Fixed Windows	4-Future	Good	200	\$90	Square Foot	\$18,000
5536	Batavia High School	1696 - Interior Doors, Coiling - Original	BFAC, Fieldhouse (2011)	BFAC Spaces		Sent to Maintenance	Room #: F100 F103B F106 F107 Cost provided for replacement	Interiors	Interior Construction	Interior Doors	Interior Coiling Doors	4-Future	Good	4	\$8,000	Each	\$32,000
5537	Batavia High School	2031 - Flooring, Stone Tile - 2011	BFAC, Fieldhouse (2011)	BFAC Spaces	2020	Sent to Maintenance	Room #: F100: lobby and vestibules BFAC 2nd level lobby Cost is to replace in kind.	Interiors	Interior Finishes	Flooring	Tile Flooring	4-Future	Good	6400	\$30	Square Foot	\$192,000
5538	Batavia High School	2031 - Flooring, Stone Tile - 2011	North Classrooms, SW Mechanical	Music Rooms	2020	Sent to Maintenance	Room #: E110	Interiors	Interior Finishes	Flooring	Tile Flooring	4-Future	Good	711	\$30	Square Foot	\$21,330
5542	Batavia High School	1816 - Interior Railings and Handrails - 2011	BFAC, Fieldhouse (2011)	BFAC Spaces	2020	Sent to Maintenance	Auditorium Stairs, Mezzanine Spaces	Interiors	Interior Construction	Interior Specialties	Interior Railings and Handrails	4-Future	Good	515	\$125	Linear Foot	\$64,375
5544	Batavia High School	2011 - Plumbing, Plumbing Fixtures - 2009	North Classrooms, SW Mechanical (2009)	Exploratories	2014	Sent to Maintenance	Room #: D111 D115 D116	Services	Plumbing	Domestic Water Distribution	Plumbing Fixtures	4-Future	Good	3	\$2,000	Each	\$6,000
5545	Batavia High School	2011 - Plumbing, Plumbing Fixtures - 2009		Music Rooms		Sent to Maintenance	Room #: E109 E!09A	Services	Plumbing	Domestic Water Distribution	Plumbing Fixtures	4-Future	Good	2	\$2,000	Each	\$4,000
5546	Batavia High School	2011 - Plumbing,		BFAC Spaces		Sent to Maintenance	Room #: F109 F109 Mens and Womens	Services	Plumbing	Domestic Water Distribution	Plumbing Fixtures	4-Future	Good	9	\$2,000	Each	\$18,000
5547	Batavia High School	2024 - Interior Wall Finish, Tile - 2011	BFAC, Fieldhouse	BFAC Spaces	2020	Sent to Maintenance	Room #: F109 Mens and Womens Cost is to replace in kind.	Interiors	Interior Finishes	Wall Finishes	Tile Wall Finish	4-Future	Good	530	\$30	Square Foot	\$15,900
5548	Batavia High School	1844 - Interior Specialties, Toilet Compartments - 2011	BFAC, Fieldhouse (2011)			Sent to Maintenance	Room #: F109 Mens and Womens Cost to replace with solid phenolic partitions.	Interiors	Interior Construction	Specialties	Toilet, Bath, and Laundry Accessories	4-Future	Good	3	\$1,800	Each	\$5,400









Assessmen	t Campus	Linked Bldg	Addition	Room	Assessment	Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID		System			Year	Status		L1	L2	L3	L4						
5549	Batavia High	1798 - Interior	South Admin	Storage		Sent to	Interior wood door in good	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good	1	\$2,400	Each	\$2,400
	School	Doors, Swinging-	Addition (2009)			Maintenance	condition		Construction		Doors						
		Wood - 2009					B102B										
		Admin															
5551	Batavia High	1709 - Interior		FACS		Sent to	HM door frame in good condition.	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good	2	\$1,950	Each	\$3,900
	School	Doors, Swinging-				Maintenance	B110		Construction		Doors						
		Hollow Metal -															
		Original												_	40		4.0
5554	Batavia High	1710 - Interior		FACS		Sent to	CMU in good condition.	Interiors	Interior	Interior Partitions		4-Future	Good	0	\$0	Linear Foot	\$0
	School	Partitions, Fixed-				Maintenance	B110		Construction		Partitions						
		CMU - Original												_	40.400		* * * * * * * * * * * * * * * * * * * *
5559	Batavia High	1894 - Interior	North Central	Culinary Arts		Sent to	Wood door in good condition -	Interiors	Interior		Interior Swinging	4-Future	Good	2	\$2,400	Each	\$4,800
	School	Doors, Swinging-	Classrooms (1969	9) A122		Maintenance	metal glazing stop needs paint toucl	n-	Construction		Doors						
		Wood - 1969					up.										
5560	Patavia High	1894 - Interior	North Central	Culinary Arts	2020	Cont to	HM door frames in good condition.	Intoriore	Intorior	Interior Doors	Interior Swinging	4 Futuro	Good	2	\$2,400	Each	\$4,800
5500	Batavia High			-		Sent to	nivi door frames in good condition.	interiors	Interior		0 0	4-ruture	Good	2	\$2,400	EdCII	\$4,800
	School	Doors, Swinging- Wood - 1969	Classrooms (1969	7) A122		Maintenance	A122		Construction		Doors						
5564	Batavia High	1920 - Interior	North Central	Culinary Arts	2020	Sent to	CMU in good condition.	Interiors	Interior	Interior Partitions	Interior Fixed	4-Future	Good	0	\$0	Linear Foot	\$0
3304	School	Partitions, Fixed-	Classrooms (1969	-		Maintenance	CIVIO III good condition.	IIIteriors	Construction	interior Partitions	Partitions	4-ruture	Good	U	3 0	Lilleal Foot	3 0
	301001	CMU - 1969	Classicollis (1905	7) A122		Maintenance	A122		Construction		Partitions						
5569	Batavia High	1853 - Interior	BFAC, Fieldhouse	Building Trades	2020	Sent to	HM door frame in good condition.	Interiors	Interior	Interior Doors	Interior Swinging	1-Euturo	Good	3	\$1,950	Each	\$5,850
3303	School	Doors, Swinging-	(2011)	F111		Maintenance	This door frame in good condition.	interiors	Construction	interior boors	Doors	4-1 utule	dood	3	\$1,930	Lacii	\$3,830
	Scriooi	Hollow Metal -	(2011)	1111		Maintenance	F111		Construction		D0013						
		2011					1111										
5571	Batavia High	1858 - Interior	BFAC, Fieldhouse	Building Trades	2020	Sent to	CMU in good condition.	Interiors	Interior	Interior Partitions	Interior Fixed	4-Future	Good	0	\$0	Linear Foot	\$0
3371	School	Partitions, Fixed-	(2011)	F111		Maintenance	civio in good condition.	meeriors	Construction	micerior rartitions	Partitions	Tracare	0000	•	70	Linear Foot	70
	30.1001	CMU - 2011	(2022)				F111		0011011 01011011								
5575	Batavia High	1674 - Exterior	BFAC, Fieldhouse	Building Trades	2020	Sent to	Exterior windows in good condition.	Shell	Exterior Vertical	Exterior Windows	Exterior Fixed	4-Future	Good	4	\$90	Each	\$360
	School	Windows, Fixed -	(2011)	F111		Maintenance	Verify size of windows in field.		Enclosures		Windows				,		,
		Original	,				, , , , , , , , , , , , , , , , , , , ,										
							F111										
5577	Batavia High	2034 - Interior	BFAC, Fieldhouse	Building Trades	2020	Sent to	Overhead coiling door in good	Interiors	Interior	Interior Doors	Interior Coiling	4-Future	Good	1	\$0	Each	\$0
	School	Doors, Coiling -	(2011)	F111		Maintenance	condition.		Construction		Doors						
		2011															
							F111										
5578	Batavia High	2013 - Plumbing,	BFAC, Fieldhouse	Building Trades	2014	Sent to	Sinks and water fountain in good	Services	Plumbing	Domestic Water	Plumbing Fixtures	4-Future	Good	3	\$2,000	Each	\$6,000
	School	Plumbing Fixtures	(2011)	F111		Maintenance	condition.			Distribution							
		- 2011															
							F111										
5581	Batavia High	2035 - Interior	BFAC, Fieldhouse	Building Trades		Sent to	Interior brick wall in good condition	. Interiors	Interior	Interior Partitions	Interior Fixed	4-Future	Good	0	\$0	Linear Foot	\$0
	School	Partitions, Fixed -	(2011)	F111		Maintenance			Construction		Partitions						
		Brick - 1969					F111										
5591	Batavia High	1875 - Interior	Central Area,	Kitchen/Servery		Sent to	HM Door in good condition	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good	1	\$1,950	Each	\$1,950
	School	Doors, Swinging-	South Entrance			Maintenance			Construction		Doors						
		Hollow Metal -	(1995)				A102 Servery										
		1995 Entry															
5594	Batavia High	1740 - Interiors,		Office / Pull-Out		Sent to	Flooring is in Excellent Condition	Interiors	Interior Finishes	Flooring	Resilient Flooring	4-Future	Excellent	380	\$10	Square Foot	\$3,800
	School	Flooring-LVT -				Maintenance	B122A (Conference Room)										
		Original															

Building Our Future TOGETHER BPS







Assessmen	nt Campus	Linked Bldg	Addition	Room	Assessment	Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID		System			Year	Status		L1	L2	L3	L4						
5605	Batavia High	1710 - Interior		Office / Pull-Out	2020	Sent to	CMU Wall is in Good Condition	Interiors	Interior	Interior Partitions	Interior Fixed	4-Future	Good	0	\$0	Linear Foot	\$0
	School	Partitions, Fixed-				Maintenance	A104B,		Construction		Partitions						
		CMU - Original					A106,										
							A108B,										
							B107A,										
							B108,										
							B114,										
							B114A,										
							B118,										
							B118A,										
							B118B,										
							B118F,										
							B118G,										
							B118H,										
							B119D,										
							B120,										
							B121,										
							B122,										
							B122,										
							B122B										
							B122C										
							B122E										
							B123										
							B123										
							B124										
							B124A										
							B124C										
							B124D										
							B124E										
5643	Batavia High		North Central	Office / Pull-Out	2020	Sent to	CMU Wall is in Good Condition		Interior	Interior Partitions		4-Future	Good	0	\$0	Linear Foot	\$0
	School		Classrooms (1969	9)		Maintenance	A125A,		Construction		Partitions						
		CMU - 1969		1			A129A										
5646	Batavia High		Central Area,	Office / Pull-Out	2020	Sent to	CMU Wall is in Good Condition		Interior	Interior Partitions		4-Future	Good	0	\$0	Linear Foot	\$0
	School		South Entrance			Maintenance	A101A, A101B, A134A		Construction		Partitions						
		CMU - 1995	(1995)														










sessment	t Campus	Linked Bldg	Addition	Room	Assessmen	Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Co
ID	•	System			Year	Status	·	L1	L2	L3	L4		-				
5647	Batavia High School	1856 - Interior Partitions, Fixed- CMU - 2009 Admin	South Admin Addition (2009)	Office / Pull-Out	2020	Sent to Maintenance	CMU Wall is in Good Condition A102C, B100, B100B, B100C, B100D, B100F, B100G, B100H, B100J, B100L, B100L, B101L, B101A, B101B, B101C, B101D, B101D, B101D, B101D, B101D, B101E, B101A, B101E, B101A, B101E, B101A, B101B, B101C, B101D, B101E, B101A, B101A, B101A, B101A, B101A,	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Linear Foot	\$0
							D117,										
5648	Batavia High School	1858 - Interior Partitions, Fixed- CMU - 2011	BFAC, Fieldhouse (2011)	Office / Pull-Out	2020	Sent to Maintenance	D211 CMU Wall is in Good Condition F102 (Auditorium Manager) F111 (Building Trades Office)	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Linear Foot	\$0
5651	Batavia High School	1708 - Interior Partitions, Fixed - GWB - Original		Office / Pull-Out	2020	Sent to Maintenance	GWB walls are in Good condition B118D, B118F, B118G, B118H, B120, B121,	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Linear Foot	\$0
5655	Batavia High School	1846 - Interior Partitions, Fixed- GWB - 2009 Admin	South Admin Addition (2009)	Office / Pull-Out	2020	Sent to Maintenance	B122 GWB walls are in Fair condition B100, B100E, B100F, B100K, B101, D110A, D112	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Linear Foot	\$0
	Batavia High School	1709 - Interior Doors, Swinging- Hollow Metal - Original		Corridor	2020	Sent to Maintenance	Interior HM doors and frames in good condition. B-CORRIDOR. B-CORRIDOR NORTH OF FAC CENTER (TEAL LOCKERS). B-CORRIDOR BETWEEN MAIN OFFICE AND STUDENT SERVICES.		Interior Construction		Interior Swinging Doors	4-Future	Good	3	\$1,950	Each	\$5,850
5746	Batavia High School	1797 - Interior Doors, Swinging- Wood - 2009	North Classrooms, SW Mechanical	Corridor	2020	Sent to Maintenance	Interior wood door in good condition PRACTICE CORRIDOR	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$2,400	Each	\$2,400









Accoccmont	t Campus	Linked Bldg	Addition	Room	Assessment	Assassment	Description	Building System	Building Sustan	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Massure	Estimated Cost
Assessment ID	Campus	System	Addition	Koom	Year	Assessment Status	Description	L1	L2	L3	L4	Priority	racility Condition	Quantity	Unit Cost	Unit Of Measure	e Estimated Cost
5747	Batavia High	1852 - Interior	North	Corridor	2020	Sent to	Interior HM door in good condition	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good)	\$1,950	Each	\$3,900
3747	School	Doors, Swinging-	Classrooms, SW	Corridor	2020	Maintenance	E CORRIDOR	IIICCTIOTS	Construction	interior boors	Doors	Tuture	2000	=	71,550	Lucii	75,500
		Hollow Metal -	Mechanical				PRACTICE CORRIDOR										
		2009	(2009)														
5750	Batavia High	1852 - Interior	North	Corridor	2020	Sent to	Interior HM frame in good condition	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good 1	Ĺ	\$1,950	Each	\$1,950
	School	Doors, Swinging-	Classrooms, SW			Maintenance	E CORRIDOR		Construction		Doors						
		Hollow Metal -	Mechanical														
		2009	(2009)														
5757	Batavia High	1857 - Interior	North	Corridor	2020	Sent to	CMU wall in good condition	Interiors	Interior	Interior Partitions	Interior Fixed	4-Future	Good)	\$0	Square Foot	\$0
	School	Partitions, Fixed-	Classrooms, SW			Maintenance	D-wing corridors level 1		Construction		Partitions						
		CMU - 2009	Mechanical				E CORRIDOR										
			(2009)				E CORRIDOR - CHORAL										
							PRACTICE CORRIDOR										
5763	Batavia High	1757 - Exterior	North	Corridor	2020	Sent to		Shell	Exterior Vertical	Exterior Windows		4-Future	Good	L	\$90	Each	\$90
	School	Windows, Fixed -	Classrooms, SW			Maintenance	Verify location and size of windows		Enclosures		Windows						
		2009	Mechanical				in field.										
			(2009)				E CORRIDOR - CHORAL								4		
5765	Batavia High	1814 - Interior	North	Corridor	2020	Sent to	stair pipe in good condition. Verify	Interiors	Interior	Interior	Interior Railings	4-Future	Good)	\$150	Linear Foot	\$0
	School	Railings and	Classrooms, SW			Maintenance	length and location in field.		Construction	Specialties	and Handrails						
		Handrails - 2009	Mechanical				E CORRIDOR										
			(2009)														
F766		4765 5	N1	0 11	2020	6	Replacement cost provided.	CI II	5	- · · · ·					47.500	- 1	47.500
5766	Batavia High	1765 - Exterior	North	Corridor	2020	Sent to	Exterior Alum. door in good	Shell	Exterior Vertical	Exterior Doors	Exterior Entrance	4-Future	Good	L	\$7,500	Each	\$7,500
	School	Entrance Doors,	Classrooms, SW			Maintenance	condition		Enclosures	and Grilles	Doors						
F7C0	Data da Histo	Aluminum - 2009	Mechanical	Camidan	2020	Cambba	E CORRIDOR	Chall	Futoviou Voution	Fisherian Deem	Futorion Fatoros	4 5	Good	<u> </u>	¢7.500	Fa ala	¢15 000
5768	Batavia High	1765 - Exterior	North	Corridor	2020	Sent to	Exterior Alum Frame in good	Shell	Exterior Vertical	Exterior Doors	Exterior Entrance	4-ruture	Good	<u> </u>	\$7,500	Each	\$15,000
	School	Entrance Doors, Aluminum - 2009	Classrooms, SW			Maintenance	condition E CORRIDOR - CHORAL		Enclosures	and Grilles	Doors						
5769	Batavia High	2112 - Flooring,	Mechanical North	Corridor	2020	Sent to	Terrazzo flooring in good condition.	Interiors	Interior Finishes	Flooring	Terrazzo Flooring	1-Euturo	Good 3	3800	\$15	Square Foot	\$57,000
3703	School	Terrazzo - 2009	Classrooms, SW	Corridor	2020	Maintenance	E CORRIDOR	interiors	interior rinishes	riooring	Terrazzo Frooring	4-1 uture	Good	8800	313	Square 100t	\$37,000
	3011001	16118220 - 2003	Mechanical			iviairiteriarice	E CORRIDOR										
			(2009)				Cost is for potential grinding and										
			(2003)				crack repair.										
5770	Batavia High	1852 - Interior	North	Stair	2020	Sent to	Interior HM door in good condition	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good)	\$1,950	Each	\$3,900
37.70	School	Doors, Swinging-	Classrooms, SW	o tun	2020	Maintenance	Stair by d110 level 1		Construction		Doors			-	42 ,330	20011	45,500
		Hollow Metal -	Mechanical				Stair by d110 level 2										
		2009	(2009)				, , , , , , , , , , , , , , , , , , , ,										
5771	Batavia High	1852 - Interior	North	Stair	2020	Sent to	Interior HM frame in good condition	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good	L	\$1,950	Each	\$1,950
	School	Doors, Swinging-	Classrooms, SW			Maintenance	Stair by d110 level 1		Construction		Doors						
		Hollow Metal -	Mechanical														
		2009	(2009)														
5776	Batavia High	1857 - Interior	North	Stair	2020	Sent to	CMU wall in good condition	Interiors	Interior	Interior Partitions	Interior Fixed	4-Future	Good)	\$0	Square Foot	\$0
	School	Partitions, Fixed-	Classrooms, SW			Maintenance	Stair by d110 level 1		Construction		Partitions						
		CMU - 2009	Mechanical				Stair by d110 level 2										
5777	Batavia High	1847 - Interior	North	Stair	2020	Sent to	GWB wall in good condition	Interiors	Interior	Interior Partitions	Interior Fixed	4-Future	Good)	\$0	Square Foot	\$0
	School	Partitions, Fixed-	Classrooms, SW			Maintenance	Stair by d110 level 1		Construction		Partitions						
		GWB - 2009	Mechanical														
5781	Batavia High	1756 - Exterior	North	Stair	2020	Sent to	Exterior window in good condition	Shell	Exterior Vertical	Exterior Windows		4-Future	Good	20	\$90	Square Foot	\$1,800
	School	Windows, Fixed -	Classrooms, SW			Maintenance			Enclosures		Windows						
		2011	Mechanical				Stair by d110 level 2										
5784	Batavia High	1765 - Exterior	North	Stair	2020	Sent to	Exterior Alum door in good	Shell	Exterior Vertical	Exterior Doors	Exterior Entrance	4-Future	Good	L	\$7,500	Each	\$7,500
	School	Entrance Doors,	Classrooms, SW			Maintenance	condition		Enclosures	and Grilles	Doors						
	1						Stair by d110 level 1	1							1.		1.
5785	Batavia High	1765 - Exterior	North	Stair	2020	Sent to	_	Shell	Exterior Vertical	Exterior Doors	Exterior Entrance	4-Future	Good	L	\$7,500	Each	\$7,500
	School		Classrooms, SW			Maintenance	condition		Enclosures	and Grilles	Doors						
		Aluminum - 2009	Mechanical				Stair by d110 level 2										









Assessment	Campus	Linked Bldg	Addition	Room	Assessment	Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID	-	System			Year	Status	•	L1	L2	L3	L4	-					
5790	Batavia High	1857 - Interior	North	Vestibule	2020	Sent to	CMU wall in good condition	Interiors	Interior	Interior Partitions	Interior Fixed	4-Future	Good)	\$0	Square Foot	\$0
	School	Partitions, Fixed-	Classrooms, SW			Maintenance	D-wing middle vestibule		Construction		Partitions						
		CMU - 2009	Mechanical					a							4		4
5792	Batavia High	1765 - Exterior	North	Vestibule	2020	Sent to	Exterior Alum door in good	Shell	Exterior Vertical	Exterior Doors	Exterior Entrance	4-Future	Good	l	\$7,500	Each	\$7,500
	School	Entrance Doors, Aluminum - 2009	Classrooms, SW			Maintenance	condition		Enclosures	and Grilles	Doors						
5793	Batavia High	1765 - Exterior	Mechanical North	Vestibule	2020	Sent to	D-wing middle vestibule Exterior Alum frame in good	Shell	Exterior Vertical	Exterior Doors	Exterior Entrance	A-Euturo	Good	1	\$7,500	Each	\$7,500
3733	School	Entrance Doors,	Classrooms, SW	vestibule	2020	Maintenance	condition	Sileii	Enclosures	and Grilles	Doors	4-1 utule	Good	L	\$7,500	Lacii	\$7,500
	3611001	Aluminum - 2009	Mechanical			Wantenance	D-wing middle vestibule		Enclosures	and ormes	50013						
5794	Batavia High	1798 - Interior	South Admin	Corridor	2020	Sent to	Interior wood door in good	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good 2	 1	\$2,400	Each	\$2,400
	School	Doors, Swinging-	Addition (2009)			Maintenance	condition		Construction		Doors						
		Wood - 2009					2009 office										
		Admin															
5795	Batavia High	1851 - Interior	South Admin	Corridor	2020	Sent to	Interior HM frame in good condition	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good	l	\$1,950	Each	\$1,950
	School	Doors, Swinging-	Addition (2009)			Maintenance	(Minor painting needed)		Construction		Doors						
		Hollow Metal -					2009 office										
		2009 Admin															
5798	Batavia High	1856 - Interior	South Admin	Corridor	2020	Sent to	CMU walls (Bullnosed corners could	Interiors	Interior	Interior Partitions		4-Future	Good)	\$0	Square Foot	\$0
	School	Partitions, Fixed-	Addition (2009)			Maintenance	use touch up paint)		Construction		Partitions						
		CMU - 2009					2009 office										
F700	Data da Histo	Admin	Cauth Admin	Camidan	2020	Cambba	CMD walls in sold and dition	luta di a da	lutorio r	Interior Doubitions	Interior Fired	4 5	Good	`	\$0	Carrage Foot	ćo
5799	Batavia High	1846 - Interior	South Admin	Corridor	2020	Sent to	GWB walls in good condition	Interiors	Interior	Interior Partitions		4-Future	Good	J	\$0	Square Foot	\$0
	School	Partitions, Fixed- GWB - 2009	Addition (2009)			Maintenance	2009 office		Construction		Partitions						
		Admin															
5816	Batavia High	1850 - Interior	East 2-Story	Vestibule	2020	Sent to	3 interior HM doors in good	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good	₹	\$1,950	Each	\$5,850
3010	School	Doors, Swinging-	Classrooms (199		2020	Maintenance	condition	IIICCTIOTS	Construction	interior boors	Doors	4 Tuture	Good	,	71,550	Eden	75,050
	33.133.	Hollow Metal -	0.000.000 (200.			aee	C-wing south vestibule				200.5						
		1995															
5819	Batavia High	1763 - Exterior	East 2-Story	Vestibule	2020	Sent to	Exterior HM door in good condition	Shell	Exterior Vertical	Exterior Doors	Exterior Entrance	4-Future	Good :	L	\$7,500	Each	\$7,500
	School	Entrance Doors,	Classrooms (199	5)		Maintenance	C-wing south vestibule		Enclosures	and Grilles	Doors						
		Hollow Metal -															
		1995															
5828	Batavia High	1921 - Interior	East 2-Story	Vestibule	2020	Sent to	CMU wall in good condition	Interiors	Interior	Interior Partitions		4-Future	Good)	\$0	Square Foot	\$0
	School	Partitions, Fixed-	Classrooms (199	5)		Maintenance	C-wing south vestibule		Construction		Partitions						
		CMU - 1995					C-wing north center vest.								4		
5844	Batavia High	1896 - Interior	East 2-Story	Stair	2020	Sent to	Interior wood door in good	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good	5	\$2,400	Each	\$12,000
	School		Classrooms (199	5)		Maintenance	condition. Stair by C101 level 1.		Construction		Doors						
F047	Potovio High	Wood - 1995	Fact 2 Story	Stair	2020	Cant to	-	Chall	Exterior Vertical	Exterior Deers	Exterior Entrance	4 Futuro	Cood	1	¢7.500	Fach	¢7.500
5847	Batavia High School	1763 - Exterior Entrance Doors,	East 2-Story Classrooms (1999)		2020	Sent to Maintenance	Exterior HM door in good condition Stair by c122 level 1	Shell	Exterior Vertical Enclosures	Exterior Doors and Grilles	Exterior Entrance Doors	4-ruture	Good	L	\$7,500	Each	\$7,500
	3011001	Hollow Metal -	Classicollis (199.	3)		ivialifice	Stail by C122 level 1		Liiciosures	and Offiles	Doors						
		1995															
5858	Batavia High	1921 - Interior	East 2-Story	Stair	2020	Sent to	CMU wall in good condition	Interiors	Interior	Interior Partitions	Interior Fixed	4-Future	Good)	\$0	Square Foot	\$0
3030	School		Classrooms (199		2020	Maintenance	C-Wing South Stair		Construction		Partitions				Ψ**	oqua.c.root	70
		CMU - 1995	,				C-Wing North Stair										
5874	Batavia High	1875 - Interior	Central Area,	Corridor	2020	Sent to	Interior HM door in good condition.	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good	5	\$1,950	Each	\$11,700
	School	Doors, Swinging-	South Entrance			Maintenance	E/W Corridor between café and		Construction		Doors						
		Hollow Metal -	(1995)				Gym.										
		1995 Entry															
5876	Batavia High	1852 - Interior	North	Corridor	2020	Sent to	Interior HM frame in good condition	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good	5	\$1,950	Each	\$11,700
	School	Doors, Swinging-	Classrooms, SW			Maintenance	N/S Corridor, near A131.		Construction		Doors						
		Hollow Metal -	Mechanical				E/W Corridor, near A132.										
		2009	(2009)						1	1	1	1	1		1		










Assessment	Campus	Linked Bldg	Addition	Room	Assessment	Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID		System			Year	Status		L1	L2	L3	L4			-			
5886	Batavia High	1921 - Interior	East 2-Story	Corridor	2020	Sent to	CMU wall in good condition	Interiors	Interior	Interior Partitions	Interior Fixed	4-Future	Good	0	\$0	Square Foot	\$0
	School	Partitions, Fixed-	Classrooms (199	5)		Maintenance	C-wing south corridor, level 1		Construction		Partitions						
		CMU - 1995															
5910	Batavia High	1921 - Interior	East 2-Story	Corridor	2020	Sent to	CMU wall in good condition	Interiors	Interior	Interior Partitions		4-Future	Good	0	\$0	Square Foot	\$0
	School	Partitions, Fixed-	Classrooms (199	5)		Maintenance	C-Wing 2nd Floor Corridor		Construction		Partitions						
5024	Data da Hilab	CMU - 1995	BFAC. Fieldhouse	. Manakiba da	2020	C 1 1 -	Extraction with down to provide any distingu	Ch - II	Francis a Manatical	Estada NACA da com	Establish Eisted	4.5	Cood	100	¢00	Carrage Facat	ć0.000
5931	Batavia High	1967 - Exterior Windows, Fixed -	(2011)	vestibule	2020	Sent to Maintenance	Exterior window in good condition. VESTIBULE SOUTH ADJACENT TO	Sneii	Exterior Vertical	Exterior Windows	Windows	4-Future	Good	100	\$90	Square Foot	\$9,000
	School	2011	(2011)			iviaintenance	PARKING LOT		Enclosures		Williaows						
5932	Batavia High	1764 - Exterior	BFAC, Fieldhouse	Vestihule	2020	Sent to	Exterior Alum door in good	Shell	Exterior Vertical	Exterior Doors	Exterior Entrance	4-Future	Good	1	\$7,500	Each	\$7,500
3302	School	Entrance Doors,	(2011)		2020	Maintenance	condition	5	Enclosures	and Grilles	Doors		3334	-	<i>ψ.</i> 1,500		ψ.,500
		Aluminum - 2011	(/				VESTIBULE SOUTH ADJACENT TO										
5933	Batavia High	1764 - Exterior	BFAC, Fieldhouse	Vestibule	2020	Sent to	Exterior Alum frame in good	Shell	Exterior Vertical	Exterior Doors	Exterior Entrance	4-Future	Good	1	\$7,500	Each	\$7,500
	School	Entrance Doors,	(2011)			Maintenance	condition		Enclosures	and Grilles	Doors						
		Aluminum - 2011					VESTIBULE SOUTH ADJACENT TO										
							PARKING LOT										
5934	Batavia High	1799 - Interior	BFAC, Fieldhouse	Stair/Corridor	2020	Sent to	Interior wood door in good	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good	1	\$2,400	Each	\$2,400
	School	Doors, Swinging-	(2011)			Maintenance	condition		Construction		Doors						
5025	Data da Hilab	Wood - 2011	DEAC Elabora	Stain/Gamidan	2020	C 1 1 -	Stair 4	Late de la	La bandan	Latarian Danna	lataria o Carinaia a	4.5	Cood	4	¢4.050	El.	Ć4 050
5935	Batavia High	1853 - Interior	BFAC, Fieldhouse (2011)	Stair/Corridor	2020	Sent to	Interior HM door in good condition Stair 4	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good	1	\$1,950	Each	\$1,950
	School	Doors, Swinging- Hollow Metal -	(2011)			Maintenance	Stall 4		Construction		Doors						
		2011															
5938	Batavia High	1858 - Interior	BFAC, Fieldhouse	Stair/Corridor	2020	Sent to	CMU wall in good condition	Interiors	Interior	Interior Partitions	Interior Fixed	4-Future	Good	0	ŚO	Square Foot	\$0
	School	Partitions, Fixed-	(2011)	, , , , , , , , , , , , , , , , , , , ,		Maintenance	Stair 4		Construction		Partitions						
		CMU - 2011															
5943	Batavia High	1816 - Interior	BFAC, Fieldhouse	Stair/Corridor	2020	Sent to	stairs pipe rails in good condition.	Interiors	Interior	Interior	Interior Railings	4-Future	Good	0	\$125	Linear Foot	\$0
	School	Railings and	(2011)			Maintenance	Verify location and quantity in field.		Construction	Specialties	and Handrails						
		Handrails - 2011					Stair 4										
5945	Datavia High	1799 - Interior	BFAC, Fieldhouse	Carridar	2020	Sent to	Replacement cost provided.	Intoriors	Interior	Interior Deers	Interior Swinging	4 Futuro	Good	2	\$2,400	Each	\$4,800
5945	Batavia High School	Doors, Swinging-	(2011)	Corridor	2020	Maintenance	Interior wood door in good condition	Interiors	Interior Construction	Interior Doors	Doors	4-ruture	Good	2	\$2,400	EdCII	\$4,800
	3011001	Wood - 2011	(2011)			Maintenance	NORTH CORRIDOR BFAC		Construction		D0013						
5947	Batavia High	1853 - Interior	BFAC, Fieldhouse	Corridor	2020	Sent to	Interior HM door in good condition	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good	4	\$1,950	Each	\$7,800
	School	Doors, Swinging-	(2011)			Maintenance	CORRIDOR BETWEEN BFAC/FIELD		Construction		Doors				7-7		7.7555
		Hollow Metal -	,				HOUSE										
		2011					NORTH CORRIDOR BFAC										
							CORRIDOR SOUTH OF FIELD HOUSE										
							CORRIDOR ADJACENT TO MECH										
5948	Batavia High	1760 - Exterior	BFAC, Fieldhouse	Corridor	2020	Sent to	Exterior HM door in good condition	Shell	Exterior Vertical	Exterior Doors	Exterior Entrance	4-Future	Good	3	\$7,500	Each	\$22,500
	School	Entrance Doors,	(2011)			Maintenance	CORRIDOR BETWEEN BFAC/FIELD		Enclosures	and Grilles	Doors						
		Hollow Metal -					HOUSE (ALUM FRAME AND DOOR										
		2011					WITH GLASS)										
							NORTH CORRIDOR BFAC										
							CORRIDOR SOUTH OF FIELD HOUSE										
5950	Batavia High	1853 - Interior	BFAC, Fieldhouse	Corridor	2020	Sent to	(ALUM. EXTERIOR). Interior HM frame in good condition	Interiors	Interior	Interior Doors	Interior Swinging	1-Future	Good	1	\$1,950	Each	\$7,800
3330	School	Doors, Swinging-	(2011)	Corridor	2020	Maintenance	CORRIDOR BETWEEN BFAC/FIELD	interiors	Construction	interior Doors	Doors	uture	Julia	7	71,550	Lacii	000,7ب
	5511001	Hollow Metal -	(_011)			ac.iaiice	HOUSE		2311311 4011011		23013						
		2011					NORTH CORRIDOR BFAC										
		2011															
		2011					CORRIDOR SOUTH OF FIELD HOUSE										

Building Our Future TOGETHER

BPS
101









Assessmen	nt Campus	Linked Bldg	Addition	Room	Assessment		Description	Building System		Building System		Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
5951	Batavia High School	System 1760 - Exterior Entrance Doors,	BFAC, Fieldhouse Cor (2011)	rridor	Year 2020	Sent to Maintenance	Exterior HM frame in good condition CORRIDOR BETWEEN BFAC/FIELD	L1 Shell	L2 Exterior Vertical Enclosures		Exterior Entrance Doors	4-Future	Good	3	\$7,500	Each	\$22,500
		Hollow Metal - 2011					HOUSE NORTH CORRIDOR BFAC (RUST AT STEEL PLATE ABOVE DOOR OPENING). CORRIDOR SOUTH OF FIELD HOUSE		Literosur es	and drines							
5957	Batavia High School	1858 - Interior Partitions, Fixed- CMU - 2011	BFAC, Fieldhouse (2011)	rridor	2020	Sent to Maintenance	CMU wall in good condition Field house corridor (PAINT SCRATCHES, BUT OVERALL GOOD CONDITION). CORRIDOR BETWEEN BFAC/FIELD HOUSE NORTH CORRIDOR BFAC CORRIDOR SOUTH OF FIELD HOUSE CORRIDOR ADJACENT TO MECH	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Square Foot	\$0
5963	Batavia High School	1796 - Interior Windows, Fixed - 2011	BFAC, Fieldhouse (2011)	rridor	2020	Sent to Maintenance		Interiors	Interior Construction	Interior Windows	Interior Fixed Windows	4-Future	Good	0	\$90	Square Foot	\$0
5964	Batavia High School	2032 - Flooring, Epoxy - 2011	BFAC, Fieldhouse (2011)	rridor	2020	Sent to Maintenance	Epoxy/SC in good condition Field house corridor CORRIDOR BETWEEN BFAC/FIELD HOUSE Cost to replace in kind	Interiors	Interior Finishes	ū	Fluid-Applied Flooring	4-Future	Good	6051	\$18	Square Foot	\$108,918
5966	Batavia High School	1873 - Interior Doors, Swinging- Hollow Metal - 1969	North Central Col Classrooms (1969)	rridor		Sent to Maintenance	Interior HM door in good condition N/S Corridor	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$1,950	Each	\$1,950
5967	Batavia High School	1873 - Interior Doors, Swinging- Hollow Metal - 1969	North Central Classrooms (1969)	rridor	2020	Sent to Maintenance	Interior HM frame in good condition N/S Corridor	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$1,950	Each	\$1,950
5970	Batavia High School	1920 - Interior Partitions, Fixed- CMU - 1969	North Central Col Classrooms (1969)	rridor		Sent to Maintenance	CMU walls in good condition N/S Corridor	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Square Foot	\$0
5983	Batavia High School	1710 - Interior Partitions, Fixed- CMU - Original	Ves	stibule	2020	Sent to Maintenance	CMU wall in good condition	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Square Foot	\$0
5990	Batavia High School	1710 - Interior Partitions, Fixed- CMU - Original	Col	rridor		Sent to Maintenance	CMU wall in good condition. Corridor north of main office. B-CORRIDOR. B-CORRIDOR NORTH OF FAC CENTER (TEAL LOCKERS). B-CORRIDOR BETWEEN MAIN OFFICE AND STUDENT SERVICES	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Square Foot	\$0
5996	Batavia High School	1694 - Interior Windows, Fixed - Original	Cor	rridor	2020	Sent to Maintenance	Interior windows in good condition. Verify size and location of window(s) in field. B-CORRIDOR NORTH OF FAC CENTER (TEAL LOCKERS)		Interior Construction	Interior Windows	Interior Fixed Windows	4-Future	Good	50	\$90	Square Foot	\$4,500










Assessmen ID	nt Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cos
5998	Batavia High School	1741 - Interior Wall Finish, Tile - Original		Corridor		Sent to Maintenance	Ceramic wall tile in good condition. Verify quantity in field. B-CORRIDOR NORTH OF FAC CENTER (TEAL LOCKERS)	Interiors	Interior Finishes			4-Future	Good	240	\$30	Square Foot	\$7,200
6012	Batavia High School	1695 - Interior Doors, Swinging- Wood - Original		Server room	2020	Sent to Maintenance	Interior wood door is in good condition B105	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$2,400	Each	\$2,400
6016	Batavia High School	1710 - Interior Partitions, Fixed- CMU - Original		Server room	2020	Sent to Maintenance	CMU walls are in a good condition B105	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Square Foot	\$0
6027	Batavia High School	1710 - Interior Partitions, Fixed- CMU - Original		Fitness Center	2020	Sent to Maintenance	CMU wall in good condition A103	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Square Foot	\$0
6031	Batavia High School	1894 - Interior Doors, Swinging- Wood - 1969	North Central Classrooms (1969)	Staff Toilet Room	2020	Sent to Maintenance	Interior wood door in good condition A129A-T	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$2,400	Each	\$2,400
6040	Batavia High School	1710 - Interior Partitions, Fixed- CMU - Original		Locker Room	2020	Sent to Maintenance	CMU wall in good condition . A104W Locker Room. A105AStaff Locker Room. A108Men's Locker Room. A110 Mens' Team Locker Room	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Square Foot	\$0
6051	Batavia High School	1711 - Interior Doors, Swinging- Wood - 1995 Entry	Central Area, South Entrance (1995)	Cafeteria	2020	Sent to Maintenance	Interior wood door in good condition (minor scuffs in veneer) A100	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	2	\$2,400	Each	\$4,800
6053	Batavia High School	1767 - Exterior Entrance Doors, Aluminum - 1995 Entry	Central Area, South Entrance (1995)	Cafeteria	2020	Sent to Maintenance	Exterior door in good condition (some paint touch-up required). A100	Shell	Exterior Vertical Enclosures	Exterior Doors and Grilles	Exterior Entrance Doors	4-Future	Good	1	\$7,500	Each	\$7,500
6054	Batavia High School	1767 - Exterior Entrance Doors, Aluminum - 1995 Entry	Central Area, South Entrance (1995)	Cafeteria		Sent to Maintenance	Exterior door frame in good condition A100	Shell	Exterior Vertical Enclosures	Exterior Doors and Grilles	Exterior Entrance Doors	4-Future	Good	2	\$7,500	Each	\$15,000
6066	Batavia High School	1855 - Interior Partitions, Fixed- CMU - 1995 Entry	South Entrance	School store		Sent to Maintenance	CMU wall in good condition A100A	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Square Foot	\$0
6069	Batavia High School	1797 - Interior Doors, Swinging- Wood - 2009	North Classrooms, SW Mechanical	Training	2020	Sent to Maintenance	Interior wood door in good condition A134	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$2,400	Each	\$2,400
6070	Batavia High School	1852 - Interior Doors, Swinging- Hollow Metal - 2009	North Classrooms, SW Mechanical (2009)	Training		Sent to Maintenance	Interior HM frame in good condition A134	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$1,950	Each	\$1,950
6073	Batavia High School	1857 - Interior Partitions, Fixed- CMU - 2009	North Classrooms, SW Mechanical	Training		Sent to Maintenance	CMU wall in good condition A134	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Square Foot	\$0
6080	Batavia High School	1855 - Interior Partitions, Fixed- CMU - 1995 Entry	Central Area, South Entrance	W locker room	2020	Sent to Maintenance	CMU wall in good condition A106	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Square Foot	\$0
6087	Batavia High School	1711 - Interior Doors, Swinging- Wood - 1995 Entry	Central Area, South Entrance (1995)	Wrestling	2020	Sent to Maintenance	Interior wood door in good condition A107A	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$2,400	Each	\$2,400









Assessment	Campus	Linked Bldg System	Addition	Room	Assessment	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
6089	Batavia High School	1875 - Interior Doors, Swinging- Hollow Metal - 1995 Entry	Central Area, South Entrance (1995)	Wrestling	2020	Sent to Maintenance	Interior HM frame in good condition A107A		Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$1,950	Each	\$1,950
6090	Batavia High School	1855 - Interior Partitions, Fixed- CMU - 1995 Entry	Central Area, South Entrance (1995)	Wrestling	2020	Sent to Maintenance	CMU wall in good condition A107A	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Square Foot	\$0
6094	Batavia High School	1797 - Interior Doors, Swinging- Wood - 2009	North Classrooms, SW Mechanical	Dance Gym	2020	Sent to Maintenance	Interior wood door in good condition A132	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$2,400	Each	\$2,400
6095	Batavia High School	1852 - Interior Doors, Swinging- Hollow Metal - 2009	North Classrooms, SW Mechanical (2009)	Dance Gym	2020	Sent to Maintenance	Interior HM frame in good condition A132	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$1,950	Each	\$1,950
6098	Batavia High School	1857 - Interior Partitions, Fixed- CMU - 2009	North Classrooms, SW Mechanical	Dance Gym	2020	Sent to Maintenance	CMU wall in good condition A132	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Square Foot	\$0
6110	Batavia High School		BFAC, Fieldhouse (2011)	Field House	2020	Sent to Maintenance	Operable gym curtain in good condition. F112	Equipment and Furnishings	Equipment	Entertainment and Recreational Equipment	Athletic Equipment	4-Future	Good	300	\$100	Linear Foot	\$30,000
6114	Batavia High School	1756 - Exterior Windows, Fixed - 2011	BFAC, Fieldhouse (2011)	Field House	2020	Sent to Maintenance	Cost is for curtain replacement only. Exterior window in good condition. Verify size of windows in field. F112	Shell	Exterior Vertical Enclosures	Exterior Windows	Exterior Fixed Windows	4-Future	Good	0	\$90	Square Foot	\$0
6115	Batavia High School	2040 - Exterior Doors, Coiling - 2011	BFAC, Fieldhouse (2011)	Field House	2020	Sent to Maintenance		Shell	Exterior Vertical Enclosures	Exterior Doors and Grilles	Exterior Entrance Doors	4-Future	Good	1	\$10,000	Each	\$10,000
6119	Batavia High School	1853 - Interior Doors, Swinging- Hollow Metal - 2011	BFAC, Fieldhouse (2011)	Storage	2020	Sent to Maintenance	Interior HM frame in good condition. F112BSTORAGE. F112CSTORAGE	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	2	\$1,950	Each	\$3,900
6121	Batavia High School	1858 - Interior Partitions, Fixed- CMU - 2011	BFAC, Fieldhouse (2011)	Storage	2020	Sent to Maintenance	CMU wall in good condition F112BSTORAGE F112CSTORAGE	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Square Foot	\$0
6127	Batavia High School	1756 - Exterior Windows, Fixed - 2011	BFAC, Fieldhouse (2011)	Storage	2020	Sent to Maintenance	Exterior window in good condition. Verify size and location in field. F112BSTORAGE. F112CSTORAGE.	Shell	Exterior Vertical Enclosures	Exterior Windows	Exterior Fixed Windows	4-Future	Good	0	\$90	Square Foot	\$0
6128	Batavia High School	1816 - Interior Railings and Handrails - 2011	BFAC, Fieldhouse (2011)	Storage	2020	Sent to Maintenance	Stair pipe in good condition. Verify location in field. F112JSTORAGE Replacement cost provided.	Interiors	Interior Construction	Interior Specialties	Interior Railings and Handrails	4-Future	Good	0	\$125	Linear Foot	\$0
6146	Batavia High School		North Classrooms, SW Mechanical (2009)	Corridor	2020	Sent to Maintenance	CMU wall in good condition. C-wing south corridor, level 1. E/W Corridor. N/S Corridor, near A131. E/W Corridor, near A132.	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Square Foot	\$0
6149	Batavia High School	1855 - Interior Partitions, Fixed- CMU - 1995 Entry		Corridor		Sent to Maintenance	CMU wall in good condition E/W Corridor between café and Gym E/W Corridor corridor between locker rooms and 120s classrooms N/S Corridor near A131	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0		\$0









ssessment	Campus	Linked Bldg	Addition	Room	Assessment	Assessment	Description	Building System	Building System	Building System	Building System	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cos
ID		System			Year	Status		L1	L2	L3	L4						
6177	Batavia High School	1736 - Sitework, Parking Lot Pavement			2020	Sent to Maintenance	Per Capital Projects Plan - Main Street parking lot scheduled for replacement in 2034.	Sitework	Site Improvements	Parking Lots	Parking Lot Pavement	4-Future	Good	0	\$6	Square Foot	\$0
							Cost is to replace with standard duty asphalt.	′									
6205	Batavia High School	1723 - HVAC, Ventilation-AHU			2020	Sent to Maintenance	Per Capital Projects Plan - all scheduled for replacement in 2034. AHU-01F AHU-02F AHU-01D AHU-02D AHU-03E AHU-04F	Services	Heating, Ventilation, and Air Conditioning (HVAC)	Ventilation	Supply Air	4-Future	Good	6	\$150,000	Each	\$900,000
6206	Batavia High School	1780 - Roofing, Low Slope - 2011	BFAC, Fieldhouse (2011)		2020	Sent to Maintenance	Per Capital Projects Plan - low slope BUR systems over music wing and Auditorium are scheduled for replacement in 2043. Metal roof area not included in this	Shell	Exterior Horizontal Enclosures	Roofing	Low-Slope Roofing	4-Future	Good	53045	\$30	Square Foot	\$1,591,350
							assessment item.										
6207	Batavia High School	1779 - Roofing, Low Slope - 2009	North Classrooms, SW Mechanical		2020	Sent to Maintenance	Per Capital Projects Plan - BUR system over D-Wing scheduled for replacement in 2043.	Shell	Exterior Horizontal Enclosures	Roofing	Low-Slope Roofing	4-Future	Good	13740	\$30	Square Foot	\$412,200
6232	Batavia High School	1724 - HVAC, Cooling-Chiller			2020	Sent to Maintenance	Per Capital Projects Plan - 2 Centravac chillers installed in 2010 and in good condition.	Services	Heating, Ventilation, and Air Conditioning (HVAC)	Cooling Systems	Central Cooling	4-Future	Good	2	\$300,000	Each	\$600,000
6233	Batavia High School	5066 - HVAC, Cooling-Cooling Tower			2020	Sent to Maintenance	Per Capital Projects Plan - 2 cooling towers installed in 2010 are scheduled for replacement in 2032.	Services	Heating, Ventilation, and Air Conditioning (HVAC)	Cooling Systems	Central Cooling	4-Future	Good	2	\$70,000	Each	\$140,000
6234	Batavia High School	1725 - HVAC, Distribution- Hydronic			2020	Sent to Maintenance	Per Capital Projects Plan - chilled water (2) and condensing water (2) pumps installed in 2010 and scheduled for replacement in 2030	Services	Heating, Ventilation, and Air Conditioning (HVAC)	Facility HVAC Distribution Systems	Facility Hydronic Distribution	4-Future	Good	1	\$180,000	Lump Sum	\$180,000
6235	Batavia High School	1725 - HVAC, Distribution- Hydronic			2020	Sent to Maintenance	Per Capital Projects Plan - heating water pumps installed in 2010 and scheduled for replacement in 2030.	Services	Heating, Ventilation, and Air Conditioning (HVAC)	Facility HVAC Distribution Systems	Facility Hydronic Distribution	4-Future	Good	5	\$36,000	Each	\$180,000
6236	Batavia High School	1721 - HVAC, Boiler Plant			2020	Sent to Maintenance	Per Capital Projects Plan - 3 Viessman condensing boilers installed in 2019 and scheduled for replacement in 234.	Services	Heating, Ventilation, and Air Conditioning (HVAC)	Heating Systems	Heat Generation	4-Future	Good	1	\$290,000	Lump Sum	\$290,000
6237	Batavia High School	5187 - HVAC, Ventilation- Makeup Air Units			2020	Sent to Maintenance	Per Capital Projects Plan - 3 makeup air units installed in 2009 and scheduled for replacement in 2034.	Services	Heating, Ventilation, and Air Conditioning (HVAC)	Ventilation		4-Future	Good	3	\$30,000	Each	\$90,000
6238	Batavia High School	1736 - Sitework, Parking Lot Pavement			2020	Sent to Maintenance	Per Capital Projects Plan - Stadium, bus lane and old Shop asphalt scheduled for replacement in 2032.	Sitework	Site Improvements	Parking Lots	Parking Lot Pavement	4-Future	Good	0	\$8	Square Foot	\$0
							Cost is to replace with heavy duty asphalt.										

Batavia High School 2020 Facility Condition Assessments





Assessment	Campus	Linked Bldg	Addition	Room	Assessmen		Description			Building System		Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
ID		System			Year	Status		L1	L2	L3	L4						4
6239	Batavia High	5342 - Flooring,	North	Dance A132	2020	Sent to	Per Capital Projects Plan - wood	Interiors	Interior Finishes	Flooring	Wood Flooring	4-Future	Good	1540	\$25	Square Foot	\$38,500
	School	Wood	Classrooms, SW			Maintenance	dance floor scheduled for										
			Mechanical				replacement in 2030.								40		4.0
7911	Batavia High	0 0	BFAC, Fieldhouse	BFAC Stage	2020	Sent to	Replaced in 2019. Needs	Services	Electrical	Lighting	Lighting Control	4-Future	Excellent	1	\$0	Each	\$0
	School	Controls, Theater	(2011)			Maintenance	replacement in 2026 per										
		Light Board				_	replacement schedule.							_			
7921	Batavia High	9268 - Equipment,		BFAC	2020	Sent to	Original. Scheduled replacement in	Equipment and	Furnishings	Fixed Furnishings	•	4-Future	Good	1	\$350,000	Lump Sum	\$350,000
	School	Theater Seating	(2011)				2041 per replacement schedule.	Furnishings			Seating						
7923	Batavia High	9270 - Equipment,	BFAC, Fieldhouse	BFAC, Black Box	2020	Sent to	Original. Scheduled replacement in	Equipment and	Furnishings	Fixed Furnishings		4-Future	Good	1	\$20,000	Lump Sum	\$20,000
	School	Theater Risers	(2011)				2031.	Furnishings			Furnishings						
7931	Batavia High	1852 - Interior	North	Corridor	2020	Sent to	Interior HM door in good condition.	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good	6	\$1,950	Each	\$11,700
	School	Doors, Swinging-	Classrooms, SW			Maintenance	N/S Corridor, near A131.		Construction		Doors						
		Hollow Metal -	Mechanical				E/W Corridor, near A132.										
		2009	(2009)														
7932	Batavia High	1852 - Interior	North	Corridor	2020	Sent to	Interior HM door frame in good	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good	6	\$1,950	Each	\$11,700
	School	Doors, Swinging-	Classrooms, SW			Maintenance	condition.		Construction		Doors						
		Hollow Metal -	Mechanical				N/S Corridor, near A131.										
		2009	(2009)				E/W Corridor, near A132.										
7933	Batavia High	1709 - Interior		Corridor	2020	Sent to	Interior HM door in good condition.		Interior	Interior Doors	Interior Swinging	4-Future	Good	6	\$1,950	Each	\$11,700
	School	Doors, Swinging-				Maintenance	E/W Corridor between locker rooms	;	Construction		Doors						
		Hollow Metal -					and 120s classrooms										
		Original															
							Cost to replace door, frame and										
							hardware.										
7934	Batavia High	1709 - Interior		Corridor	2020	Sent to	Interior HM door frames in good	Interiors	Interior	Interior Doors	Interior Swinging	4-Future	Good	3	\$1,950	Each	\$5,850
	School	Doors, Swinging-				Maintenance	condition.		Construction		Doors						
		Hollow Metal -					E/W Corridor between locker rooms	;									
		Original					and 120s classrooms										
							Cost is to replace door, frame and										
							hardware.										
																Total Cost	\$45,852,248
												1				Total Cost	Ç-3,032,2 -1 0
																Priority 1	\$4,752,620
																Priority 2	\$19,288,438