

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4259	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems		Classrooms	2020	Sent to Maintenance	Missing ceiling tiles around classroom - might be done on purpose? Room 108	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	1-Must Do	Poor	870	\$7	Square Foot	\$6,090
4286	Sam Rotolo Middle School	1414 - Interior Partitions, Operable		Classrooms	2020	Sent to Maintenance	Operable partitions are never used, they're cumbersome and difficult to move. The overall condition is fair, but the usability is poor. Rooms: 103/104, 109/110, 111/112, 114/115, 107/108	Interiors	Interior Construction	Interior Partitions	Interior Operable Partitions	1-Must Do	Poor	160	\$400	Linear Foot	\$64,000
4287	Sam Rotolo Middle School	1469 - Interior Partitions, Operable	North/South Classroom Extensions, SW Classrooms	Classrooms	2020	Sent to Maintenance	Operable partitions are never used, they're cumbersome and difficult to move. The overall condition is fair, but the usability is poor. Rooms: 118/119	Interiors	Interior Construction	Interior Partitions	Interior Operable Partitions	1-Must Do	Poor	32	\$400	Linear Foot	\$12,800
4288	Sam Rotolo Middle School	1416 - HVAC, Ventilation-Unit Ventilators	North/South Classroom Extensions, SW Classrooms	Classrooms	2020	Sent to Maintenance	Cover falling off unit vent. Rooms: 117	Services	Heating, Ventilation, and Air Conditioning (HVAC)	Ventilation	Supply Air	1-Must Do	Poor	1	\$4,500	Each	\$4,500
4289	Sam Rotolo Middle School	1416 - HVAC, Ventilation-Unit Ventilators		Classrooms	2020	Sent to Maintenance	Edge of unit vent falling off. Refer to large scale replacement. Room 117	Services	Heating, Ventilation, and Air Conditioning (HVAC)	Ventilation	Supply Air	1-Must Do	Poor	0	\$4,500	Each	\$4,500
4301	Sam Rotolo Middle School	1432 - Flooring, VCT		Classrooms	2020	Sent to Maintenance	VCT in poor condition - several areas around classroom where tile is badly scuffed, wax worn off, discoloration. Cost to replace with rubber flooring. Rooms: 215	Interiors	Interior Finishes	Flooring	Resilient Flooring	1-Must Do	Poor	879	\$12	Square Foot	\$10,548
4321	Sam Rotolo Middle School	1414 - Interior Partitions, Operable		Classrooms	2020	Sent to Maintenance	Operable partitions are never used, they're cumbersome and difficult to move. The overall condition is fair, but the usability is poor. Rooms: 203/204, 207/208, 209/210, 211/212, 214/215, 224/225, 226/227, 229/230, 231/232, 233/234	Interiors	Interior Construction	Interior Partitions	Interior Operable Partitions	1-Must Do	Poor	320	\$400	Linear Foot	\$128,000
4322	Sam Rotolo Middle School	1469 - Interior Partitions, Operable	North/South Classroom Extensions, SW Classrooms	Classrooms	2020	Sent to Maintenance	Operable partitions are never used, they're cumbersome and difficult to move. The overall condition is fair, but the usability is poor. Rooms: 218/219, 236/237, 238/239	Interiors	Interior Construction	Interior Partitions	Interior Operable Partitions	1-Must Do	Poor	96	\$400	Linear Foot	\$38,400
4326	Sam Rotolo Middle School	1416 - HVAC, Ventilation-Unit Ventilators		Classrooms	2020	Sent to Maintenance	The grille of the ceiling-mounted mechanical unit is deteriorating. Refer to large scale replacement. Room 240	Services	Heating, Ventilation, and Air Conditioning (HVAC)	Ventilation	Supply Air	1-Must Do	Poor	0	\$4,500	Each	\$4,500

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4333	Sam Rotolo Middle School	1432 - Flooring, VCT		Individual Toilets	2020	Sent to Maintenance	VCT in poor condition - yellowed, multiple stains, gaps at joints. Cost to replace with epoxy. Rooms: T-20	Interiors	Interior Finishes	Flooring	Resilient Flooring	1-Must Do	Poor	72	\$20	Square Foot	\$1,440
4353	Sam Rotolo Middle School	1432 - Flooring, VCT		Individual Toilets	2020	Sent to Maintenance	VCT in poor condition - yellowed, multiple stains, gaps at joints Rooms: T-31	Interiors	Interior Finishes	Flooring	Resilient Flooring	1-Must Do	Poor	35	\$7	Square Foot	\$245
4361	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Individual Toilets	2020	Sent to Maintenance	Paint is in poor condition - walls not completely painted, faded, scuffed. Quantity reflects total SF of all listed spaces. T-31	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	1-Must Do	Poor	40	\$1	Square Foot	\$36
4367	Sam Rotolo Middle School	1420 - Ceilings, Gypsum		Grouped Toilets	2020	Sent to Maintenance	GWB Ceiling is damaged and spalling near exhaust vent T-32, T-33 (locker room toilets)	Interiors	Interior Construction	Suspended Ceiling Construction	Suspended Plaster and Gypsum Board Ceilings	1-Must Do	Poor	384	\$12	Square Foot	\$4,608
4368	Sam Rotolo Middle School	1432 - Flooring, VCT		Grouped Toilets	2020	Sent to Maintenance	VCT is in poor condition - yellowed, stained, gaps between tiles. T-10	Interiors	Interior Finishes	Flooring	Resilient Flooring	1-Must Do	Poor	60	\$7	Square Foot	\$420
4381	Sam Rotolo Middle School	1451 - Plumbing, Plumbing Fixtures		Grouped Toilets	2020	Sent to Maintenance	One WC out of order, rest good. T-10	Services	Plumbing	Domestic Water Distribution	Plumbing Fixtures	1-Must Do	Poor	1	\$2,000	Each	\$2,000
4393	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		Grouped Toilets	2020	Sent to Maintenance	Hole in CMU, cleanout exploded. T-27	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	1-Must Do	Poor	6	\$40	Square Foot	\$240
4402	Sam Rotolo Middle School	1474 - Ceilings, Acoustical Suspended Systems	North/South Classroom Extensions, SW Classrooms	Grouped Toilets	2020	Sent to Maintenance	ACT in poor condition - tiles missing, water damaged from wet paper towels being thrown at the ceiling. T-37	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	1-Must Do	Poor	126	\$8	Square Foot	\$945
4440	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems		Kitchen	2020	Sent to Maintenance	Grid is very dirty and several tiles are yellowing and/or have been replaced individually over time (809 SF).	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	1-Must Do	Poor	809	\$8	Square Foot	\$6,068
4444	Sam Rotolo Middle School	1452 - Interior Partitions, Fixed-GWB		Kitchen	2020	Sent to Maintenance	West wall is severely scuffed. Quantity reflects wall length x approx. height. -Room 145	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	1-Must Do	Poor	220	\$15	Square Foot	\$3,300
4452	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems		Dish Washing	2020	Sent to Maintenance	Grid is very dirty and several tiles are yellowing and/or have been replaced individually over time (286 SF)	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	1-Must Do	Poor	286	\$8	Square Foot	\$2,145
4454	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Offices/Pull-Out Spaces	2020	Sent to Maintenance	012A: Wood door is badly damaged, see attached photo 122: multiple chips/gouges in veneer, edge badly worn; see	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	1-Must Do	Poor	2	\$1,950	Each	\$3,900
4457	Sam Rotolo Middle School	1452 - Interior Partitions, Fixed-GWB		Dish Washing	2020	Sent to Maintenance	Walls are scratched and damaged throughout (286 SF) -Room 145B	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	1-Must Do	Poor	286	\$15	Square Foot	\$4,290

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4480	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		Offices/Pull-Out Spaces	2020	Sent to Maintenance	CMU in poor condition - diagonal crack through blocks, see photo. Room 012A	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	1-Must Do	Poor	20	\$15	Linear Foot	\$300
4482	Sam Rotolo Middle School	1947 - Interior Wall Finish, FRP		Serving	2020	Sent to Maintenance	Panels are scatched and discolored. -Room 146	Interiors	Interior Finishes	Wall Finishes	Tile Wall Finish	1-Must Do	Poor	740	\$8	Square Foot	\$5,920
4506	Sam Rotolo Middle School	1437 - Fixed Equipment, Casework		Offices/Pull-Out Spaces	2020	Sent to Maintenance	Casework in poor condition - Older plastic laminate desks that have delaminated and chipped in several locations; delaminated edgebanding at countertops, crooked door fronts, damaged corners 018A, 019A, 135A	Equipment and Furnishings	Furnishings	Fixed Furnishings	Casework	1-Must Do	Poor	20	\$800	Linear Foot	\$16,000
4534	Sam Rotolo Middle School	1432 - Flooring, VCT		Offices/Pull-Out Spaces	2020	Sent to Maintenance	VCT in poor condition - tiles separating, cracked, different colored tiles throughout room. See photos.	Interiors	Interior Finishes	Flooring	Resilient Flooring	1-Must Do	Poor	375	\$7	Square Foot	\$2,625
4572	Sam Rotolo Middle School	1531 - Fixed Equipment, Casework		Science	2020	Sent to Maintenance	Casework in poor condition, very chipped. Cost to replace entirely. Classrooms: 205, 206, and 213	Equipment and Furnishings	Furnishings	Fixed Furnishings	Casework	1-Must Do	Poor	210	\$800	Linear Foot	\$168,000
4586	Sam Rotolo Middle School	1453 - Interior Doors, Swinging-Hollow Metal		Mechanical/Electrical Rooms	2020	Sent to Maintenance	HM door in poor condition - badly damaged at the base. Cost to replace. Mechanical 147A	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	1-Must Do	Poor	2	\$600	Each	\$1,200
4589	Sam Rotolo Middle School	1432 - Flooring, VCT		Mechanical/Electrical Rooms	2020	Sent to Maintenance	Concrete floor in poor condition. Confirm unit cost. Electrical 705	Interiors	Interior Finishes	Flooring	Resilient Flooring	1-Must Do	Poor	130	\$50	Square Foot	\$6,500
4594	Sam Rotolo Middle School	1403 - Slab on Grade		Mechanical/Electrical Rooms	2020	Sent to Maintenance	Concrete floor in poor condition. Confirm unit cost. Electrical 705	Substructure	Slabs-On-Grade	Standard Slabs-on-Grade		1-Must Do	Poor	130	\$50	Square Foot	\$6,500
4596	Sam Rotolo Middle School	1404 - Elevated Concrete Slab		GYM	2020	Sent to Maintenance	Flooring has been significantly damaged at areas where the bleachers retract backwards. Confirm unit cost - Upper GYM	Shell	Superstructure	Floor Construction	Floor Decks, Slabs, and Toppings	1-Must Do	Poor	5051	\$75	Square Foot	\$378,825
4607	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Mechanical/Electrical Rooms	2020	Sent to Maintenance	Paint in poor condition. Quantity reflects total SF of all listed spaces. 143 - all walls could be redone. 705	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	1-Must Do	Poor	2475	\$1	Square Foot	\$2,228
4645	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Locker Room	2020	Sent to Maintenance	Door shows significant signs of age and push hardware is rusted - 18 & 19	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	1-Must Do	Poor	4	\$1,950	Each	\$7,800
4650	Sam Rotolo Middle School	1499 - Interior Doors, Swinging-Hollow Metal		Locker Room	2020	Sent to Maintenance	Significant rusting on inside face of the HM exit door - 18	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	1-Must Do	Poor	1	\$600	Each	\$600
4666	Sam Rotolo Middle School	1553 - Interiors, Wall Finish - Paint	North/South Classroom Extensions, SW Classrooms	Janitor	2020	Sent to Maintenance	Paint in poor condition. Quantity reflects total SF of all listed spaces. J-7	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	1-Must Do	Poor	34	\$1	Square Foot	\$31

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4672	Sam Rotolo Middle School	1451 - Plumbing, Plumbing Fixtures		Science	2020	Sent to Maintenance	All science lab classrooms are missing an ADA accessible lab sink. 105, 106, 113	Services	Plumbing	Domestic Water Distribution	Plumbing Fixtures	1-Must Do	Bldg Code Rqmt	3	\$5,700	Each	\$17,100
4674	Sam Rotolo Middle School	1451 - Plumbing, Plumbing Fixtures		Science	2020	Sent to Maintenance	All science lab classrooms are missing an ADA accessible lab sink. 205, 206, 213	Services	Plumbing	Domestic Water Distribution	Plumbing Fixtures	1-Must Do	Bldg Code Rqmt	3	\$5,700	Each	\$17,100
4676	Sam Rotolo Middle School	1497 - Plumbing, Plumbing Fixtures	North/South Classroom Extensions, SW Classrooms	Science	2020	Sent to Maintenance	All science lab classrooms are missing an ADA accessible lab sink. 216	Services	Plumbing	Domestic Water Distribution	Plumbing Fixtures	1-Must Do	Bldg Code Rqmt	1	\$5,700	Each	\$5,700
4677	Sam Rotolo Middle School	1497 - Plumbing, Plumbing Fixtures	North/South Classroom Extensions, SW Classrooms	Science	2020	Sent to Maintenance	All science lab classrooms are missing an ADA accessible lab sink. 116	Services	Plumbing	Domestic Water Distribution	Plumbing Fixtures	1-Must Do	Bldg Code Rqmt	1	\$5,700	Each	\$5,700
4686	Sam Rotolo Middle School	1499 - Interior Doors, Swinging-Hollow Metal		Stage/Cafeteria/ Multipurpose	2020	Sent to Maintenance	-HM Frames are rusted, removable mullions are in bad shape - 24	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	1-Must Do	Poor	5	\$450	Each	\$2,250
4690	Sam Rotolo Middle School	1409 - Exterior Entrance Doors, Hollow Metal		Stage/Cafeteria/ Multipurpose	2020	Sent to Maintenance	Hollow metal exterior Frame serverly rusting on the multipurpose room side at the base - 31	Shell	Exterior Vertical Enclosures	Exterior Doors and Grilles	Exterior Entrance Doors	1-Must Do	Poor	2	\$600	Each	\$1,200
4698	Sam Rotolo Middle School	1551 - Interior Wall Finishes, Wall Base		Stage/Cafeteria/ Multipurpose	2020	Sent to Maintenance	- Base is damaged and peeling - 23	Interiors	Interior Finishes	Wall Finishes		1-Must Do	Poor	512	\$6	Linear Foot	\$3,072
4733	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems		Corridor	2020	Sent to Maintenance	- most tiles bowed, some stained/damaged (add photo) - Corridor btwn Stu. Services and Café.	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	1-Must Do	Poor	1000	\$8	Square Foot	\$7,500
4737	Sam Rotolo Middle School	1484 - Flooring, VCT		Corridor	2020	Sent to Maintenance	- VCT chipped, discolored, tiles separating, cracked - 7th North.	Interiors	Interior Finishes	Flooring	Resilient Flooring	1-Must Do	Poor	409	\$7	Square Foot	\$2,863
4748	Sam Rotolo Middle School	8624 - Equipment, Lockers		Corridor	2020	Sent to Maintenance	Per Capital Projects Plan - lockers scheduled for replacement and in poor condition; 12"w, full-height metal lockers. Locker count provided by BPS101: 1,330 (original 1992 building)	Equipment and Furnishings	Equipment	Institutional Equipment	Educational and Scientific Equipment	1-Must Do	Poor	1330	\$200	Each	\$266,000
4763	Sam Rotolo Middle School	1420 - Ceilings, Gypsum		Stair	2020	Sent to Maintenance	-Significant chipping at Upper gymnasium landing - Stair - Above Mech 017C	Interiors	Interior Construction	Suspended Ceiling Construction	Suspended Plaster and Gypsum Board	1-Must Do	Poor	249	\$12	Square Foot	\$2,988
4776	Sam Rotolo Middle School	1528 - Interior Stair Finishes, Resilient		Stair	2020	Sent to Maintenance	Tread nosings peeling off stairs, missing in some locations - Stair - 8th gr. North Corr.	Interiors	Interior Finishes	Stair Finishes	Resilient Stair Finish	1-Must Do	Poor	18	\$90	Each	\$1,620
4869	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Storage	2020	Sent to Maintenance	Wood door in poor condition - veneer severely damaged. 007A, 012C	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	1-Must Do	Poor	2	\$1,950	Each	\$3,900
4883	Sam Rotolo Middle School	1403 - Slab on Grade		Storage	2020	Sent to Maintenance	Concrete floor in poor condition - spalling throughout. 33, 139, 149A	Substructure	Slabs-On-Grade	Standard Slabs-on-Grade		1-Must Do	Poor	1394	\$50	Square Foot	\$69,700
4884	Sam Rotolo Middle School	1432 - Flooring, VCT		Storage	2020	Sent to Maintenance	VCT in poor condition - extensive scuffing and scratches throughout room. 147	Interiors	Interior Finishes	Flooring	Resilient Flooring	1-Must Do	Poor	1018	\$7	Square Foot	\$7,126

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4888	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		Storage	2020	Sent to Maintenance	CMU in poor condition - missing sealant at corner, diagonal cracking. 007A, 012B	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	1-Must Do	Poor	20	\$15	Linear Foot	\$300
4894	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Storage	2020	Sent to Maintenance	Paint in poor condition - all walls should be redone. Quantity reflects total SF of all listed spaces. 139, 142	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	1-Must Do	Poor	1900	\$1	Square Foot	\$1,710
4903	Sam Rotolo Middle School	1454 - Electrical, Lighting Fixtures		Storage	2020	Sent to Maintenance	Lighting in poor condition - light doesn't turn on. 129A. 148C.	Services	Electrical	Lighting	Lighting Fixtures	1-Must Do	Poor	0	\$0	Square Foot	\$0
4910	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems		Storage	2020	Sent to Maintenance	ACT in poor condition. 148C. 605	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	1-Must Do	Poor	134	\$8	Square Foot	\$1,005
4912	Sam Rotolo Middle School	1432 - Flooring, VCT		Storage	2020	Sent to Maintenance	VCT in poor condition. 605. 020A - Floor is significantly scuffed from storage materials coming in and out.	Interiors	Interior Finishes	Flooring	Resilient Flooring	1-Must Do	Poor	538	\$7	Square Foot	\$3,766
4914	Sam Rotolo Middle School	1404 - Elevated Concrete Slab		Storage	2020	Sent to Maintenance	Concrete flooring in poor condition, significant crack through middle of floor. 020C	Shell	Superstructure	Floor Construction	Floor Decks, Slabs, and Toppings	1-Must Do	Poor	176	\$75	Square Foot	\$13,200
4928	Sam Rotolo Middle School	1432 - Flooring, VCT	North/South Classroom Extensions, SW Classrooms	Storage	2020	Sent to Maintenance	VCT in poor condition. 216A - especially bad at doorway. 216B.	Interiors	Interior Finishes	Flooring	Resilient Flooring	1-Must Do	Poor	286	\$7	Square Foot	\$2,002
4983	Sam Rotolo Middle School	1437 - Fixed Equipment, Casework		FACS/Sewing	2020	Sent to Maintenance	Casework in poor condition - edge banding delaminating throughout. Verify quantity in field, not shown in plan. 010, 011	Equipment and Furnishings	Furnishings	Fixed Furnishings	Casework	1-Must Do	Poor	176	\$800	Linear Foot	\$140,800
4989	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Music	2020	Sent to Maintenance	Wood doors in poor condition - veneer very damaged, especially edges. 005. 006. 007 - panic hardware rusted. 016.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	1-Must Do	Poor	5	\$1,950	Each	\$9,750
5037	Sam Rotolo Middle School	1439 - Flooring, Carpet		Music	2020	Sent to Maintenance	Carpet in poor condition, visible wearing at risers. 007	Interiors	Interior Finishes	Flooring	Carpeting	1-Must Do	Poor	2426	\$7	Square Foot	\$15,769
5054	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		Music	2020	Sent to Maintenance	CMU in poor condition - cracking at ext wall openings, multiple nail holes, cracking at sealant in corners. 006. Note: area is total SF for room as issues are present throughout room. Confirm how to price.	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	1-Must Do	Poor	1368	\$0	Square Foot	\$0

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
5059	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Music	2020	Sent to Maintenance	Paint in poor condition - see photos. Quantity reflects total SF of all listed spaces. 005	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	1-Must Do	Poor	1390	\$1	Square Foot	\$1,251
5073	Sam Rotolo Middle School	1437 - Fixed Equipment, Casework		Music	2020	Sent to Maintenance	Casework in poor condition - instrument storage shelving damaged, shelves are bowing under weight, see photos. 006	Equipment and Furnishings	Furnishings	Fixed Furnishings	Casework	1-Must Do	Poor	31	\$800	Linear Foot	\$24,800
5088	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Visual/Digital Arts	2020	Sent to Maintenance	Wood door in poor condition - damaged veneer, rusting glazing stops. 1 - tape used as repair. 4.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	1-Must Do	Poor	2	\$1,950	Each	\$3,900
5107	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems		Visual/Digital Arts	2020	Sent to Maintenance	ACT in poor condition - 50% borrowed or damaged. See photo. 001	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	1-Must Do	Poor	967	\$8	Square Foot	\$7,253
5125	Sam Rotolo Middle School	1403 - Slab on Grade		Wood Shop 012	2020	Sent to Maintenance	Concrete flooring in poor condition - finish worn away from slab throughout wood shop. 012	Substructure	Slabs-On-Grade	Standard Slabs-on-Grade		1-Must Do	Poor	1978	\$50	Square Foot	\$98,900
5370	Sam Rotolo Middle School	1437 - Fixed Equipment, Casework		Office/Pull-out	2020	Sent to Maintenance	Staff Lounge 148B: Non-ADA compliant sink base at casework; New staff lounge created during admin area renovations completed recently (one staff member indicated it was completed in 2019).	Equipment and Furnishings	Furnishings	Fixed Furnishings	Casework	1-Must Do	Bldg Code Rqmt	1	\$2,500	Each	\$2,500
5586	Sam Rotolo Middle School	1452 - Interior Partitions, Fixed-GWB		Corridor	2020	Sent to Maintenance	GWB in poor condition: GWB has gouges, damaged corner bead at corners Admin north corridor	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	1-Must Do	Poor	10	\$15	Square Foot	\$150
5588	Sam Rotolo Middle School	1498 - Interior Partitions, Fixed-GWB		Corridor	2020	Sent to Maintenance	GWB in fair condition: GWB small has gouges in select areas Admin corridor near staff toilets, Admin south corridor, Admin east corridor	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	1-Must Do	Poor	10	\$15	Square Foot	\$150
7841	Sam Rotolo Middle School	1417 - HVAC, Ventilation-AHU			2020	Sent to Maintenance	Per Capital Projects Plan - AHUs 1-10 were scheduled for replacement in 2017.	Services	Heating, Ventilation, and Air Conditioning (HVAC)	Ventilation	Supply Air	1-Must Do	Poor	10	\$95,000	Each	\$950,000
7842	Sam Rotolo Middle School	1416 - HVAC, Ventilation-Unit Ventilators			2020	Sent to Maintenance	Per Capital Projects Plan - UVs were scheduled for replacement in 2017.	Services	Heating, Ventilation, and Air Conditioning (HVAC)	Ventilation	Supply Air	1-Must Do	Poor	1	\$750,000	Lump Sum	\$750,000
7851	Sam Rotolo Middle School	1440 - Sitework, Parking Lot Pavement			2020	Sent to Maintenance	Per Capital Projects Plan - north lot scheduled for replacement in 2039, but lot in poor condition. Cost for replacement of heavy-duty asphalt paving.	Sitework	Site Improvements	Parking Lots	Parking Lot Pavement	1-Must Do	Poor	80500	\$8	Square Foot	\$603,750

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
7852	Sam Rotolo Middle School	1440 - Sitework, Parking Lot Pavement			2020	Sent to Maintenance	Per Capital Projects Plan - east/front lot scheduled for replacement in 2034, but lot in poor condition. Cost for heavy-duty asphalt replacement.	Sitework	Site Improvements	Parking Lots	Parking Lot Pavement	1-Must Do	Poor	31000	\$8	Square Foot	\$232,500
8081	Sam Rotolo Middle School	11245 - Flooring, Epoxy		Wood Shop 012	2020	Sent to Maintenance	Epoxy flooring in poor condition: finish is worn away throughout (see photo) 012	Interiors	Interior Finishes	Flooring	Fluid-Applied Flooring	1-Must Do	Poor	1978	\$20	Square Foot	\$39,560
8082	Sam Rotolo Middle School	11245 - Flooring, Epoxy		Storage	2020	Sent to Maintenance	epoxy Flooring in poor condition: significantly worn away from surface of slab (see photos) 012B 012C	Interiors	Interior Finishes	Flooring	Fluid-Applied Flooring	1-Must Do	Poor	243	\$20	Square Foot	\$4,860
11620	Sam Rotolo Middle School	1432 - Flooring, VCT		Classrooms	2020	Sent to Maintenance	VCT in poor condition - has been patched over the years, different colors throughout room. Cost to replace with rubber flooring. Rooms: 201/202	Interiors	Interior Finishes	Flooring	Resilient Flooring	1-Must Do	Poor	802	\$12	Square Foot	\$9,624
11625	Sam Rotolo Middle School	1484 - Flooring, VCT	North/South Classroom Extensions, SW Classrooms	Science	2020	Sent to Maintenance	VCT in fair condition. Cost to replace with rubber flooring. 116	Interiors	Interior Finishes	Flooring	Resilient Flooring	1-Must Do	Bldg Code Rqmt	1191	\$12	Each	\$14,292
4250	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Classrooms	2020	Sent to Maintenance	Wood doors scuffed, scratched, chipped. Rooms: 103, 104, 107, 108, 109, 110, 114, 115, 101/102, 028	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	11	\$1,950	Each	\$21,450
4251	Sam Rotolo Middle School	1452 - Interior Partitions, Fixed-GWB		Classrooms	2020	Sent to Maintenance	GWB chase wall dented and damaged. Rooms: 101/102	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair	125	\$15	Square Foot	\$1,875
4253	Sam Rotolo Middle School	1467 - Interior Doors, Swinging-Wood	North/South Classroom Extensions, SW Classrooms	Classrooms	2020	Sent to Maintenance	Door scuffed, chipped, scratched. Cost to replace door and hardware Room 117	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$1,950	Each	\$1,950
4257	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Classrooms	2020	Sent to Maintenance	HM door frames rusted at base, paint chipping from frame. Cost to repaint frame. Rooms: 108, 115, 030	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	3	\$60	Each	\$180
4263	Sam Rotolo Middle School	1432 - Flooring, VCT		Classrooms	2020	Sent to Maintenance	VCT in fair condition. Significant scuffing, cracking through tiles, discoloration. Cost to replace VCT with rubber flooring. Rooms: 103 (15' crack), 104, 114 (10 cracked tiles), 115, 101/102, 029	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	5178	\$12	Square Foot	\$62,136
4265	Sam Rotolo Middle School	1484 - Flooring, VCT	North/South Classroom Extensions, SW Classrooms	Classrooms	2020	Sent to Maintenance	VCT chipped and cracked all along exterior walls, scuffed throughout. Cost to replace with rubber flooring. Room 117	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	866	\$12	Square Foot	\$10,392

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4268	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		Classrooms	2020	Sent to Maintenance	CMU has stair step cracks, cracks through blocks (mostly at window sills). Rooms: 103, 104, 108, 110, 111, 114, 115, 101/102	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair	60	\$15	Linear Foot	\$900
4272	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base	North/South Classroom Extensions, SW Classrooms	Classrooms	2020	Sent to Maintenance	Wall base in fair condition. A lot of scuffs, minor damage. Cost to replace. Rooms: 119	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	120	\$6	Linear Foot	\$720
4273	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base		Classrooms	2020	Sent to Maintenance	Wall base in fair condition, minor scuffs, no damage. Cost to replace in kind. Rooms: 002, 003, 104, 107, 108, 109, 110, 111, 112, 115, 101/102, 027, 028, 029, 030	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	1784	\$6	Linear Foot	\$10,704
4274	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base		Classrooms	2020	Sent to Maintenance	Wall base in fair condition. A lot of scuff marks, minor damage. Cost to replace. Rooms: 103, 114	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	244	\$6	Linear Foot	\$1,464
4276	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Classrooms	2020	Sent to Maintenance	Paint in fair condition - marked up, discolored, minor peeling/chipping. Quantity reflects total SF of all listed spaces. Rooms: 103, 104, 107, 108, 109, 110, 111, 112, 114, 115, 101/102	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	8669	\$1	Square Foot	\$7,802
4277	Sam Rotolo Middle School	1553 - Interiors, Wall Finish - Paint	North/South Classroom Extensions, SW Classrooms	Classrooms	2020	Sent to Maintenance	Paint in fair condition - marked up, discolored, minor peeling/chipping. Quantity reflects total SF of all listed spaces. Rooms: 117, 118, 119	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	2600	\$1	Square Foot	\$2,340
4283	Sam Rotolo Middle School	1405 - Exterior Windows, Operating		Classrooms	2020	Sent to Maintenance	Holes in window screen. Confirm SF of window screen and unit cost for replacing window screen only. Room 112	Shell	Exterior Vertical Enclosures	Exterior Windows	Exterior Operating Windows	2-Should Do	Fair	10	\$5	Square Foot	\$50
4293	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Classrooms	2020	Sent to Maintenance	Wood doors in fair condition - scuffed, scratched, chipped. Cost to replace door and hardware. Rooms: 203, 208, 209, 210, 211, 212, 214, 223, 224, 225, 226, 227, 228, 201/202, 222/221	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	17	\$1,950	Each	\$33,150
4300	Sam Rotolo Middle School	1432 - Flooring, VCT		Classrooms	2020	Sent to Maintenance	VCT in fair condition - cracked and scuffed tiles, discoloration. Cost to replace with rubber flooring. Rooms: 204, 208, 223, 225, 228, 233, 234, 235, 229, 230, 231	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	12275	\$12	Square Foot	\$147,300

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4304	Sam Rotolo Middle School	1484 - Flooring, VCT	North/South Classroom Extensions, SW Classrooms	Classrooms	2020	Sent to Maintenance	VCT in fair condition, cracking along wall. Cost to replace with rubber flooring. Room 118, 119	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	1735	\$12	Square Foot	\$20,820
4305	Sam Rotolo Middle School	1484 - Flooring, VCT	North/South Classroom Extensions, SW Classrooms	Classrooms	2020	Sent to Maintenance	VCT in fair condition - cracked, discolored, scuffed. Cost to replace with rubber flooring. Rooms: 217, 218 (14 sf cracked tile at doorway), 219	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	2500	\$12	Square Foot	\$30,000
4307	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		Classrooms	2020	Sent to Maintenance	CMU has stair step cracks, cracks through blocks (mostly at window sills), cracking sealant. Confirm quantity in field. Rooms: 209 (cracking in corner by hallway), 211 (sealant cracking in corner), 214, 221/222	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair	30	\$15	Linear Foot	\$450
4311	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Classrooms	2020	Sent to Maintenance	Paint in fair condition - marked up, discolored, minor peeling/chipping. Rooms: 203, 204, 207, 208, 209, 210, 211, 212, 214, 215, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 240, 201/202, 221/222	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	22900	\$1	Square Foot	\$20,610
4312	Sam Rotolo Middle School	1553 - Interiors, Wall Finish - Paint	North/South Classroom Extensions, SW Classrooms	Classrooms	2020	Sent to Maintenance	Paint in fair condition - marked up, discolored, minor peeling/chipping. Quantity reflects total SF of all listed spaces. Rooms: 217, 218, 219, 236, 237, 238, 239	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	6023	\$1	Square Foot	\$5,421
4315	Sam Rotolo Middle School	1437 - Fixed Equipment, Casework		Classrooms	2020	Sent to Maintenance	Casework missing 2 pulls. Verify quantity. Cost to repair hardware and re-hang doors. Room 240	Equipment and Furnishings	Furnishings	Fixed Furnishings	Casework	2-Should Do	Fair	30	\$50	Linear Foot	\$1,500
4316	Sam Rotolo Middle School	1486 - Fixed Equipment, Casework	North/South Classroom Extensions, SW Classrooms	Classrooms	2020	Sent to Maintenance	Casework has 1 broken pull. Cost to repair hardware and re-hang doors. Room 119	Equipment and Furnishings	Furnishings	Fixed Furnishings	Casework	2-Should Do	Fair	10	\$50	Linear Foot	\$500
4324	Sam Rotolo Middle School	1416 - HVAC, Ventilation-Unit Ventilators		Classrooms	2020	Sent to Maintenance	Unit vent in fair condition - scuffed, marked up, dented. Refer to large scale replacement. Rooms: 203, 214, 224, 201/202	Services	Heating, Ventilation, and Air Conditioning (HVAC)	Ventilation	Supply Air	2-Should Do	Fair	0	\$4,500	Each	\$22,500
4327	Sam Rotolo Middle School	1467 - Interior Doors, Swinging-Wood	North/South Classroom Extensions, SW Classrooms	Classrooms	2020	Sent to Maintenance	HM door frames rusted at base, paint chipping from frame. Cost to repaint frame. Room 117	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$60	Each	\$60

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4328	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Individual Toilets	2020	Sent to Maintenance	Doors in fair condition - veneers chipped, scratched. Cost to replace door and hardware. Rooms: T-5, T-6, T-7, T-8, T-16	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	5	\$1,950	Each	\$9,750
4331	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems		Individual Toilets	2020	Sent to Maintenance	ACT in fair condition - water damaged/cracked tiles, bowing, discoloration. Cost to replace entire ACT system. Rooms: T-7, T-8, T-15	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	2-Should Do	Fair	100	\$8	Square Foot	\$750
4334	Sam Rotolo Middle School	1432 - Flooring, VCT		Individual Toilets	2020	Sent to Maintenance	VCT in fair condition. Cost to replace with epoxy. Rooms: T-14, T-15	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	380	\$20	Square Foot	\$7,600
4337	Sam Rotolo Middle School	1430 - Flooring, Ceramic Tile		Individual Toilets	2020	Sent to Maintenance	Some light browning/rusting near the floor drain. Cost to clean grout/tile.	Interiors	Interior Finishes	Flooring	Tile Flooring	2-Should Do	Fair	105	\$5	Square Foot	\$525
4340	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Individual Toilets	2020	Sent to Maintenance	Paint is in fair condition - fading, discolored, chipped. T-1. T-2. T-5. T-15. T-16.	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	621	\$1	Square Foot	\$559
4342	Sam Rotolo Middle School	1451 - Plumbing, Plumbing Fixtures		Individual Toilets	2020	Sent to Maintenance	Sink is in good condition, toilet has large crack in it. T-8	Services	Plumbing	Domestic Water Distribution	Plumbing Fixtures	2-Should Do	Fair	1	\$2,000		\$2,000
4344	Sam Rotolo Middle School	1452 - Interior Partitions, Fixed-GWB		Individual Toilets	2020	Sent to Maintenance	GWB is in fair condition - damaged at sink. T-16.	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair	5	\$15	Square Foot	\$75
4346	Sam Rotolo Middle School	1454 - Electrical, Lighting Fixtures		Individual Toilets	2020	Sent to Maintenance	Lighting is in fair condition - older, singular light over mirror. T-5. T-6. T-7. T-8.	Services	Electrical	Lighting	Lighting Fixtures	2-Should Do	Fair	0	\$0		\$0
4349	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Individual Toilets	2020	Sent to Maintenance	Doors in fair condition - stained at base, chipped veneer. Cost to replace door and hardware. Rooms: T-24	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$1,950	Each	\$1,950
4354	Sam Rotolo Middle School	1432 - Flooring, VCT		Individual Toilets	2020	Sent to Maintenance	VCT in fair condition. Cost to replace with epoxy. T-25, T-30	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	379	\$20	Square Foot	\$7,580
4359	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base		Individual Toilets	2020	Sent to Maintenance	Wall base is in fair condition. Cost to replace in kind. T-31	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	55	\$6	Linear Foot	\$330

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4360	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Individual Toilets	2020	Sent to Maintenance	Paint is in fair condition. Quantity reflects total SF of all listed spaces. T-24, T-25, T-30	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	100	\$1	Square Foot	\$90
4369	Sam Rotolo Middle School	1432 - Flooring, VCT		Grouped Toilets	2020	Sent to Maintenance	VCT is in fair condition - discolored/yellowed. Cost to replace with epoxy. T-9. T-12. T-13.	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	180	\$20	Square Foot	\$3,600
4371	Sam Rotolo Middle School	1430 - Flooring, Ceramic Tile		Grouped Toilets	2020	Sent to Maintenance	Ceramic floor tile is in fair condition - dirty grout lines, some damaged tiles. Cost to replace tiles in kind. T-10	Interiors	Interior Finishes	Flooring	Tile Flooring	2-Should Do	Fair	216	\$30	Square Foot	\$6,480
4374	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		Grouped Toilets	2020	Sent to Maintenance	CMU wall in fair condition - exposed valve in wall. T-10	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair	5	\$40	Square Foot	\$200
4377	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base		Grouped Toilets	2020	Sent to Maintenance	Tile wall base in fair condition - grout needs cleaning, but no damaged tiles. Cost to clean grout. T-1. T-2. T-9. T-10. T-32. T-33. T-12. T-13.	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	464	\$5	Square Foot	\$2,320
4379	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Grouped Toilets	2020	Sent to Maintenance	Paint in fair condition - touch ups needed throughout. GWB ceiling to be repainted after ceiling is repaired in locker rooms. T-1. T-2. T-17. T-32. T-33.	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	964	\$1	Square Foot	\$868
4383	Sam Rotolo Middle School	1445 - Interior Specialties, Toilet Compartments		Grouped Toilets	2020	Sent to Maintenance	Toilet partitions in fair condition, visible signs of rust at the base. Cost to replace with solid phenolic partitions. T-32	Interiors	Interior Construction	Interior Specialties	Toilet, Bath, and Laundry Accessories	2-Should Do	Fair	4	\$1,800	Each	\$7,200

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4390	Sam Rotolo Middle School	1432 - Flooring, VCT		Grouped Toilets	2020	Sent to Maintenance	VCT in fair condition. Cost to replace with epoxy. T-22. T-23. T-26. T-27. T-28. T-29.	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	750	\$20	Square Foot	\$15,000
4391	Sam Rotolo Middle School	1430 - Flooring, Ceramic Tile		Grouped Toilets	2020	Sent to Maintenance	Ceramic floor tile in fair condition. Some tiles damaged. Cost to replace in kind. T-22, T-23	Interiors	Interior Finishes	Flooring	Tile Flooring	2-Should Do	Fair	550	\$30	Square Foot	\$16,500
4397	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Grouped Toilets	2020	Sent to Maintenance	Paint in fair condition. T-22. T-23. T-26. T-27. T-28. T-29.	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	980	\$1	Square Foot	\$882
4400	Sam Rotolo Middle School	1445 - Interior Specialties, Toilet Compartments		Grouped Toilets	2020	Sent to Maintenance	Toilet partitions in fair condition - new, but have graffiti. Cost to replace with solid phenolic panels, if desired. T-23	Interiors	Interior Construction	Interior Specialties	Toilet, Bath, and Laundry Accessories	2-Should Do	Fair	3	\$1,800	Each	\$5,400
4405	Sam Rotolo Middle School	1525 - Flooring, Ceramic Tile	North/South Classroom Extensions, SW Classrooms	Grouped Toilets	2020	Sent to Maintenance	Ceramic floor tile in fair condition - 2 sf of damaged tile. Cost to replace in kind. T-35	Interiors	Interior Finishes	Flooring	Tile Flooring	2-Should Do	Fair	249	\$30	Square Foot	\$7,470
4408	Sam Rotolo Middle School	1551 - Interior Wall Finishes, Wall Base	North/South Classroom Extensions, SW Classrooms	Grouped Toilets	2020	Sent to Maintenance	Tile wall base in fair condition - grout is extremely dirty at corner of wall and floor. Cost to clean grout. T-35	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	36	\$5	Square Foot	\$180
4410	Sam Rotolo Middle School	1553 - Interiors, Wall Finish - Paint	North/South Classroom Extensions, SW Classrooms	Grouped Toilets	2020	Sent to Maintenance	Paint in fair condition. Quantity reflects total SF of all listed spaces. T-35	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	261	\$1	Square Foot	\$235
4412	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		LMC	2020	Sent to Maintenance	Doors in fair condition veneer is chipped and scratched. Cost to replace door and hardware. LMC	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	4	\$1,950	Each	\$7,800
4417	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems		LMC	2020	Sent to Maintenance	ACT Discoloration (5498 SF). Cost to replace entire ACT system. LMC	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	2-Should Do	Fair	5498	\$8	Square Foot	\$41,235
4420	Sam Rotolo Middle School	1525 - Flooring, Ceramic Tile	North/South Classroom Extensions, SW Classrooms	Grouped Toilets	2020	Sent to Maintenance	Ceramic floor tile in fair condition - 3 sf of cracked tile. Cost to replace tile in kind. T-37	Interiors	Interior Finishes	Flooring	Tile Flooring	2-Should Do	Fair	249	\$30	Square Foot	\$7,470

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4425	Sam Rotolo Middle School	1553 - Interiors, Wall Finish - Paint	North/South Classroom Extensions, SW Classrooms	Grouped Toilets	2020	Sent to Maintenance	Paint in fair condition. Quantity reflects total SF of all listed spaces. T-37	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	261	\$1	Square Foot	\$235
4427	Sam Rotolo Middle School	1439 - Flooring, Carpet		LMC	2020	Sent to Maintenance	Very Worn. Cost to replace in kind - LMC	Interiors	Interior Finishes	Flooring	Carpeting	2-Should Do	Fair	5498	\$7	Square Foot	\$35,737
4430	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		LMC	2020	Sent to Maintenance	-Large cracks through blocks and stair step cracking on wall adjacent to commons. -Large cracks down north wall (opposite of commons) -Cracking on wall adjacent to offices. LMC 220	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair	100	\$15	Linear Foot	\$1,500
4431	Sam Rotolo Middle School	1452 - Interior Partitions, Fixed-GWB		LMC	2020	Sent to Maintenance	Wall-GWB in a fair condition. LMC 220	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair	0	\$15	Square Foot	\$0
4432	Sam Rotolo Middle School	1551 - Interior Wall Finishes, Wall Base		LMC	2020	Sent to Maintenance	Wall Base in a fair condition. Cost to replace. LMC 220	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	300	\$6	Linear Foot	\$1,800
4433	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		LMC	2020	Sent to Maintenance	Wall Paint in a fair condition. Quantity reflects total SF of all listed spaces. LMC 220	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	5500	\$1	Square Foot	\$4,950
4436	Sam Rotolo Middle School	1486 - Fixed Equipment, Casework		LMC	2020	Sent to Maintenance	Casework in a fair condition. Not shown in plan, verify quantity and location in field. Cost to replace entirely.	Equipment and Furnishings	Furnishings	Fixed Furnishings	Casework	2-Should Do	Fair	0	\$800	Linear Foot	\$0
4438	Sam Rotolo Middle School	1467 - Interior Doors, Swinging-Wood		Kitchen	2020	Sent to Maintenance	Wood door damaged from heavy traffic. -Room 145	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$1,950	Each	\$1,950
4439	Sam Rotolo Middle School	1499 - Interior Doors, Swinging-Hollow Metal		Kitchen	2020	Sent to Maintenance	Needs to be re-painted. Cost to repaint HM door. -Room 145	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$75	Each	\$75
4442	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		Kitchen	2020	Sent to Maintenance	Bull-nosed corners are badly damaged. Confirm quantity in field. -Room 145	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair	40	\$40	Square Foot	\$1,600
4445	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base		Kitchen	2020	Sent to Maintenance	Mostly good throughout, tile is chipped off at concrete walls near Kitchen Office -Room 145	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	135	\$6	Linear Foot	\$810
4446	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Kitchen	2020	Sent to Maintenance	Wall paint is in fair condition. Quantity reflects total SF of all listed spaces. -Room 145	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	809	\$1	Square Foot	\$728
4449	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Dish Washing	2020	Sent to Maintenance	Doors are chipped where it engages the removable mullion. Cost to replace door and hardware. -Room 145B	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$1,950	Each	\$1,950
4451	Sam Rotolo Middle School	1453 - Interior Doors, Swinging-Hollow Metal		Dish Washing	2020	Sent to Maintenance	Needs to be re-painted. Cost to repaint HM door. -Room 145B	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$75	Each	\$75
4456	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Offices/Pull-Out Spaces	2020	Sent to Maintenance	HM door frames in fair condition - paint chipping, damaged at base. Cost to repaint frame.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	4	\$60	Each	\$240

033, 125, 135, 144,

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4458	Sam Rotolo Middle School	1946 - Interior Wall Finish, Tile		Dish Washing	2020	Sent to Maintenance	Tiles are in a fair condition. Verify quantity in field, estimated to be up to 6'-0" AFF on every wall. Cost to clean grout and tiles. -Room 145B	Interiors	Interior Finishes	Wall Finishes	Tile Wall Finish	2-Should Do	Fair	450	\$5	Square Foot	\$2,250
4461	Sam Rotolo Middle School	1554 - Interiors, Wall Finish - Paint		Dish Washing	2020	Sent to Maintenance	Paint is in a fair condition. Quantity reflects total SF of all listed spaces. -Room 145B	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	286	\$1	Square Foot	\$257
4464	Sam Rotolo Middle School	1453 - Interior Doors, Swinging-Hollow Metal		Offices/Pull-Out Spaces	2020	Sent to Maintenance	HM doors in fair condition - need to be re-painted. 144. 006C	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	2	\$75	Each	\$150
4466	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Serving	2020	Sent to Maintenance	Doors are chipped where it engages the removable mullion. Cost to replace door and hardware. -Room 146	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$1,950	Each	\$1,950
4467	Sam Rotolo Middle School	1453 - Interior Doors, Swinging-Hollow Metal		Serving	2020	Sent to Maintenance	Removable mullion is rusted and chipped. Cost to replace frame. -Room 146	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$450	Each	\$450
4468	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems		Offices/Pull-Out Spaces	2020	Sent to Maintenance	ACT in fair condition - older system, some damaged tiles, many tiles bowing. Cost to replace entire system. 005A. 018A. 019A. 033. 014A. 130. 131. 132. 135. 135B. 136. 137. 144. 702. 703.	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	2-Should Do	Fair	4434	\$8	Square Foot	\$33,255
4470	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems		Serving	2020	Sent to Maintenance	Older 2x4 ACT tiles with minor surface damage (146 SF). Cost to replace entire system. -Room 146	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	2-Should Do	Fair	146	\$8	Square Foot	\$1,095
4471	Sam Rotolo Middle School	1431 - Flooring, Quarry Tile		Serving	2020	Sent to Maintenance	Quarry tile is in good shape, but is older overall (146 SF). Cost to replace. -Room 146	Interiors	Interior Finishes	Flooring	Tile Flooring	2-Should Do	Fair	146	\$30	Square Foot	\$4,380
4472	Sam Rotolo Middle School	1432 - Flooring, VCT		Offices/Pull-Out Spaces	2020	Sent to Maintenance	VCT in fair condition - major scuffs, cracks, worn wax finish. Cost to replace with rubber flooring. 012A. 018A. 019A. 033.	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	580	\$12	Square Foot	\$6,960

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4473	Sam Rotolo Middle School	1452 - Interior Partitions, Fixed-GWB		Serving	2020	Sent to Maintenance	GWB wall damaged near entrance to Kitchen (145). Quantity reflects estimated size of entire wall. -Room 146	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair	330	\$15	Square Foot	\$4,950
4474	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base		Serving	2020	Sent to Maintenance	Wall base is in a fair condition, cost to replace in kind. -Room 146	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	113	\$6	Linear Foot	\$678
4479	Sam Rotolo Middle School	1476 - Interior Railings and Handrails		Serving	2020	Sent to Maintenance	Pipes separating lines need to be scraped and re-painted. -Room 146	Interiors	Interior Construction	Interior Specialties	Interior Railings and Handrails	2-Should Do	Fair	60	\$125	Linear Foot	\$7,500
4483	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base		Offices/Pull-Out Spaces	2020	Sent to Maintenance	Wall base in fair condition - major scuffs but not damaged. Room 703	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	95	\$6	Linear Foot	\$570
4485	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Offices/Pull-Out Spaces	2020	Sent to Maintenance	Paint in fair condition - dirty/scuffed and uneven in some spots. Room 005A, 136, 137, 148, 703	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	1892	\$1	Square Foot	\$1,703
4495	Sam Rotolo Middle School	1497 - Plumbing, Plumbing Fixtures	North/South Classroom Extensions, SW Classrooms	Science	2020	Sent to Maintenance	One sink loose in counter top -Classroom 105	Services	Plumbing	Domestic Water Distribution	Plumbing Fixtures	2-Should Do	Fair	0	\$2,500	Each	\$0
4501	Sam Rotolo Middle School	1437 - Fixed Equipment, Casework		Offices/Pull-Out Spaces	2020	Sent to Maintenance	Casework in fair condition. Verify quantity in field. Cost to replace entirely. Room 703	Equipment and Furnishings	Furnishings	Fixed Furnishings	Casework	2-Should Do	Fair	20	\$800	Linear Foot	\$16,000
4502	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint	North/South Classroom Extensions, SW Classrooms	Science	2020	Sent to Maintenance	-Wall paint is in a fair condition. Quantity reflects total SF of all listed spaces. -Classroom 116	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	1191	\$1	Square Foot	\$1,072
4512	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Offices/Pull-Out Spaces	2020	Sent to Maintenance	Wood doors in fair condition (chips/gouges in veneer, damaged veneer at bottom of door). Cost to replace door and hardware. 124. 134. 135A. 135B. 137. 138. 601. 802. 803. 220A.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	11	\$1,950	Each	\$21,450
4520	Sam Rotolo Middle School	1668 - Flooring, VCT	North/South Classroom Extensions, SW Classrooms	Science	2020	Sent to Maintenance	VCT flooring is in a fair condition. Cost to replace with rubber flooring. -Classroom 216 (1192 SF)	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	1192	\$12	Square Foot	\$14,304
4522	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base	North/South Classroom Extensions, SW Classrooms	Science	2020	Sent to Maintenance	Wall Base in a fair condition -Classroom 216	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	132	\$6	Linear Foot	\$792

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4524	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint	North/South Classroom Extensions, SW Classrooms	Science	2020	Sent to Maintenance	Wall paint in a fair condition. Quantity reflects total SF of all listed spaces. -Classroom 216	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	1192	\$1	Square Foot	\$1,073
4525	Sam Rotolo Middle School	1486 - Fixed Equipment, Casework	North/South Classroom Extensions, SW Classrooms	Science	2020	Sent to Maintenance	Several missing pulls. Cost to repair hardware and re-hang doors. -Classroom 216	Equipment and Furnishings	Furnishings	Fixed Furnishings	Casework	2-Should Do	Fair	130	\$50	Linear Foot	\$6,500
4527	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems		Offices/Pull-Out Spaces	2020	Sent to Maintenance	ACT in fair condition. Room 602	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	2-Should Do	Fair	585	\$8	Square Foot	\$4,388
4530	Sam Rotolo Middle School	1503 - Exterior Windows, Operating	North/South Classroom Extensions, SW Classrooms	Science	2020	Sent to Maintenance	One window taped at sealant and edge of sill. Cost to repair sealant. -Classroom 216 (confirm if 216 or 217)	Shell	Exterior Vertical Enclosures	Exterior Windows	Exterior Operating Windows	2-Should Do	Fair	5	\$6	Linear Foot	\$30
4538	Sam Rotolo Middle School	1668 - Flooring, VCT		Science	2020	Sent to Maintenance	-VCT discolored, water damaged by floor drain classroom 105 (1209 SF). Cost to replace with rubber flooring. - Classroom 105, 106 & 113	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	4866	\$12	Square Foot	\$58,392
4539	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems		Science	2020	Sent to Maintenance	-Several water damaged, one missing (106) (1209 SF) -Some water damaged ceiling tiles, discoloration, missing infill cover at edge of room see pic (113) (1209 SF) -Bowling and damaged ACT - Classroom 105 - Classroom 105, 106 & 113	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	2-Should Do	Fair	5715	\$8	Square Foot	\$42,863
4540	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		Science	2020	Sent to Maintenance	Wall CMU in a fair condition. CMU cracking at window sill and by upper casework. Confirm quantity in field. - Classroom 105	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair	10	\$15	Linear Foot	\$150
4543	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base		Science	2020	Sent to Maintenance	Wall Base in a good condition - Classrooms 113	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	136	\$6	Linear Foot	\$816
4544	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Science	2020	Sent to Maintenance	Paint are in a good condition. Quantity reflects total SF of all listed spaces. - Classrooms 105, 106 & 113	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	3657	\$1	Square Foot	\$3,291
4546	Sam Rotolo Middle School	1531 - Fixed Equipment, Casework		Science	2020	Sent to Maintenance	Casework in a fair condition. Cost to repaint entirely. - Classrooms 105, 106 & 113	Equipment and Furnishings	Furnishings	Fixed Furnishings	Casework	2-Should Do	Fair	210	\$800	Linear Foot	\$168,000
4549	Sam Rotolo Middle School	1439 - Flooring, Carpet		Offices/Pull-Out Spaces	2020	Sent to Maintenance	Carpet in fair condition - old, worn, discolored. Room 220A	Interiors	Interior Finishes	Flooring	Carpeting	2-Should Do	Fair	406	\$7	Square Foot	\$2,639
4550	Sam Rotolo Middle School	1545 - Plumbing, Plumbing Fixtures		Science	2020	Sent to Maintenance	One sink loose in counter top - Classrooms 105	Services	Plumbing	Domestic Water Distribution	Plumbing Fixtures	2-Should Do	Fair	0	\$2,500	Each	\$0
4555	Sam Rotolo Middle School	1545 - Plumbing, Plumbing Fixtures		Science	2014	Sent to Maintenance	Sinks: One loose faucet by front of classroom (106) - Classrooms 106 & 113 Per 2014 H/LS Report - no reference to classroom sinks.	Services	Plumbing	Domestic Water Distribution	Plumbing Fixtures	2-Should Do	Fair	0	\$2,500	Each	\$0

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4556	Sam Rotolo Middle School	1416 - HVAC, Ventilation-Unit Ventilators		Science	2020	Sent to Maintenance	Unit vents in a fair condition. Refer to large scale replacement. - Classrooms 105 & 106	Services	Heating, Ventilation, and Air Conditioning (HVAC)	Ventilation	Supply Air	2-Should Do	Fair	0	\$4,500	Each	\$9,000
4558	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Offices/Pull-Out Spaces	2020	Sent to Maintenance	Paint in fair condition. Quantity reflects total SF of all listed spaces. 601, 604, 804	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	625	\$1	Square Foot	\$563
4568	Sam Rotolo Middle School	1668 - Flooring, VCT		Science	2020	Sent to Maintenance	Missing tiles by UV (206). Cost to replace VCT in entire room with rubber flooring. Classrooms: 205, 206, and 213	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	3633	\$12	Linear Foot	\$43,596
4569	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		Science	2020	Sent to Maintenance	Sealant separates at structure in corner, other corner sealant damaged (206) Missing sealant in corner, minor cracking by window sill (213) Classrooms: 205, 206, and 213	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair	50	\$15	Linear Foot	\$750
4570	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base		Science	2020	Sent to Maintenance	Wall base in Fair condition. Classrooms: 205, 206, and 213	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	420	\$6	Linear Foot	\$2,520
4571	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Science	2020	Sent to Maintenance	Paint in Fair condition. Quantity reflects total SF of all listed spaces. Classrooms: 205, 206, and 213	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	3633	\$1	Square Foot	\$3,270
4577	Sam Rotolo Middle School	1497 - Plumbing, Plumbing Fixtures		Science	2014	Sent to Maintenance	2 loose faucets (205) 1 loose faucets (206) Classrooms: 205, 206 Per 2014 H/LS Report - no reference to classroom sinks.	Services	Plumbing	Domestic Water Distribution	Plumbing Fixtures	2-Should Do	Fair	0	\$2,500	Each	\$0
4578	Sam Rotolo Middle School	1545 - Plumbing, Plumbing Fixtures		Science	2020	Sent to Maintenance	A couple loose faucets and low flow fixtures Classroom: 213	Services	Plumbing	Domestic Water Distribution	Plumbing Fixtures	2-Should Do	Fair	0	\$2,500	Each	\$0
4579	Sam Rotolo Middle School	1545 - Plumbing, Plumbing Fixtures		Science	2020	Sent to Maintenance	Sinks in a fair condition Classroom: 205	Services	Plumbing	Domestic Water Distribution	Plumbing Fixtures	2-Should Do	Fair	0	\$2,500	Each	\$0
4582	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Mechanical/Electrical Rooms	2020	Sent to Maintenance	Wood door in fair condition. Cost to replace door and hardware. 705	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$1,950	Each	\$1,950
4583	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Mechanical/Electrical Rooms	2020	Sent to Maintenance	Wood door in fair condition. Cost to replace door and hardware. 220C	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$1,950	Square Foot	\$1,950
4585	Sam Rotolo Middle School	1453 - Interior Doors, Swinging-Hollow Metal		Mechanical/Electrical Rooms	2020	Sent to Maintenance	HM door in fair condition - Door is rusting at the bottom and kick plate needs to be replaced soon. Cost to repaint door. Boiler Room 143	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$75	Square Foot	\$75
4587	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Mechanical/Electrical Rooms	2020	Sent to Maintenance	HM door frame in fair condition, damaged at jamb. Cost to replace. 143, 32, 147A	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	3	\$450	Square Foot	\$1,350

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4590	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		GYM	2020	Sent to Maintenance	Several doors have darker stains on them and have chips on the bottom of them. -West GYM	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	3	\$1,950	Each	\$5,850
4592	Sam Rotolo Middle School	1453 - Interior Doors, Swinging-Hollow Metal		GYM	2020	Sent to Maintenance	Doors are scuffed up and hardware is rusting - East GYM. Door hardware is rusting. Doors mostly covered with pads - Upper GYM. Cost to replace HM doors and hardware.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	7	\$1,600	Each	\$11,200
4593	Sam Rotolo Middle School	1453 - Interior Doors, Swinging-Hollow Metal		GYM	2020	Sent to Maintenance	Frames are rusting slightly in several locations, base of all jambs have slight damage to them - West GYM.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	4	\$450	Each	\$1,800
4597	Sam Rotolo Middle School	1403 - Slab on Grade		Mechanical/Electrical Rooms	2020	Sent to Maintenance	Concrete floor in fair condition - floor is painted but badly scuffed throughout. 143, 147A	Substructure	Slabs-On-Grade	Standard Slabs-on-Grade		2-Should Do	Fair	3363	\$20	Square Foot	\$67,260
4600	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		Mechanical/Electrical Rooms	2020	Sent to Maintenance	CMU in fair condition - Vertical cracking at the corners and on the east wall that appears to have been repaired. Sprinkler Room 32	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair	0	\$15	Linear Foot	\$0
4602	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base		Mechanical/Electrical Rooms	2020	Sent to Maintenance	Wall base in fair condition. 143 - Wear and tear from having materials up against it. 705.	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	240	\$6	Linear Foot	\$1,440
4606	Sam Rotolo Middle School	1400 - Interiors, Flooring - Wood		GYM	2020	Sent to Maintenance	Floor boards are beginning to separate in some areas. More significant scuffs near the exit doors of the gym - East GYM Per Capital Projects Plan - East Gym floor scheduled for replacement in 2031. Cost to replace flooring.	Interiors	Interior Finishes	Flooring	Wood Flooring	2-Should Do	Fair	7408	\$25	Square Foot	\$185,200
4610	Sam Rotolo Middle School	1454 - Electrical, Lighting Fixtures		Mechanical/Electrical Rooms	2020	Sent to Maintenance	Lighting in fair condition. Electrical 705	Services	Electrical	Lighting	Lighting Fixtures	2-Should Do	Fair	0	\$0	Each	\$0
4614	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base		GYM	2020	Sent to Maintenance	Vented cove base is dirty throughout and splitting between individual sections - East GYM	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	320	\$6	Linear Foot	\$1,920
4615	Sam Rotolo Middle School	1404 - Elevated Concrete Slab		Mechanical/Electrical Rooms	2020	Sent to Maintenance	Concrete floor in fair condition. Confirm cost to refinish concrete floor without slab replacement. Mechanical 020A	Shell	Superstructure	Floor Construction	Floor Decks, Slabs, and Toppings	2-Should Do	Fair	588	\$20	Square Foot	\$11,760
4617	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base		GYM	2020	Sent to Maintenance	Vented cove base is dirty throughout and splitting between individual sections - East GYM	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	250	\$6	Linear Foot	\$1,500

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4619	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		GYM	2020	Sent to Maintenance	Quantity reflects total SF of estimated wainscot height x gym perimeter - verify in field. - Grey wainscoat could use a refresh, but area's above pad line are good - West GYM - Black wainscoat of paint is peeling throughout - Upper GYM	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	3600	\$1	Square Foot	\$3,240
4623	Sam Rotolo Middle School	1453 - Interior Doors, Swinging-Hollow Metal	South Gym	GYM	2020	Sent to Maintenance	-Base of doors have some abuse - would benefit from a kick plate - South GYM. Cost to repaint doors.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	4	\$75	Each	\$300
4625	Sam Rotolo Middle School	1453 - Interior Doors, Swinging-Hollow Metal		Janitor	2020	Sent to Maintenance	HM door in fair condition. Cost to repaint. J-3	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$75	Each	\$75
4628	Sam Rotolo Middle School	1462 - Interior Partitions, Fixed-CMU	South Gym	GYM	2020	Sent to Maintenance	Sealant joints are cracking vertically throughout the space - South GYM. Cost to repair sealant.	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair	100	\$6	Linear Foot	\$600
4629	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base	South Gym	GYM	2020	Sent to Maintenance	Vented cove base is dirty throughout and splitting between individual sections - South GYM	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	316	\$6	Linear Foot	\$1,896
4630	Sam Rotolo Middle School	1453 - Interior Doors, Swinging-Hollow Metal		Janitor	2020	Sent to Maintenance	HM door frame in fair condition. Cost to repaint. J-3	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$60	Each	\$60
4634	Sam Rotolo Middle School	1548 - Electrical, Lighting Fixtures	South Gym	GYM	2020	Sent to Maintenance	Older high bay lights than the other gyms - South GYM	Services	Electrical	Lighting	Lighting Fixtures	2-Should Do	Fair	0	\$0		\$0
4635	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Janitor	2020	Sent to Maintenance	Paint in fair condition. Quantity reflects total SF of all listed spaces. J-3	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	49	\$1	Square Foot	\$44
4637	Sam Rotolo Middle School	1454 - Electrical, Lighting Fixtures		Janitor	2020	Sent to Maintenance	Lighting in fair condition. J-3	Services	Electrical	Lighting	Lighting Fixtures	2-Should Do	Fair	0	\$0	Each	\$0
4639	Sam Rotolo Middle School	1454 - Electrical, Lighting Fixtures		Janitor	2020	Sent to Maintenance	Lighting in fair condition. J-4	Services	Electrical	Lighting	Lighting Fixtures	2-Should Do	Fair	0	\$0	Each	\$0
4640	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Janitor	2020	Sent to Maintenance	Paint in fair condition. Quantity reflects total SF of all listed spaces. J-4	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	49	\$1	Square Foot	\$44
4642	Sam Rotolo Middle School	1404 - Elevated Concrete Slab		Janitor	2020	Sent to Maintenance	Concrete flooring is in fair condition. Confirm cost to refinish concrete floor without slab replacement. J-4	Shell	Superstructure	Floor Construction	Floor Decks, Slabs, and Toppings	2-Should Do	Fair	49	\$20	Square Foot	\$980
4643	Sam Rotolo Middle School	1453 - Interior Doors, Swinging-Hollow Metal		Janitor	2020	Sent to Maintenance	HM door frame in fair condition. Cost to repaint. J-4	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$60	Each	\$60

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4644	Sam Rotolo Middle School	1453 - Interior Doors, Swinging-Hollow Metal		Janitor	2020	Sent to Maintenance	HM door in fair condition. Cost to repaint. J-4	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$75	Each	\$75
4646	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Locker Room	2020	Sent to Maintenance	Interior wood doors are in a fair condition - 18C & 19B. Cost to replace door and hardware.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	2	\$1,950	Each	\$3,900
4648	Sam Rotolo Middle School	1553 - Interiors, Wall Finish - Paint	North/South Classroom Extensions, SW Classrooms	Janitor	2020	Sent to Maintenance	Paint in fair condition. Quantity reflects total SF of all listed spaces. J-8	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	45	\$1	Square Foot	\$41
4651	Sam Rotolo Middle School	1459 - Elevated Concrete Slab	North/South Classroom Extensions, SW Classrooms	Janitor	2020	Sent to Maintenance	Concrete flooring is in fair condition. Confirm cost to refinish concrete flooring without slab replacement. J-8	Shell	Superstructure	Floor Construction	Floor Decks, Slabs, and Toppings	2-Should Do	Fair	50	\$20	Square Foot	\$1,000
4653	Sam Rotolo Middle School	1547 - Interior Doors, Swinging-Hollow Metal		Locker Room	2020	Sent to Maintenance	Door has narrow lite, Girl's locker room does not - 19	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$1,600	Each	\$1,600
4654	Sam Rotolo Middle School	1547 - Interior Doors, Swinging-Hollow Metal		Locker Room	2020	Sent to Maintenance	Interior hollow metal frames are in a fair condition. Cost to repaint. Rooms 18 & 19	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	2	\$60	Each	\$120
4658	Sam Rotolo Middle School	1551 - Interior Wall Finishes, Wall Base	North/South Classroom Extensions, SW Classrooms	Janitor	2020	Sent to Maintenance	Wall base in fair condition. J-8	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	22	\$6	Linear Foot	\$132
4659	Sam Rotolo Middle School	1420 - Ceilings, Gypsum		Locker Room	2020	Sent to Maintenance	- Ceiling cracking near transition to Storage room 019C - 19	Interiors	Interior Construction	Suspended Ceiling Construction	Suspended Plaster and Gypsum Board	2-Should Do	Fair	1690	\$12	Square Foot	\$20,280
4661	Sam Rotolo Middle School	1403 - Slab on Grade		Locker Room	2020	Sent to Maintenance	- Slab is in overall good shape, but the floor topping is peeling and spalling throughout. 18- (1363 SF) 19- (1554)	Substructure	Slabs-On-Grade	Standard Slabs-on-Grade		2-Should Do	Fair	2917	\$25	Square Foot	\$72,925
4663	Sam Rotolo Middle School	1459 - Elevated Concrete Slab	North/South Classroom Extensions, SW Classrooms	Janitor	2020	Sent to Maintenance	Concrete flooring in fair condition. Confirm cost to refinish concrete flooring without slab replacement. J-7	Shell	Superstructure	Floor Construction	Floor Decks, Slabs, and Toppings	2-Should Do	Fair	49	\$20	Square Foot	\$980
4665	Sam Rotolo Middle School	1551 - Interior Wall Finishes, Wall Base	North/South Classroom Extensions, SW Classrooms	Janitor	2020	Sent to Maintenance	Wall base in fair condition. J-7	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	22	\$6	Linear Foot	\$132
4671	Sam Rotolo Middle School	1668 - Flooring, VCT		Locker Room	2020	Sent to Maintenance	VCT flooring is in a fair condition - 19B. Cost to replace with epoxy.	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	124	\$20	Square Foot	\$2,480
4678	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base		Locker Room	2020	Sent to Maintenance	Scuffs throughout - 19B	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	55	\$6	Linear Foot	\$330
4679	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Locker Room	2020	Sent to Maintenance	Walls are very dirty from 2'-0" down. Quantity reflects total SF of all listed spaces. - 18 & 19	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	3000	\$1	Square Foot	\$2,700
4683	Sam Rotolo Middle School	1548 - Electrical, Lighting Fixtures		Locker Room	2020	Sent to Maintenance	Older recessed lights in GWB ceiling - 18C & 19B	Services	Electrical	Lighting	Lighting Fixtures	2-Should Do	Fair	0	\$0		\$0

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4684	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Stage/Cafeteria/Multipurpose	2020	Sent to Maintenance	- Interior wood door is in a fair condition - 23 - Doors are older and are chipped along the edges throughout - 24 - Doors have damage where the door meets the jamb and the bottom of the doors on the corridor side - 31.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	8	\$1,950	Each	\$15,600
4685	Sam Rotolo Middle School	1547 - Interior Doors, Swinging-Hollow Metal		Stage/Cafeteria/Multipurpose	2020	Sent to Maintenance	- Residual paint from wall and scratched - 23 - Missing kick plate, bottom of door is damaged - 24 & 31. Cost to replace HM doors.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	7	\$600	Each	\$4,200
4687	Sam Rotolo Middle School	1547 - Interior Doors, Swinging-Hollow Metal		Stage/Cafeteria/Multipurpose	2020	Sent to Maintenance	-Removable mullion is damaged on the base and frames could use re-painting - 31. Cost to replace frames.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	2	\$450	Each	\$900
4689	Sam Rotolo Middle School	1409 - Exterior Entrance Doors, Hollow Metal		Stage/Cafeteria/Multipurpose	2020	Sent to Maintenance	Exterior HM door is in a fair condition - 31. Cost to repaint.	Shell	Exterior Vertical Enclosures	Exterior Doors and Grilles	Exterior Entrance Doors	2-Should Do	Fair	2	\$60	Each	\$120
4692	Sam Rotolo Middle School	1484 - Flooring, VCT		Stage/Cafeteria/Multipurpose	2020	Sent to Maintenance	- VCT is scuffed from use and damaged tiles at operable wall panel - 23 - Tile has scuffs from table legs - 24 - Original flooring - significant scuffs, some seapartion between tile seams - 31 24- (5261 SF) 31- (3373 SF) Cost to replace with rubber flooring.	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	12147	\$12	Square Foot	\$145,764
4693	Sam Rotolo Middle School	1462 - Interior Partitions, Fixed-CMU		Stage/Cafeteria/Multipurpose	2020	Sent to Maintenance	- Damaged at bull nosed corners throughout - 23 - Vertical cracking at joints on two walls - 31. Confirm quantity in field. Cost to repair damaged CMU.	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair	50	\$40	Square Foot	\$2,000
4695	Sam Rotolo Middle School	1452 - Interior Partitions, Fixed-GWB		Stage/Cafeteria/Multipurpose	2020	Sent to Maintenance	- Soffits are cracking on the east walls and GWB at operable partition jambs are damaged - 24. Confirm quantity in field.	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair	75	\$15	Square Foot	\$1,125
4699	Sam Rotolo Middle School	1551 - Interior Wall Finishes, Wall Base		Stage/Cafeteria/Multipurpose	2020	Sent to Maintenance	- Wall base is in a fair condition - 24	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	221	\$6	Linear Foot	\$1,326
4701	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Stage/Cafeteria/Multipurpose	2020	Sent to Maintenance	Quantity reflects total SF of all listed spaces. - Wall paint is in fair condition - 23 - Grey wainscoat is dirty and needs to be re-painted - 24	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	9260	\$1	Square Foot	\$8,334
4703	Sam Rotolo Middle School	1548 - Electrical, Lighting Fixtures		Stage/Cafeteria/Multipurpose	2020	Sent to Maintenance	-Lighting is in fair condition - 23	Services	Electrical	Lighting	Lighting Fixtures	2-Should Do	Fair	0	\$0		\$0

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4706	Sam Rotolo Middle School	1434 - Interior Stair Finishes, Resilient		Stage/Cafeteria/ Multipurpose	2020	Sent to Maintenance	- Rubber treads at back stairs and ramp are worn and discolored - 23 - Stair treads are worn and have been patched in several locations - 24 - confirm how to quantify these stairs because they're much larger than normal stairs. Current quantity reflects stairs to stage only.	Interiors	Interior Finishes	Stair Finishes	Resilient Stair Finish	2-Should Do	Fair	6	\$90	Each	\$540
4708	Sam Rotolo Middle School	1949 - Equipment, Bleachers	South Gym	Gym	2020	Sent to Maintenance	Bleachers are in fair condition - South GYM Cost per seat	Equipment and Furnishings	Equipment	Entertainment and Recreational Equipment	Athletic Equipment	2-Should Do	Fair	0	\$450	Each	\$0
4709	Sam Rotolo Middle School	8675 - Equipment, Wall Pads	South Gym	Gym	2020	Sent to Maintenance	Wall Pads are in fair condition - South GYM	Equipment and Furnishings	Equipment	Entertainment and Recreational Equipment	Athletic Equipment	2-Should Do	Fair	292	\$50	Linear Foot	\$14,600
4712	Sam Rotolo Middle School	1949 - Equipment, Bleachers		Gym	2020	Sent to Maintenance	Specialty Bleachers are in fair condition - East GYM Cost is per seat.	Equipment and Furnishings	Equipment	Entertainment and Recreational Equipment	Athletic Equipment	2-Should Do	Fair	0	\$450	Each	\$0
4713	Sam Rotolo Middle School	1949 - Equipment, Bleachers		GYM	2020	Sent to Maintenance	- North wall pads has a sagging section, overall are pretty dirty - west GYM - Individual pads throughout the space are sagging - Upper Gym	Equipment and Furnishings	Equipment	Entertainment and Recreational Equipment	Athletic Equipment	2-Should Do	Fair	460	\$50	Linear Foot	\$23,000
4715	Sam Rotolo Middle School	1545 - Plumbing, Plumbing Fixtures		Locker Room	2020	Sent to Maintenance	Showers appear to not be used anymore - storage items in there - 18C	Services	Plumbing	Domestic Water Distribution	Plumbing Fixtures	2-Should Do	Fair	1	\$0	Each	\$0
4717	Sam Rotolo Middle School	8676 - Equipment, Benches		Locker Rooms	2020	Sent to Maintenance	Benches wood has seen significant use, metal supports and bases have signs of rusting	Equipment and Furnishings	Equipment	Entertainment and Recreational Equipment	Athletic Equipment	2-Should Do	Fair	16	\$600	Each	\$9,600
4718	Sam Rotolo Middle School	8626 - Equipment, Athletic Lockers		Locker Room	2020	Sent to Maintenance	Lockers appear to be original. Most doors have minor denting and some rust spotting consistently throughout on the outside face of each locker. Cost to replace. Locker count provided by BPS101: Boys Locker Room – 816 small, 160 med, 64 large (1,040 total) Girls Locker Room – 816 small, 138 med, 0 large (954 total) .	Equipment and Furnishings	Equipment	Institutional Equipment	Educational and Scientific Equipment	2-Should Do	Fair	1994	\$200	Each	\$398,800
4726	Sam Rotolo Middle School	1499 - Interior Doors, Swinging-Hollow Metal		Corridor	2020	Sent to Maintenance	- Corridor between Gyms and Exploratory is in a fair condition. - rusted, paint chipping - 7th East and 7th North. -8th West and 8th North are in a fair condition. - 6th South and 6th Central are in a fair condition. Cost to repaint HM doors.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	12	\$75	Each	\$900
4727	Sam Rotolo Middle School	1409 - Exterior Entrance Doors, Hollow Metal		Corridor	2020	Sent to Maintenance	- Door is HM with Full Lites - door is chipped and scratched and needs re-painting - Corridor - Mechanical. Cost to repaint.	Shell	Exterior Vertical Enclosures	Exterior Doors and Grilles	Exterior Entrance Doors	2-Should Do	Fair	1	\$75	Each	\$75

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4728	Sam Rotolo Middle School	1453 - Interior Doors, Swinging-Hollow Metal		Corridor	2020	Sent to Maintenance	- Interior HM Frame and removable mullion are damaged - need to be repainted - Corridor - Mechanical. - Interior HM frame Gasketing at exterior doors is loose at the full lite glazing units - Corridor - Gymnasiums. - Interior HM frame Corridor between Gyms and Exploratory is in a fair condition. -Interior HM frame rusted, paint chipping - 7th West and North. Cost to repaint.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	4	\$60	Each	\$240
4730	Sam Rotolo Middle School	1409 - Exterior Entrance Doors, Hollow Metal		Corridor	2020	Sent to Maintenance	- Exterior Frame is HM and is chipped on the edges - Corridor - Mechanical. Cost to repaint.	Shell	Exterior Vertical Enclosures	Exterior Doors and Grilles	Exterior Entrance Doors	2-Should Do	Fair	1	\$60	Each	\$60
4732	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems		Corridor	2020	Sent to Maintenance	- Tiles are bowing slightly throughout - Corridor - Mechanical. - Miscellaneous tiles replaced over time. Some tiles are chipped - Corridor - Gymnasiums. - ACT Corridor between Gyms and Exploratory is in a fair condition. - ACT corridor 7th North is in fair condition. Cost to replace entire system.	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	2-Should Do	Fair	2807	\$8	Square Foot	\$21,053
4736	Sam Rotolo Middle School	1526 - Flooring, VCT		Corridor	2020	Sent to Maintenance	- Scuffing from carts and dollies - Corridor - Mechanical. - Scuffs throughout and some cracking at individual tiles - Corridor - Gymnasiums. - 12 lf crack in VCT, other cracking throughout corridor, tiles are different colors - Corridor between Gyms and Exploratory. - VCT is in fair condition - 7th East and West. - 12 lf crack at opening between central and north corridors - 7th Central. - 7 cracked tiles outside of classrooms 203/204 - 8th East. - VCT is in fair condition - 8th West and 8th North. - 4 cracked tiles outside of classroom 206, 4 cracked tiles outside of 215- 8th Central. - 7 cracked tiles outside of classrooms 203/204 - 6th East. - VCT is in fair condition - 6th West and 6th South.	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	12978	\$12	Square Foot	\$155,736

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4740	Sam Rotolo Middle School	1462 - Interior Partitions, Fixed-CMU		Corridor	2020	Sent to Maintenance	- CMU walls are in a fair condition - 8th East, West, North. - sealant separated at structure at classrooms 206 and 213 - 8th central. - CMU walls are in a fair condition - 6th East, West, North. - sealant separated at structure at classrooms 206 and 213 - 6th central. - cracking through block - corridor by 021	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair	60	\$15	Linear Foot	\$900
4742	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base		Corridor	2020	Sent to Maintenance	- Wall Base Mostly good throughout, some areas have completely chipped off at the top - Corridor - Mechanical. - Wall Base in a fair condition - Corridor - Gymnasiums. - Wall Base in a fair condition - Corridor between Gyms and Exploratory. - Wall Base in a fair condition - 7th East, West, North and Central. - Wall Base in a fair condition - 8th East, West, North and Central. - Wall Base in a fair condition - 6th	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	2200	\$6	Linear Foot	\$13,200
4745	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Corridor	2020	Sent to Maintenance	Quantity reflects total SF of all listed spaces. - Wall paint in fair condition - Corridor - Gymnasiums. - Wall paint in fair condition - Corridor between Gyms and Exploratory. - multiple scuffs/stains throughout - Corridor near Art/Drafting. - Wall paint in fair condition - Corridor - 7th East, West, North and Central. - Wall paint in fair condition - Corridor - 8th East, West, North and Central. - Wall paint in fair condition - Corridor - 6th East, West, North and Central.	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	13000	\$1	Square Foot	\$11,700
4750	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Stair	2020	Sent to Maintenance	- 2 doors are in fair condition - Stair - 8th gr. North Corridor. Cost to replace door and hardware.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	2	\$1,950	Each	\$3,900
4754	Sam Rotolo Middle School	1409 - Exterior Entrance Doors, Hollow Metal		Stair	2020	Sent to Maintenance	-Exterior Intermediate mullion is rusting -Stair - West Gymnasium NE. Cost to repaint frame.	Shell	Exterior Vertical Enclosures	Exterior Doors and Grilles	Exterior Entrance Doors	2-Should Do	Fair	1	\$60	Each	\$60

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4760	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems		Stair	2020	Sent to Maintenance	-Top of stairwell ACT is all bowing - Stair - Above Mech 020B & Stair - Above Mech 017C -Tiles are bowing - Stair - West Gymnasium NE. Cost to replace system entirely.	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	2-Should Do	Fair	1125	\$8	Square Foot	\$8,438
4762	Sam Rotolo Middle School	1668 - Flooring, VCT		Stair	2020	Sent to Maintenance	-VCT at top landing is chipped and cracking near the detectable warning rubber - Stair - Above Mech 020B. - Intermediate landing has small section of VCT that could be replaced with all rubber treads - Stair - West Gymnasium NE.	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	875	\$12	Square Foot	\$10,500
4764	Sam Rotolo Middle School	1533 - Flooring, Carpet		Stair	2020	Sent to Maintenance	-walk off carpet stained at one of the ext. doors - (5) 2x2 carpet tiles - Stair - 7th gr. North Corr.	Interiors	Interior Finishes	Flooring	Carpeting	2-Should Do	Fair	1485	\$7	Square Foot	\$9,653
4767	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		Stair	2020	Sent to Maintenance	Vertical cracking occurring through several CMU blocks - Stair - Above Mech 020B. & Stair - Above Mech 017C. Confirm quantity in field.	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair	50	\$15	Linear Foot	\$750
4770	Sam Rotolo Middle School	1551 - Interior Wall Finishes, Wall Base		Stair	2020	Sent to Maintenance	wall base Seriously scuffed but not broken - Stair - Near Main Entrance	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	44	\$6	Linear Foot	\$264
4771	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Stair	2020	Sent to Maintenance	wall paint in a fair condition. Quantity reflects total SF of all listed spaces. - Stair - 7th gr. North Corr.	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	350	\$1	Square Foot	\$315
4774	Sam Rotolo Middle School	1548 - Electrical, Lighting Fixtures		Stair	2020	Sent to Maintenance	Wall lights do not provide enough coverage for the entire stairwell - Stair - West Gymnasium NE	Services	Electrical	Lighting	Lighting Fixtures	2-Should Do	Fair	0	\$0		\$0
4777	Sam Rotolo Middle School	1528 - Interior Stair Finishes, Resilient		Stair	2020	Sent to Maintenance	Stairs- treads/Risers in fair condition - Stair - Near Main Entrance, and Commons stair by 6th grade. Miscellaneous rubber treads have been replaced individually over time. Treads and risers are worn down from heavy traffic - Stair - Above Mech 020B - Stair - Above Mech 017C. Treads have slight chips in them throughout and some cracking - Stair - West Gymnasium NE.	Interiors	Interior Finishes	Stair Finishes	Resilient Stair Finish	2-Should Do	Fair	90	\$90	Each	\$8,100
4779	Sam Rotolo Middle School	1421 - Interior Railings and Handrails		Stair	2020	Sent to Maintenance	Stained wood railings, stain is chipping off - Stair - Near Main Entrance. Pipe rails are in fair condition - Commons stair by 6th grade. Cost to repair	Interiors	Interior Construction	Interior Specialties	Interior Railings and Handrails	2-Should Do	Fair	50	\$25	Linear Foot	\$1,250
4789	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint	North/South Classroom Extensions, SW Classrooms	Stair by door N-2	2020	Sent to Maintenance	Wall paint is in a fair condition. Quantity reflects total SF of all listed spaces.	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	581	\$1	Square Foot	\$523

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4795	Sam Rotolo Middle School	1453 - Interior Doors, Swinging-Hollow Metal	North/South Classroom Extensions, SW Classrooms	Corridor	2020	Sent to Maintenance	Interior HM door needs to be re painted - 8th and 6th New Central	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	2	\$75	Each	\$150
4800	Sam Rotolo Middle School	1668 - Flooring, VCT	North/South Classroom Extensions, SW Classrooms	Corridor	2020	Sent to Maintenance	VCT flooring is in fair condition. Cost to replace with rubber flooring. - 8th and 6th New Central.	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	1214	\$12	Square Foot	\$14,568
4802	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU	North/South Classroom Extensions, SW Classrooms	Corridor	2020	Sent to Maintenance	- cracking through blocks at door frame, cracks in corner where addition attaches to original building - 8th and 6th New Central - major sealant separation at expansion joint on exterior north wall	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair	30	\$15	Linear Foot	\$450
4803	Sam Rotolo Middle School	1551 - Interior Wall Finishes, Wall Base	North/South Classroom Extensions, SW Classrooms	Corridor	2020	Sent to Maintenance	- wall base is in a fair condition - 6th, 7th, and 8th New central	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	655	\$6	Linear Foot	\$3,930
4804	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint	North/South Classroom Extensions, SW Classrooms	Corridor	2020	Sent to Maintenance	wall paint is in a fair condition. Quantity reflects total SF of all listed spaces. - 6th, 7th, and 8th New central	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	2700	\$1	Square Foot	\$2,430
4856	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems		Stairs	2020	Sent to Maintenance	ACT ceiling is in a fair condition. Cost to replace entire system. Stairs by Classroom 229	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	2-Should Do	Fair	225	\$8	Square Foot	\$1,688
4858	Sam Rotolo Middle School	1554 - Interiors, Wall Finish - Paint		Stairs	2020	Sent to Maintenance	Wall paint is in a fair condition. Quantity reflects total SF of all listed spaces. Stairs by Classroom 229	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	230	\$1	Square Foot	\$207
4860	Sam Rotolo Middle School	1528 - Interior Stair Finishes, Resilient		Stairs	2020	Sent to Maintenance	Stairs-Treads and Risers are in fair condition. Stairs by Classroom 229	Interiors	Interior Finishes	Stair Finishes	Resilient Stair Finish	2-Should Do	Fair	18	\$90	Each	\$1,620
4861	Sam Rotolo Middle School	1476 - Interior Railings and Handrails		Stairs	2020	Sent to Maintenance	Stairs-Pipe rails are in fair condition. Cost repaint. Stairs by Classroom 229	Interiors	Interior Construction	Interior Specialties	Interior Railings and Handrails	2-Should Do	Fair	28	\$20	Linear Foot	\$560
4867	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Storage	2020	Sent to Maintenance	Wood door in fair condition - doors chipped, veneer has major scratches. Cost to replace door and hardware. 012B. 014B. 017A. 031A. 148C.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	6	\$1,950	Each	\$11,700

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4868	Sam Rotolo Middle School	1453 - Interior Doors, Swinging-Hollow Metal		Storage	2020	Sent to Maintenance	HM door in fair condition - door is dented, base is rusted, kick plate needs to be replaced. Cost to replace door and hardware. 33. 147. 019C - rusting on locker room side. 139. 142.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	5	\$1,600	Each	\$8,000
4872	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Storage	2020	Sent to Maintenance	HM door frame in fair condition - rusting at base, paint chipped. Cost to repaint. 706, 031A, 149A	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	3	\$60	Each	\$180
4873	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Storage	2020	Sent to Maintenance	HM door frame in fair condition - rusting at base, paint chipped. Cost to repaint. 33, 147, 139, 142	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	4	\$60	Each	\$240
4876	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems		Storage	2020	Sent to Maintenance	ACT in fair condition - hole in tile, light missing? Cost to replace entire system. 129A	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	2-Should Do	Fair	10	\$8	Square Foot	\$75
4878	Sam Rotolo Middle School	1420 - Ceilings, Gypsum		Storage	2020	Sent to Maintenance	GWB ceiling in fair condition - not fully sealed around edges. 149A	Interiors	Interior Construction	Suspended Ceiling Construction	Suspended Plaster and Gypsum Board Ceilings	2-Should Do	Fair	39	\$12	Square Foot	\$468
4880	Sam Rotolo Middle School	1432 - Flooring, VCT		Storage	2020	Sent to Maintenance	VCT in fair condition - significant scuffs throughout, polish worn down, missing one or two tiles at perimeter. Cost to replace with rubber flooring. 33. 139. 706. 017A. 019C.	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	1928	\$12	Square Foot	\$23,136
4882	Sam Rotolo Middle School	1403 - Slab on Grade		Storage	2020	Sent to Maintenance	Concrete floor in fair condition - paint on floor worn off, cracking in slab. Confirm unit cost/scope. 141. 142. 149. 031A - Slab has large crack near double doors - appears to have been patched over time.	Substructure	Slabs-On-Grade	Standard Slabs-on-Grade		2-Should Do	Fair	1352	\$25	Square Foot	\$33,800
4886	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		Storage	2020	Sent to Maintenance	CMU in fair condition. Confirm scope in field. 031B - vertical cracking in west wall that appears to have been sealed.	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair	0	\$15	Square Foot	\$0

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4890	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base		Storage	2020	Sent to Maintenance	Wall base in fair condition - Wear and tear from having materials up against it. 33. 139. 142. 149A.	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	239	\$6	Square Foot	\$1,434
4892	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Storage	2020	Sent to Maintenance	Paint in fair condition, uneven in some areas. Quantity reflects total SF of all listed spaces. 007A	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	350	\$1	Square Foot	\$315
4899	Sam Rotolo Middle School	1668 - Flooring, VCT	South Gym	Storage	2020	Sent to Maintenance	VCT in fair condition - Significant scuffs from storage materials. Cost to replace with rubber flooring. 034A	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	87	\$12	Square Foot	\$1,044
4904	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Storage	2020	Sent to Maintenance	Wood door in fair condition. Cost to replace door and hardware. 605	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$1,950	Each	\$1,950
4906	Sam Rotolo Middle School	1453 - Interior Doors, Swinging-Hollow Metal		Storage	2020	Sent to Maintenance	HM door in fair condition - Door needs to be repainted. More damage at the base than anywhere else. 020A	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$75	Each	\$75
4911	Sam Rotolo Middle School	1432 - Flooring, VCT		Storage	2020	Sent to Maintenance	VCT in fair condition. Cost to replace with rubber flooring. 805, 212A (missing tiles at unit vent)	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	130	\$12	Square Foot	\$1,560
4913	Sam Rotolo Middle School	1404 - Elevated Concrete Slab		Storage	2020	Sent to Maintenance	Concrete flooring in fair condition, slight cracking throughout. Cost to repair cracking. 020B	Shell	Superstructure	Floor Construction	Floor Decks, Slabs, and Toppings	2-Should Do	Fair	249	\$10	Square Foot	\$2,490
4915	Sam Rotolo Middle School	1439 - Flooring, Carpet		Storage	2020	Sent to Maintenance	Carpet in fair condition. 220B	Interiors	Interior Finishes	Flooring	Carpeting	2-Should Do	Fair	332	\$7	Square Foot	\$2,158
4916	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		Storage	2020	Sent to Maintenance	CMU in fair condition. 212A - Cracked sealant in 2 corners. 220B - Horizontal stair step crack at door frame.	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair	30	\$15	Each	\$450
4918	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base		Storage	2020	Sent to Maintenance	Wall base in fair condition. 605, 020A, 212A	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	92	\$6	Linear Foot	\$552
4920	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Storage	2020	Sent to Maintenance	Paint in fair condition. Quantity reflects total SF of all listed spaces. 605, 212A	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	321	\$1	Square Foot	\$289
4923	Sam Rotolo Middle School	1416 - HVAC, Ventilation-Unit Ventilators		Storage	2020	Sent to Maintenance	Unit vent in fair condition. Refer to large scale replacement. 212A	Services	Heating, Ventilation, and Air Conditioning (HVAC)	Ventilation	Supply Air	2-Should Do	Fair	0	\$4,500	Each	\$4,500

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4929	Sam Rotolo Middle School	1462 - Interior Partitions, Fixed-CMU	North/South Classroom Extensions, SW Classrooms	Storage	2020	Sent to Maintenance	CMU in fair condition. 216A - Minor stair step cracks, cracks at corners	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair	10	\$15	Linear Foot	\$150
4931	Sam Rotolo Middle School	1498 - Interior Partitions, Fixed-GWB	North/South Classroom Extensions, SW Classrooms	Storage	2020	Sent to Maintenance	GWB in fair condition. Confirm scope. 216A	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair	0	\$15	Square Foot	\$0
4932	Sam Rotolo Middle School	1551 - Interior Wall Finishes, Wall Base	North/South Classroom Extensions, SW Classrooms	Storage	2020	Sent to Maintenance	Wall base in fair condition. 216A, 216B	Interiors	Interior Finishes	Wall Finishes		2-Should Do	Fair	100	\$6	Linear Foot	\$600
4933	Sam Rotolo Middle School	1553 - Interiors, Wall Finish - Paint	North/South Classroom Extensions, SW Classrooms	Storage	2020	Sent to Maintenance	Paint in fair condition. Quantity reflects total SF of all listed spaces. 216A, 216B	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	286	\$1	Square Foot	\$257
4943	Sam Rotolo Middle School	1454 - Electrical, Lighting Fixtures		Copier 704	2020	Sent to Maintenance	Lighting in fair condition, one fixture missing a lens. 704	Services	Electrical	Lighting	Lighting Fixtures	2-Should Do	Fair	0	\$0	Each	\$0
4949	Sam Rotolo Middle School	1432 - Flooring, VCT		Science Prep 701	2020	Sent to Maintenance	VCT in fair condition, discolored throughout. Cost to replace with rubber flooring. 701	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	440	\$12	Square Foot	\$5,280
4950	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		Science Prep 701	2020	Sent to Maintenance	CMU in fair condition. Cracks in corners, above door frame. Confirm quantity in field. 701	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair	50	\$15	Linear Foot	\$750
4962	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Science Prep 801	2020	Sent to Maintenance	Wood door in fair condition. 801	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$1,950	Each	\$1,950
4963	Sam Rotolo Middle School	1453 - Interior Doors, Swinging-Hollow Metal		Science Prep 801	2020	Sent to Maintenance	HM door in fair condition. Cost to repaint. 801	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$75	Each	\$75
4964	Sam Rotolo Middle School	1432 - Flooring, VCT		Science Prep 801	2020	Sent to Maintenance	VCT in fair condition, discolored throughout. Cost to replace with rubber flooring. 801	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	440	\$12	Square Foot	\$5,280
4965	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Science Prep 801	2020	Sent to Maintenance	Paint in fair condition. Quantity reflects total SF of all listed spaces. 801	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	440	\$1	Square Foot	\$396
4968	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		FACS/Sewing	2020	Sent to Maintenance	Wood door in fair condition - veneer scratched towards bottom. 10, 11	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	2	\$1,950	Each	\$3,900
4976	Sam Rotolo Middle School	1439 - Flooring, Carpet		FACS/Sewing	2020	Sent to Maintenance	Carpet in fair condition - worn and stained throughout. 11	Interiors	Interior Finishes	Flooring	Carpeting	2-Should Do	Fair	1105	\$7	Square Foot	\$7,183

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4981	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		FACS/Sewing	2020	Sent to Maintenance	Paint in fair condition - uneven, chipped in multiple locations. 11	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	1105	\$1	Square Foot	\$995
4995	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Music	2020	Sent to Maintenance	HM door frames in fair condition. 5. 6. 7. 16.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	4	\$60	Each	\$240
4996	Sam Rotolo Middle School	1453 - Interior Doors, Swinging-Hollow Metal		Music	2020	Sent to Maintenance	HM door frames in fair condition. 006A. 006B. 007b.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	3	\$60	Each	\$180
5014	Sam Rotolo Middle School	1453 - Interior Doors, Swinging-Hollow Metal		Music	2020	Sent to Maintenance	HM doors in fair condition. 006A. 006B.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	2	\$75	Each	\$150
5031	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems		Music	2020	Sent to Maintenance	ACT in fair condition, a mixture of old and new tiles. 7.	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	2-Should Do	Fair	2426	\$8	Square Foot	\$18,195
5035	Sam Rotolo Middle School	1439 - Flooring, Carpet		Music	2020	Sent to Maintenance	Carpet in fair condition, visible seams at patches. 005B	Interiors	Interior Finishes	Flooring	Carpeting	2-Should Do	Fair	92	\$7	Square Foot	\$598
5052	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		Music	2020	Sent to Maintenance	CMU in fair condition - multiple nail holes, sealant cracking in multiple locations. 5. 007B	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair	30	\$15	Linear Foot	\$450
5058	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Music	2020	Sent to Maintenance	Paint in fair condition - uneven, dirty throughout, unpainted patches, chipped in some places. 006. 007. 006A. 007B.	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	4045	\$1	Square Foot	\$3,641
5080	Sam Rotolo Middle School	1963 - Interiors, Wall Finish - Acoustical Panels		Music	2020	Sent to Maintenance	Acoustic wall panels in fair condition - fabric is peeling off at one panel. Confirm unit cost. 007	Interiors	Interior Finishes	Wall Finishes	Acoustical Wall Treatment	2-Should Do	Fair	40	\$18	Square Foot	\$720
5083	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Visual/Digital Arts	2020	Sent to Maintenance	Wood door in fair condition - veneer scratched. 13, 15	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	2	\$1,950	Each	\$3,900
5102	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems		Visual/Digital Arts	2020	Sent to Maintenance	ACT in fair condition - 1/3 of tiles are stained/damaged. 14, 15	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	2-Should Do	Fair	2383	\$8	Square Foot	\$17,873

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
5112	Sam Rotolo Middle School	1432 - Flooring, VCT		Visual/Digital Arts	2020	Sent to Maintenance	VCT in fair condition - scuffs throughout floor, some damaged tiles . Cost to replace with rubber flooring. 15	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	1200	\$12	Square Foot	\$14,400
5119	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Visual/Digital Arts	2020	Sent to Maintenance	Paint in fair condition - scuffs/stains throughout. 13, 14	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	2426	\$1	Square Foot	\$2,183
5127	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		Wood Shop 012	2020	Sent to Maintenance	CMU in fair condition - diagonal cracking in multiple locations. See photos. 012	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair	25	\$15	Linear Foot	\$375
5137	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Wood Shop 012	2020	Sent to Maintenance	Paint in fair condition - good for a wood shop except at utility sink. 012	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	2-Should Do	Fair	1978	\$1	Square Foot	\$1,780
5142	Sam Rotolo Middle School	1541 - HVAC, Distribution-Air		Wood Shop 012	2020	Sent to Maintenance	Exhaust fans in fair condition - need touch up paint. 012	Services	Heating, Ventilation, and Air Conditioning (HVAC)	Facility HVAC Distribution Systems	HVAC Air Distribution	2-Should Do	Fair	1	\$0	Each	\$0
5150	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Office/Pull-Out	2020	Sent to Maintenance	Wood door in fair condition (scratches in wood veneer) 123.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	2-Should Do	Fair	1	\$1,950	Each	\$1,950
5203	Sam Rotolo Middle School	1668 - Flooring, VCT		Office/Pull-Out	2020	Sent to Maintenance	Stained tile, missing tile. Cost to replace with rubber flooring. 136A	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	228	\$12	Square Foot	\$2,736
5232	Sam Rotolo Middle School	1452 - Interior Partitions, Fixed-GWB		Office/Pull-Out	2020	Sent to Maintenance	GWB in fair condition: multiple small gouges/scratches in GWB surface, damaged corner beads 136, 148B	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair	15	\$15	Square Foot	\$225
7840	Sam Rotolo Middle School	8622 - Electrical, Generator			2020	Sent to Maintenance	Per Capital Projects Plan - generator was scheduled for replacement in 2017.	Services	Electrical	Facility Power Generation	Packaged Generator Assemblies	2-Should Do	Fair	1	\$3,000	Each	\$3,000
7845	Sam Rotolo Middle School	1446 - HVAC, Distribution-Hydronic			2020	Sent to Maintenance	Per Capital Projects Plan - 11 pumps were scheduled for replacement in 2012 and are in fair condition.	Services	Heating, Ventilation, and Air Conditioning (HVAC)	Facility HVAC Distribution Systems	Facility Hydronic Distribution	2-Should Do	Fair	1	\$38,500	Lump Sum	\$38,500
7847	Sam Rotolo Middle School	1424 - Roofing, Low Slope			2020	Sent to Maintenance	Per Capital Projects Plan - roof scheduled for replacement over original building in 2026 Per 2019 roof assessment, BUR and gravel roof in fair condition.	Shell	Exterior Horizontal Enclosures	Roofing	Low-Slope Roofing	2-Should Do	Fair	123910	\$30	Square Foot	\$3,717,300
7848	Sam Rotolo Middle School	1479 - Roofing, Low Slope	North/South Classroom Extensions, SW Classrooms		2020	Sent to Maintenance	Per Capital Projects Plan - roof scheduled for replacement over original building in 2026 Per 2019 roof assessment, BUR and gravel roof in fair condition.	Shell	Exterior Horizontal Enclosures	Roofing	Low-Slope Roofing	2-Should Do	Fair	19098	\$30	Square Foot	\$572,940

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
7850	Sam Rotolo Middle School	1520 - Roofing, Low Slope	South Gym		2020	Sent to Maintenance	Per Capital Projects Plan - roof scheduled for replacement over original building in 2026 Per 2019 roof assessment, BUR and gravel roof in fair condition.	Shell	Exterior Horizontal Enclosures	Roofing	Low-Slope Roofing	2-Should Do	Fair	7674	\$30	Square Foot	\$230,220
11616	Sam Rotolo Middle School	1462 - Interior Partitions, Fixed-CMU	North/South Classroom Extensions, SW Classrooms	Stair by T-37	2020	Sent to Maintenance	Limestone wall cap in fair condition; dirty, needs to be cleaned. Cost to clean limestone (confirm). Stair by T-37	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	2-Should Do	Fair	20	\$5	Square Foot	\$100
11631	Sam Rotolo Middle School	1432 - Flooring, VCT		Classrooms	2020	Sent to Maintenance	VCT in poor condition. Significant scuffing, cracking through tiles, discoloration. Cost to replace VCT with rubber flooring. Room 030, 027, 028	Interiors	Interior Finishes	Flooring	Resilient Flooring	2-Should Do	Fair	2654	\$12	Square Foot	\$31,848
4260	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems		Classrooms	2020	Sent to Maintenance	ACT in overall good condition. Rooms: 104, 110, 111, 114, 115 (1 water damaged tile), 101/102 (1 water damaged/moldy tile), 002, 003, 027, 028, 029, 030	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	10279	\$8	Square Foot	\$77,093
4261	Sam Rotolo Middle School	1474 - Ceilings, Acoustical Suspended Systems	North/South Classroom Extensions, SW Classrooms	Classrooms	2020	Sent to Maintenance	ACT in overall good condition. Rooms: 117, 118, 119 (2 water damaged tiles)	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	2598	\$8	Square Foot	\$19,485
4264	Sam Rotolo Middle School	1432 - Flooring, VCT		Classrooms	2020	Sent to Maintenance	VCT in generally good condition. Rooms: 002, 003, 109, 110, 111, 112	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	4911	\$12	Square Foot	\$58,932
4271	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base	North/South Classroom Extensions, SW Classrooms	Classrooms	2020	Sent to Maintenance	Wall base in good condition, some minor scuffs but no damage. Rooms: 117, 118	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	240	\$6	Linear Foot	\$1,440
4275	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Classrooms	2020	Sent to Maintenance	Paint in good condition. Quantity reflects total SF of all listed spaces. Rooms 002, 003, 027, 028, 029, 030	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	3-Like To Do	Good	4900	\$2	Square Foot	\$11,025
4278	Sam Rotolo Middle School	1437 - Fixed Equipment, Casework		Classrooms	2020	Sent to Maintenance	Casework in good condition. Rooms: 002, 003, 103, 104, 107, 108, 109, 110, 111, 112, 114, 115, 101/102, 027, 028, 029, 030	Equipment and Furnishings	Furnishings	Fixed Furnishings	Casework	3-Like To Do	Good	362	\$800	Linear Foot	\$289,600
4279	Sam Rotolo Middle School	1486 - Fixed Equipment, Casework	North/South Classroom Extensions, SW Classrooms	Classrooms	2020	Sent to Maintenance	Casework in good condition. Rooms: 117, 118	Equipment and Furnishings	Furnishings	Fixed Furnishings	Casework	3-Like To Do	Good	42	\$800	Linear Foot	\$33,600
4284	Sam Rotolo Middle School	1503 - Exterior Windows, Operating	North/South Classroom Extensions, SW Classrooms	Classrooms	2020	Sent to Maintenance	Exterior windows in good condition. Rooms: 117, 118, 119	Shell	Exterior Vertical Enclosures	Exterior Windows	Exterior Operating Windows	3-Like To Do	Good	6	\$100	Square Foot	\$600
4285	Sam Rotolo Middle School	1405 - Exterior Windows, Operating		Classrooms	2020	Sent to Maintenance	Exterior windows in good condition. Rooms: 002, 003, 103, 104, 107, 108, 109, 110, 111, 114, 115, 101/102, 027, 028, 029, 030	Shell	Exterior Vertical Enclosures	Exterior Windows	Exterior Operating Windows	3-Like To Do	Good	0	\$100	Square Foot	\$0

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4298	Sam Rotolo Middle School	1474 - Ceilings, Acoustical Suspended Systems	North/South Classroom Extensions, SW Classrooms	Classrooms	2020	Sent to Maintenance	ACT in good condition. Rooms: 217, 218, 219, 236, 237, 238, 239	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	6023	\$8	Square Foot	\$45,173
4299	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems		Classrooms	2020	Sent to Maintenance	ACT in good condition. Rooms: 203, 204, 207, 208, 209 (2 cracked tiles, 1 water damaged), 210, 211, 212, 214, 215, 223, 224, 225, 226, 227, 228, 232, 233, 234, 235, 201/202, 221/222, 229, 230,	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	21944	\$8	Square Foot	\$164,580
4302	Sam Rotolo Middle School	1432 - Flooring, VCT		Classrooms	2020	Sent to Maintenance	VCT in good condition. Rooms: 203, 207, 209, 210, 211, 212, 214, 224, 226, 227, 232	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	9742	\$12	Square Foot	\$116,904
4303	Sam Rotolo Middle School	1484 - Flooring, VCT	North/South Classroom Extensions, SW Classrooms	Classrooms	2020	Sent to Maintenance	VCT in good condition. Rooms: 236, 237, 238, 239	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	3526	\$12	Square Foot	\$42,312
4309	Sam Rotolo Middle School	1551 - Interior Wall Finishes, Wall Base	North/South Classroom Extensions, SW Classrooms	Classrooms	2020	Sent to Maintenance	Wall base in good condition. Rooms: 217, 218, 219, 236, 237, 238, 239	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	626	\$6	Linear Foot	\$3,756
4310	Sam Rotolo Middle School	1551 - Interior Wall Finishes, Wall Base		Classrooms	2020	Sent to Maintenance	Wall base in good condition. Rooms: 203, 204, 207, 208, 209, 210, 211, 212, 214, 215, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 240, 201/202, 221/222	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	2352	\$6	Linear Foot	\$14,112
4313	Sam Rotolo Middle School	1486 - Fixed Equipment, Casework	North/South Classroom Extensions, SW Classrooms	Classrooms	2020	Sent to Maintenance	Casework in good condition. Rooms: 217, 218, 219, 236, 237, 238, 239	Equipment and Furnishings	Furnishings	Fixed Furnishings	Casework	3-Like To Do	Good	150	\$800	Linear Foot	\$120,000
4314	Sam Rotolo Middle School	1437 - Fixed Equipment, Casework		Classrooms	2020	Sent to Maintenance	Casework in overall good condition. Rooms: 203 (1 crooked door), 204, 207, 208, 209, 210, 211, 212, 214, 215, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 201/202, 221/222	Equipment and Furnishings	Furnishings	Fixed Furnishings	Casework	3-Like To Do	Good	475	\$800	Linear Foot	\$380,000
4319	Sam Rotolo Middle School	1503 - Exterior Windows, Operating	North/South Classroom Extensions, SW Classrooms	Classrooms	2020	Sent to Maintenance	Exterior windows in good condition. Rooms: 217, 218, 219	Shell	Exterior Vertical Enclosures	Exterior Windows	Exterior Operating Windows	3-Like To Do	Good	6	\$100	Square Foot	\$600
4320	Sam Rotolo Middle School	1405 - Exterior Windows, Operating		Classrooms	2020	Sent to Maintenance	Exterior windows in good condition. Rooms: 203, 204, 207, 208, 209, 210, 211, 212, 214, 215, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 201/202, 221/222	Shell	Exterior Vertical Enclosures	Exterior Windows	Exterior Operating Windows	3-Like To Do	Good	0	\$100	Square Foot	\$0
4332	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems		Individual Toilets	2020	Sent to Maintenance	ACT in good condition. Rooms: T-3, T-4, T-5, T-6, T-11, T-14, T-16, T-20	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	353	\$8	Square Foot	\$2,648

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4335	Sam Rotolo Middle School	1432 - Flooring, VCT		Individual Toilets	2020	Sent to Maintenance	VCT in good condition. Rooms: T-3, T-4, T-5, T-6, T-11, T-16	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	256	\$12	Square Foot	\$3,072
4339	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base		Individual Toilets	2020	Sent to Maintenance	Wall base is in good condition. T-3. T-4. T-5. T-6. T-7. T-8. T-11. T-14. T-15. T-16. T-17. T-20.	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	407	\$6	Linear Foot	\$2,442
4341	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Individual Toilets	2020	Sent to Maintenance	Paint is in good condition. T-3. T-4. T-6. T-7. T-8. T-11. T-14. T-20.	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	3-Like To Do	Good	341	\$2	Square Foot	\$767
4348	Sam Rotolo Middle School	1437 - Fixed Equipment, Casework		Individual Toilets	2020	Sent to Maintenance	Tall cabinets in good condition. T-20	Equipment and Furnishings	Furnishings	Fixed Furnishings	Casework	3-Like To Do	Good	8	\$800	Linear Foot	\$6,400
4352	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems		Individual Toilets	2020	Sent to Maintenance	ACT in good condition. T-25. T-31. T-30.	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	800	\$8	Square Foot	\$6,000
4356	Sam Rotolo Middle School	1432 - Flooring, VCT		Individual Toilets	2020	Sent to Maintenance	VCT in good condition. Rooms: T-24	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	35	\$12	Square Foot	\$420
4358	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base		Individual Toilets	2020	Sent to Maintenance	Wall base is in good condition. T-24, T-25, T-30	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	220	\$6	Linear Foot	\$1,320
4366	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems		Grouped Toilets	2020	Sent to Maintenance	ACT older but in good condition. T-1. T-2. T-9. T-10. T-12. T-13. T-17.	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	1650	\$8	Square Foot	\$12,375
4370	Sam Rotolo Middle School	1432 - Flooring, VCT		Grouped Toilets	2020	Sent to Maintenance	VCT is in good condition. T-17	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	109	\$12	Square Foot	\$1,308
4378	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base		Grouped Toilets	2020	Sent to Maintenance	Tile wall base in good condition. T-17	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	44	\$6	Linear Foot	\$264

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4380	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Grouped Toilets	2020	Sent to Maintenance	Paint is in good condition. T-9. T-10. T-12. T-13.	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	3-Like To Do	Good	1042	\$2	Square Foot	\$2,345
4384	Sam Rotolo Middle School	1445 - Interior Specialties, Toilet Compartments		Grouped Toilets	2020	Sent to Maintenance	Toilet partitions in good condition. T-1, T-2, T-9, T-10, T-12, T-13, T-17, T-32, T-33	Interiors	Interior Construction	Interior Specialties	Toilet, Bath, and Laundry Accessories	3-Like To Do	Good	26	\$1,800	Each	\$46,800
4389	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems		Grouped Toilets	2020	Sent to Maintenance	ACT in good condition. T-22. T-23. T-26. T-27. T-28. T-29.	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	1650	\$8	Square Foot	\$12,375
4396	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base		Grouped Toilets	2020	Sent to Maintenance	Wall base in good condition - clean grout. T-22. T-23. T-26. T-27. T-28. T-29.	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	288	\$6	Linear Foot	\$1,728
4399	Sam Rotolo Middle School	1445 - Interior Specialties, Toilet Compartments		Grouped Toilets	2020	Sent to Maintenance	Toilet partitions in good condition. T-22, T-23, T-26, T-27, T-28, T-29	Interiors	Interior Construction	Interior Specialties	Toilet, Bath, and Laundry Accessories	3-Like To Do	Good	18	\$1,800	Each	\$32,400
4401	Sam Rotolo Middle School	1474 - Ceilings, Acoustical Suspended Systems	North/South Classroom Extensions, SW Classrooms	Grouped Toilets	2020	Sent to Maintenance	ACT in good condition. T-36	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	249	\$8	Square Foot	\$1,868
4403	Sam Rotolo Middle School	1474 - Ceilings, Acoustical Suspended Systems	North/South Classroom Extensions, SW Classrooms	Grouped Toilets	2020	Sent to Maintenance	ACT in good condition. T-34, T-35	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	550	\$8	Square Foot	\$4,125
4407	Sam Rotolo Middle School	1551 - Interior Wall Finishes, Wall Base	North/South Classroom Extensions, SW Classrooms	Grouped Toilets	2020	Sent to Maintenance	Tile wall base in good condition. T-34	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	72	\$6	Linear Foot	\$432
4409	Sam Rotolo Middle School	1553 - Interiors, Wall Finish - Paint	North/South Classroom Extensions, SW Classrooms	Grouped Toilets	2020	Sent to Maintenance	Paint in good condition. Quantity reflects total SF of all listed spaces. T-34	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	3-Like To Do	Good	275	\$2	Square Foot	\$619
4416	Sam Rotolo Middle School	1539 - Interior Specialties, Toilet Compartments	North/South Classroom Extensions, SW Classrooms	Grouped Toilets	2020	Sent to Maintenance	Toilet stall partitions in good condition. T-34 T-35	Interiors	Interior Construction	Interior Specialties	Toilet, Bath, and Laundry Accessories	3-Like To Do	Good	9	\$1,800	Each	\$16,200
4422	Sam Rotolo Middle School	1420 - Ceilings, Gypsum		LMC	2020	Sent to Maintenance	GWB ceiling is in good condition (5498 SF)	Interiors	Interior Construction	Suspended Ceiling Construction	Suspended Plaster and Gypsum Board	3-Like To Do	Good	5498	\$1	Square Foot	\$5,498

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4423	Sam Rotolo Middle School	1551 - Interior Wall Finishes, Wall Base	North/South Classroom Extensions, SW Classrooms	Grouped Toilets	2020	Sent to Maintenance	Tile wall base in good condition. T-36, T-37	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	144	\$6	Linear Foot	\$864
4424	Sam Rotolo Middle School	1553 - Interiors, Wall Finish - Paint	North/South Classroom Extensions, SW Classrooms	Grouped Toilets	2020	Sent to Maintenance	Paint in good condition. Quantity reflects total SF of all listed spaces. T-36	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	3-Like To Do	Good	275	\$2	Square Foot	\$619
4428	Sam Rotolo Middle School	1539 - Interior Specialties, Toilet Compartments	North/South Classroom Extensions, SW Classrooms	Grouped Toilets	2020	Sent to Maintenance	Toilet stall partitions in good condition. T-36, T-37	Interiors	Interior Construction	Interior Specialties	Toilet, Bath, and Laundry Accessories	3-Like To Do	Good	9	\$1,800	Each	\$16,200
4435	Sam Rotolo Middle School	1504 - Exterior Windows, Fixed		LMC	2020	Sent to Maintenance	Exterior Window in a good condition LMC 220	Shell	Exterior Vertical Enclosures	Exterior Windows	Exterior Fixed Windows	3-Like To Do	Good	1	\$90	Square Foot	\$90
4460	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base		Dish Washing	2020	Sent to Maintenance	Wall base is in a good condition -Room 145B	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	76	\$6	Linear Foot	\$456
4469	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems		Offices/Pull-Out Spaces	2020	Sent to Maintenance	ACT in overall good condition. 006C. 008. 009. 010A. 012A. 121. 121A. 121B. 122. 123. 124. 125. 126. 127. 128. 129. 133. 134. 135A. 135C. 136A. 138. 147. 148. 148B.	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	7602	\$8	Square Foot	\$57,015

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4475	Sam Rotolo Middle School	1432 - Flooring, VCT		Offices/Pull-Out Spaces	2020	Sent to Maintenance	VCT in good condition. 008. 009. 014A. 134. 135. 135A. 135B. 135C. 144. 702. 703.	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	2980	\$12	Square Foot	\$35,760
4476	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Serving	2020	Sent to Maintenance	Wall paint is in a good condition. Quantity reflects total SF of all listed spaces. -Room 146	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	3-Like To Do	Good	775	\$2	Square Foot	\$1,744
4477	Sam Rotolo Middle School	1439 - Flooring, Carpet		Offices/Pull-Out Spaces	2020	Sent to Maintenance	Carpet in good condition. 005A. 006C. 010A. 121. 121A. 121B. 122. 123. 124. 125. 126. 127. 128. 129. 130. 131. 132. 133. 134. 136. 137. 138. 148. 148B.	Interiors	Interior Finishes	Flooring	Carpeting	3-Like To Do	Good	6131	\$7	Square Foot	\$39,852

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4484	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base		Offices/Pull-Out Spaces	2020	Sent to Maintenance	Wall base in good condition. 005A. 006C. 008. 009. 010A. 014A. 018A. 019A. 033. 012A. 121. 121A. 121B. 122. 123. 124. 125. 126. 127. 128. 129. 130. 131. 132. 134. 135. 135A	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	3494	\$6	Linear Foot	\$20,964

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4486	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Offices/Pull-Out Spaces	2020	Sent to Maintenance	Paint in good condition with minimal marks (one or two scuffs/stains). Quantity reflects total SF of all listed spaces. 006C. 008. 009. 010A. 014A. 033. 012A. 121. 121A. 121B. 122. 123. 124. 125. 126. 127. 128. 129. 130. 131. 132. 133. 134. 135.	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	3-Like To Do	Good	11000	\$2	Square Foot	\$24,750
4493	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems	North/South Classroom Extensions, SW Classrooms	Science	2020	Sent to Maintenance	2 water damaged ceiling tile -Classroom 116	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	1209	\$8	Square Foot	\$9,068
4499	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base	North/South Classroom Extensions, SW Classrooms	Science	2020	Sent to Maintenance	Wall base is in a good condition -Classroom 116	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	140	\$6	Linear Foot	\$840
4505	Sam Rotolo Middle School	1437 - Fixed Equipment, Casework		Offices/Pull-Out Spaces	2020	Sent to Maintenance	Casework in good condition. 008. 010A. 014A. 122. 135. 148B.	Equipment and Furnishings	Furnishings	Fixed Furnishings	Casework	3-Like To Do	Good	80	\$800	Linear Foot	\$64,000
4510	Sam Rotolo Middle School	1486 - Fixed Equipment, Casework	North/South Classroom Extensions, SW Classrooms	Science	2020	Sent to Maintenance	Casework is in a good condition -Classroom 116	Equipment and Furnishings	Furnishings	Fixed Furnishings	Casework	3-Like To Do	Good	70	\$800	Linear Foot	\$56,000
4513	Sam Rotolo Middle School	1504 - Exterior Windows, Fixed	North/South Classroom Extensions, SW Classrooms	Science	2020	Sent to Maintenance	Exterior window is in a good condition -Classroom 116	Shell	Exterior Vertical Enclosures	Exterior Windows	Exterior Fixed Windows	3-Like To Do	Good	2	\$90	Square Foot	\$180
4519	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems	North/South Classroom Extensions, SW Classrooms	Science	2020	Sent to Maintenance	-Classroom 216 (1192 SF)	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	1192	\$8	Square Foot	\$8,940

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4531	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems		Offices/Pull-Out Spaces	2020	Sent to Maintenance	ACT in good condition, only minor damage from tape. 601. 604. 802. 803. 804. 220A.	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	1955	\$8	Square Foot	\$14,663
4542	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base		Science	2020	Sent to Maintenance	Wall base in a good condition - Classrooms 105 &106	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	280	\$6	Linear Foot	\$1,680
4545	Sam Rotolo Middle School	1432 - Flooring, VCT		Offices/Pull-Out Spaces	2020	Sent to Maintenance	VCT in good condition. 602. 604. 802. 803. 804.	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	1760	\$12	Square Foot	\$21,120
4548	Sam Rotolo Middle School	1504 - Exterior Windows, Fixed		Science	2020	Sent to Maintenance	Exterior windows are in good condition - Classrooms 105, 106 & 113	Shell	Exterior Vertical Enclosures	Exterior Windows	Exterior Fixed Windows	3-Like To Do	Good	6	\$90	Square Foot	\$540
4557	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base		Offices/Pull-Out Spaces	2020	Sent to Maintenance	Wall base in good condition. 601. 602. 604. 802. 803. 804. 220A.	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	500	\$6	Linear Foot	\$3,000
4559	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Offices/Pull-Out Spaces	2020	Sent to Maintenance	Paint in good condition. Quantity reflects total SF of all listed spaces. 602. 802. 803. 220A.	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	3-Like To Do	Good	1916	\$2	Square Foot	\$4,311
4566	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems		Science	2020	Sent to Maintenance	Missing edge seal piece (206) Classrooms: 205, 206, and 213	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	3633	\$8	Square Foot	\$27,248
4574	Sam Rotolo Middle School	1437 - Fixed Equipment, Casework		Offices/Pull-Out Spaces	2020	Sent to Maintenance	Casework in good condition. Verify quantity in field. 803, 220A	Equipment and Furnishings	Furnishings	Fixed Furnishings	Casework	3-Like To Do	Good	30	\$800	Linear Foot	\$24,000
4576	Sam Rotolo Middle School	1406 - Exterior Windows, Fixed		Science	2020	Sent to Maintenance	Exterior windows in a good condition Classrooms:	Shell	Exterior Vertical Enclosures	Exterior Windows	Exterior Fixed Windows	3-Like To Do	Good	6	\$90	Square Foot	\$540
4603	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base		Mechanical/Electrical Rooms	2020	Sent to Maintenance	Wall base in good condition. Mechanical 147A	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	142	\$6	Linear Foot	\$852
4609	Sam Rotolo Middle School	1414 - Interior Partitions, Operable		GYM	2020	Sent to Maintenance	Operable wall is in a good condition East GYM	Interiors	Interior Construction	Interior Partitions	Interior Operable Partitions	3-Like To Do	Good	65	\$600	Linear Foot	\$39,000

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4612	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base		GYM	2020	Sent to Maintenance	Wall Base is in a good condition West GYM Upper GYM	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	578	\$6	Linear Foot	\$3,468
4620	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base		Mechanical/Electrical Rooms	2020	Sent to Maintenance	Wall base in good condition. Mechanical 020A	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	98	\$6	Linear Foot	\$588
4631	Sam Rotolo Middle School	1403 - Slab on Grade		Janitor	2020	Sent to Maintenance	Concrete flooring is in good condition - Slab is good compared to other elevated slabs, but finish could be improved. J-3	Substructure	Slabs-On-Grade	Standard Slabs-on-Grade		3-Like To Do	Good	50	\$20	Square Foot	\$1,000
4632	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint	South Gym	GYM	2020	Sent to Maintenance	Wall Paint is in a good condition. Quantity reflects total SF of all listed spaces. - South GYM	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	3-Like To Do	Good	6000	\$2	Square Foot	\$13,500
4636	Sam Rotolo Middle School	1461 - Exterior Windows, Fixed	South Gym	GYM	2020	Sent to Maintenance	Kalwall system appears in good shape - South GYM	Shell	Exterior Vertical Enclosures	Exterior Windows	Exterior Fixed Windows	3-Like To Do	Good	1	\$90	Square Foot	\$90
4656	Sam Rotolo Middle School	1420 - Ceilings, Gypsum		Locker Room	2020	Sent to Maintenance	- GWB ceilings are in a good condition -18 & 19B - Ceiling could be resealed at the edges - 18C	Interiors	Interior Construction	Suspended Ceiling Construction	Suspended Plaster and Gypsum Board Ceilings	3-Like To Do	Good	1611	\$1	Square Foot	\$1,611
4667	Sam Rotolo Middle School	1668 - Flooring, VCT		Locker Room	2020	Sent to Maintenance	VCT flooring is in a good condition - 18C	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	169	\$12	Square Foot	\$2,028
4681	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Locker Room	2020	Sent to Maintenance	Walls paints are in a good condition. Quantity reflects total SF of all listed spaces. - 18C & 19B	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	3-Like To Do	Good	327	\$2	Square Foot	\$736
4691	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems		Stage/Cafeteria/ Multipurpose	2020	Sent to Maintenance	- Ceilings are older but in good condition- 24 - Older looking ceiling tiles and grid but in good condition - 31	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	12147	\$8	Square Foot	\$91,103
4697	Sam Rotolo Middle School	1414 - Interior Partitions, Operable		Stage/Cafeteria/ Multipurpose	2020	Sent to Maintenance	- Operable partition is in a good condition - 23 - Panels are in good shape, track is slightly damaged - 24	Interiors	Interior Construction	Interior Partitions	Interior Operable Partitions	3-Like To Do	Good	67	\$450	Linear Foot	\$30,150
4700	Sam Rotolo Middle School	1551 - Interior Wall Finishes, Wall Base		Stage/Cafeteria/ Multipurpose	2020	Sent to Maintenance	- Wall base is in a good condition - 31	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	232	\$6	Linear Foot	\$1,392
4702	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Stage/Cafeteria/ Multipurpose	2020	Sent to Maintenance	Quantity reflects total SF of all listed spaces. Could use a refresh coat due to wall smudges - 31	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	3-Like To Do	Good	3375	\$2	Square Foot	\$7,594
4705	Sam Rotolo Middle School	1406 - Exterior Windows, Fixed		Stage/Cafeteria/ Multipurpose	2020	Sent to Maintenance	- exterior window in a good condition - MP 31	Shell	Exterior Vertical Enclosures	Exterior Windows	Exterior Fixed Windows	3-Like To Do	Good	3	\$90	Square Foot	\$270
4714	Sam Rotolo Middle School	8675 - Equipment, Wall Pads		Gym	2020	Sent to Maintenance	Pads have scuff marks but are in overall good condition - East GYM	Equipment and Furnishings	Equipment	Entertainment and Recreational Equipment	Athletic Equipment	3-Like To Do	Good	160	\$50	Linear Foot	\$8,000
4720	Sam Rotolo Middle School	1420 - Ceilings, Gypsum		commons	2020	Sent to Maintenance	Popcorn ceiling is in good condition	Interiors	Interior Construction	Suspended Ceiling Construction	Suspended Plaster and Gypsum Board	3-Like To Do	Good	5338	\$1	Square Foot	\$5,338
4722	Sam Rotolo Middle School	1439 - Flooring, Carpet		commons	2020	Sent to Maintenance	Carpet flooring is in good condition	Interiors	Interior Finishes	Flooring	Carpeting	3-Like To Do	Good	5321	\$7	Square Foot	\$34,587

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4734	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems		Corridor	2020	Sent to Maintenance	- ACT's are in good condition - Corridor near Art/Drafting, 7th East and West. - ACT's are in good condition - 7th Central. - ACT's are in good condition - 8th East, West, North, central. - ACT's are in good condition - 6th East, West, North, central. ACT in good condition - Admin north corridor, Admin east corridor, Admin corridor between staff toilets, Admin south corridor, Admin corridor to staff lounge	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	13461	\$8	Square Foot	\$100,958
4735	Sam Rotolo Middle School	1420 - Ceilings, Gypsum		Corridor	2020	Sent to Maintenance	- GWB ceiling is in good condition - 7th central. - GWB ceiling is in good condition - 6th central. GWB soffits in good condition - Admin north corridor, Admin corridor between staff toilets	Interiors	Interior Construction	Suspended Ceiling Construction	Suspended Plaster and Gypsum Board Ceilings	3-Like To Do	Good	2915	\$1	Square Foot	\$2,915
4738	Sam Rotolo Middle School	1526 - Flooring, VCT		Corridor	2020	Sent to Maintenance	-some scuff marks - Corridor btwn Stu. Services and Café. - some visible patching and scuffing, but good throughout - Corridor near Art/Drafting.	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	1980	\$12	Square Foot	\$23,760
4743	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base		Corridor	2020	Sent to Maintenance	- Wall base is in good condition - Corridor btwn Stu. Services and Café. - Wall base is in good condition - Corridor near Art/Drafting. - Wall base in good condition: Admin Corridors: north corridor, corridor to staff lounge, corridor	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	790	\$6	Linear Foot	\$4,740
4744	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Corridor	2020	Sent to Maintenance	- scuffs/staines near entry doors - Corridor btwn Stu. Services and Café	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	3-Like To Do	Good	1000	\$2	Square Foot	\$2,250
4759	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems		Stair	2020	Sent to Maintenance	-ACT ceiling are in good condition - Stair - 7th gr. North Corr. & Stair - 8th gr. North Corr.	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	2975	\$8	Square Foot	\$22,313
4761	Sam Rotolo Middle School	1420 - Ceilings, Gypsum		Stair	2020	Sent to Maintenance	-Popcorn ceilings are in good condition - Stair - Near Main Entrance & Commons stair by 6th grade	Interiors	Interior Construction	Suspended Ceiling Construction	Suspended Plaster and Gypsum Board Ceilings	3-Like To Do	Good	225	\$1	Square Foot	\$225
4769	Sam Rotolo Middle School	1551 - Interior Wall Finishes, Wall Base		Stair	2020	Sent to Maintenance	wall base is in good condition - Stair - 8th gr. North Corr., -Stair - Above Mech 020B, Stair - Above Mech 017C, -Stair - West Gymnasium NE.	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	120	\$6	Linear Foot	\$720
4775	Sam Rotolo Middle School	1528 - Interior Stair Finishes, Resilient		Stair	2020	Sent to Maintenance	Stair- treads and risers are in good condition - Stair - 7th gr. North Corr.	Interiors	Interior Finishes	Stair Finishes	Resilient Stair Finish	3-Like To Do	Good	18	\$90	Each	\$1,620
4785	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems	North/South Classroom Extensions, SW Classrooms	Stair by door N-2	2020	Sent to Maintenance	-ACT ceiling is in a good condition.	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	340	\$8	Square Foot	\$2,550

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4786	Sam Rotolo Middle School	1668 - Flooring, VCT	North/South Classroom Extensions, SW Classrooms	Stair by door N-2	2020	Sent to Maintenance	-VCT flooring is in a good condition.	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	340	\$12	Square Foot	\$4,080
4788	Sam Rotolo Middle School	1551 - Interior Wall Finishes, Wall Base	North/South Classroom Extensions, SW Classrooms	Stair by door N-2	2020	Sent to Maintenance	- Wall base is in a good condition	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	102	\$6	Linear Foot	\$612
4791	Sam Rotolo Middle School	1406 - Exterior Windows, Fixed	North/South Classroom Extensions, SW Classrooms	Stair by door N-2	2020	Sent to Maintenance	-Exterior window is in a good condition	Shell	Exterior Vertical Enclosures	Exterior Windows	Exterior Fixed Windows	3-Like To Do	Good	1	\$90	Square Foot	\$90
4792	Sam Rotolo Middle School	1434 - Interior Stair Finishes, Resilient	North/South Classroom Extensions, SW Classrooms	Stair by door N-2	2020	Sent to Maintenance	-Stairs, treads and risers are in good condition	Interiors	Interior Finishes	Stair Finishes	Resilient Stair Finish	3-Like To Do	Good	20	\$90	Each	\$1,800
4797	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems	North/South Classroom Extensions, SW Classrooms	Corridor	2020	Sent to Maintenance	ACT ceilings are in good condition - 7th, 8th and 6th New Central.	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	2600	\$8	Square Foot	\$19,500
4798	Sam Rotolo Middle School	1420 - Ceilings, Gypsum	North/South Classroom Extensions, SW Classrooms	Corridor	2020	Sent to Maintenance	GWB ceilings are in good condition - 8th and 6th New Central.	Interiors	Interior Construction	Suspended Ceiling Construction	Suspended Plaster and Gypsum Board Ceilings	3-Like To Do	Good	1701	\$1	Square Foot	\$1,701
4799	Sam Rotolo Middle School	1668 - Flooring, VCT	North/South Classroom Extensions, SW Classrooms	Corridor	2020	Sent to Maintenance	VCT- 6 lf crack at door btwn central and new central corridors - 7th New Central.	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	888	\$12	Square Foot	\$10,656
4806	Sam Rotolo Middle School	8624 - Equipment, Lockers	North/South Classroom Extensions, SW Classrooms	Corridor	2020	Sent to Maintenance	Lockers are in good condition; 12'w, full-height metal lockers. 6th, 7th, and 8th grade additions Locker count provided by BPS101: 273 (1999 Classroom Add) Cost provided is to go to stacked half-height lockers.	Equipment and Furnishings	Equipment	Institutional Equipment	Educational and Scientific Equipment	3-Like To Do	Good	273	\$200	Each	\$54,600
4877	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems		Storage	2020	Sent to Maintenance	ACT in good condition. 26, 007C, 013B	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	376	\$8	Square Foot	\$2,820
4879	Sam Rotolo Middle School	1420 - Ceilings, Gypsum		Storage	2020	Sent to Maintenance	GWB ceiling in good condition. 019C	Interiors	Interior Construction	Suspended Ceiling Construction	Suspended Plaster and Gypsum Board	3-Like To Do	Good	136	\$1	Square Foot	\$136
4881	Sam Rotolo Middle School	1432 - Flooring, VCT		Storage	2020	Sent to Maintenance	VCT in good condition. 26. 007A. 007C. 014B. 014C.	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	947	\$12	Square Foot	\$11,364
4885	Sam Rotolo Middle School	1439 - Flooring, Carpet		Storage	2020	Sent to Maintenance	Carpet in good condition. 129A	Interiors	Interior Finishes	Flooring	Carpeting	3-Like To Do	Good	10	\$7	Square Foot	\$65

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4891	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base		Storage	2020	Sent to Maintenance	Wall base in good condition. 26. 141. 147. 706. 007A. 007C. 012B. 012C. 014B. 014C. 017A. 019C. 031A. 031B. 129A.	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	880	\$6	Linear Foot	\$5,280
4893	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Storage	2020	Sent to Maintenance	Paint in good condition. Quantity reflects total SF of all listed spaces. 26. 141. 148C. 147 - Wall painted to about 8'-0" - minor imperfections. 007C. 012B. 012C. 014B. 014C. 019C. 031A. 031B. 129A.	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	3-Like To Do	Good	3800	\$2	Square Foot	\$8,550
4901	Sam Rotolo Middle School	1554 - Interiors, Wall Finish - Paint	South Gym	Storage	2020	Sent to Maintenance	Paint in good condition. Quantity reflects total SF of all listed spaces. 034A	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	3-Like To Do	Good	87	\$2	Square Foot	\$196
4909	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems		Storage	2020	Sent to Maintenance	ACT in good condition. 805. 212A - one damaged tile. 220B.	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	132	\$8	Square Foot	\$990
4919	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base		Storage	2020	Sent to Maintenance	Wall base in good condition. 805. 020B. 020C. 220B	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	248	\$6	Linear Foot	\$1,488
4921	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Storage	2020	Sent to Maintenance	Paint in good condition. Quantity reflects total SF of all listed spaces. 805, 220B	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	3-Like To Do	Good	462	\$2	Square Foot	\$1,040
4927	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems	North/South Classroom Extensions, SW Classrooms	Storage	2020	Sent to Maintenance	ACT in good condition. 216A	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	204	\$8	Square Foot	\$1,530

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4938	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems		Copier 704	2020	Sent to Maintenance	ACT in good condition. 704	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	126	\$8	Square Foot	\$945
4939	Sam Rotolo Middle School	1432 - Flooring, VCT		Copier 704	2020	Sent to Maintenance	VCT in good condition. 704	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	126	\$12	Square Foot	\$1,512
4941	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base		Copier 704	2020	Sent to Maintenance	Wall base in good condition, scuffed but not damaged. 704	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	24	\$6	Linear Foot	\$144
4942	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Copier 704	2020	Sent to Maintenance	Paint in good condition. Quantity reflects total SF of all listed spaces. 704	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	3-Like To Do	Good	126	\$2	Square Foot	\$284
4948	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems		Science Prep 701	2020	Sent to Maintenance	ACT in good condition. 701	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	440	\$8	Square Foot	\$3,300
4951	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base		Science Prep 701	2020	Sent to Maintenance	Wall base in good condition. 701	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	777	\$6	Linear Foot	\$4,662
4952	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Science Prep 701	2020	Sent to Maintenance	paint in good condition. Quantity reflects total SF of all listed spaces. 701	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	3-Like To Do	Good	440	\$2	Square Foot	\$990
4954	Sam Rotolo Middle School	1437 - Fixed Equipment, Casework		Science Prep 701	2020	Sent to Maintenance	casework in good condition. 701	Equipment and Furnishings	Furnishings	Fixed Furnishings	Casework	3-Like To Do	Good	75	\$800	Linear Foot	\$60,000
4955	Sam Rotolo Middle School	1437 - Fixed Equipment, Casework		Science Prep 801	2020	Sent to Maintenance	casework in good condition. 801	Equipment and Furnishings	Furnishings	Fixed Furnishings	Casework	3-Like To Do	Good	75	\$800	Linear Foot	\$60,000
4957	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base		Science Prep 801	2020	Sent to Maintenance	Wall base in good condition. 801	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	84	\$6	Linear Foot	\$504
4959	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems		Science Prep 801	2020	Sent to Maintenance	ACT in good condition. 801	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	440	\$8	Square Foot	\$3,300
4974	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems		FACS/Sewing	2020	Sent to Maintenance	ACT in good condition. 10, 11	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	2586	\$8	Square Foot	\$19,395
4975	Sam Rotolo Middle School	1432 - Flooring, VCT		FACS/Sewing	2020	Sent to Maintenance	VCT in mostly good condition, some minor cracking throughout. 10	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	1481	\$12	Square Foot	\$17,772
4978	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base		FACS/Sewing	2020	Sent to Maintenance	Wall base in good condition. 10, 11	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	300	\$6	Linear Foot	\$1,800
4979	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		FACS/Sewing	2020	Sent to Maintenance	Paint in good condition. 10	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	3-Like To Do	Good	1481	\$2	Square Foot	\$3,332

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
5030	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems		Music	2020	Sent to Maintenance	ACT in good condition. 5. 6. 16. 005B. 006A - a couple damaged/bowed. 006B. 007B - old but good condition.	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	4280	\$8	Square Foot	\$32,100
5033	Sam Rotolo Middle School	1432 - Flooring, VCT		Music	2020	Sent to Maintenance	VCT in good condition. 6, 006A	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	1521	\$12	Square Foot	\$18,252
5040	Sam Rotolo Middle School	1439 - Flooring, Carpet		Music	2020	Sent to Maintenance	Carpet in good condition. 5. 16. 006B. 007b.	Interiors	Interior Finishes	Flooring	Carpeting	3-Like To Do	Good	2667	\$7	Square Foot	\$17,336
5044	Sam Rotolo Middle School	1956 - Flooring, Interior - Rubber		Music	2020	Sent to Maintenance	Rubber flooring at ramp in good condition. Band 7	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	356	\$12	Square Foot	\$4,272
5057	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base		Music	2020	Sent to Maintenance	Wall base in good condition. 5. 6. 7. 16. 005B. 006A. 006B. 007b.	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	693	\$6	Linear Foot	\$4,158
5062	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Music	2020	Sent to Maintenance	Paint in good condition. 16. 005B. 006B.	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	3-Like To Do	Good	1251	\$2	Square Foot	\$2,815
5065	Sam Rotolo Middle School	1437 - Fixed Equipment, Casework		Music	2020	Sent to Maintenance	Casework in overall good condition - some doors need adjusting. 005, 016	Equipment and Furnishings	Furnishings	Fixed Furnishings	Casework	3-Like To Do	Good	46	\$800	Linear Foot	\$36,800
5077	Sam Rotolo Middle School	1405 - Exterior Windows, Operating		Music	2020	Sent to Maintenance	Windows and window sills in good condition. 5. 6. 7. 16.	Shell	Exterior Vertical Enclosures	Exterior Windows	Exterior Operating Windows	3-Like To Do	Good	4	\$100	Square Foot	\$400
5106	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems		Visual/Digital Arts	2020	Sent to Maintenance	ACT in good condition. 4, 13	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	3-Like To Do	Good	2200	\$8	Square Foot	\$16,500

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
5109	Sam Rotolo Middle School	1432 - Flooring, VCT		Visual/Digital Arts	2020	Sent to Maintenance	VCT in good condition. 1. 4. 13. 14.	Interiors	Interior Finishes	Flooring	Resilient Flooring	3-Like To Do	Good	4350	\$12	Square Foot	\$52,200
5115	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base		Visual/Digital Arts	2020	Sent to Maintenance	Wall base in good condition. 1. 4. 13. 14. 15.	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	676	\$6	Linear Foot	\$4,056
5117	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Visual/Digital Arts	2020	Sent to Maintenance	Paint in good condition. 1, 4, 15	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	3-Like To Do	Good	3122	\$2	Square Foot	\$7,025
5120	Sam Rotolo Middle School	1437 - Fixed Equipment, Casework		Visual/Digital Arts	2020	Sent to Maintenance	Casework in good condition. 4. 13. 14. 15.	Equipment and Furnishings	Furnishings	Fixed Furnishings	Casework	3-Like To Do	Good	143	\$800	Linear Foot	\$114,400
5133	Sam Rotolo Middle School	1457 - Interior Wall Finishes, Wall Base		Wood Shop 012	2020	Sent to Maintenance	Wall base in good condition. 012	Interiors	Interior Finishes	Wall Finishes		3-Like To Do	Good	186	\$6	Linear Foot	\$1,116
5200	Sam Rotolo Middle School	1420 - Ceilings, Gypsum		Office/Pull-Out	2020	Sent to Maintenance	GWB soffit in overall good condition 121	Interiors	Interior Construction	Suspended Ceiling Construction	Suspended Plaster and Gypsum Board	3-Like To Do	Good	604	\$1	Square Foot	\$604
5380	Sam Rotolo Middle School	1439 - Flooring, Carpet		Corridor	2020	Sent to Maintenance	Carpet tile in good condition Admin north corridor, Admin corridor to staff lounge, Admin corridor between staff toilets, Admin east corridor, Admin south	Interiors	Interior Finishes	Flooring	Carpeting	3-Like To Do	Good	738	\$7	Square Foot	\$4,797
5589	Sam Rotolo Middle School	1552 - Interiors, Wall Finish - Paint		Corridor	2020	Sent to Maintenance	Paint finish in good condition (some minor scuffs) Admin north corridor, Admin corridor to staff lounge, Admin corridor between staff toilets, Admin south corridor, Admin east	Interiors	Interior Finishes	Wall Finishes	Wall Painting and Coating	3-Like To Do	Good	800	\$2	Square Foot	\$1,800
8083	Sam Rotolo Middle School	1531 - Fixed Equipment, Casework		Individual Toilets	2020	Sent to Maintenance	Casework in good condition T-11	Equipment and Furnishings	Furnishings	Fixed Furnishings	Casework	3-Like To Do	Good	8	\$800	Linear Foot	\$6,400
4252	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Classrooms	2020	Sent to Maintenance	Doors in good condition. Rooms: 111, 112, 002, 003, 027, 029, 030	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	7	\$2,400	Each	\$16,800
4254	Sam Rotolo Middle School	1467 - Interior Doors, Swinging-Wood	North/South Classroom Extensions, SW Classrooms	Classrooms	2020	Sent to Maintenance	Wood doors in good condition. Rooms: 118, 119	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	2	\$2,400	Each	\$4,800
4256	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Classrooms	2020	Sent to Maintenance	HM door frames in good condition. Rooms: 103, 104, 107, 109, 110, 111, 112, 114, 101/102, 002, 003	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	12	\$2,400	Each	\$28,800

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4258	Sam Rotolo Middle School	1467 - Interior Doors, Swinging-Wood	North/South Classroom Extensions, SW Classrooms	Classrooms	2020	Sent to Maintenance	HM door frames in good condition. Rooms: 118, 119	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	2	\$2,400	Each	\$4,800
4262	Sam Rotolo Middle School	1409 - Exterior Entrance Doors, Hollow Metal		Classrooms	2020	Sent to Maintenance	Exterior HM door frame in good condition. Room 002	Shell	Exterior Vertical Enclosures	Exterior Doors and Grilles	Exterior Entrance Doors	4-Future	Good	1	\$1,950	Each	\$1,950
4266	Sam Rotolo Middle School	1669 - Flooring, LVT		Classrooms	2020	Sent to Maintenance	LVT in good condition. Rooms: 107, 108	Interiors	Interior Finishes	Flooring	Resilient Flooring	4-Future	Good	1740	\$10	Square Foot	\$17,400
4267	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		Classrooms	2020	Sent to Maintenance	CMU in good condition, no stair step cracking or cracking through blocks. Rooms: 002, 003, 107, 109, 112, 027, 028, 029, 030	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0		\$0
4269	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU	North/South Classroom Extensions, SW Classrooms	Classrooms	2020	Sent to Maintenance	CMU in good condition, no stair step cracking or cracking through blocks. Rooms: 117, 118, 119	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0		\$0
4294	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Classrooms	2020	Sent to Maintenance	Wood doors in good condition. Rooms: 204, 207, 215, 232, 233, 234, 235, 229, 230, 231	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	10	\$2,400	Each	\$24,000
4295	Sam Rotolo Middle School	1467 - Interior Doors, Swinging-Wood	North/South Classroom Extensions, SW Classrooms	Classrooms	2020	Sent to Maintenance	Wood doors in good condition. Rooms: 217, 218, 219, 236, 237, 238, 239	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	7	\$2,400	Each	\$16,800
4296	Sam Rotolo Middle School	1467 - Interior Doors, Swinging-Wood	North/South Classroom Extensions, SW Classrooms	Classrooms	2020	Sent to Maintenance	HM door frames in good condition. Rooms: 217, 218, 219, 236, 237, 238, 239	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	7	\$2,400	Each	\$16,800
4297	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Classrooms	2020	Sent to Maintenance	HM door frames in good condition. Rooms: 203, 204, 207, 208, 209, 210, 211, 212, 214, 215, 223, 224, 225, 226, 227, 228, 232, 233, 234, 235, 201/202, 221/222, 229, 230, 231	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	27	\$2,400	Each	\$64,800
4306	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		Classrooms	2020	Sent to Maintenance	CMU in good condition, no stair step cracking or cracking through blocks. Rooms: 203, 204, 207, 208, 210, 212, 215, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 240, 201/202	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0		\$0
4308	Sam Rotolo Middle School	1462 - Interior Partitions, Fixed-CMU	North/South Classroom Extensions, SW Classrooms	Classrooms	2020	Sent to Maintenance	CMU in good condition, no stair step cracking or cracking through blocks. Rooms: 217, 218, 219, 236, 237, 238, 239	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0		\$0
4329	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Individual Toilets	2020	Sent to Maintenance	Doors in good condition. Rooms: T-3, T-4, T-11, T-14, T-15, T-20	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	7	\$2,400	Each	\$16,800

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4330	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Individual Toilets	2020	Sent to Maintenance	HM door frames in good condition. Rooms: T-3, T-4, T-5, T-6, T-7, T-8, T-11, T-14, T-15, T-16, T-20	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	12	\$2,400	Each	\$28,800
4336	Sam Rotolo Middle School	1430 - Flooring, Ceramic Tile		Individual Toilets	2020	Sent to Maintenance	Ceramic floor tile in good condition. Rooms: T-6	Interiors	Interior Finishes	Flooring	Tile Flooring	4-Future	Good	35	\$30	Square Foot	\$1,050
4338	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		Individual Toilets	2020	Sent to Maintenance	CMU is in good condition. T-3. T-4. T-5. T-6. T-7. T-8. T-11. T-14. T-15.	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0		\$0
4343	Sam Rotolo Middle School	1451 - Plumbing, Plumbing Fixtures		Individual Toilets	2014	Sent to Maintenance	T-3, T-4, T-5, T-6, T-7, T-11, T-14, T-15, T-16, T-20 (1 WC, 1 lav each) Per 2014 H/LS Report - There are an adequate number of fixtures in the building to meet the requirements of the Illinois Plumbing Code. The plumbing fixtures range from fair to new condition and appear to be operating correctly. The lavatories, urinals, and water closets are wall mounted. Cost is for water closet replacement.	Services	Plumbing	Domestic Water Distribution	Plumbing Fixtures	4-Future	Good	20	\$2,000	Each	\$40,000
4345	Sam Rotolo Middle School	1452 - Interior Partitions, Fixed-GWB		Individual Toilets	2020	Sent to Maintenance	GWB is in good condition. T-20.	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0		\$0
4350	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Individual Toilets	2020	Sent to Maintenance	Doors in good condition. T-25. T-31. T-30.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	3	\$2,400	Each	\$7,200
4351	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Individual Toilets	2020	Sent to Maintenance	HM door frames in good condition. T-24. T-25. T-31. T-30.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	4	\$2,400	Each	\$9,600
4355	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems		Individual Toilets	2020	Sent to Maintenance	ACT in excellent condition. T-24	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	4-Future	Excellent	217	\$8	Square Foot	\$1,628

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4357	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		Individual Toilets	2020	Sent to Maintenance	CMU is in good condition. T-24. T-25. T-31. T-30.	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0		\$0
4362	Sam Rotolo Middle School	1451 - Plumbing, Plumbing Fixtures		Individual Toilets	2014	Sent to Maintenance	T-24, T-25, T-31, T-30 (1WC, 1 lav each) Per 2014 H/LS Report - There are an adequate number of fixtures in the building to meet the requirements of the Illinois Plumbing Code. The plumbing fixtures range from fair to new condition and appear to be operating correctly. The lavatories, urinals, and water closets are wall mounted. Cost is for water closet replacement.	Services	Plumbing	Domestic Water Distribution	Plumbing Fixtures	4-Future	Good	8	\$2,000	Each	\$16,000
4364	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Grouped Toilets	2020	Sent to Maintenance	Wood door kickplate is dirty, but otherwise in good condition. T-17	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$2,400	Each	\$2,400
4365	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Grouped Toilets	2020	Sent to Maintenance	HM door frame in good condition. T-17	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$2,400	Each	\$2,400
4372	Sam Rotolo Middle School	1430 - Flooring, Ceramic Tile		Grouped Toilets	2020	Sent to Maintenance	Ceramic floor tile is in good conditions - dirty grout lines, but otherwise good. T-1. T-2. T-9. T-12. T-13. T-32. T-33.	Interiors	Interior Finishes	Flooring	Tile Flooring	4-Future	Good	1322	\$30	Square Foot	\$39,660
4373	Sam Rotolo Middle School	1945 - Interior Partitions, Fixed - Brick		Grouped Toilets	2020	Sent to Maintenance	Exposed brick wall in good condition. T-1. T-2. T-12.	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0		\$0
4375	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		Grouped Toilets	2020	Sent to Maintenance	CMU wall in good condition. T-1. T-2. T-9. T-12. T-13. T-32. T-33.	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0		\$0
4376	Sam Rotolo Middle School	1452 - Interior Partitions, Fixed-GWB		Grouped Toilets	2020	Sent to Maintenance	GWB walls in good condition. T-17	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0		\$0

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4382	Sam Rotolo Middle School	1451 - Plumbing, Plumbing Fixtures		Grouped Toilets	2014	Sent to Maintenance	T-1, T-2, T-9, T-12, T-13, T-17, T-32, T-33 (32 WC, 17 urinals, 24 lavs) Per 2014 H/LS Report - There are an adequate number of fixtures in the building to meet the requirements of the Illinois Plumbing Code. The plumbing fixtures range from fair to new condition and appear to be operating correctly. The lavatories, urinals, and water closets are wall mounted. Cost is for water closet replacement.	Services	Plumbing	Domestic Water Distribution	Plumbing Fixtures	4-Future	Good	73	\$2,000	Each	\$146,000
4387	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Grouped Toilets	2020	Sent to Maintenance	Wood doors in good condition. T-26. T-27. T-28. T-29.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	4	\$2,400	Each	\$9,600
4388	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Grouped Toilets	2020	Sent to Maintenance	HM door frames in good condition. T-26. T-27. T-28. T-29.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	4	\$2,400	Each	\$9,600
4392	Sam Rotolo Middle School	1430 - Flooring, Ceramic Tile		Grouped Toilets	2020	Sent to Maintenance	Ceramic floor tile in good condition - dirty grout, but no damaged tiles. T-26. T-27. T-28. T-29.	Interiors	Interior Finishes	Flooring	Tile Flooring	4-Future	Good	1100	\$30	Square Foot	\$33,000
4394	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		Grouped Toilets	2020	Sent to Maintenance	CMU in good condition. T-22. T-23. T-26. T-28. T-29.	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0		\$0
4395	Sam Rotolo Middle School	1945 - Interior Partitions, Fixed - Brick		Grouped Toilets	2020	Sent to Maintenance	Exposed brick wall in good condition. T-22, T-23	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0		\$0

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4398	Sam Rotolo Middle School	1451 - Plumbing, Plumbing Fixtures		Grouped Toilets	2014	Sent to Maintenance	T-22, T-23, T-26, T-27, T-28, T-29 (17 WC, 7 urinals, 12 lavs) Per 2014 H/LS Report - There are an adequate number of fixtures in the building to meet the requirements of the Illinois Plumbing Code. The plumbing fixtures range from fair to new condition and appear to be operating correctly. The lavatories, urinals, and water closets are wall mounted. Cost is for water closet replacement.	Services	Plumbing	Domestic Water Distribution	Plumbing Fixtures	4-Future	Good	36	\$2,000	Each	\$72,000
4404	Sam Rotolo Middle School	1525 - Flooring, Ceramic Tile	North/South Classroom Extensions, SW Classrooms	Grouped Toilets	2020	Sent to Maintenance	Ceramic floor tile in good condition - grout dirty, but no damaged tiles. T-34	Interiors	Interior Finishes	Flooring	Tile Flooring	4-Future	Good	150	\$30	Square Foot	\$4,500
4406	Sam Rotolo Middle School	1462 - Interior Partitions, Fixed-CMU	North/South Classroom Extensions, SW Classrooms	Grouped Toilets	2020	Sent to Maintenance	CMU in good condition. T-34 T-35	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0		\$0
4413	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		LMC	2020	Sent to Maintenance	Hollow metal doors in good condition	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	4	\$2,400	Each	\$9,600
4414	Sam Rotolo Middle School	1497 - Plumbing, Plumbing Fixtures	North/South Classroom Extensions, SW Classrooms	Grouped Toilets	2014	Sent to Maintenance	T-34, T-35 (9 WC, 4 urinals, 8 lavs) Per 2014 H/LS Report - There are an adequate number of fixtures in the building to meet the requirements of the Illinois Plumbing Code. The plumbing fixtures range from fair to new condition and appear to be operating correctly. The lavatories, urinals, and water closets are wall mounted. Cost is for water closet replacement.	Services	Plumbing	Domestic Water Distribution	Plumbing Fixtures	4-Future	Good	22	\$2,000	Each	\$44,000
4419	Sam Rotolo Middle School	1525 - Flooring, Ceramic Tile	North/South Classroom Extensions, SW Classrooms	Grouped Toilets	2020	Sent to Maintenance	Ceramic floor tile in good condition. T-36	Interiors	Interior Finishes	Flooring	Tile Flooring	4-Future	Good	35	\$30	Square Foot	\$1,050
4421	Sam Rotolo Middle School	1462 - Interior Partitions, Fixed-CMU	North/South Classroom Extensions, SW Classrooms	Grouped Toilets	2020	Sent to Maintenance	CMU in good condition. T-36, T-37	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0		\$0

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4426	Sam Rotolo Middle School	1497 - Plumbing, Plumbing Fixtures	North/South Classroom Extensions, SW Classrooms	Grouped Toilets	2014	Sent to Maintenance	T-36, T-37 (9 WC, 4 urinals, 8 lavs) Per 2014 H/LS Report - There are an adequate number of fixtures in the building to meet the requirements of the Illinois Plumbing Code. The plumbing fixtures range from fair to new condition and appear to be operating correctly. The lavatories, urinals, and water closets are wall mounted. Cost is for water closet replacement.	Services	Plumbing	Domestic Water Distribution	Plumbing Fixtures	4-Future	Good	21	\$2,000	Each	\$42,000
4441	Sam Rotolo Middle School	1431 - Flooring, Quarry Tile		Kitchen	2020	Sent to Maintenance	flooring (809 SF). -Room 145	Interiors	Interior Finishes	Flooring	Tile Flooring	4-Future	Good	809	\$30	Square Foot	\$24,270
4450	Sam Rotolo Middle School	1413 - Interior Doors, Coiling		Dish Washing	2020	Sent to Maintenance	Coiling door is in a good condition -Room 145B	Interiors	Interior Construction	Interior Doors	Interior Coiling Doors	4-Future	Good	2	\$2,000	Each	\$4,000
4453	Sam Rotolo Middle School	1431 - Flooring, Quarry Tile		Dish Washing	2020	Sent to Maintenance	Flooring is in a good condition -Room 145B	Interiors	Interior Finishes	Flooring	Tile Flooring	4-Future	Good	286	\$30	Square Foot	\$8,580
4455	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Offices/Pull-Out Spaces	2020	Sent to Maintenance	Wood door in good condition. 008. 009. 010A. 014A. 018A. 019A. 033. 121. (includes closet doors) 121A. 121B. 125. 126. 127. 128. 129. 130. 131. 132. 133. 135. 135C. 136. 136A. 147. 148. 148B 702	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	30	\$2,400	Each	\$72,000

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4459	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Offices/Pull-Out Spaces	2020	Sent to Maintenance	HM door frames in good condition. 005A. 006C. 008. 009. 010A. 012A. 014A. 018A. 019A. 121 (includes closet doors) 121A. 121B. 123. 126. 127. 128. 129. 130. 131. 132. 133. 135B. 135C. 136. 136A. 147. 148.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	34	\$2,400	Each	\$81,600
4463	Sam Rotolo Middle School	1947 - Interior Wall Finish, FRP		Dish Washing	2020	Sent to Maintenance	FRP is in a good condition -Room 145B	Interiors	Interior Finishes	Wall Finishes	Tile Wall Finish	4-Future	Good	286	\$8	Square Foot	\$2,288
4465	Sam Rotolo Middle School	1453 - Interior Doors, Swinging-Hollow Metal		Offices/Pull-Out Spaces	2020	Sent to Maintenance	HM doors in good condition. 703. 005A. 018A. 019A.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	4	\$1,950	Each	\$7,800

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4481	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		Offices/Pull-Out Spaces	2020	Sent to Maintenance	CMU in good condition. 005A. 006C. 008. 009. 010A. 014A. 018A. 019A. 033. 122. 124. 125. 126. 127. 128. 129. 130. 131. 132. 133. 134. 135A. 135B. 135C. 148. 148B. 144.	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Linear Foot	\$0
4487	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood	North/South Classroom Extensions, SW Classrooms	Science	2020	Sent to Maintenance	interior wood door in a good condition - Classroom 116	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	2	\$2,400	Each	\$4,800
4497	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU	North/South Classroom Extensions, SW Classrooms	Science	2020	Sent to Maintenance	CMU wall is in a good condition -Classroom 116	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0		\$0

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4508	Sam Rotolo Middle School	1411 - Interior Windows, Fixed		Offices/Pull-Out Spaces	2020	Sent to Maintenance	Interior windows in good condition. 121. 122. 123. 125. 126. 127. 128. 129. 130. 131. 132. 133. 135A. 135B. 135C. 138. 144. 005A. 018A. 019A.	Interiors	Interior Construction	Interior Windows	Interior Fixed Windows	4-Future	Good	0	\$45	Square Foot	\$0
4509	Sam Rotolo Middle School	1411 - Interior Windows, Fixed		Offices/Pull-Out Spaces	2020	Sent to Maintenance	Interior windows in good condition. 220A	Interiors	Interior Construction	Interior Windows	Interior Fixed Windows	4-Future	Good	0	\$45	Square Foot	\$0
4514	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Offices/Pull-Out Spaces	2020	Sent to Maintenance	Wood doors in good condition. 602. 604. 804.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	3	\$2,400	Each	\$7,200
4515	Sam Rotolo Middle School	1545 - Plumbing, Plumbing Fixtures	North/South Classroom Extensions, SW Classrooms	Science	2014	Sent to Maintenance	-Classroom 116 Per 2014 H/LS Report - no reference to classroom sinks.	Services	Plumbing	Domestic Water Distribution	Plumbing Fixtures	4-Future	Good	0	\$2,500	Each	\$0
4517	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Offices/Pull-Out Spaces	2020	Sent to Maintenance	HM door frame in good condition. Could be repainted. 601. 602. 604. 802. 803. 804. 220A.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	7	\$2,400	Each	\$16,800
4518	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood	North/South Classroom Extensions, SW Classrooms	Science	2020	Sent to Maintenance	interior wood door in a good condition -Classroom 216	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	2	\$2,400	Each	\$4,800
4521	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU	North/South Classroom Extensions, SW Classrooms	Science	2020	Sent to Maintenance	CMU wall in a good condition -Classroom 216	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0		\$0
4523	Sam Rotolo Middle School	1453 - Interior Doors, Swinging-Hollow Metal		Offices/Pull-Out Spaces	2020	Sent to Maintenance	HM door in good condition. 602, 803	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	2	\$1,950	Each	\$3,900

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4532	Sam Rotolo Middle School	1545 - Plumbing, Plumbing Fixtures	North/South Classroom Extensions, SW Classrooms	Science	2014	Sent to Maintenance	-Classroom 216 Per 2014 H/LS Report - no reference to classroom sinks.	Services	Plumbing	Domestic Water Distribution	Plumbing Fixtures	4-Future	Good	0	\$2,500	Each	\$0
4537	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Science	2020	Sent to Maintenance	- Door fair, frame good classroom 105 and 106 -Hallway side of door good, inside classroom fair, frame good classroom 113	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	6	\$2,400	Each	\$14,400
4541	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		Science	2020	Sent to Maintenance	-Crack by window sill classroom 106 - Classrooms 106 &113	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0		\$0
4552	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		Offices/Pull-Out Spaces	2020	Sent to Maintenance	CMU in good condition. 601. 602. 604. 802. 803. 804. 220A - sealant cracking in 2 corners.	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Square Foot	\$0
4565	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Science	2020	Sent to Maintenance	Door fair, frame good Classrooms 205, 206, and 213	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	6	\$2,400	Each	\$14,400
4580	Sam Rotolo Middle School	1545 - Plumbing, Plumbing Fixtures		Science	2014	Sent to Maintenance	Classrooms: 206 & 213 Per 2014 H/LS Report - no reference to classroom sinks.	Services	Plumbing	Domestic Water Distribution	Plumbing Fixtures	4-Future	Good	0	\$2,500	Each	\$0
4581	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Mechanical/Electrical Rooms	2020	Sent to Maintenance	Wood door in good condition. Sprinkler Room 32	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$2,400	Each	\$2,400
4584	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Mechanical/Electrical Rooms	2020	Sent to Maintenance	Wood door in good condition. 020A	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$2,400	Each	\$2,400
4588	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Mechanical/Electrical Rooms	2020	Sent to Maintenance	HM door frame in good condition. Electrical 705	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$2,400	Each	\$2,400
4591	Sam Rotolo Middle School	1453 - Interior Doors, Swinging-Hollow Metal		GYM	2020	Sent to Maintenance	Door leading to back corridor has minimal scrapes -West GYM	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	3	\$1,950	Each	\$5,850
4595	Sam Rotolo Middle School	1453 - Interior Doors, Swinging-Hollow Metal		GYM	2020	Sent to Maintenance	Frames are overall in good shape, could used some re-painting - East GYM frames in Upper Gym are in a good condition - Upper GYM	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	8	\$1,950	Each	\$15,600
4598	Sam Rotolo Middle School	1403 - Slab on Grade		Mechanical/Electrical Rooms	2020	Sent to Maintenance	Concrete floor in good condition. Sprinkler Room 32	Substructure	Slabs-On-Grade	Standard Slabs-on-Grade		4-Future	Good	338	\$20	Square Foot	\$6,760

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4599	Sam Rotolo Middle School	1400 - Interiors, Flooring - Wood		Gym	2020	Sent to Maintenance	Floor appears to have recently been waxed. Minor scuffs but in good overall condition - West GYM Per Capital Projects Plan - West Gym floor scheduled for replacement in 2035. Cost is to replace flooring.	Interiors	Interior Finishes	Flooring	Wood Flooring	4-Future	Good	4795	\$25	Square Foot	\$119,875
4601	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		Mechanical/Electrical Rooms	2020	Sent to Maintenance	CMU in good condition. 143. 705. 147A.	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Each	\$0
4605	Sam Rotolo Middle School	1402 - Interiors, Flooring - Wood	South Gym	Gym	2020	Sent to Maintenance	Original flooring - minor scuffs, due for resanding. South Gym Per Capital Projects Plan - South Gym floor due for replacement in 2050.	Interiors	Interior Finishes	Flooring	Wood Flooring	4-Future	Good	5986	\$25	Square Foot	\$149,650
4608	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		GYM	2020	Sent to Maintenance	CMU walls are in a good condition East GYM West GYM Upper GYM	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0		\$0
4613	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Mechanical/Electrical Rooms	2020	Sent to Maintenance	HM door frame in good condition. 020A, 220C	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	2	\$2,400	Each	\$4,800
4618	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		Mechanical/Electrical Rooms	2020	Sent to Maintenance	CMU in good condition. Mechanical 020A	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Each	\$0
4624	Sam Rotolo Middle School	1499 - Interior Doors, Swinging-Hollow Metal	South Gym	GYM	2020	Sent to Maintenance	-Interior Hollow Metal Frame is in a good condition - South GYM	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$1,950	Each	\$1,950
4626	Sam Rotolo Middle School	1409 - Exterior Entrance Doors, Hollow Metal	South Gym	GYM	2020	Sent to Maintenance	Exterior Hollow metal door is in a good condition - South GYM	Shell	Exterior Vertical Enclosures	Exterior Doors and Grilles	Exterior Entrance Doors	4-Future	Good	4	\$1,950	Each	\$7,800
4627	Sam Rotolo Middle School	1409 - Exterior Entrance Doors, Hollow Metal	South Gym	GYM	2020	Sent to Maintenance	Exterior Hollow metal frame is in a good condition - South GYM	Shell	Exterior Vertical Enclosures	Exterior Doors and Grilles	Exterior Entrance Doors	4-Future	Good	4	\$1,950	Each	\$7,800
4633	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		Janitor	2020	Sent to Maintenance	CMU in good condition. J-3	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Each	\$0
4641	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		Janitor	2020	Sent to Maintenance	CMU in good condition. J-4	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Each	\$0
4649	Sam Rotolo Middle School	1462 - Interior Partitions, Fixed-CMU	North/South Classroom Extensions, SW Classrooms	Janitor	2020	Sent to Maintenance	CMU in good condition. J-8	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Each	\$0
4652	Sam Rotolo Middle School	1467 - Interior Doors, Swinging-Wood	North/South Classroom Extensions, SW Classrooms	Janitor	2020	Sent to Maintenance	HM door frame in good condition. J-8	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$2,400	Each	\$2,400

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4655	Sam Rotolo Middle School	1547 - Interior Doors, Swinging-Hollow Metal		Locker Room	2020	Sent to Maintenance	Interior hollow metal frames are in a good condition 18C & 19B	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	2	\$1,950	Each	\$3,900
4657	Sam Rotolo Middle School	1467 - Interior Doors, Swinging-Wood	North/South Classroom Extensions, SW Classrooms	Janitor	2020	Sent to Maintenance	Wood door in good condition. J-8	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$2,400	Each	\$2,400
4660	Sam Rotolo Middle School	1499 - Interior Doors, Swinging-Hollow Metal	North/South Classroom Extensions, SW Classrooms	Janitor	2020	Sent to Maintenance	HM door in good condition. J-7	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$1,950	Each	\$1,950
4662	Sam Rotolo Middle School	1499 - Interior Doors, Swinging-Hollow Metal	North/South Classroom Extensions, SW Classrooms	Janitor	2020	Sent to Maintenance	HM door frame in good condition. J-7	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$1,950	Each	\$1,950
4664	Sam Rotolo Middle School	1462 - Interior Partitions, Fixed-CMU	North/South Classroom Extensions, SW Classrooms	Janitor	2020	Sent to Maintenance	CMU in good condition. J-7	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Each	\$0
4673	Sam Rotolo Middle School	1430 - Flooring, Ceramic Tile		Locker Room	2020	Sent to Maintenance	Flooring Ceramic tile is in a good condition - 18C & 19B	Interiors	Interior Finishes	Flooring	Tile Flooring	4-Future	Good	250	\$30	Square Foot	\$7,500
4675	Sam Rotolo Middle School	1462 - Interior Partitions, Fixed-CMU		Locker Room	2020	Sent to Maintenance	CMU walls are in a good condition - 18, 19, 18C & 19B	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0		\$0
4694	Sam Rotolo Middle School	1505 - Interior Partitions, Fixed-CMU		Stage/Cafeteria/ Multipurpose	2020	Sent to Maintenance	- CMU sealant is splitting at the corners of the room - 24	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0		\$0
4707	Sam Rotolo Middle School	1421 - Interior Railings and Handrails		Stage/Cafeteria/ Multipurpose	2020	Sent to Maintenance	-Stairs and pipe rails are in good condition - 23 & 24	Interiors	Interior Construction	Interior Specialties	Interior Railings and Handrails	4-Future	Good	0	\$125	Linear Foot	\$0
4719	Sam Rotolo Middle School	1419 - Ceilings, Acoustical Suspended Systems		commons	2020	Sent to Maintenance	ACT is in Excellent condition	Interiors	Interior Construction	Suspended Ceiling Construction	Acoustical Suspended Ceilings	4-Future	Excellent	3000	\$8	Square Foot	\$22,500
4721	Sam Rotolo Middle School	1669 - Flooring, LVT		commons	2020	Sent to Maintenance	LVT flooring is in good condition	Interiors	Interior Finishes	Flooring	Resilient Flooring	4-Future	Excellent	5338	\$10	Square Foot	\$53,380
4723	Sam Rotolo Middle School	1945 - Interior Partitions, Fixed - Brick		commons	2020	Sent to Maintenance	Brick wall is in good condition	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0		\$0
4724	Sam Rotolo Middle School	1498 - Interior Partitions, Fixed-GWB		commons	2020	Sent to Maintenance	GWB wall is in good condition	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0		\$0
4725	Sam Rotolo Middle School	1499 - Interior Doors, Swinging-Hollow Metal		Corridor	2020	Sent to Maintenance	- Minor scratches but door is on hold opens and in pretty good shape - Corridor/Mechanical. - Corridor near Art/Drafting is in a good condition. - 8th East 6th East - 6th East 6th East.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	6	\$1,950	Each	\$11,700

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4729	Sam Rotolo Middle School	1499 - Interior Doors, Swinging-Hollow Metal		Corridor	2020	Sent to Maintenance	- Interior HM frame is in a good condition - Corridor btwn Stu. Services and Café. - Interior HM frame is in a good condition - Corridor near Art/Drafting. - Interior HM frame is in a good condition - 8th East. - Interior HM frame CENTER MULLION PAINT CHIPPING - 8th West. - Interior HM frame is in a good condition - 8th North. - Interior HM frame is in a good condition - 6th East. - Interior HM frame CENTER MULLION PAINT CHIPPING - 6th West. - Interior HM frame is in a good condition - 6th Central.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	8	\$1,950	Each	\$15,600
4731	Sam Rotolo Middle School	1409 - Exterior Entrance Doors, Hollow Metal		Corridor	2020	Sent to Maintenance	- Exterior Frame Corridor - Gymnasiums is in a good condition.	Shell	Exterior Vertical Enclosures	Exterior Doors and Grilles	Exterior Entrance Doors	4-Future	Good	1	\$1,950	Each	\$1,950
4739	Sam Rotolo Middle School	1462 - Interior Partitions, Fixed-CMU		Corridor	2020	Sent to Maintenance	-CMU walls are in a good condition - Corridor - Gymnasiums. - CMU walls are in a good condition - Corridor between Gyms and Exploratory. - CMU walls are in a good condition - Corridor btwn Stu. Services and Café. - CMU walls are in a good condition - Corridor near Art/Drafting. - CMU walls are in a good condition -	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0		\$0
4751	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Stair	2020	Sent to Maintenance	- wood door Push hardware is slightly rusting, but doors are in good shape - Stair - West	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$2,400	Each	\$2,400
4752	Sam Rotolo Middle School	1499 - Interior Doors, Swinging-Hollow Metal		Stair	2020	Sent to Maintenance	-HM door Located at top of the stairs connected to upper gymnasium, mostly covered by pads - Stair - West Gymnasium NE.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$1,950	Each	\$1,950
4753	Sam Rotolo Middle School	1409 - Exterior Entrance Doors, Hollow Metal		Stair	2020	Sent to Maintenance	-Exterior Doors are in good condition - Stair - 7th gr. North Corr. & Stair - 8th gr. North Corr.	Shell	Exterior Vertical Enclosures	Exterior Doors and Grilles	Exterior Entrance Doors	4-Future	Good	4	\$1,950	Each	\$7,800
4757	Sam Rotolo Middle School	1499 - Interior Doors, Swinging-Hollow Metal		Stair	2020	Sent to Maintenance	-Interior frame is in good condition - Stair - 8th gr. North Corr.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$1,950	Each	\$1,950
4758	Sam Rotolo Middle School	1464 - Exterior Entrance Doors, Hollow Metal		Stair	2020	Sent to Maintenance	-Exterior frame is in good condition - Stair - Near Main Entrance & Commons stair by 6th grade	Shell	Exterior Vertical Enclosures	Exterior Doors and Grilles	Exterior Entrance Doors	4-Future	Good	1	\$1,950	Each	\$1,950
4765	Sam Rotolo Middle School	1533 - Flooring, Carpet		Stair	2020	Sent to Maintenance	Carpet in a good condition. -Stair - 8th gr. North Corr.	Interiors	Interior Finishes	Flooring	Carpeting	4-Future	Good	1493	\$7	Square Foot	\$9,705

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4766	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		Stair	2020	Sent to Maintenance	CMU walls are in good condition - Stair - 7th gr. North Corr. CMU walls are in good condition - Stair - 8th gr. North Corr. CMU walls are in good condition - Stair - West Gymnasium NE.	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0		\$0
4768	Sam Rotolo Middle School	1945 - Interior Partitions, Fixed - Brick		Stair	2020	Sent to Maintenance	Brick walls are in good condition - Stair - Near Main Entrance - Commons stair by 6th grade.	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0		\$0
4778	Sam Rotolo Middle School	1421 - Interior Railings and Handrails		Stair	2020	Sent to Maintenance	Stairs- pipe rails are in good condition - Stair - 7th gr. North Corr., Stair - 8th gr. North Corr., Stair - Above Mech 020B, -Stair - Above Mech 017C, - Stair - West Gymnasium NE.	Interiors	Interior Construction	Interior Specialties	Interior Railings and Handrails	4-Future	Good	0	\$125	Linear Foot	\$0
4780	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood	North/South Classroom Extensions, SW Classrooms	Stair by door N-2	2020	Sent to Maintenance	- Interior wood door is in a good condition.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$2,400	Each	\$2,400
4782	Sam Rotolo Middle School	1409 - Exterior Entrance Doors, Hollow Metal	North/South Classroom Extensions, SW Classrooms	Stair by door N-2	2020	Sent to Maintenance	- Exterior door is in a good condition.	Shell	Exterior Vertical Enclosures	Exterior Doors and Grilles	Exterior Entrance Doors	4-Future	Good	1	\$1,950	Each	\$1,950
4783	Sam Rotolo Middle School	1453 - Interior Doors, Swinging-Hollow Metal	North/South Classroom Extensions, SW Classrooms	Stair by door N-2	2020	Sent to Maintenance	- Interior door frame is in a good condition.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$1,950	Each	\$1,950
4784	Sam Rotolo Middle School	1409 - Exterior Entrance Doors, Hollow Metal	North/South Classroom Extensions, SW Classrooms	Stair by door N-2	2020	Sent to Maintenance	- Exterior door frame is in a good condition.	Shell	Exterior Vertical Enclosures	Exterior Doors and Grilles	Exterior Entrance Doors	4-Future	Good	1	\$1,950	Each	\$1,950
4787	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU	North/South Classroom Extensions, SW Classrooms	Stair by door N-2	2020	Sent to Maintenance	-CMU wall Stone cap on guardrail walls is dirty	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0		\$0
4793	Sam Rotolo Middle School	1421 - Interior Railings and Handrails	North/South Classroom Extensions, SW Classrooms	Stair by door N-2	2020	Sent to Maintenance	Stair pipe and rails are in good condition	Interiors	Interior Construction	Interior Specialties	Interior Railings and Handrails	4-Future	Good	0	\$125	Linear Foot	\$0
4794	Sam Rotolo Middle School	1453 - Interior Doors, Swinging-Hollow Metal	North/South Classroom Extensions, SW Classrooms	Corridor	2020	Sent to Maintenance	Interior HM door is in a good condition - 7th New Central.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$1,950	Each	\$1,950
4796	Sam Rotolo Middle School	1453 - Interior Doors, Swinging-Hollow Metal	North/South Classroom Extensions, SW Classrooms	Corridor	2020	Sent to Maintenance	Interior HM door frame is in a good condition - 7th, 8th, and 6th New Central	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	3	\$1,950	Each	\$5,850
4801	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU	North/South Classroom Extensions, SW Classrooms	Corridor	2020	Sent to Maintenance	Wall CMU is in a good condition - 7th New central	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0		\$0
4857	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		Stairs by Classroom 229	2020	Sent to Maintenance	CMU wall is in a good condition	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0		\$0

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4870	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Storage	2020	Sent to Maintenance	Wood door in good condition. 26. 706. 007C. 014C. 129A.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	5	\$2,400	Each	\$12,000
4871	Sam Rotolo Middle School	1453 - Interior Doors, Swinging-Hollow Metal		Storage	2020	Sent to Maintenance	HM door in good condition. 031B	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$1,950	Each	\$1,950
4874	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Storage	2020	Sent to Maintenance	HM door frame in good condition. 26. 007A. 007C. 012B. 014B. 014C. 017A. 129A.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	8	\$2,400	Each	\$19,200
4875	Sam Rotolo Middle School	1453 - Interior Doors, Swinging-Hollow Metal		Storage	2020	Sent to Maintenance	HM door frame in good condition. 019C, 031B	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	2	\$1,950	Each	\$3,900
4887	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		Storage	2020	Sent to Maintenance	CMU in good condition. 26. 33. 139. 141. 142. 147. 148C. 149. 706. 007C. 012C. 014B. 014C. 017A. 019C. 129A. 149A.	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Square Foot	\$0
4889	Sam Rotolo Middle School	1452 - Interior Partitions, Fixed-GWB		Storage	2020	Sent to Maintenance	GWB walls in good condition. 129A	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Square Foot	\$0
4897	Sam Rotolo Middle School	1547 - Interior Doors, Swinging-Hollow Metal	South Gym	Storage	2020	Sent to Maintenance	HM door in good condition - covered mostly by wall pads. 034A	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$1,950	Each	\$1,950
4898	Sam Rotolo Middle School	1547 - Interior Doors, Swinging-Hollow Metal	South Gym	Storage	2020	Sent to Maintenance	HM door frame in good condition. 034A	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$1,950	Each	\$1,950
4900	Sam Rotolo Middle School	1505 - Interior Partitions, Fixed-CMU	South Gym	Storage	2020	Sent to Maintenance	CMU in good condition. 034A	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Square Foot	\$0

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4905	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Storage	2020	Sent to Maintenance	Wood door in good condition. 805. 020B. 020C. 212A. 220B.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	5	\$2,400	Each	\$12,000
4907	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Storage	2020	Sent to Maintenance	HM door frame in good condition. 605. 805. 020B. 020C. 212A. 220B.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	6	\$2,400	Each	\$14,400
4908	Sam Rotolo Middle School	1453 - Interior Doors, Swinging-Hollow Metal		Storage	2020	Sent to Maintenance	HM door frame in good condition. 020A	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$1,950	Each	\$1,950
4917	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		Storage	2020	Sent to Maintenance	CMU in good condition. 605. 805. 020A. 020B. 020C.	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Each	\$0
4925	Sam Rotolo Middle School	1467 - Interior Doors, Swinging-Wood	North/South Classroom Extensions, SW Classrooms	Storage	2020	Sent to Maintenance	Wood door in good condition. 216A. 216B.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	2	\$2,400	Each	\$4,800
4926	Sam Rotolo Middle School	1467 - Interior Doors, Swinging-Wood	North/South Classroom Extensions, SW Classrooms	Storage	2020	Sent to Maintenance	HM door frame in good condition. 216A. 216B.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	2	\$2,400	Each	\$4,800
4930	Sam Rotolo Middle School	1462 - Interior Partitions, Fixed-CMU	North/South Classroom Extensions, SW Classrooms	Storage	2020	Sent to Maintenance	CMU in good condition. 216B	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Each	\$0
4936	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Copier 704	2020	Sent to Maintenance	Wood door in good condition. 704	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$2,400	Each	\$2,400
4937	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Copier 704	2020	Sent to Maintenance	HM door frame in good condition. 704	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$2,400	Each	\$2,400
4940	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		Copier 704	2020	Sent to Maintenance	CMU in good condition. 704	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Each	\$0
4944	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Science Prep 701	2020	Sent to Maintenance	Wood door in good condition. 701	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$2,400	Each	\$2,400
4945	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Science Prep 701	2020	Sent to Maintenance	HM door frame in good condition. 701	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$2,400	Each	\$2,400
4946	Sam Rotolo Middle School	1453 - Interior Doors, Swinging-Hollow Metal		Science Prep 701	2020	Sent to Maintenance	HM door frame in good condition. 701	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$1,950	Each	\$1,950

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
4947	Sam Rotolo Middle School	1453 - Interior Doors, Swinging-Hollow Metal		Science Prep 701	2020	Sent to Maintenance	HM door in good condition. 701	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$1,950	Each	\$1,950
4958	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		Science Prep 801	2020	Sent to Maintenance	CMU in good condition. 801	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Each	\$0
4960	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Science Prep 801	2020	Sent to Maintenance	HM frame in good condition. 801	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$2,400	Each	\$2,400
4961	Sam Rotolo Middle School	1453 - Interior Doors, Swinging-Hollow Metal		Science Prep 801	2020	Sent to Maintenance	HM frame in good condition. 801	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$1,950	Each	\$1,950
4971	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		FACS/Sewing	2020	Sent to Maintenance	HM door frame in good condition. 10, 11	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	2	\$2,400	Each	\$4,800
4973	Sam Rotolo Middle School	1409 - Exterior Entrance Doors, Hollow Metal		FACS/Sewing	2020	Sent to Maintenance	Exterior HM door and frame in good condition - touch up paint required. 10	Shell	Exterior Vertical Enclosures	Exterior Doors and Grilles	Exterior Entrance Doors	4-Future	Good	1	\$1,950	Each	\$1,950
4977	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		FACS/Sewing	2020	Sent to Maintenance	CMU in good condition. 10, 11	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Each	\$0
5016	Sam Rotolo Middle School	1453 - Interior Doors, Swinging-Hollow Metal		Music	2020	Sent to Maintenance	HM doors in good condition. 005B. 007B.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	2	\$1,950	Each	\$3,900
5019	Sam Rotolo Middle School	1453 - Interior Doors, Swinging-Hollow Metal		Music	2020	Sent to Maintenance	HM door frame in good condition. 005B.	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$1,950	Each	\$1,950
5022	Sam Rotolo Middle School	1409 - Exterior Entrance Doors, Hollow Metal		Music	2020	Sent to Maintenance	Exterior HM door and frame in good condition, just need touch up paint. 5. 6.	Shell	Exterior Vertical Enclosures	Exterior Doors and Grilles	Exterior Entrance Doors	4-Future	Good	2	\$1,950	Each	\$3,900
5056	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		Music	2020	Sent to Maintenance	CMU in good condition - minor cracking at exterior windows and sealant joints, some nail holes. 7. 16. 005B. 006A. 006B. Note: quantity includes 10 LF/room	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	50	\$0	Linear Foot	\$0
5084	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Visual/Digital Arts	2020	Sent to Maintenance	HM door frame in good condition. 13, 14, 15	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	3	\$2,400	Each	\$7,200
5086	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Visual/Digital Arts	2020	Sent to Maintenance	HM door frame in fair condition. 1, 4	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	2	\$2,400	Each	\$4,800
5091	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Visual/Digital Arts	2020	Sent to Maintenance	Wood door in good condition. 014	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$2,400	Each	\$2,400

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost
5099	Sam Rotolo Middle School	1409 - Exterior Entrance Doors, Hollow Metal		Visual/Digital Arts	2020	Sent to Maintenance	Exterior HM door and frame in good condition - only need touch up paint.	Shell	Exterior Vertical Enclosures	Exterior Doors and Grilles	Exterior Entrance Doors	4-Future	Good	2	\$1,950	Each	\$3,900
5114	Sam Rotolo Middle School	1407 - Interior Partitions, Fixed-CMU		Visual/Digital Arts	2020	Sent to Maintenance	CMU in good condition. 1. 4. 13. 14. 15.	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Square Foot	\$0
5123	Sam Rotolo Middle School	1412 - Interior Doors, Swinging-Wood		Wood Shop 012	2020	Sent to Maintenance	Wood door and frame in good condition. 012	Interiors	Interior Construction	Interior Doors	Interior Swinging Doors	4-Future	Good	1	\$2,400	Each	\$2,400
5124	Sam Rotolo Middle School	1409 - Exterior Entrance Doors, Hollow Metal		Wood Shop 012	2020	Sent to Maintenance	Exterior HM door and frame in good condition - some touch up paint required. 012	Shell	Exterior Vertical Enclosures	Exterior Doors and Grilles	Exterior Entrance Doors	4-Future	Good	1	\$1,950	Each	\$1,950
5206	Sam Rotolo Middle School	1669 - Flooring, LVT		Office/Pull-Out	2020	Sent to Maintenance	LVT in overall good condition 147.	Interiors	Interior Finishes	Flooring	Resilient Flooring	4-Future	Good	149	\$10	Square Foot	\$1,490
5208	Sam Rotolo Middle School	1669 - Flooring, LVT		Office/Pull-Out	2020	Sent to Maintenance	LVT in excellent (like new) condition. 148B	Interiors	Interior Finishes	Flooring	Resilient Flooring	4-Future	Excellent	677	\$10	Square Foot	\$6,770
5236	Sam Rotolo Middle School	1452 - Interior Partitions, Fixed-GWB		Office/Pull-Out	2020	Sent to Maintenance	GWB partitions in overall good condition. 121, 121A, 121B, 122, 123, 124, 125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 135A, 135C, 136A, 137, 138, 148	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Linear Foot	\$0
5254	Sam Rotolo Middle School	1437 - Fixed Equipment, Casework		Office/Pull-Out	2020	Sent to Maintenance	Casework is in excellent (like-new) condition 121	Equipment and Furnishings	Furnishings	Fixed Furnishings	Casework	4-Future	Excellent	34	\$800	Linear Foot	\$27,200
5357	Sam Rotolo Middle School	2027 - Interiors, Millwork - Sills		Office/Pull-Out	2020	Sent to Maintenance	Plastic laminate window sills at exterior windows are in good condition 123, 124, 125, 126, 127, 128, 129, 130, 131	Interiors	Interior Finishes	Interior Fabrications		4-Future	Good	0	\$75	Linear Foot	\$0
5371	Sam Rotolo Middle School	1438 - Fixed Equipment, Window Treatments-Manual		Office/Pull-Out	2020	Sent to Maintenance	Roller Shades at exterior windows are in good condition 123, 124, 125, 126, 127, 128, 129, 130, 131	Equipment and Furnishings	Furnishings	Fixed Furnishings	Window Treatments	4-Future	Good	0	\$90	Linear Foot	\$0
5587	Sam Rotolo Middle School	1452 - Interior Partitions, Fixed-GWB		Corridor	2020	Sent to Maintenance	GWB in good condition Admin corridor to Staff Lounge	Interiors	Interior Construction	Interior Partitions	Interior Fixed Partitions	4-Future	Good	0	\$0	Linear Foot	\$0
7843	Sam Rotolo Middle School	1415 - HVAC, Boiler Plant			2020	Sent to Maintenance	Per Capital Projects Plan - boiler plant scheduled for replacement in 2050	Services	Heating, Ventilation, and Air Conditioning (HVAC)	Heating Systems	Heat Generation	4-Future	Good	1	\$450,000	Lump Sum	\$450,000

Assessment ID	Campus	Linked Bldg System	Addition	Room	Assessment Year	Assessment Status	Description	Building System L1	Building System L2	Building System L3	Building System L4	Priority	Facility Condition	Quantity	Unit Cost	Unit Of Measure	Estimated Cost			
7844	Sam Rotolo Middle School	1418 - HVAC, Cooling-Chiller			2020	Sent to Maintenance	Per Capital Projects Plan - chiller plant scheduled for replacement in 2035	Services	Heating, Ventilation, and Air Conditioning (HVAC)	Cooling Systems	Central Cooling	4-Future	Good	1	\$525,000	Lump Sum	\$525,000			
7846	Sam Rotolo Middle School	8623 - Sitework, Track			2020	Sent to Maintenance	Per Capital Projects Plan - Athletic track scheduled for replacement in 2038. Cost to rebuild track.	Sitework	Site Improvements	Athletic, Recreational, and Playfield Areas	Athletic Areas	4-Future	Good	1	\$210,000	Lump Sum	\$210,000			
7963	Sam Rotolo Middle School	1669 - Flooring, LVT		Storage	2020	Sent to Maintenance	LVT in like-new condition 148C	Interiors	Interior Finishes	Flooring	Resilient Flooring	4-Future	Excellent	8	\$10	Square Foot	\$80			
																		Total Cost	\$17,273,115	
																			Priority 1	\$4,245,113
																			Priority 2	\$7,168,688